

MORA INDEPENDENT SCHOOL DISTRICT 5 Year Facilities Master Plan

FINAL • 2019-2023 • # 5372









SECTION 0: INTRODUCTION

Master Plan Team

Executive Summary

- Requirement
- Process and Adoption
- School District Information
- Facilities
- Demographics and Enrollment
- Utilization and Capacity
- District Financial Information
- Technology and Preventive Maintenance
- PSCOC Facilities Assessment Database
- School District Priorities
- School District Capital Plan

Acronyms/Definitions

SECTION 1: FACILITY GOALS/PROCESS

1.1 Goals

- District Mission Statement and Core Values
- District Educational Goals / Program of Instruction
- District Relationship with the Community
- District Facilities Alignment to NMAS
- Long Range District Facility Goals

1.2 Public Process

- Decision Making Authority
- Facilities Master Plan Process
- FMP Prioritization Schedule

1.3 Issues and Findings

SECTION 2: EXISTING & PROJECTED CONDITIONS

2.1 Programs

- 2.1.1 District Information including:
 - Total Enrollment
 - Number of Schools
 - Types of Schools / Grade Configuration
 - School Feeder Chart
 - Pupil to Teacher Ratio
 - School Grades
 - Educational Programs
- 2.1.2 Anticipated Changes in Educational Programs
- 2.1.3 Shared/Joint Use of Facilities

2.2 Sites/ Facilities

- 2.2.1 District Site Information
 - District Site Maps
- 2.2.2 District Facilities Inventory

2.3 District Growth

- District Regional Perspectives
 - Maps of District Region
- Demographic Trends
 - County, District, Town Population Comparisons
 - Median Ages
 - Population Projections
 - County Births to Kindergarten Enrollment
 - Ethnicity
 - Household Types
- Economic and Development Analysis
 - County Industries
 - Occupations and Earnings
 - Poverty Designation

2.4 Enrollment

- Relevant Factors
- Projection Method
- 2.4.1 and 2.4.2 Historic and Projected Enrollment
 - District Wide Enrollment Trends
 - Elementary School Enrollment
 - Middle School Enrollment
 - High School Enrollment

2.5 Utilization/Capacity

- 2.5.1 Required and Existing Classroom Spaces
- 2.5.2 Special Factors Influencing Facility Use
 - Pupil to Teacher Ratio
 - Special Education Spaces
 - Student Transfers, Magnet and Other Special Programs
 - Boundary Areas
 - Instructional Space Comparisons
- 2.5.3 Utilization and Capacity Analysis
 - Capacity Based on NM Adequacy Standards
 - Maximum and Functional Facility Capacity
 - Instructional Space Capacity
 - Utilization Analysis
- 2.5.4 Strategies to Meet Space Needs
- 2.5.5 Under-utilized Spaces

SECTION 3: CAPITAL IMPROVEMENTS PLAN

3.1 Total Capital Needs

- Capital Improvement Project History
- District's Financial Resources
- Anticipated Capital Needs and Funding Sources
- Facility Needs by Facility

3.2 Prioritization Process and Budgeting

- 3.2.1 Development of FMP and Prioritization Process
 - FMP Steering Committee and Community Input
 - Process and Criteria for Prioritizing District Needs
 - FMP Prioritization Schedule
- Facility Needs by Category

3.3 Capital Plan

- 3.3.1 Priority Capital Improvements for Next 5 Years
 - FMP District Priorities
 - Facilities Assessment Database (FAD)
- 3.3.2 Financial Strategies and Alternatives
- 3.3.3 Capital Plan

SECTION 4: MASTER PLAN SUPPORT MATERIALS

4.1 Support Material by School

- 4.1.1 Site/School Details
 - FAD Mark-up/FMAR Reports
 - Executive Summary Report
 - School Details
 - Technology Overview
 - Energy Management Plan Overview
 - School Aerial
 - Construction Dates Plan
 - Building Floor Plans
 - Capacity Plans
 - School Utilization Spreadsheet


4.2 Support Material by District

- 4.2.1 Additional Information for School District
 - Technology Overview
 - Energy Management Plan Overview
 - Preventative Maintenance Plan

Appendix

- Additional Comments/Notes/Support Material
 - Presentations & Meetings

This page intentionally left blank



Master Plan Team

MORA INDEPENDENT SCHOOL DISTRICT REPRESENTATIVES

Mora Independent School District Board of Education

Tranquilino Hurtado – President George A. Trujillo – Vice President Dennis Romero – Secretary Lillian Maestas – Member Michael G. Benjamin – Member

Superintendent

Dr. Carla Spaniel - Interim Superintendent

FMP Core Committee

Ella Arellano Eugene Abeyta Miguel Martinez Bo Sanchez

PUBLIC SCHOOLS FACILITY AUTHORITY REPRESENTATIVES

Bill Sprick - Facilities Master Planner Karl Sitzberger - Regional Manager

PLANNING PROFESSIONAL Greer Stafford / SJCF Architecture

Marilyn Strube, Head Planner Gabriela Ochoa, Planner Alyssa Metoyer, Intern Jacqueline Zamora, Intern



1717 Louisiana Blvd. NE, Suite 205 Albuquerque, NM 87110 505.821.0235 SECTION

0

Master Plan Team

IN SECTION OF THE PARTY OF THE

Acronyms and Definitions

ADMIN – Administration

ANC – Ancillary

ART - Art

ATD - Attendance Office

AUD – Auditorium **AUX** – Auxiliary

AV - Audio/Video (room, closet)

B – Boy's Toilet

BDCP – Broadband Deficiences Corrections

Program

BKRM – Book Room BLDG – Building BR – Boiler Room BRK – Break Room

Building Efficiency – Ratio - NASF/ GSF

BUS - Business

BYOD - Bring Your Own Device

CA – Career Academy **CAF** – Cafeteria

CCSS – Common Core State Standards

CLRM – Classroom
CNC – Concessions
CNG – Changing Room
COMP – Computer Lab
CON – Conference

CONF – Conference Room

COR – Corridor **COUN** – Counseling

CSCI – Computer Science (lab, room)

DD Program – Developmentally Delayed

Program

DW – Dish Wash (room, area)

E – Electrical **ENG** – English

EPSS – Educational Plan for Student

Success

EQ – Equipment **F** – File Room

FAD – Facility Assessment Database **FCI** – Facility Condition Index (the ratio of

need repairs to current replacement value) **FF&E** – Furniture, Fixtures and Equipment

FF&E – Furniture, Fixtures and Equ

FIN – Finance Office

FMP - Facilities Master Plan

FO – Front Office FP – Free Play (area) FS – Food Service FZ – Freezer

G – Girl's Toilet

GSF – Gross Square Feet, or the sum of the net assignable square feet plus all other building area that is not assignable.

GYM – Gymnasium

ITV – Interactive TelevisionJ – Janitor's / Custodial ClosetHES – Holman Elementary School

HL – Hall KIT – Kitchen LA – Language Arts

LGMS – Lazaro Garcia Middle School

LEA – Local Education Agency

LHSS - Life-Health-Safety-Security-ADA

Code **LIB** – Library

LKRM – Lockers (room, area)

LNG – Lounge **LOB** – Lobby **M** – Men's Toilet

MACC – Maximum Allowable Construction

Cost

MAT – Material Storage MBPS – Megabits per second

MC – Media Center

MCS - Mora Combined School

MECH – Mechanical

MES – Mora Elementary School MHS – Mora High School

MISD – Mora Independent School District

MNT – Maintenance (room, area) MP – Multi-Purpose Room

MS – Media Storage

MT – Math N – Nurse

NASF – Net Assignable Square Feet, or building area that can be assigned to specific task, not including building

Acronyms and Definitions

circulation, wall thickness, mechanical equipment and toilet facilities

NMAS - New Mexico Adequacy Standards

O - Office

PE – Physical Education

PED – Public Education Department

PER – Personnel Office

PERM – Permanent building

PLC- Professional Learning Communities

PORT – Portable Building

PSCOC – Public School Capital Outlay

Council

PSFA – Public School Facilities Authority

PTR - Pupil to Teacher Ratio

REF – Refrigerator

SB - Sport's Booth

SCI – Science (room, lab)

SEAT – Seating (area)

SF – Square Feet

SHWR – Shower (area)

SLP – Speech / Language Pathology

SPED – Special Education

SQFT – Square Feet

S/R – Secretary / Receptionist

SRVC – Service (area)

SRVG – Cafeteria Serving (room, area)

SS - Social Studies

State FCI – State Facilities Condition Index

State ID - State Building Identification

Number

STG - Stage

STO - Storage

SUP – Supply (room, closet)

T – Toilet (unisex)

TARE – The area allowing circulation, space

for electrical,

mechanical, bldg and tech systems, toilets

and wall thickness

V - Vault

VE – Vestibule

VOC – Vocational (room, lab)

W - Women's Toilet

WAIT – Waiting (area, room)

WR – Work Room **WTS** – Weight Room

Executive Summary

REQUIREMENT

The Public School Capital Outlay Council (PSCOC)/Public School Facilities Authority (PSFA) require that New Mexico Public School Districts have a Facilities Master Plan as a prerequisite for eligibility to receive state capital outlay assistance (New Mexico Statutes Section [22-25-5 NMSA 1978]). This 5-Year Facilities Master Plan (FMP) was developed utilizing the School District Facilities Master Plan Components and Guidelines issued by the Public School Capital Outlay Council and the Public School Facilities Authority, 2014 Revision 6. It incorporates all public schools within the Mora Independent School District (MISD).

PROCESS AND ADOPTION

The following process was followed to conduct the facility assessment and to formulate the FMP. Refer to Section 1.2 for a detailed explanation of the FMP process.

- 1. School Board Develop and approve facilities master plan process
- 2. Gather/formulate data
- 3. FMP Committee Meetings Review, discuss data and develop recommendations
- 4. School Board Adoption of final FMP document

The Mora Independent School District Board of Education adopted the completed 5-Year Facilities Master Plan on April 24, 2019.

SCHOOL DISTRICT INFORMATION

Address

Mora Independent School District

#10 Ranger Drive Mora, NM 87732 Phone: 575.387.3100



Mora Independent Schools exists as a concrete foundation to prioritize every student, every day, in every way. We will provide students with the resources necessary to be successful in life. Our school culture will be one of security, respect, honesty, loyalty, accountability, investment, and positivity.

Vision

We the leadership of the Mora Independent Schools are committed to a vision in which the roots and values of our broader community shape our school culture and create an environment that is the best place to be, learn, work, grow and enjoy life!

Number of Schools 4
Types of Schools

1 Elementary School	pre K - K Grades
1 Combined School (ES, MS, HS)	1st - 12th Grades

Executive Summary

FACILITIES

Mora Independent School District has a total of four schools, three of them are in one combined campus. The state identification number is 44330000 and the sites are district owned. The total facility inventory square footage is 180,621 square feet including administration and support.

Of the 61 total classrooms, 31 are general use, 20 are special use and 10 special education. There are three portable classrooms in the district; two are located at Holman Elementary and one is located at the Mora Campus. Total enrollment at 2017/2018 PED 40-Day count was 420 students. There are approximately 461 square feet per student of district facilities. Total permanent instructional facility square footage according to PSFA is 164,325 square feet. This number does not include administration and support.

DEMOGRAPHICS/ENROLLMENT




Mora Independent School District schools are located in the town of Mora and in the community of Holman. The district's service area is located in north central New Mexico in Mora County.

Mora County have experienced steady declines in population since 2010. Population projections from the Bureau of Business and Economic Research (BBER) indicate that the population in Mora County may continue to decline through 2040.


The graph in the right shows the population by age of Mora County and the MISD Service Area. This graph shows that the largest percentage of MISD population is in the 65 to 74 age range,

followed by the 35 to 44 age range. In 2016, the median age for the MISD service area was 37 which is slightly lower than the median age of Mora County that was 41 years in 2016 and. The median age of the MISD service area is the same as the state median age.



Executive Summary

Mora Independent School District enrollment has been slightly declining for the past ten years. In 2006/2007 district enrollment was 603 students. By 2017/2018 it declined to 420 students. Projections anticipate that overall student enrollment will decrease and then remain stable for the next five years with enrollment to be around 399 students by 2023/2024.



UTILIZATION AND CAPACITY

The table below identifies the 2017/2018 enrollment and available capacity at each MISD school. The Functional Facility Capacity analysis indicates that the district facilities are under capacity and could accommodate additional students. New Mexico Adequacy Standards recommended capacity for the district based on the existing square footage is 1,006 students. The current enrollment of MISD district wide is 420 students. Based on these analyses, the district is under capacity by approximately 520 students.

Instructional Space Capacity

School	2017-18 Enrollment	Maximum Facility Capacity w/Portables	Functional Facility Capacity w/Portables	Instructional Space Capacity w/ Portables @ 67%	NMAS Capacity based on Existing SF/Student
Holman ES	38	120	40	80	143
Mora ES	176	370	276	248	252
Elementary Subtotal:	214	490	316	328	395
Lazaro Garcia MS	78	409	205	274	215
Middle School Subtotal:	78	409	205	274	215
Mora HS	128	544	378	364	396
High School Subtotal:	128	544	378	364	396
DISTRICT TOTALS:	420	1,443	899	967	1,006

The overall Classroom Utilization Rate of MISD is 46 percent. This rate is lower than the PSCOC/PSFA recommended value of between 85 to 95 percent. The overall Facility Utilization Rate of the district is 45 percent. This indicates that the facilities could be utilized in a more efficient way. The table on the right shows a detailed breakdown of classroom and facility utilization by school.

Executive Summary

Utilization of Spaces

School	Grades	2017-18 Enrollment	Existing # of Classrooms w/Portables	Classroom Utilization Rate	Facility Utilization Rate
Holman ES	PreK-K	38	8	95%	25%
Mora ES	1-6	176	17	64%	71%
Elementary Subtotal:		214	25	80%	48%
Lazaro Garcia MS	7-8	78	16	29%	30%
Middle School Subtotal:		78	16	29%	30%
Mora HS	9-12	128	23	28%	58%
High School Subtotal:		128	23	28%	58%
DISTRICT TOTALS:		420	64	46%	45%

PREVENTIVE MAINTENANCE PLAN

The district is working to update its Preventive Maintenance Plan. Under the 2018 assessment by PSFA of MISD facilities, the district currently has an average Facility Maintenance Assessment Report (FMAR) ranking of 53.42 percent and fell into the "Poor" rated category, indicating that "Maintenance activities are poor and demonstrate a need for immediate improvement as systems, safety and the environment are at risk of failure."

Since the 2018 FMAR assessment, the district is working diligently at improving the ranking at all MISD schools.

DISTRICT FINANCIAL INFORMATION

State Share / District Share 32% / 68%
Property Valuations: \$ 101,531,411
Bonding Capacity: \$ 6,091,885
Bonding Debt: \$ 0

 SB-9 State/District:
 \$ 203,932

 Last GOB Election - 2005:
 \$ 2,300,000

 Anticipated GOB Election 2020:
 \$ 3,000,000

PSCOC FACILITIES ASSESSMENT DATABASE

The condition of facilities and the FAD ranking was considered in the FMP Committee's prioritization of the District's needs. According to the Facilities Assessment Database (FAD) ranking, it would appear that Mora Combined School will be eligible for PSCOC/PSFA funding during the life span of this FMP; however, the FAD ranking are subject to change as the database is updated. The District should review the ranking periodically to monitor any changes and apply for PSCOC / PSFA funding when appropriate. The latest FAD ranking were published April 18, 2018.

MISD PSFA Facilities Assessment Database (FAD)

School	2018-19 Rank	Weighted NMCI
Holman ES	480	17.82%
Mora Combined School (ES/MS/HS)	73	41.34%

State Share 32%, District Share 68% of a PSCOC/PSFA approved project.

Executive Summary

SCHOOL DISTRICT PRIORITIES

The FMP Steering Committee presented the following district Priorities as recommendations to the Mora Independent School District Board on October 16, 2018.

MISD FINAL FMP 2019-2023 PRIORITIES

Priority RANK Priority Description Source 1A Life-Health-Safety-Security SB-9 1B Maintenance/Preventive Maintenance SB-9 1C Technology SB-9 Priority 1 Subtotal: 2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB	PSFA Funding	Schedule 2019-23 2019-23 2019-23	Total Project \$250,000 \$520,735 \$250,000
1A Life-Health-Safety-Security SB-9 1B Maintenance/Preventive Maintenance SB-9 1C Technology SB-9 Priority 1 Subtotal: 2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB	1	2019-23 2019-23	\$250,000 \$520,735 \$250,000
1B Maintenance/Preventive Maintenance SB-9 1C Technology SB-9 Priority 1 Subtotal: 2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB		2019-23	\$520,735 \$250,000
1C Technology SB-9 Priority 1 Subtotal: 2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB	1		\$250,000
Priority 1 Subtotal: 2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB	1	2019-23	
2 School Building / Site System Renewal: 2A LHSS: Communications/Security: Districtwide BS-GOB			
2A LHSS: Communications/Security: Districtwide BS-GOB			\$1,020,735
2A LHSS: Communications/Security: Districtwide BS-GOB			
2D Doofo, Admin LCMC	2	2019-23	\$464,854
2B Roofs: Admin, LGMS BS-GOB	2	2019-23	\$348,699
2C LHSS: Site Utilities: ES/MS Gym, Lift Stations BS-GOB	2	2019-23	\$71,500
2D Plumbing/Water Treatment: MES, MHS, ES/MS Gym BS-GOB	2	2019-24	\$705,250
2E HVAC: MES, MHS, LGMS, Admin, ES/MS Gym, HS Gym BS-GOB	2	2019-25	\$3,020,380
2F Exterior Walls: MES, LGMS, ES/MS Gym, Admin BS-GOB	2	2019-26	\$262,080
2G Parking Lots: Districtwide BS-GOB	2	2019-23	\$975,000
2H Miscellaneous Building / Site System Renewals BS-GOB	2	2019-23	\$2,032,835
Priority 2 Subtotal:			\$7,880,597
3 Potential Capital Projects:			
3A Restructure Mora Campus: See Option 1 and 2 GOB	3	2019	******
3B Repurpose Swimming Pool Building GOB	-	2021	\$2,056,665
3C HS Gym Lobby: Renovate concessions and restrooms GOB	4	2021	\$812,500
Maintenance Building: Replace & Demolish or Renovate (See priority 3A) GOB		2022	-
3E ES/MS Gym Restroom Renovation GOB		2021	\$786,500
3F New Athletic Event Restrooms and Concessions GOB		2022	\$546,000
3G Other Miscellaneous Projects GOB		2023	\$1,540,500
Priority 3 Subtotal:			\$5,742,165
MISD 2019-2023 FMP Priorities TOTAL:			\$14,643,497
Restructure Mora Campus: Demolish ES Gym,			1
Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES;			
Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building;			044 404 040
Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building; Option 1 move MS to HS Building	3		\$11,421,313
Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building; Option 1 move MS to HS Building Restructure Mora Campus: Demolish ES Gym,	3		\$11,421,313
Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building; Option 1 move MS to HS Building	3		\$11,421,313

SCHOOL DISTRICT CAPITAL PLAN

The district anticipates a potential budget of \$4,020,735 to meet its 2019-2023 facility needs. The district identifies SB-9 and GOB as available funding sources. When these funds become available they will be used to begin addressing the district's most critical needs, building system upgrades, and the larger capital plan projects. According to the Facilities Assessment Database (FAD) rankings, the district anticipates the possibility to partner with PSCOC/PSFA during the life of this FMP to address the needs of Mora Combined School.

Executive Summary

The district has received approximately \$240,000 of direct appropriations from the legislature since 2011 but those funds are not guaranteed and usually not large enough for a capital project. With current economic conditions, it is unlikely that MISD will receive any direct appropriations for capital projects. The district will continue to seek available funding from various sources.

The last SB-9 successful election was in 2013. The district will ask its community to support another SB-9 election in May 2019 to continue funding its life-health-safety-security, general maintenance, preventive maintenance issues, and building system upgrades. The district receives approximately \$204,147 from SB-9 funds.

Mora Independent School District applies for and receives E-rate funding to support its technology needs.


The district has been focused on addressing its priorities and accomplishing one project at a time as funds are available. The district will continue this strategy and use the majority of its anticipated GOB funds to address the capital needs identified in this FMP. The district anticipates its next GOB election for 2020.

The following table shows the MISD anticipated capital funding for the next five years.

MISD Anticipated Capital Funding

Funding Source	Project Type	Year	Amount
SB-9 Funds	Life-Health-Safety-Security-Code, Building System upgrades, and Technology needs	2019-2023	\$1,020,735
GOB Funds	Life-Health-Safety-Security-Code, major Building System upgrades, Preventive Maintenance needs, and Capital projects	2020	\$3,000,000
TOTAL MISD Facility Needs Anticipated Budget 2019-2023			\$4,020,735

SECTION 1: FACILITY GOALS/PROCESS



1.1

Goals

Mora Independent School District Mission and Vision Statements

Mission

Mora Independent Schools exists as a concrete foundation to prioritize every student, every day, in every way. We will provide students with the resources necessary to be successful in life. Our school culture will be one of security, respect, honesty, loyalty, accountability, investment, and positivity.

Vision Statement

We the leadership of the Mora Independent Schools are committed to a vision in which the roots and values of our broader community shape our school culture and create an environment that is the best place to be, learn, work, grow and enjoy life!



"Mora first, Mora always"

MISD Educational Goals

Ensure academic excellence through growth and achievement by maintaining the necessary self-discipline to enable them to become productive, responsible members of their community.

Strengthen the effectiveness of communication between the district and the community by working with students, staff and parents to develop learners.

Encourage students to assume part of the responsibility for creating a stimulating academic and social environment.

Improve performance of all programs, staff, students, and the board of education by utilizing a systematic evaluation approach.

Relationship with MISD Community

Mora Independent School District realizes community partnership is an essential part of the success of the district. Mora Independent School District makes every effort to involve the local community in school functions and programmatic decisions and to make school facilities available for community use. The district is committed to continuing community involvement in all aspects of MISD.

District Facilities Alignment to New Mexico Adequacy Standards

Mora Independent School District is functioning above New Mexico Adequacy Standards (NMAS) recommended square footage per student. The district has reviewed all utilization and capacity at all schools that exceed NMAS and the issues are addressed in the district's needs and priorities.

1.1

Goals

Long Range Facility Goals

The long range facilities vision of MISD is to provide quality education to all of its students in comfortable and stimulating learning environments that are housed in safe, efficient and effective facilities that support its educational programming.

The identified goals for this Facilities Master Plan are:

- To gain an understanding of Mora School facilities
- To provide a comfortable, secure environment for staff and students
- Better utilization of existing space

DECISION MAKING AUTHORITY


The board of education commissioned the development of this 5-Year Facilities Master Plan (FMP) to serve as a reference and guide for Mora Independent School District (MISD). It is recommended that this plan be reviewed yearly and modified as necessary to reflect the direction and accomplishments of MISD. It is the responsibility of MISD to review and revise the content of this FMP every five years.

FACILITIES MASTER PLAN PROCESS

Mora Independent School District recognizes that success of this FMP and subsequent projects depend on the district developing strong partnerships between MISD staff, the state of New Mexico and the local community. Each entity plays a vital role in the progress of the district. Without the support of all partners, the district will not be able to move forward with its capital plan.

District and Committee Participation

Mora Independent School District has developed a long, successful relationship with the local community and with the state's PSCOC/PSFA representatives. Mora Independent School District continuously seeks input from the local community and is aware of their concerns for the future of the district. To serve as a liaison between the school board and the community, an advisory committee was appointed by MISD to assure that all aspects of the district were represented. The committee included members from the state, district administration, faculty, department heads, staff and community.



Utilization of Data in the FMP Process

The driving force behind recommendations made by the advisory committee, MISD community and the board of education was accurate representation of the accumulated data. Through each phase of the process, participants were presented with data and information which they analyzed, discussed and used to develop recommendations.

Committee members and the community were asked to provide insight behind the data that may be causing certain situations to develop in the Mora district area. Community members' insight is crucial in making strong recommendations of how the FMP will use funds towards capital projects that affect MISD.

1.2

Process

District Data

The data presented to partners and stakeholders during the FMP process included:

Enrollment History/Projections based on:

Births

Migration

Housing

Programming Requirements

Historical Enrollment

Community and School Profile based on:

Demographics

Educational program

Academic Achievement

Financial Information

Educational Facility Assessments based on:

Capacity/Utilization Studies

Profiles

Priorities

Quantitative/Qualitative Analysis

Facilities Assessment Database (FAD) information

Code Review

ADA compliance




FMP Participatory Process

The Greer Stafford planning team conducted interviews with MISD administration and staff. This information along with the data listed above was used by the FMP advisory committee as a basis for discussion of MISD facilities.

Initially, the FMP advisory committee had the task of reviewing information about the Mora Independent School District facilities, understanding the requirements of a facility master plan and generating goals and recommendations for the district's facilities.

As the process advanced, the FMP advisory committee worked closely with the MISD School Board, reviewed all documents for accuracy, correlated all information acquired during the meetings, and made a final recommendation to the MISD School Board. Ultimately, the school board is responsible for approval of the final FMP.



FMP PRIORITIZATION SCHEDULE

The following is a list of all meetings and agendas in the FMP process. Refer to Section 4.2- Appendix for the sign-in sheets, agendas, and presentations of each FMP meeting.

Mora Independent School District 2019-2023 FMP FMP Process & Schedule


Participants	Meeting Description	Location	Date	Time
MISD Schools FMP Core Committee	Strategic Planning Meeting: Review PSFA concerns; Establish FMP Process & Schedule; Establish Roles, Responsibilities & Decision Making Process; Establish Committees; Discuss FMP Goals; District Issues, Concerns & Needs		6-Jun-18	1:30 PM
Greer Stafford	Site Assessment / Principal Interviews		14-Jun-18	12:00 PM
MISD Schools Maintenance	Review FAD & FMAR Reports		6-Jun-18	2:30 PM
Greer Stafford	Site Assessment / Principal Interviews		25-Jun-19	12:00 PM
Greer Stafford	Department Interviews			
MISD Schools Core FMP Committee	Review Site Assessment and Principal Interview Data; Review School Board Presentation; 1st FMP advisory Committee Agenda; Discuss FMP Goals; District Issues, Concerns & Needs		-	
MISD Schools School Board & Community	Review of FMP Process and committees; District Issues, Concerns & Needs		19-Jun-18	3:30 PM
MISD Schools Core FMP Committee	Review Data; Review 1st FMP advisory Committee presentation; Discuss Use of Surveys; Discuss FMP Goals; Discuss District Issues, Concerns, Needs, Priorities & Options; Develop Agenda for 2nd advisory Committee Mtg		26-Jun-19	2:00 PM
1st MISD Schools FMP advisory Committee	Review & Discuss FMP Process & Schedule; Review Data & District Background Info; Review and input on draft Surveys; Input on FMP Goals, Issues, Concerns & Needs		26-Jun-19	3:30 PM
MISD Schools Maintenance	Finalize FAD & FMAR Reports		25-Jun-19	
MISD Schools Core FMP Committee	Review Data & Surveys; Review 1st FMP advisory Committee input; Review 2nd FMP advisory Committee presentation; Discuss FMP Goals; District Issues, Concerns, Needs, Priorities & Options; Develop Agenda for 3rd advisory Committee Mto		7-Aug-18	2:00 PM
2nd MISD Schools FMP advisory Committee	for 3rd advisory Committee Mto Review & Discuss Data Summary; Discuss & Input on Goals, Issues, Concerns & Needs; Finalize Student & Community Surveys; Discuss Community Meetings		7-Aug-18	3:30 PM

MISD Schools Core FMP Committee	Review 2nd FMP Steering Mtg input. Develop District Options & Priorities; Discuss Community Meetings & 3rd FMP Steering mtg.; Finalize Surveys	-	
MISD Schools Community Meeting	Review & Discuss Data and Background Summary; Discuss & Input on Goals, Issues, Concerns &	-	
Greer Stafford	Issue Community Surveys		
MISD Schools Core FMP Committee	Review Community Input and Survey summary; Review 3rd FMP advisory Mtg presentation; Discuss and outline Priorities; Options; Discuss Capital Plan and Recommendations	11-Sep-18	2:00 PM
3rd MISD Schools FMP advisory Committee	Review Community Input and Survey Summary; Review & Discuss Data; Discuss & Input on District Options, Priorities, Capital Plan and Recommendations	11-Sep-18	3:30 PM
MISD Schools Core FMP Committee	Review of School Board presentation for District Priorities, Capital Plan and Recommendations.	16-Oct-18	3:30 PM
MISD Schools School Board and Community	Review of District Priorities, Capital Plan and Recommendations.	16-Oct-18	5:00 PM
MISD Schools School Board	Adopt FMP	24-Apr-19	

Conclusion

The process of participation for the MISD FMP reflects the level of commitment of the MISD community to its students. This process was possible because of the groundwork for engagement already established by the district. The FMP document contains the priorities, objectives and goals the committees put forth.

The following page contains a graphic representation of each stage of the process to arrive at a final FMP document.



This page intentionally left blank

Issues and Findings

ISSUES, CONCERNS AND NEEDS OF THE DISTRICT

- Security: The issue of school security has gained more importance lately throughout the state's districts. Mora Independent School District (MISD) is dedicated to providing a comfortable and secure environment for staff and students. During the process of this FMP, the district reviewed different aspects related to security that would help MISD in establishing districtwide security standards.
- Best Use and Better Utilization of Facilities: Mora Independent School District is currently functioning above N.M. Adequacy Standards. The total facilities of the district exceed by 131 percent the recommended NMAS square footage. The district's recommended NMAS square

footage is 70,574 square feet based on current enrollment while the actual square footage is 163,169 square feet. The district would like to address this issue to better utilize its facilities.

- Facility Funding: The district has not been able to establish a proper community and district partnership. The last GOB was passed 12 years ago. Since then, the district has struggled to obtain funding to support its facilities and only receives SB-9 funds to operate and maintain its facilities. The district is expecting to pass a GOB election in 2020 for approximately \$3,000,000. The current offset for Mora Independent schools is \$809,366.
- Facility Condition: Funds have not been sufficient to maintain all MISD facilities. This has deferred maintenance in many building systems. The district is working to improve the condition of its facilities with the limited funds available.
- Integration of Technology into Educational Program: The district is
 working to improve technology districtwide and to integrate new
 evolving technologies into classrooms and as part of the curriculum.
 The district has struggled with acquiring technology resources to
 support its educational programs.
- Improve Facilities Maintenance Assessment Report (FMAR): Limited
 availability of funds has caused maintenance needs to be deferred
 which has negatively affected the district's FMAR score. The district is
 concerned about this score since MISD is looking at the possibility to
 apply for PSFA/PSCOC funding which requires to improve the FMAR
 score to at least 60 percent in order to be eligible to apply for state
 funding.
- *Enrollment:* The enrollment has declined by 183 students in the last 12 years. The district is tracking this trend and taking enrollment levels into consideration for future planning.
- *Teacher Retention and Housing*: Declining enrollment impacts funding which can impact teacher retention. The rural location may contribute to teachers moving on to larger urban areas once they have accrued work experience.

Security Utilization **Funding Technology Enrollment** Maintenance **SECTION**

1.3


Issues and Findings

• State Mandated pre-K: Lakes and Pines C.A.C. Is the direct provider of Head Start pre-K services for children from disadvantaged households in the village of Mora. The state of New Mexico is working toward making pre-K education mandatory for all children. This will change the capacity needs of Mora Independent Schools and potentially terminate the Head Start program. Currently the facilities at MISD are able to accommodate pre-K classes without affecting the capacity needs of elementary, middle and high school, however, this increase in enrollment could affect the maintenance needs of the facility. The district will need to make the necessary capacity adjustments if this state-mandated program gets approved.

2.1.1 OVERVIEW OF CURRENT EDUCATIONAL PROGRAMS AND FACILITIES

2017-2018 Enrollment	420 Students
Number of Schools	4 Schools
Types of Schools	1 High School
	1 Middle School
	2 Elementary Schools
Average MISD Pupil to Teacher Ratio (PTR)	Elementary School = 17:1
	Middle School = 9:1
	High School = 8 :1
State Charter Schools Operating within MISD	None
Alternative Schools Operating within MISD	None
Private Schools Operating within MISD	None
BIE Schools Operating within MISD	None

Feeder Chart for Mora Independent School District



School Grades

The Public Education Department (PED) uses a school grading system for each school across the State of New Mexico. The following are the 2017/2018 grades for MISD schools:

Holman Elementary School	D
Mora Elementary School	D
Lazaro Garcia Middle School	F
Mora High School	С

Educational Programs

Federal Programs

Mora Independent School District participates in and receives federal monies from the following programs:

Title I - Rural / Low Income Schools

Title II - Professional Development

Title III - English Language Acquisition

School Programs

Mora Independent School District provides its students with a diverse and comprehensive package of educational programs that supplement academics.

Mora Independent School District provides the following programs and services to its students throughout the District:

Special Education

Response Through Intervention(RTI)

Tutoring

Bilingual Programs

Reading First Programs

NM Pre-K and District Pre-K programs

Mora Independent School District provides the following programs to Middle and High School:

Advanced Placement (AP) -

English

Math

Science

Gifted Programs

Fine Arts

Technology

Languages

Distance on-line and Interactive Television (ITV) Courses

Career Academy

Advanced Placement College Credit Programs

Extracurricular Programs

Athletics:

Basketball

Baseball

Softball

Volleyball

Track and Field

Cross Country

2.1.2 ANTICIPATED CHANGES IN EDUCATIONAL PROGRAMS

Mora Independent School District did not identify any anticipated changes in their educational programs during the time of this Facility Master Plan.

2.1.3 SHARED / JOINT USE OF FACILITIES


Mora Independent School District does not have joint or shared use with any other private or public entities and does not have any plans to increase shared or joint use in the near future.

THE STATE OF THE S


2.2.1 MAPS

Mora Independent School District Boundaries

Mora Independent School District (MISD) is located in north central New Mexico in Mora County. Mora schools are located in the town of Mora and in the community of Holman, New Mexico. The district shares borders with the Wagon Mound, Cimarron, Taos, Peñasco, Española, Pojoaque, Pecos, and Las Vegas City school districts. Mora Independent School District incorporates 753 square miles. The map of New Mexico school districts below shows the location of the Mora Independent School District in the state.



The map below shows Mora Independent School District boundaries in relation to Mora County. Most of the district's students live in the town of Mora, the community of Holman and in the surrounding rural areas.



Mora Independent School District Locations

In the following map each MISD school location is depicted. The district has four schools: Holman Elementary School, Mora Elementary School, Lazaro Garcia Middle School and Mora High School. The last three schools are part of Mora Combined School and are located in the Mora Campus which is approximately 31.6 acres. Holman Elementary School is located in the community of Holman approximately six miles northwest of the town of Mora.



Schools

- Holman ES
- O Mora ES*
- Lazaro Garcia MS*
- Mora HS*
- Mora Central Office


*Part of Mora Combined School



This page intentionally left blank

Site/Facilities

Mora Independent School District Sites



Mora Combined School Campus

Site/Facilities

Mora Independent School District Sites



Holman ES

Source: Google Maps

Sites / Facilities

2.2.2 FACILITY INVENTORY

Mora Independent School District Facility Inventory

Mora Independent School District (MISD) has four schools. The state identification number is 44330 and the sites are district owned. The total facility inventory square footage is 180,621 square feet. This number includes administration and support buildings.

There are three portable classrooms district wide; two are located at Holman Elementary School and one is part of Mora High School. Of the 61 total classrooms, 31 are general use, 20 are special use and 10 are special education. Total enrollment at 2017/2018 Public Education District 40-Day count was 420 students. There are approximately 461 square feet per student of district facilities. Total educational facility square footage including portables, according to the Public School Facilities Authority is 166,117 square feet. However, based on current drawings the actual total is 163,169 square feet.

Facilities Assessment Database Rankings

The following table contains the FAD Rankings for all district schools:

MISD PSFA Facilities Assessment Database (FAD)

School	2018-19 Rank	Weighted NMCI
Holman ES	480	17.82%
Mora Combined School (ES/MS/HS)	73	41.34%

The following page contains the Mora Independent School District Facility Inventory Table.

Sites / Facilities

This page intentionally left blank

Site/Facilities

MORA INDEPENDENT SCHOOL DISTRICT FACILITY INVENTORY 2019-2023

Facility Name	State ID	Address	Open Date	Age (Years)	Dates of Major Additions and Renovations	State FCI	Replacement Value from State Database	Weighted NMCI	Site Acreage	Owned or Leased	Total Permanent Bldg Area	Total Portable Bldg Area	Total Bldg Area (GSF)	Grades	Current Year Enrollment (40 day)	No. of General Classrooms	No. of Special Ed Classrooms	No. of Special Use Classrooms	Classro	No. Single Portables	Port CR % of Total	GSF Per Student
Elementary	7																					
Holman ES	44331059	P.O. Box 140 Mora, NM 87732	1969	49	1987, 2006	47.43%	\$3,682,434	17.82%	2.78	Owned	18,879	1,831	20,710	PreK-K	38	6	2	0	8	2	25%	545
Mora ES	44331104	P.O. Box 140 Mora, NM 87732	1950	68	1999, 2000, 2001	Same as HS			Shared	Owned	35,207	0	35,207	1-6	176	12	2	3	17	0	0%	200
	l	· · · · · · · · · · · · · · · · · · ·			Sub-totals	n/a	\$3,682,434	n/a	2.78	n/a	54,086	1,831	55,917	n/a	214	18	4	3	25	2	8%	373
Middle School							ı															
Lazaro Garcia MS	44331001	P.O. Box 687 Mora, NM 87732	1997	21	1950, 1971	Same as HS	Same as HS	41.34%	Shared	Owned	34,335	0	34,335	7-8	78	6	2	5	13	0	0%	440
		•			Sub-totals	n/a	\$0	n/a	0.00	n/a	34,335	0	34,335	n/a	78	6	2	5	13	0	0%	440
High School																						
Mora HS	44331105	P.O. Box 180 Mora, NM 87732	1968	50	1974, 90, 91, 2003, 04	65.52%	\$27,145,451	41.34%	31.68	Owned	72,917	0	72,917	9-12	128	7	4	12	23	1	4%	570
					Sub-totals	n/a	\$27,145,451	n/a	31.68	n/a	72,917	0	72,917	n/a	128	7	4	12	23	1	4%	570
					Schools Totals	n/a	\$30,827,885	n/a	34.46	n/a	161,338	1,831	163,169	n/a	420	31	10	20	61	3	5%	461
Administrative and Support																						
Administration Office	44330000	Highway 518, Mora, NM 87732	1950	68	1995, 2007	n/a	0	n/a	Shared	Owned	Part of MES	0	Part of MES	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Swimming Pool	44330000	P.O. Box 179, Mora, NM 87732	1970	48	1994	n/a	0	n/a	Shared	Owned	10,520	0	10,520	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Maintenance Building	44330000	P.O. Box 179, Mora, NM 87732	unk.			n/a	0	n/a	Shared	Owned	6,868	0	6,868	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Security	44330000	P.O. Box 179, Mora, NM 87732	unk.			n/a	0	n/a	Shared	Owned	64	0	64	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
					Sub-totals	n/a	\$0	n/a	0.00	n/a	17,452	0	17,452	n/a	0	0	0	0	0	0	0	0
					District Totals	n/a	\$30,827,885	n/a	34.46	n/a	178,790	1,831	180,621	n/a	420	31	10	20	61	3	5%	461

Notes

The Training Room square footage is included in the HS. The funding to develop this facility was given to the District as a grant trough a local community college. MISD didn't spend any money in conditioning this facility. The Facility Sq.Ft. Including Portables is from the FMP drawings and it might differ from the sq.ft. identified on the FAD.

Site/Facilities

This page intentionally left blank

This District Growth Analysis takes a look at the demographic and economic factors affecting the region of the Mora Independent School District (MISD). In this section relevant demographic information regarding the populations living in Mora County and the MISD service area will be documented. The first part of this section focuses on demographic factors affecting MISD, the second part focuses on economic and development factors that may contribute to growth within the district.

Data Resources


Data used in this District Growth Analysis was primarily obtained from the Bureau of Business and Economic Research (BBER), and both American Community Survey (ACS) data and U.S. Census Bureau data. The 2012-2016 ACS provides estimates regarding demographic profiles including population and economic characteristics of geographic areas in the United States. American Community Survey data is collected in one year and five year periods and provide a more detailed analysis of a given population than 10-year census data. The population estimates of the ACS do not match the official counts of the 2010 census, but provide a reliable outlook regarding the demographic conditions of a particular geographic area. State and county data resources are also used throughout this section, please see source information in each subheading for details.

New Mexico Department of Health Statistics and Mora County data is used for detailed county wide analysis. All data is used interchangeably to yield a thorough interpretation of the demographic factors affecting Mora County and the MISD service area.

Mora Independent School District Service Area Regional Perspective *Mora County*

The county of Mora is located in north central New Mexico. The region encompassing MISD service area is located in the western corner of Mora County and its central facilities are located within the town of Mora. The region's economic development is diverse, with jobs in healthcare, social service, public education, retail trade and a strong farming community. The largest population center in the district is the town of Mora. Mora County boundaries include Pecos Wilderness, Santa Fe National Forest and Carson National Forest and the borders of Taos, San Miguel and Rio Arriba counties.

The historic town of Mora can be accessed through Highway 518, departing 32 miles from the town of Las Vegas, New Mexico. is Mora approximately 152 miles northeast of the city of Albuquerque and its estimated acreage is of 480,000. Mora Independent School District boundaries are shown on the map to the right. The county of Mora




Map shows the location of MISD

and the Mora River watershed has been labeled as one of the most beautiful places in the State of New Mexico for its scenery stretching from the Sangre de Cristo mountains in the west to the Canadian River in the east. This landscape, along with the strong farming community and easily accessable fishing waters, has not been enough to retain population in the county. Mora county has historically experienced high unemployment rates and low per capita income (source: http://www.newmexico.org).

DEMOGRAPHIC TRENDS


MISD Service Area Population Comparisons


According to the 2016 American Community Survey, median age in Mora County was 41 years. The median age for the MISD Service area was 37. Mora County age range is slightly higher than the New Mexico median age of 37.2, while MISD is closer to the state's number with a median age of 37 (source: ACS 5-Year Estimates, 2012-2016).



In the MISD service area, the percentage of the population that is school age is approximately 28.23 percent. Mora Independent School District service area has a strong percentage of the population

in the wage-earning age categories and a lower percentile of its population in the older age categories. This is a sign of growth in district enrollment, which relies on young families to keep enrollment robust (source: ACS 5-Year Estimates, 2012-2016).






New Mexico County Median Age Comparison Map

The map to the left compares median age by county across New Mexico in 2016. In this map Mora County's median age is shown at 41.3, which is slightly higher than the overall median age for the state of New Mexico. Mora County's age range is comparable to other counties of similar population characteristics in New Mexico (source: ACS 5-Year Estimates, 2012-2016).

Mora County Historic and Projected Population Estimates

Population in Mora County denoted a 0.04 percent decrease in population from 2010 to 2015. Bureau of Business and Economic Research population projections for New Mexico counties from the present through 2040 projects that Mora County population will continue to show a slight decline in population growth from 2020 through 2040 (sources: UNM Geospatial and Population Studies, New Mexico County Projections July 1, 2010 to July 1, 2040; Bureau of Business and Economic Research, UNM, released Oct. 2012).



Population Growth Comparisons


Comparisons between the Mora County, the MISD service area and MISD enrollment show that the population in each category has decreased slightly. Mora County has seen a minor decrease in population while the MISD service Area and MISD enrollment continue to reflect a steady decline in population. Mora Independent School District enrollment declined by the largest percentage of the three categories and may be an indication of out migration by young families.

Total Population	2011	2016	% Change
New Mexico	2,037,136	2,082,669	2.24%
Mora County	4,878	4,598	-5.74%
MISD Service Area	3,873	3,578	-7.62%
MISD Enrollment	509	420	-17.49%

In 2011 district enrollment constituted approximately 10.43 percent of the county's population. In 2016 enrollment increased slightly to 11.41 percent of the county's population, however, the county's overall population decreased 9.13 percent. This indicates that MISD enrollment is in line with the decrease in population for the MISD service area (source: ACS 5-Year Estimates, 2007-2011, 2012-2016; PED 40 Day Count Enrollment Trends, 2016-2017).

Mora County Births


The following graph shows the historic birth rate in Mora County for the last 12 years. These births provide a point of reference to the number of students entering kindergarten in the MISD. The graph shows that an average of 43 children were born per year from 2006 to 2017. In 2012 there were 41 births, this number provides us with an estimate of the number of students entering kindergarden in the 2017-2018 school year (source: NM Department of Health).



Kindergarten Enrollment

In the next chart, births to kindergarten enrollment are compared in two separate seven-year periods (the top coordinate represents the number of births in Mora County and the bottom coordinate represents the number of kindergarden students). The relationship between the two sets show that the number of births in a given year are an indicator of the number of kindergarten students five years later. For example, year one of birth (2006) corresponds to year one of kindergarten enrollment (2011) because a child who was born in 2006 will attend kindergarten in 2011.

The average number of Mora County births from 2006-2012 was 44 per year. Kindergarten




enrollment at MISD constituted about 69 percent of the share of births in the county, in the year one period shown above (e.g. kindergarten enrollment in 2011 at MISD, [34]. County births in 2006, [49]). This ratio increased to 92.7 percent share by year seven of the related period (source: PED 40 Day Count, Fall 2017; NM Department of Health, 2016). The change shows that MISD retains more of the county births from Mora County. This comparison charts also shows fluctuating births to enrollment comparison that is expected to remain the same in the following years.

Race and Ethnicity


The following two charts represent the expressed racial and ethnic identities of the MISD service area population.

The first chart on the right reveals that over half of the MISD area population identifies as white and the other half as "some other race", leaving the rest of the other categories under 1 percent (source: ACS 5-Year Estimates, 2012-2016).



Because populations that identify their ethnic origin as Hispanic or Latino can be from any race, the U.S. Census provides a category to measure Hispanic or Latino ethnic identity.

The chart to the right represents the population that identifies as Hispanic and the population that does not. It shows that 83 percent in the MISD service area population identify as Hispanic and 17 percent identify themselves as "Not Hispanic or Latino" (source: ACS 5-Year Estimates, 2012-2016).



MISD Service Area Household Types

There are 1,230 households in the MISD service area. Of these households, 14.3 percent have one or more children under 18 compared to 50.1 percent of households which have one or more people over 60 (source: ACS 5-Year Estimates, 2012-2016). These numbers show that the older population is larger than the younger population and this could alter the enrollment for MISD in the coming years.

Total family households	601
Average family size	4.65
Total Households	1,230
Average household size	2.9
Households with one or more people under 18 years	14.3%
Households with one or more people 60 years and over	50.1%


ECONOMIC AND DEVELOPMENT ANALYSIS

Mora County and MISD Service Area Occupations

The primary industries in Mora County are in health care and social assistance, followed by educational services and retail trade (source: NM Department of Workforce Solutions, 4th Quarter 2017). Most of the industry is fueled by economic development in the town of Mora.




The MISD service area population primary occupations are sales and office occupations followed closely by service occupations. There are approximately 876 people 16 years and over employed in the MISD service area (source: ACS 5-Year Estimates, 2012-2016).




Mora County and MISD Service Area Earnings and Incomes

According to the U.S. Census, earnings refer to the direct compensation workers collect from their occupation, and income refers to earnings as well as income derived from alternative sources such as investments, retirement or pension, and social security insurance programs. The following graph shows the median income comparison between Mora County, the MISD service area, and the State of New Mexico.

The median income for the MISD service area in 2016 was \$19,740 and the median income for Mora County which is \$21,190. Both values are less than half of the median income for the State of New Mexico at \$45,674. This gives a clear presentation of the economic hardships and lack of opportunity within the town of Mora, the county and MISD Service Area (source: ACS 5-Year Estimates, 2012-2016).




Unemployment rate for Mora County in 2010 was 12.4 percent, a considerably higher rate than the overall state of New Mexico unemployment rate of 8.0 percent. Since 2010 this rate in Mora County has decreased to 7.7 percent, slightly higher than the overall New Mexico unemployment rate of 6.7 percent. A lower unemployment rate can be a contributing factor to a stable population ratio for the MISD district (source: Statistics by County, UNM Bureau of Business and Economic Research, 2010-2017).



MISD Boundary Area Poverty Designation

The U.S. Census has determined that the status of the entire population residing in the MISD service area is considered living at or below poverty level, with a total of 603 people in the MISD service area living below poverty level. The population of those living below poverty level who are under 18 years of age is approximately 55. The largest population living below poverty level range between the ages of 18 to 64 (source: ACS 5-Year Estimates, 2012-2016). According to the district, MISD is approved for 100 percent free lunch as part of the assistance to supplement the nutritional conditions for a population with low earning income.



The table below presents a comparison of poverty levels between the State of New Mexico, Mora County and the MISD service area (source: ACS 5-Year Estimates, 2012-2016).

2016	Total Population	Population Below Poverty Level	Percent Below Poverty Level
New Mexico	2,082,669	426,814	20.5%
Mora County	4,598	1,036	22.5%
MISD	3,578	603	16.9%

Demographic Summary

The district growth analysis for the MISD shows that Mora County and the town of Mora have a steady decline in population and school enrollment. While the county of Mora is one of the New Mexico's most beautiful landscape attractions, it has not been able to produce further economic development in order to maintain or increase population numbers. The decline in population in the MISD service area could be attributed to an aging population and young families migrating from MISD service area to a location with greater employment opportunities.

RELEVANT FACTORS

Mora Independent School District (MISD) is located in the western seat of Mora County and borders the eastern corner of Santa Fe County and the southern corners of Taos and Rio Arriba counties in New Mexico. The district is surrounded by three national forests: Carson, Santa Fe and Pecos Wilderness. Population growth within the district is less dependent on economic factors than in other areas of the state and is more dependent on the birth and death rates among the residents in Mora County. In the economic sector, the town of Mora depends on healthcare services and education as their two leading hiring industries to provide meaningful employment to its labor-ready population. Having access to gainful employment is a contributing factor to the population retention in the town of Mora and the county population as a whole. The median income for Mora county and the MISD service area are well below half of the median income for the State of New Mexico. This low income could be one of the leading attributing factors to the decline in population and enrollment due to migration out of the service area to larger metro areas with more economic and labor opportunities.

Population within Mora County and MISD has shown a continual decrease since 2006 with an additional projected decrease through 2024.

PROJECTION METHOD

There are several methods of projecting student enrollment for school districts. The most common of which is the cohort-survival method. In this method, the numbers of students in a cohort (a group of students of a certain age who move together through one grade level to the next) are tracked through past grades. Based on historical enrollments, survival rates (ratios of the number of students who remain from one year to the next) are calculated. Prevailing birth rates (for kindergarten) and average survival rates (for other grades) are used to calculate future enrollment. As warranted, ratios can be adjusted to reflect major factors identified during the growth analysis. Since the cohort-survival method addresses students who are currently in the system, it tends to be very accurate for five to seven years.

The population method is another projection technique. This method uses information about a known population (usually derived from U.S. Census data) and actual attendance from the area. Projected enrollment is calculated based on the ratio of students attending classes to the general population, multiplied by the projected change for the population in the general area.

These methods were combined to project the enrollment for Mora Independent School District. Overall student enrollment was calculated at the district level using the population method and housing method. This number is used as a control total for detailed cohort-survival projections at the school level.

2.4.1 & 2.4.2 HISTORICAL AND PROJECTED ENROLLMENT TABLES

MISD Districtwide Enrollment Trends

In 2006/2007 district enrollment was 603 students. By 2017/2018 enrollment had declined by nearly 180 students. The decline has been steady, indicating that it is likely to continue (source: NM PED Official 40-Day Count). The declines may have multiple factors, including families moving out of the Mora Service area for jobs, or relocating to nearby larger cities such as Las Vegas, New Mexico for more employment opportunities.

Enrollment projections for MISD anticipate that overall student enrollment will steadily continue to decline for the next five years, remaining near the 390 student range through in 2023/2024. These enrollment projections were reached after analyzing the following factors:

- Historical enrollment trends
- Out migration of young families from the MISD Service Area
- Birth rates in Mora County
- Limited growth in crucial economic sectors


The following page contains tables for historical and projected enrollment and a trend graph comparing MISD districtwide enrollment trends over time.

MISD Districtwide Enrollment History

Grade Level	2006-07	2007-08	2008-09	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18
Pre-K	0	0	0	0	0	0	0	0	0	0	0	0
KN	43	37	32	35	49	34	39	35	29	27	35	38
1st	48	47	37	34	39	46	37	34	36	36	28	35
2nd	42	47	48	34	31	37	45	36	32	32	32	26
3rd	34	45	47	41	35	31	34	45	36	31	27	32
4th	42	32	46	42	39	36	30	31	39	33	26	26
5th	43	38	33	45	45	41	37	31	27	40	31	26
6th	41	41	38	34	50	41	40	34	27	29	41	31
7th	42	43	44	39	30	47	42	38	33	26	31	45
8th	49	36	42	33	42	32	45	44	39	29	26	33
9th	59	52	46	43	33	52	39	45	39	37	29	26
10th	53	56	52	39	39	29	39	36	40	36	37	26
11th	52	42	35	46	37	40	25	36	32	38	34	41
12th	55	49	41	32	39	34	32	22	32	34	34	35
TOTAL	603	565	541	497	508	500	484	467	441	428	411	420
w/out PreK	603	565	541	497	508	500	484	467	441	428	411	420

MISD Districtwide Projected Enrollment

Grade Level	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
Pre-K	0	0	0	0	0	0
KN	30	34	33	38	39	39
1st	38	31	35	34	38	39
2nd	35	36	30	33	32	38
3rd	26	34	36	29	32	31
4th	30	24	33	34	27	31
5th	23	30	24	33	34	27
6th	26	23	29	24	32	33
7th	32	26	23	30	24	33
8th	38	31	26	22	29	23
9th	34	40	31	28	24	30
10th	24	34	36	28	25	25
11th	28	23	32	33	26	25
12th	34	26	21	30	33	25
TOTAL	397	392	389	394	394	399
w/out PreK	397	392	389	394	394	399




MISD Elementary Enrollment

The elementary schools located in Mora Independent School District include one pre-K thru kindergarten school, Holman Elementary School (HES); and one first through sixth-grade school, Mora Elementary School (MES).

Historical elementary enrollment shows steady declines in elementary enrollment between 2010/2011 and 2016/2017 with a loss of approximately 60 students. The elementary enrollment had an increase of 35 students between 2016/2017 and 2017/2018.

Projected elementary enrollment is expected to increase slightly to a total of 230 students through 2023/2024 with a slight decrease in 2018/2019.




The following page contains historical and projected enrollment tables and an enrollment trends graph for each MISD elementary school.

Holman Elementary School Enrollment History

Grade Level	2006-07	2007-08	2008-09	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18
Pre-K	0	0	0	0	0	0	0	0	0	0	0	0
KN	43	37	32	35	49	34	39	35	29	27	35	38
TOTAL	43	37	32	35	49	34	39	35	29	27	35	38

Holman Elementary School Projected Enrollment

Grade Level	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
Pre-K	0	0	0	0	0	0
KN	30	34	33	38	39	39
TOTAL	30	34	33	38	39	39




Mora Elementary School Enrollment History

Grade Level	2006-07	2007-08	2008-09	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18
1st	48	47	37	34	39	46	37	34	36	36	28	35
2nd	42	47	48	34	31	37	45	36	32	32	32	26
3rd	34	45	47	41	35	31	34	45	36	31	27	32
4th	42	32	46	42	39	36	30	31	39	33	26	26
5th	43	38	33	45	45	41	37	31	27	40	31	26
6th	0	0	0	0	0	0	0	0	0	0	0	31
TOTAL	209	209	211	196	189	191	183	177	170	172	144	176

Mora Elementary School Projected Enrollment

Grade Level	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
1st	38	31	35	34	38	39
2nd	35	36	30	33	32	38
3rd	26	34	36	29	32	31
4th	30	24	33	34	27	31
5th	23	30	24	33	34	27
6th	26	23	29	24	32	33
TOTAL	178	178	187	186	195	199



Middle and High School Enrollment

Middle School

The district has one middle school for seventh and eighth grades, Lazaro Garcia Middle School (LGMS).

Middle school enrollment shows increases and decreases during the last 10 years. It has historically stayed between 80 and 130 students. In 2017/2018 the district moved sixth grade to Mora Elementary School which reduced the middle school enrollment to 78 students. Lazaro Garcia Middle School enrollment is projected to decline to around 50 to 55 students.

High School

The district has one high school serving ninth to 12th grades, Mora High School (MHS)

High school enrollment has declined along with districtwide enrollment. Overall high school enrollment has decreased to stay between 90 and 120 students in the last 12 years. Projections for high school enrollment anticipate that given current conditions, enrollment will continue to decline to around 105 students.


The following page contains tables for historical and projected enrollment and a trend graphs for LGMS and MHS.

Lazaro Garcia Middle School Enrollment History

Grade Level	2006-07	2007-08	2008-09	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18
6th	41	41	38	34	50	41	40	34	27	29	41	0
7th	42	43	44	39	30	47	42	38	33	26	31	45
8th	49	36	42	33	42	32	45	44	39	29	26	33
TOTAL	132	120	124	106	122	120	127	116	99	84	98	78

Lazaro Garcia Middle School Enrollment Projection

Grade Level	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
6th	0	0	0	0	0	0
7th	32	26	23	30	24	33
8th	38	31	26	22	29	23
TOTAL	70	57	49	52	53	56




Mora High School Enrollment History

Grade Level	2006-07	2007-08	2008-09	2009-10	2010-11	2011-12	2012-13	2013-14	2014-15	2015-16	2016-17	2017-18
9th	59	52	46	43	33	52	39	45	39	37	29	26
10th	53	56	52	39	39	29	39	36	40	36	37	26
11th	52	42	35	46	37	40	25	36	32	38	34	41
12th	55	49	41	32	39	34	32	22	32	34	34	35
TOTAL	219	199	174	160	148	155	135	139	143	145	134	128

Mora High School Enrollment Projection

Grade Level	2018-19	2019-20	2020-21	2021-22	2022-23	2023-24
9th	34	40	31	28	24	30
10th	24	34	36	28	25	25
11th	28	23	32	33	26	25
12th	34	26	21	30	33	25
TOTAL	120	123	121	118	108	105



This page intentionally left blank

2.5.1 REQUIRED AND EXISTING CLASSROOM SPACES

The following table shows the **minimum** number of classrooms required to accommodate the current enrollment at Mora Independent School District (MISD); the **minimum** number of classrooms that are projected to be required in the next five years for projected enrollment at MISD; and the number of **existing** classrooms per school.

For the 2017/2018 school year, a minimum of 33 classrooms were required to accommodate the year's enrollment; while a minimum of 29 classrooms are projected to be required for the 2023/2024 projected enrollment. The district has 64 existing classrooms.

The enrollment numbers identified in this table don't reflect the total enrollment at Holman ES. The

Minimum Number of Classrooms Required

	201	7-18	2023	-24	
School	Total Current Enroll	2017-18 Minimal Clrms Rqd	Total Projected Enroll	2023-24 Minimal Clrms Rqd	# of Existing Clrms
Holman ES	38	3	39	3	8
Mora ES	176	16	199	16	17
Elementary Subtotal:	214	19	238	19	25
Lazaro Garcia MS	78	6	56	4	16
Middle School Subtotal:	78	6	56	4	16
Mora HS	128	8	105	6	23
High School Subtotal:	128	8	105	6	23
DISTRICT TOTALS:	420	33	399	29	64

Number of existing classrooms is based upon existing permanent and portable classrooms.

school offers a Head Start program that includes both "developmentally delayed" students (DD) and "typically developing" students. The Head Start program serves approximately 56 students. The total 2017/2018 enrollment for Holman ES was 94 students (including Head Start and K students). The school has to provide adequate space to support this program.

It is important to note that the minimum classrooms required is not always optimal due to the educational program and the special services provided at each school. The number of classrooms identified in the table reflects the minimal number of classrooms required to house students but does not take into consideration the educational programs offered at each school. The middle school and high school of MISD provide robust class offerings to their students which could require additional classrooms to adequately support their programs.



As noted in the previous tables, the district overall has more classrooms than is required for the current enrollment. As for individual schools, each MISD school has more than the minimum required number of classrooms for both the existing and projected student enrollment. The middle school and the high school have twice the minimum number of required classrooms. During the FMP process, the district discussed options to utilize existing square footage more efficiently if enrollment continues to decrease over the next five years.

2.5.2 SPECIAL FACTORS INFLUENCING FACILITY USE

To get an overall picture of the utilization of a school it is important to take a look at how the instructional spaces are being utilized and the different factors that can influence their use. These factors include the Pupil Teacher Ratios (PTRs), special programs, student transfers, boundary areas, and other special and magnet programs. Analysis and identification of these factors will help determine their impact on the facility use of spaces.

Lower than state required PTRs

The Pupil Teacher Ratios (PTRs), determined by the New Mexico Public Education Department (PED), indicates the maximum number of students that should be assigned to each teacher in a classroom. A school's average PTR is based on PED's pupil-to-teacher ratio by grade level. It is important to consider this factor since it can influence the number of teachers and classrooms required for a given facility.

The following is the allowable PTR by grade level from PED:

Pre - K	8 - 12 with aides
Kindergarten	15 without an aide; 20 with an aide
1st - 3rd	22
4th - 6th	24
7th - 8th	Max English class size; 27 or 150 / teacher / day
9th - 12th	Max English class size: 30 or 150 / teacher / day

The table on the following page compares the district PTR to PED's allowable PTR. The sixth column of the table shows the average PTRs of each school in the district and the average PED PTR by school level. These values are calculated based on the total current enrollment of each school and divided by the total number of assigned classrooms/teachers. The fifth column shows the average allowable PED PTR based on the grade configuration of each school.

According to the results shown on the table, the elementary schools have an average PTR of 16.83 which is below PED's average allowable PTR of 22. The middle school has a PTR of 8.63 and the PED's allowable PTR is 27. The high school has a PTR of 8 and PED's allowable PTR is 30. The district overall has an average PTR of 11.15 compared to PED's allowable PTR of 26. All the schools have values that are low compared to PED's allowable PTR which indicates that there could be more teachers and classrooms than are required. However, the lower PTR may be a reflection of a robust educational program in the schools.

Pupil Teacher Ratios

School	Grades	2017-18 Enrollment	2017-18 # of MISD Assigned Teachers / Classrooms	PED PTR	2017-18 MISD PTR w/ Existing Classrooms
Holman ES	PreK-K	38	2	20	19.00
Mora ES	1-6	176	12	23	14.67
Elementary Subtotal:		214	14	22	16.83
Lazaro Garcia MS	7-8	78	9	27	8.63
Middle School Subtotal:		78	9	27	8.63
Mora HS	9-12	128	16	30	8.00
High School Subtotal:		128	16	30	8.00
DISTRICT TOTALS:		420	39	26	11.15

Special Education Spaces

The Special Education (SPED) program must be reviewed whenever determining the capacity and utilization of facilities. It is important to understand the impact that special education programs

have on each school. The table on the right identifies the number of students at MISD that are eligible to receive C and D levels of special education instruction, but does not include A and B levels or gifted and pre-school. Five percent of the total student population receive C and D levels of special education instruction at MISD.

SPED Enrollment Comparisons

School	2016-17 Enrollment	Special Ed Enrollment	Special Ed as % of Total
Holman ES	38	0	0%
Mora ES	176	2	1%
Elementary Subtotal:	214	2	1%
Lazaro Garcia MS	78	1	1%
Middle School Subtotal:	78	1	1%
Mora HS	128	4	3%
High School Subtotal:	128	4	3%
DISTRICT TOTALS:	420	7	5%

Student Transfers, Magnet Programs, and Other Special Programs

Mora Independent School District experiences very low transfers into and out of the district. The district does not have any other special programs and magnet programs.

Boundary Areas

The district does not have any school level attendance boundaries within it and does not anticipate any change to its service area boundary.

Instructional Space Comparisons

When calculating capacity and utilization it is necessary to know how many general instruction, special education and special use spaces are located within a school in order to determine how the spaces are being utilized. General instruction classrooms are those spaces dedicated to regular education, while special use spaces are those spaces used for career, art, music, physical education, computer, science labs, which require specialized spaces.

The following two tables identify the number of instructional spaces in the three different categories. The first table shows the number of spaces that are used for general instruction, special education, and special use, while the second table shows the percentage of the overall facility.

Instructional Space Comparisons


School	# of General Use Classrooms	# Special Ed Classrooms	# Special Use Classrooms	Total Instructional Spaces	Portable Classrooms Total # of Instructional Spaces
Holman ES	7	1	0	8	2
Mora ES	12	2	3	17	0
Elementary Subtotal:	19	3	3	25	2
Lazaro Garcia MS	8	2	6	16	0
Middle School Subtotal:	8	2	6	16	0
Mora HS	7	4	12	23	1
High School Subtotal:	7	4	12	23	1
DISTRICT TOTALS:	34	9	21	64	3

The above table shows that the district has 64 permanent instructional spaces. There are three portable classrooms in the district. Of the 64 spaces, 34 instructional spaces are for general use, nine instructional spaces are for special education, and 21 instructional spaces are for special use. This corresponds to 53 percent general use spaces, 14 percent special education spaces, and 33 percent special use spaces as shown in the following table.

Instructional Space Usage as a Percent

School	General Use % Room Usage	Special Ed % Room Usage	Special Use % Room Usage
Holman ES	88%	13%	0%
Mora ES	71%	12%	18%
Elementary Subtotal:	76%	12%	12%
Lazaro Garcia MS	50%	13%	38%
Middle School Subtotal:	50%	13%	38%
Mora HS	30%	17%	52%
High School Subtotal:	30%	17%	52%
DISTRICT TOTALS:	53%	14%	33%

Additionally, the graph on the following page has a line at 67 percent which serves as a **benchmark** for the ideal amount of assigned spaces in a school. Both elementary schools are above the 67 percent benchmark. Holman ES with 88 percent and Mora with 71 percent corresponding to assigned spaces. Mora High School has the lowest percentage at 30 percent. Overall, the district has an average of 53 percent of assigned spaces, indicating there could be room for improvement for space utilization, especially at the high school.



2.5.3 UTILIZATION AND CAPACITY ANALYSIS

School utilization and capacity are not stationary numbers; they can change from year to year depending on the educational programs available at the school, the Pupil to Teacher Ratio, scheduling, and special needs of the students. Special programs that the district provides to meet the needs of its students can have a dramatic impact on the capacity and utilization of educational facilities. For that reason, it is recommended that the utilization and capacity of the facilities be reviewed annually and updated as necessary to realize the most effective use of the buildings and to enable the district to effectively plan for the future.

The methodology used to determine facility capacity can be slightly different for each school type due to their educational programs and use of facilities. For this Facilities Master Plan, capacities were analyzed using three different capacity calculation methods to provide a comprehensive look at school capacities. The first method is based on N.M. Adequacy Standards (NMAS) which is based on the permanent square footages of schools. The second is Functional Facility Capacity which is based on the number of instructional spaces and educational programming of each school. The third method is Instructional Space Capacity which is based on the number of instructional spaces at each school and is used as a benchmark. All three capacity analyses are based on existing facilities. The capacities are calculated for permanent plus portable facilities. The square footage used in these calculations is based on the square footage identified in the floor plans for each school. It is important to mention that the floor plans in this FMP have been updated and reflect changes to school facilities that PSFA might have not recorded.

New Mexico Adequacy Standards (NMAS) Capacity Methodology

The first capacity calculation method is based on the comparison of the existing square feet of each school to the NMAS recommended square feet per student for a new school as calculated by the New Mexico Public Schools Facility Authority (PSFA) recommendations. The authority recommendations for overall square footage of a school are based on student population and

derived from the Maximum Building Gross Square Foot Calculator located on the PSFA website. Recommended square footage per student in the NMAS is intended to functionally support all of a school's educational programs, yet encourage multi-use spaces.

In determining the capacity that the Public Schools Capital Outlay Council (PSCOC) and Public School Facilities Authority (PSFA) anticipates for a new school, the overall square footage of the school is compared to square footages in the Maximum Building Gross Square Foot Calculator and the capacity associated with that square footage. Existing schools were not originally designed utilizing today's standards, but this comparison provides insight into the capacity of existing schools and provides a benchmark.

The NMAS recommended square feet per student provides insight to student capacity of existing school facilities based on the existing square feet of each school, both permanent and portable. This method of calculating capacity provides a look at how the existing school compares to NMAS. The square footage per student is based solely on NMAS square footage and does not take into consideration the number of existing instructional spaces or the educational program of the school.

Maximum and Functional Facility Capacity Methodology

This method is based partly on the New Mexico Public Education Department (PED) Pupil to Teacher Ratio (PTR) and partly on the number of existing classrooms including portables and the educational program. This capacity method looks at the Maximum Facility Capacity and the Functional Facility Capacity of each school. These two capacities are explained in greater detail below.

Maximum Facility Capacity: This capacity is the **maximum** number of students that can be assigned to each classroom or instructional space. The maximum number of students that can be assigned to each instructional space including classrooms, gymnasiums, computer labs, and multi-purpose rooms, is based upon the PED standard for PTR or the NMAS for minimum square feet required per student, whichever is more restrictive. When calculating Maximum Facility Capacity, consideration is based solely on how many students are allowed in each instructional space. It does not take into consideration the educational program delivered at the school and how the classrooms are used. It is understood that this is not a realistic capacity for a school but serves to identify a facility's **maximum capacity.**

Functional Facility Capacity: This is the potential **best use** of classrooms or instructional spaces based on the school's educational program and facility design. Unlike Maximum Facility Capacity, this calculation includes only spaces that have assigned classes functioning within; however, it excludes specialized instructional spaces such as science labs, art, music, computer labs, specialty labs, and certain special education spaces that are not assigned classrooms. Similar to Maximum Facility Capacity, the number of students that can be assigned to each classroom is based upon the PED standard for PTR or the NMAS for square feet per student, whichever is more restrictive. This calculation of capacity allows for the distinct **functional** uses of the facility based on the number of classrooms and educational programming.

When analyzing Functional Facility Capacity of a school it is important to remember that schools with excess classrooms may convert these classrooms into 'other' use rooms such as storage, meeting rooms or may leave them as vacant classrooms. In that case, those classrooms will not show up in the final Functional Facility Capacity number. This will reduce the school's overall capacity numbers and may not be a realistic representation of the school's capacity, but rather a reflection of the current use of the instructional spaces at each school.

For elementary schools, only the general use classrooms are counted for Functional Facility Capacity. The special use rooms such as art, music, computer, and gym are not counted. Except for level D or DD classrooms, special education classrooms are not included in the functional capacity count. The functional capacity calculation accounts for the potential to fill classrooms that function as "homeroom instruction" for students.

For middle and high schools the only rooms deducted from the Functional Facility Capacity are rooms identified as special education or unassigned support labs such as computer labs, science labs, specialty labs, etc. unless they have assigned classes functioning in the space. The exclusion of special use and support classrooms provides a more realistic capacity that reflects the educational program of the school.

Instructional Space Capacity Methodology

This capacity method, also known as the 67 Percent Instructional Space Capacity, is based partly on the New Mexico Public Education Department (PED) Pupil to Teacher Ratio (PTR) and partly on the number and size of existing classrooms including portables.

The 67 Percent Instructional Space Capacity is a BENCHMARK based on the Instructional Space Capacity calculations to provide insight to MISD. It is based on the premises that a benchmark school capacity of 67 percent of its **maximum** capacity is an ideal capacity. An overall instructional capacity of 67 percent should be attainable for schools. The majority of elementary, middle and high schools in New Mexico are able to achieve this rate. If a school is below the benchmark capacity of 67 percent, it is an indicator that the district might need to review the educational program of the school and develop a plan to increase the utilization and efficiency of the school.

Capacity Analysis Based on the New Mexico Adequacy Standards (NMAS) Method

The table on the following page shows the current MISD enrollment and the NMAS recommended square feet per student per school. The NMAS recommended facility square footage is based on the 2017/2018 enrollment and the NMAS current recommended square feet per student. The differences between existing school square footages and NMAS recommended facility square footages are shown in the subsequent columns for comparison. The table also shows the existing percentage of difference between the existing square footage and the NMAS recommended square footage. The total combined NMAS totals are calculated across the bottom of the table.


Mora Independent School District has four schools with a 2017/2018 student population of 420 and an overall square footage of permanent and portable facilities of 163,169 according to the FMP floor plans. This square footage is comprised of 64 permanent and portable instructional spaces.

NMAS Recommended Square Footage

School	2017-18 Enrollment	NMAS CURRENT Rcmd SF/Student	NMAS Rcmd Facility SF	Actual Facility SF (w/Portables)	Difference	Ratio of Existing SF to Rcmd SF
Holman ES	38	149	5,677	20,710	15,033	365%
Mora ES	176	143	25,147	35,207	10,060	140%
Elementary Subtotal:	214		30,824	55,917	25,093	181%
Lazaro Garcia MS	78	168	13,122	34,335	21,213	262%
Middle School Subtotal:	78		13,122	34,335	21,213	262%
Mora HS	128	208	26,628	72,917	46,289	274%
High School Subtotal:	128		26,628	72,917	46,289	274%
DISTRICT TOTALS:	420		70,574	163,169	92,595	231%

The NMAS recommended square footage for the four schools based on 420 students is 70,574 square feet. The existing square footage is 163,169, or 92,595 square feet more than the recommended size. Holman Elementary School exceeds NMAS recommendations by 15,033 square feet. Mora Elementary School exceeds NMAS recommendations by 10,060 square feet. Lazaro Garcia Middle School exceeds NMAS recommendations by 21,213 square feet. Lastly Mora High School exceeds the recommendations by 46,289 square feet. If the district removes all portables, it would still exceed the recommended square footage by 90,764. The NMAS recommendations do not include full-size gymnasiums for elementary schools, or auxiliary gymnasiums and performing arts centers for middle and high schools.

The next figure shows the NMAS recommended and existing square footages for each school level as well as the difference between the two.



The following table shows the NMAS recommended student capacity which is based on the existing square footage of each school in the district including portables. The NMAS recommended overall district capacity for the two schools is based on a total of 163,169 square feet and the NMAS calculator. The NMAS recommended capacity is approximately 1,006 students. This is 586 students more than the 2017/2018 student population of 420.

NM Adequacy Standards Capacity

School	Grades	2017-18 Enrollment	NMAS Rcmd Facility SF	Actual Facility SF (w/Portables)	NMAS Capacity
Holman ES	PreK-K	38	5,677	20,710	143
Mora ES	1-6	176	25,147	35,207	252
Elementary Subtotal:		214	30,824	55,917	395
Lazaro Garcia MS	7-8	78	13,122	34,335	215
Middle School Subtotal:		78	13,122	34,335	215
Mora HS	9-12	128	26,628	72,917	396
High School Subtotal:		128	26,628	72,917	396
DISTRICT TOTALS:		420	70,574	163,169	1,006

These capacities are based upon square foot per student and include portables.

Based on this method all MISD schools are under capacity. Holman Elementary School has a NMAS capacity of 143 students and its 2017/2018 enrollment was 38 students, not counting the 56 Head Start students. Mora Elementary School has a NMAS capacity of 252 students and its 2017/2018 enrollment was 176 students. Lazaro Garcia Middle School has a NMAS capacity of 215 students and its 2017/2018 enrollment was 78 students. Mora High School has a NMAS capacity of 396 and has an enrollment of 128. The results of this method show that there could be room for improvement to utilize square footage more efficiently at all MISD schools.

Capacity Analysis Results Based on the Functional Facility Capacity Method

The following table shows Maximum Facility Capacity and Functional Facility Capacity. This analysis indicates that the district's Maximum Facility Capacity with portables is 1,443 students and its Functional Facility Capacity with portables is 899 students. Mora Independent School District 2017/2018 enrollment was 420 which is 479 students less than the Functional Facility Capacity. The Functional Facility Capacity of 899 students reflects that there is a potential need to address underutilized space in the district in the near future. Without portables, the district has a Maximum Facility Capacity of 1,377 and a Functional Facility Capacity of 899.

Functional Facility Capacity Compared to Maximum Facility Capacity

School	Grades	2017-18 Enrollment	Existing # of Classrooms w/o Portables	Maximum Facility Capacity w/o Portables	Functional Facility Capacity w/o Portables	Existing # of Classrooms w/ Portables	Maximum Facility Capacity w/Portables	Functional Facility Capacity w/Portables
Holman ES	PreK-K	38	6	84	40	8	120	40
Mora ES	1-6	176	17	370	276	17	370	276
Elementary Subtotal:		214	23	454	316	25	490	316
Lazaro Garcia MS	7-8	78	16	409	205	16	409	205
Middle School Subtotal:		78	16	409	205	16	409	205
Mora HS	9-12	128	22	514	378	23	544	378
High School Subtotal:		128	22	514	378	23	544	378
DISTRICT TOTALS:		420	61	1,377	899	64	1,443	899

These capacities are based upon the number of classrooms in the District.

The Functional Facility Capacity results show that all MISD schools except Holman Elementary are under capacity. Holman Elementary has a functional capacity of 40 and an enrollment of 38. Mora Elementary has a functional capacity of 276 and an enrollment of 176. Lazaro Garcia Middle School has a functional capacity of 205 and an enrollment of 78. Mora High School has a functional capacity of 378 and an enrollment of 128 students.

Based on the functional capacity, the district could accommodate an additional 479 students with the current educational program and still remain under the identified Functional Facility Capacity.

Capacity Analysis Results Based on the Instructional Space Capacity Method

The following table shows the results of the third method of analysis, the 67 Percent Instructional Space Capacity or Benchmark Capacity. This method serves as a benchmark and can be used to compare and validate the values obtained from the other two capacity methods.

Instructional Space Capacity - 67% Benchmark Capacity

School	Grades	2017-18 Enrollment	Existing # of Classrooms w/Portables	Instructional Space Capacity w/ Portables @ 67%
Holman ES	PreK-K	38	8	80
Mora ES	1-6	176	17	248
Elementary Subtotal:		214	25	328
Lazaro Garcia MS	7-8	78	16	274
Middle School Subtotal:		78	16	274
Mora HS	9-12	128	23	364
High School Subtotal:		128	23	364
DISTRICT TOTALS:		420	64	967

According to the results, the district's Instructional Space Capacity or Benchmark Capacity is 967 students which is 547 students more than its 2017/2018 enrollment of 420. All of MISD schools appear to be under capacity. Holman Elementary School has a benchmark capacity of 80 and could accommodate 42 additional students. Mora Elementary School has a benchmark capacity of 248 and could accommodate 72 additional students. Lazaro Garcia Middle School has a benchmark capacity of 274 and could accommodate 196 additional students. Mora High School has a benchmark capacity of 364 and could accommodate 236 additional students.

Capacity Analysis Summary


The table on the next page shows a summary of the three capacity methods used for MISD: **NM Adequacy Standards Capacity**, **The Maximum Facility Capacity** / **Functional Facility Capacity** and the **67 Percent Instructional Space Capacity**. According to the results of all three methods, the capacities exceed the current student population of the schools. The capacities show that all the schools at MISD could be oversized.

The NM Adequacy Standards Capacity, the Functional Facility Capacity, and the 67% Capacity methods show consensus for the overall district's capacity indicating that the schools' capacity exceeds the enrollment of the schools and there could be excess square footage in the district.

Instructional Space Capacity

School	2017-18 Enrollment	Maximum Facility Capacity w/Portables	Functional Facility Capacity w/Portables	Instructional Space Capacity w/ Portables @ 67%	NMAS Capacity based on Existing SF/Student
Holman ES	38	120	40	80	143
Mora ES	176	370	276	248	252
Elementary Subtotal:	214	490	316	328	395
Lazaro Garcia MS	78	409	205	274	215
Middle School Subtotal:	78	409	205	274	215
Mora HS	128	544	378	364	396
High School Subtotal:	128	544	378	364	396
DISTRICT TOTALS:	420	1,443	899	967	1,006

Finally, the next graph shows a comparison of the total district capacities of all three methods of analysis. Based on the current square footage of existing facilities, the current educational program, and the number of instructional spaces, the district can accommodate approximately 479 additional students. From this number, approximately 102 students correspond to the elementary schools, 127 to the middle school, and 250 to the high school.




Utilization Studies

There are two indicators of space utilization: **Classroom Utilization Rate** and **Facility Utilization Rate**. The first indicator, Classroom Utilization Rate, is based on the percentage rate of assigned classroom occupancy. Whereas the second indicator, Facility Utilization Rate, is the percentage of assigned spaces compared to unassigned classroom spaces during a typical school day. Both indicators are explained in greater detail on the following pages.


Classroom Utilization Rate Indicator


The Classroom Utilization Rate indicator is based on the percentage rate of assigned classroom occupancy and does not include instructional support spaces. The State of New Mexico strives for an optimal instructional space utilization of 95 to 100 percent of general use classrooms for elementary schools and an optimal rate of 80 to 95 percent for middle and high schools. These **utilization** percentages are not to be confused with the **capacity** studies just discussed in this FMP. The 95 to 100 percent utilization rate identified for elementary schools and the 80 to 95 percent





utilization rate identified for middle and high schools refers to utilization of the scheduled and assigned classrooms or instructional spaces. For example, if an elementary classroom / instructional space has a capacity of 22 students, the state anticipates 21 to 22 students to occupy that space, or a utilization rate of 95 to 100 percent.

Mora Independent School District has an average Classroom Utilization Rate of 46 percent districtwide. This rate is considerably below the 80 to 95 percent NMAS recommended rate. The elementary schools have an average classroom utilization rate of approximately 80 percent, the middle school has a rate of 29 percent, and the high school has a classroom utilization rate of 28 percent. The MISD schools Classroom Utilization Rates are not consistent with the N.M. utilization guidelines of 80 to 95 percent. This indicates there could be room for improvement in the use of assigned classrooms at all MISD schools. These results are shown graphically in the next figure.









Facility Utilization Rate Indicator


The Facility Utilization Rate indicator is the percentage that indicates the number of assigned and unassigned classroom spaces during a typical school day. The Facility Utilization Rate separates classrooms that are assigned on a given school day and the number of classrooms that are used for support spaces or are unassigned.

An optimal benchmark for facility utilization for schools is 67 percent of its classrooms should be assigned classrooms. For example, a school with 12 total classrooms at 67 percent utilization would have eight




assigned classrooms and no more than four unassigned classrooms. Elementary school unassigned classrooms for support are different from the middle and high school levels.

67% Capacity of a 12 Classroom School



The chart on the right shows the percentage of assigned classroom spaces support spaces of the overall district. District students occupy 45 percent of the instructional spaces during the school day. The 45 percent overall Facility Utilization Rate does not reflect the capacity of students in the classroom spaces, only that 45 percent of those spaces are used during the day by any number of students.

Currently, the elementary schools have a facility utilization rate of 48 percent, the middle school has a rate of 30 percent and the high school has 58 percent of its instructional spaces assigned during the day.



All the average facility utilization rates are below the 67 percent benchmark. This indicates that there could be an excess of instructional spaces and an above average number of instructional spaces that are not assigned and being used as support spaces in the school.








Utilization Studies Summary

The following table shows each MISD school, their Classroom Utilization Rate and their Facility Utilization Rate.


Utilization of Spaces

School	Grades	2017-18 Enrollment	Existing # of Classrooms w/Portables	Classroom Utilization Rate	Facility Utilization Rate
Holman ES	PreK-K	38	8	95%	25%
Mora ES	1-6	176	17	64%	71%
Elementary Subtotal:		214	25	80%	48%
Lazaro Garcia MS	7-8	78	16	29%	30%
Middle School Subtotal:		78	16	29%	30%
Mora HS	9-12	128	23	28%	58%
High School Subtotal:		128	23	28%	58%
DISTRICT TOTALS:		420	64	46%	45%

In addition, the following graphs present a comparison of each school's classroom and utilization rates in relation to the recommended and optimal rates. The first graph shows that only Holman Elementary School has a classroom utilization rate of 95 percent that complies with the state's recommended values of 95 to 100 percent. The remaining schools have classroom utilization rates that are below the recommended values. Mora Elementary School has a classroom utilization rate of 64 percent. Lazaro Garcia Middle School has a classroom utilization rate of 29 percent. Mora High School has the lowest classroom utilization rate at 28 percent.



In regard to the Facility Utilization Rates, only Mora Elementary has a facility utilization rate that is above the 67 percent optimal benchmark rate. The remaining schools have facility utilization rates that are below the optimal benchmark value. Mora High School is close to the benchmark rate with a facility utilization rate of 58 percent. Lazaro Garcia Middle School has a facility utilization rate at 30 percent while Holman Elementary School has the lowest rate at 25 percent. Low facility utilization rates indicate that there could be an excess of instructional spaces and the facilities could be underutilized at these schools; however, this could also indicate a robust educational program in these schools.



Utilization and Capacity Summary

Mora Independent School District (MISD) has experienced declines in its enrollment over the past 10 years. In addition, the forecasted economic conditions in the local area could cause the student enrollment to continue its declining trend. As a result, declining enrollment has left MISD schools under capacity. The previous analyses indicate that the overall district is under capacity and has low classroom and facility utilization rates.

The three capacity methods show that the district can accommodate, at a minimum, approximately 479 additional students. From this number, around 102 students correspond to the elementary schools, 127 to the middle school and 250 to the high school. If the overall student population of MISD continues to decrease in the coming years, this may exacerbate the under-utilized spaces in the district.

Regarding the classroom and facility utilization studies, the overall district is below the recommended rates in both indicators. Holman Elementary School shows the highest classroom utilization rate at 95 percent which is compliant with the recommended 95 to 100 percent rate. The remaining schools are below the state's recommended classroom utilization rates. The high school shows the lowest classroom utilization rate at 28 percent which is significantly below the 80 percent to 95 percent recommended rate.

The facility utilization rates also indicate that the facilities in the district appear to be under-utilized. Mora Elementary School is the only school that has a facility utilization rate higher than the 67 percent optimal benchmark at 71 percent. The other schools have lower values. Holman Elementary School is the school that has the lowest facility utilization rate at 25 percent; however, but this does not reflect that the Head Start program utilizes two classrooms. Low facility utilization rates indicate that there could be an excess of instructional spaces and the facilities could be underutilized at these schools.

During the FMP process, MISD acknowledged that its facilities are under-utilized and discussed the importance of reducing square footage in order to meet adequacy standards and reduce maintenance costs of district facilities. The district identified spaces where it could reduce square footage in order to meet NMAS and reduce maintenance costs. Unfortunately, the availability of funding makes it difficult for the district to address the excess of space. Mora Independent School District will continue to monitor its declining enrollment and will make adjustments as necessary and as funds allow to improve utilization.

2.5.4 STRATEGIES TO MEET SPACE NEEDS

Mora Independent School District realizes the need to reduce square footage in district facilities because the majority of the schools are oversized and under capacity due to declining enrollment for the past 10 years. During the FMP process, the district discussed and identified different strategies that could be implemented to reduce square footage and to reduce maintenance costs; however, availability of funding makes it difficult for the district to implement these strategies.

One strategy to reduce square footage and improve efficiency discussed during the FMP process was to restructure the MISD Mora campus when funding becomes available. The district would like to replace the majority of its buildings on the Mora campus, especially the older ones. These include the administration building, the elementary school, Martinez Gym, and the cafeteria-kitchen building. The district would demolish these buildings and replace them with a multi-purpose facility that will support 21st Century Learning, testing, training, and will be based on NMAS.

The district does not have plans to reduce any permanent square footage at Holman Elementary School at this time. If enrollment continues to decline the district will revisit the utilization of its schools and take appropriate measures to provide efficient utilization.


2.5.5 UNDER-UTILIZED SPACES

Mora Independent School District discussed the importance of reducing square footage in order to meet adequacy standards and reduce maintenance costs of district facilities; however, availability of funds is a concern to the district and makes it difficult to implement any strategies to reduce square footage.

As a whole, the Mora Combined Campus square footage is 77,562 square feet above the recommended NMAS square footage; however, MISD expressed its concern about reducing its entire excess of square footage since the Mora Campus is an active part of community life and the center of community activities in town.

As previously mentioned, Mora High School is the school that has the least utilized space and could accommodate around 250 additional students; however, the school also has a robust educational program and requires a large number of classrooms to adequately support its programs. Currently, MISD does not have any plans to reduce square footage at this school so it can maintain its educational program. If the enrollment continues to decrease, the district would need to revise the utilization of the facilities and take appropriate measures to provide efficient utilization of the school.

Lits of the state of the state



CAPITAL IMPROVEMENT PROJECT HISTORY

In previous years, Mora Independent School District (MISD) has developed capital improvement plans that addressed the highest facility priorities as funds were available. The local community has shown its support of the district by passing Senate Bill-9 (SB-9) mill levies; however, MISD has not been successful in partnering with the local community to obtain General Obligation Bonds since 2005. Due to the lack of GOB funds MISD has not been able to partner with PSCOC/PSFA for any state funding of capital projects. The district continues to pursue funding opportunities with PSCOC/PSFA which resulted in an award from the state's security program. The lack of funding from PSCOC/PSFA for capital projects places the burden of providing a safe and comfortable learning environment on the local community which has not shown support for the district's capital projects. The district continues to maintain their facilities through prudent use of available funding. The following list shows a history of GOB bond elections for MISD since 2005.

Bond Election Date	Election Amount
February, 2005	\$2,300,000
Total	\$2,300,000

As the chart above shows, the community has supported MISD by passing General Obligation Bonds (GOB) for a total of \$2,300,000 over the past fourteen years. The district anticipates requesting community support in a 2020 GOB election.

The last successful SB-9 mill levy election was held in 2013. The next SB-9 election will be held on May 2019. The district typically receives approximately \$204,147 per year from SB-9.

The district has also received PSCOC/PSFA awards for a total of \$1,543,305 since 2005.

Using funds from these sources, the district has been able to accomplish various capital projects throughout the district. The following table shows the capital projects that the district has completed since 2004 and the funding source for each project.

MISD Capital Projects since 2004

Year	School	Project	Funding Source
2004	Mora HS	Enclosure and Renovation	SB-9
2006	Holman ES	Addition	GOB
2007	Admin Building	Addition and Renovation	GOB
2007	Mora Cafeteria	Roof Replacement	SB-9
2008	Track Field	New Field	Legislative Appropriations
2015	Mora HS Gym	Gym Boiler Upgrades	SB-9
2017	Mora Campus & Activity Bus	Paving Improvements	SB-9
2017	Mora ES	Playground Upgrades	SB-9
2017	Mora HS Gym	Half of Bleachers Upgrade	SB-9
2017	Mora HS Gym	Gym Lighting Upgrade	SB-9
2017	Mora Campus	Baseball Infield Upgrade	SB-9
2017	Mora Campus	Technology Upgrade	SB-9 & E-rate
2018	District Wide	Fire Alarm Upgrade	SB-9
2018	Mora Campus	Cafeteria Plumbing Upgrade	SB-9

2018	Holman ES	Cafeteria & Gym Lighting Upgrade	SB-9
2018	Holman ES	Fence and Playground Upgrade	SB-9
2018	Holman ES	Technology Upgrade	SB-9 & E-rate
2018	Holman ES	Paving Upgrade	SB-9

CURRENT AND ANTICIPATED FINANCIAL RESOURCES

General Obligation Bonds (GOB)

The 2018 assessed land valuation of MISD was \$101,531,411. The MISD maximum bonding capacity at 6 percent of its 2018 assessed valuation was approximately \$6,091,885. As of December of 2018, the district does not have any bonds outstanding. Currently MISD available bonding capacity is \$6,091,885. The district anticipates its next GOB election in 2020 for approximately \$3,000,000. Since MISD does not have any outstanding bonds and is bonded at zero percent to capacity, the tax rate has declined and any successful GOB election will result in an increase to taxpayers.

Mill Levies

Mora Independent School District has a 2 mill levy in place to take advantage of state matching funds under the NM Senate Bill 9 (SB-9) program. SB-9 revenues provided approximately \$204,147 for the 2017-2018 school year for general maintenance and small projects. The levy is subject to renewal through an election every six years. The last SB-9 successful election was in 2013, the next SB-9 election is scheduled for May 2019.

The district does not have a mill levy in place allowed under N.M. House Bill 33 (HB33) and does not anticipate asking the community to support a HB33 levy. HB33 funding is generally used for renovation, additions to existing facilities and technology. Mill levies under HB33 must be approved through an election every five years.

Deficiencies Correction Unit Funding

New Mexico House Bill 31 (HB31) was a funding program that was established to provide additional funding to New Mexico Public School Districts to primarily address health and safety needs. The district has received funding under HB31 to address health and safety needs at all school campuses within the district. All identified projects receiving funds from this source have been completed. The fund was administered by the New Mexico Department of Education Deficiencies Correction Unit (DCU) which has evolved into the Public School Facilities Authority (PSFA). The PSFA/DCU provided funds to MISD for addressing health and safety needs throughout the district. The exact amount of funds provided to the district could vary slightly based upon the final project completion cost. There is no additional funding available for school districts through this program at this time.

Broadband Deficiencies Correction Program

The state created a broadband deficiencies correction program in 2016 which provides funding to assist New Mexico public school districts to increase their broadband and/or technology capabilities. This program works with funds from the district, E-rate and PSCOC and is funded through PSCOC and overseen by PSFA. Mora Independent School District applied for and received funding through this program for one project. The project included \$3,221 from PSCOC, \$52,159 from E-rate and 5,983 from

3.1

Total Capital Needs

the district. The funding was used to upgrade wireless access, switches and a network route at Mora Campus.

School Security Funding

The state created a program in 2018 which provides funding to assist New Mexico public school districts in upgrading security at school campuses as needed. This program is funded through PSCOC and overseen by PSFA. Mora Independent School District applied for and received school security funding in 2018. The district was awarded \$21,139 from the state to address security needs at Mora Campus. This funding through PSCOC for school security projects required a district funding match of \$44,920 for a total security project cost of \$66,060.

Legislative Appropriations

Mora Independent School District can receive special appropriations granted by the legislature. Amounts appropriated can vary or can be zero. The amount of money from legislative appropriations accepted by the district will be deducted from critical capital outlay funds. The district has received \$240,000 from legislative appropriations since 2011; however, the district does have an offset of \$809,366.

Federal Impact Aid

Mora Independent School District does not receive PL874 Federal Impact Aid funds. Federal Impact Aid funds are provided to school districts in lieu of local property taxes for students residing on federal lands within their service area. This includes Native American lands, military installments, federal public domain, and national forest lands.

Grants/E-Rate

Mora Independent School District is an E-rate funded district and receives a variable amount of funding every year for technology and broadband projects through the E-rate program.

Public School Capital Outlay Act

Effective September 1, 2003 any school district can apply for capital outlay funds regardless of its percentage of indebtedness. Priorities for funding of school projects are determined by using the facilities assessment database (FAD) ranking of each public school in the state. The FAD ranking is based on the statewide adequacy standards and national building systems standards. All districts must present their needs before the PSCOC which is comprised of nine members. The following or their designees are identified in statute: the Governor, the Secretary of the Department of Finance and Administration, the Director of the Construction Industries Division of the Regulation and Licensing Department, the Secretary of Education, the President of the State Board of Education, the President of the State School Boards Association, and the Directors of the Legislative Education Study Committee, Legislative Finance Committee, and the Legislative Council Services.

The Council shall establish criteria to be used in public school capital outlay projects that receive grant assistance including the feasibility of using design, build and finance arrangements; the potential use of more durable construction materials; and any other financing or construction concept that may maximize the dollar effect of the state grant assistance.

3.1

Total Capital Needs

No more than 10 percent of the combined total of grants in a funding cycle shall be used for retrofitting existing facilities for technology infrastructure. No application for grant assistance shall be approved unless the Council determines that: the project is needed and included in the school district's five-year facilities plan; the school district has used its capital resources in a prudent manner; the school district has provided insurance for buildings; the school district has submitted a five-year facilities master plan that includes enrollment projections, a current preventive maintenance plan, and projections for the facilities needed in order to maintain a full-day kindergarten program; the school district is willing and able to pay any portion of the total cost not funded with grant assistance from the fund; the application includes the capital needs of any charter schools located in the district; and the school district has agreed to comply with reporting requirements.

Mora Independent School District must compete with all other New Mexico public school districts for this funding. As of April 2018, MISD's match for this funding source is 68 percent and the state's match is 32 percent. Since 2005 MISD has received \$1,543,305 from PSCOC for capital projects.

MISD TOTAL 2019-2023 ANTICIPATED CAPITAL NEEDS AND FUNDING SOURCES

The total 2019-2023 facilities needs identified for MISD during the FMP process is approximately \$14,643,497. This is the total needs of all district facilities including Holman Elementary School, Mora Combined School, and all district support facilities.

The 2019-2023 facility needs of MISD have been broken down into eight funding categories to identify the type of need and potential funding source to address that type of need:

- 1. BS-GOB, Building Systems Upgrades-GOB: Identified building/site systems upgrades anticipated to be funded by GOB.
- 2. BS-SB9, Building Systems Upgrades-SB-9: Identified building/site systems upgrades anticipated to be funded by SB-9.
- 3. L-GOB, Life-Health-Safety-Security-GOB: Identified life, health, safety, security, code and ADA needs anticipated to be funded by GOB.
- 4. L-SB9, Life-Health-Safety-Security-SB-9: Identified life, health, safety, security, code and ADA needs anticipated to be funded by SB-9.
- 5. MP-GOB, Miscellaneous Capital Projects-GOB: Identified miscellaneous capital projects, not related to building system upgrades, anticipated to be funded by GOB.
- 6. MP-SB9, Miscellaneous Capital Projects-SB-9: Identified miscellaneous capital projects, not related to building system upgrades, anticipated to be funded by SB-9.
- 7. PreVent, Preventive Maintenance: Identified miscellaneous preventive maintenance projects anticipated to be funded by SB-9.
- 8. Tech: Technology: Identified technology projects anticipated to be funded by E-rate and SB-9 funds.

The following table lists the sources of funding that the school utilizes to address life-health-safety-security-code-ADA, maintenance, building system renewal, capital projects, and technology/broadband needs:

MISD Funding Sources

Sources of Funding for:	GOB	SB-9	E-Rate
Life/Health/Safety/Security/Code Issues		✓	
Maintenance / Preventive Maintenance		✓	
Technology / Broadband		✓	✓
Building Systems Upgrades	✓		
Capital Projects	✓		

The next table summarizes the type of need, its potential funding source, and the cost of the project.

MISD Project Cost by Funding Source

Project Type	Funding Source	Total Projects Cost	Percentage of Total
Building Systems Upgrades	GOB	\$5,958,111	41%
Building Systems Upgrades	SB-9	\$716,633	5%
Life/Health/Safety/Security/Code Issues	GOB	\$1,511,354	10%
Life/Health/Safety/Security/Code Issues	SB-9	\$250,000	2%
Miscellaneous Projects	GOB	\$5,436,665	37%
Miscellaneous Projects	SB-9	\$0	0%
Preventive Maintenance	SB-9	\$520,735	4%
Technology	GOB & E-Rate	\$250,000	2%
DIS	STRICT TOTALS	\$14,643,497	100%

To meet the 2019-2023 facilities needs of MISD based on the above funding categories, the district anticipates a potential budget of approximately \$4,020,735. This amount does not include any funds from partnering with PSCOC on qualifying projects.

MISD Anticipated Capital Funding

Funding Source	Project Type	Year	Amount
SB-9 Funds	Life-Health-Safety-Security-Code, Building System upgrades, and Technology needs	2019-2023	\$1,020,735
GOB Funds	Life-Health-Safety-Security-Code, major Building System upgrades, Preventive Maintenance needs, and Capital projects	2020	\$3,000,000
TOTA	AL MISD Facility Needs Anticipated Budge	et 2019-2023	\$4,020,735

The potential budget for MISD identifies SB-9, GOB, and E-rate as available funding sources to address its facility needs. At this time, due to the current Facilities Assessment Database (FAD) ranking of district facilities, MISD anticipates being able to partner with PSCOC/PSFA for the identified facility needs at Mora Combined School during the life of this FMP if they can obtain community support through a GOB election. The district will continue to work with PSFA, monitor the FAD ranking of all district schools and apply for PSCOC/PSFA funding as they qualify and their funding match is available.

FACILITY NEEDS BY FACILITY

The district's identified capital needs cover ALL district schools and support buildings. The district identified capital needs at each of its facilities as follows:



HOLMAN ELEMENTARY SCHOOL: \$63,427

Holman Elementary School (HES) is located in the community of Holman. It is located 6.4 miles north to the Mora Campus. The main building opened prior to 1969. There have been some additions to it in 1969, 1987 and 2006. The north portion of the building was renovated in 1987. There is one double portable classroom on site. Holman Elementary School serves pre-K and kindergarten grades. The Mora County HeadStart program is housed at Holman Elementary School.



Holman Elementary School is an older school which has been renovated several times, but some of its building systems are past their useful life. The majority of needs identified at Holman ES are related to Life-Health-Safety-Security (LHSS) and Preventive Maintenance. The majority of the LHSS issues at the school are due to the age of the building and condition of the systems. The majority of the LHSS needs at this school has been grandfathered in and do not require immediate attention; however, any major renovation of this school would require that the grandfathered items be corrected. The majority of Preventive Maintenance needs are related to building systems that require preventive maintenance to extend their useful life.




The district has been addressing the facility needs as funding is available, keeping the facilities safe and comfortable for use, and will continue to do so. The HES major building system needs that could require GOB funds to address are:



Drain, Waste, and Vent Water Distribution

- There are no areas of HES that have been identified to be replaced at this time.
- There are no areas of HES that have been identified for major renovation at this time.



- There are no areas of HES that have been scheduled for minor renovation at this time.
- All sections of HES need continued general maintenance.
- All sections of HES require continued preventive maintenance.





- There are no areas of HES that have been identified for disposal or demolition.
- There are no portables on HES campus that have been identified for disposal.
- There are no instructional spaces of HES that are under consideration for closure at this time.
- There is no plan to consolidate HES with any other district school at this time.



MORA COMBINED SCHOOL (ES/MS/HS): \$11,502,670

Mora Combined School (MCS) is located on the village of Mora at the Mora Campus and is an active part of community life. Mora Combined School is comprised of Mora Elementary School, Lazaro Garcia Middle School and Mora High School and all support buildings. The original campus construction was in 1950 and consisted of what is now the district administration building, the elementary school and what is now the elementary and middle school gym with an addition to the gym around 1971 and an addition to and complete renovation of the elementary school in 2001. The district administration building burned down




and was rebuilt on the existing foundation in 1995. Mora High School was built in 1968 and completed in 2004. Lazaro Garcia Middle School was built in 1997. Mora High School Gym was built in 1974 with an addition in 1991. The campus cafeteria/kitchen was built in 1965 and expanded in 1998. The Mora Industrial Arts building was constructed in 1990 with an addition in 2003. The district built an outdoor swimming pool and locker rooms in 1970 and covered the pool in 1994. The school received a grant from New Mexico Highlands University for a weight training building which consists of two double portables on site.



Mora Combined School is comprised of older and newer buildings with many of its building and site systems past their useful life. With the decline in student population, the district has identified the need to reorganize the Mora campus into a more efficient and effective campus that could better service students' needs; however, it has been difficult to obtain community support for any capital projects. Some of the older buildings could be demolished and replaced with new, efficient buildings which would help to reduce square footage. The majority of needs identified at MCS are related to Facility Renewal, Life-Health-Safety-Security-Code-ADA (LHSS) and Preventive Maintenance. The majority of the Facility Renewal needs are related to building and site systems that are past their useful life and need to be replaced. The majority of needs, related to LHSS at this school, have been grandfathered in and do not require immediate









The cost associated with the MCS includes renovation of the ES/MS gym locker and restrooms, the band room, HS gym restrooms and lobby and work to bring up the conditions at the athletic fields. The work identified for the athletic fields includes upgrading the track surface; a sprinkler system at the football field; creation of a softball field, concessions and restrooms; and lighting for the baseball and softball fields.



The district has been addressing the facility needs as funding is available, keeping the facilities safe and comfortable for use, and will continue to do so; however, the lack of funding has made it difficult for the district to maintain its facilities with many of their building systems facing deferred maintenance. The Mora Combined School major building system needs that could require GOB funds to address are:



Ceiling finishes
Exterior Walls
Exterior Windows & Doors
Floor Finishes
HVAC
HVAC Controls
Institutional equipment
Interior Doors
Other Electrical Systems
Plumbing
Roofs

Wall Finishes



- There are sections of MCS that have been identified to be replaced as soon as funding is available. The District would like to replace Mora Cafeteria/Kitchen and Martinez Gym with a new multi-purpose building that will support 21st century learning and will incorporate training and technology into MCS educational programs.
- There are sections of MCS that have been identified for major renovation at this time, specifically restrooms at the high school gym.
- The majority of building systems have been identified to be updated at MCS. See above.
- The HS Gym Lobby has been scheduled for minor renovation at this time.





- All sections of MCS require continued preventive maintenance.
- The maintenance building at MCS has been identified for demolition.
- There are no portables on MCS campus that have been identified for disposal.
- There are no instructional spaces of MCS that are under consideration for closure at this time.
- There is no plan to consolidate MCS with any other district school at this time.



During this FMP process two options were discussed and developed for the Mora Combined Campus. Both of these options focus on the need to reorganize the campus and create a more efficient, effective foot print.



Option A would demolish the ES/MS gym building, the cafeteria/kitchen building, and the old maintenance building. These buildings would be replaced with a multi-purpose building that would include an ES/MS gym, band, training, testing, cafeteria and kitchen. The probable cost of this option is \$7,742,085, but would eliminate the need and cost associated with the renovation of the building systems associated with these buildings.




Option B would demolish the ES/MS gym building, the cafeteria/kitchen building, the old maintenance building, the administration building and the elementary school. These buildings would be replaced with a multipurpose building that would include an ES/MS gym, band, training, testing, cafeteria and kitchen. The elementary school could move into the middle school building and the middle school students could be moved into the high school building with the high school students. The probable cost of this option is \$11,502,670, but would eliminate the need and cost associated with the renovation of the building systems associated with these buildings and create the most efficient school footprint. This is the district's preferred option.



District School Facilities Total: \$ 11,566,097
District Support Facilities / District Wide Needs: \$ 3,077,400

District Total Facility Needs: \$ 14,643,497

The graph on the following page illustrates the probable cost of the needs at each facility. Refer to the NEEDS spreadsheet sorted by FACILITY at the end of this section for a detailed list of MISD needs related to the facilities identified above.



													TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
Priority 1 Life-Health-Safe	ety-Security / Ma	intenance / Techno	logy:	•										
					Life-Health-Safety-Security-									
District Wide					ADA-Code	LHSS	L-SB9	Address life-health-safety-security issues		yr.	\$50,000	\$250,000	\$250,000	
District Wide				Dist.	Maintenance	PreVent	Prevent	Preventive and Regular Maintenance needs	5	yr.	\$104,147.00	\$520,735	\$520,735	
								Upgrade technology district wide: Hardware,						
District Wide		District		Dist.	Technology	Tech	Tech	Software, Training, Broadband	5	yr.	\$50,000.00	\$250,000	\$250,000	\$1,020,735
		HES Original												
Holman ES	1969	Const		FAD	Drain, Waste and Vent	LHSS	L-GOB	\$24.55	1	FAD	\$0.00	\$0	\$0	
	4007	LIEO A LIBE		E. D	F. A. dan B			Replace exit classroom doors to ADA compliant,		E 4 D	00.00		ФО	
Holman ES	1987 2006	HES Addition		FAD	Exterior Doors	LHSS	L-GOB L-SB9	\$14,098	1	FAD	\$0.00	\$0	\$0	
Holman ES	2006	HES Addition HES Original		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Replace broken front window		ea.		\$0	\$0	
Holman ES	1969	Const		FAD	Water Distribution	LHSS	L-GOB	\$24.554	1	FAD	\$0.00	¢ο	\$0	
Holman ES	1969	HES Site		Dist.	Z-Fencing	LHSS	L-GOB L-GOB	Upgrade playground fencing : 2018 In Progress		If	\$0.00	\$0 \$0	· ·	
Holman ES	1969	HES Site		Dist.	Z-Fencing Z-Fencing	LHSS	L-GOB	Repair perimeter fencing: 2018 In Progress		lf		\$0 \$0	1 -	
Holman ES	1969	HES Site		FAD	Z-Parking Lots	LHSS	L-GOB	Beyond expected life by aging \$76,509		FAD	\$0.00		, ·	
Holitian E3	1909	TILO OILE		I AD	Z-i arking Lots	LIIOO	L-GOB	Redesign Pick-Up/Drop-Off area to separate bus and		ו אט	ψ0.00	ΨΟ	ΨΟ	
Holman ES	1969	HES Site		Dist.	Z-Parking Lots	LHSS	L-GOB	parent traffic	1	ea.	\$0.00	\$0	\$0	
Holman ES	1969	HES Site		Dist.	Z-Site Lighting	LHSS	L-GOB	Install site lighting		ea.	\$0.00	\$0	1 -	
Holman Eo	1000	TILO OILO		Dist.	Z Olio Lighting	LITOO	L GGB	motali otto lighting		cu.	ψ0.00	ΨΟ	ΨΟ	
								Create an evacuation route in the back of building.						
Holman ES	2006	HES Addition		Dist.	Z-Walkways	LHSS	L-GOB	There is only evacuation route in the front.	1	ea.	\$0.00	\$0	\$0	
Holman ES	1969	HES Site			Z-Walkways	LHSS	L-GOB	Replace walkways	300		\$0.00	\$0	T -	
Holman ES	1987	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in corridor		sf	*****	\$0	· ·	
					3			Replace / repair stained ceiling tiles in library's exit				**	, -	
Holman ES	1995	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	and in office area		ea.		\$0	\$0	
Holman ES	2006	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Repair ceiling tiles; ceiling bubble in kitchen		sf		\$0	\$0	
		HES Original			-									
Holman ES	1969	Const		Dist.	Ceiling Finishes	PreVent	PreVent	Replace / repair stained ceiling tiles in corridor		sf		\$0	\$0	
		HES Original												
Holman ES	1969	Const		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair water damage in sill at director's office		sf		\$0	\$0	
Holman ES	1987	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Replace / repair cracked VCT in corridor		sf		\$0	· ·	
Holman ES	1995	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Repair carpet snag in nurse's office		ea.		\$0	\$0	
										_				
Holman ES	2006	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Repair / replace cracked VCT outside girls restroom		sf		\$0	\$0	
		HES Original												
Holman ES	1969	Const		Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in reception		ea.		\$0	\$0	
								Ceramic tile in this area \$58,787: Replace cracked						
								ceramic tile in commons area and at north entrance						
Mora Combined School	2004	HS Commons Addition		FAD	Floor Finishes	FacBan	BS-GOB	of building and Replace / Repair buckled VCT in		of	\$0.00	¢ο	ФО	
Mora Combined School	2004	Addition		FAD	Floor Finishes	FacRen	BS-GOB	Conference room and music room		SI	\$0.00	\$0	\$0	
Mora Combined School	1991	HS Gym Addition		FAD	Floor Finishes	FacRen	BS-GOB	Original \$31,041: Replace cracked VCT in lobby		sf	\$0.00	\$0	\$0	
Mora Combined School	1991	113 Gylli Addition		FAD	Floor Fillisties	racken	B3-G0B	alea		51	φυ.υυ	φυ	φυ	
Mana Canalisa di Calada	4000	LIO Maio Dido		EAD	Elece Efetales	F B	DO 00D	Original \$101,101: Replace cracked VCT in			00.00	40	ФО.	
Mora Combined School	1968	HS Main Bldg.		FAD	Floor Finishes	FacRen	BS-GOB	computer lab 112 and at entrance of classroom 109		st	\$0.00	\$0	\$0	
Mana Camabinad Cabaal	4074	HS Original Const		EAD.	C	11100	L COD	DOLL 03 040 #04 040			#0.00	ф о	¢ο	
Mora Combined School Mora Combined School	1974 1968	(gym) HS Main Bldg.		FAD FAD	Communications / Security Communications / Security	LHSS LHSS	L-GOB	DCU 03-019 \$24,249 DCU 03-019 \$27,677: Updated 2003		ea.	\$0.00 \$0.00	\$0 \$0		
Mora Combined School	1968	HS Industrial Arts		FAD	Communications / Security	LHSS	L-GOB L-GOB	Intercom installed. DCU 03-019 \$7,805		ea. ea.	\$0.00	\$0 \$0		
Mora Combined School	1991	HS Gym Addition			Communications / Security	LHSS	L-GOB	DCU 03-019 \$3,850		ea.	\$0.00	\$0 \$0		
word Combined School	1991	HS Commons		ו עט	Communications / Occurry	L1100	<u> </u>	Σ 5 5 5 5 1 5 ψ0,000		ca.	φυ.υυ	φυ	Ψ	
Mora Combined School	2004	Addition		FAD	Communications / Security	LHSS	L-GOB	\$17,498		ea.	\$0.00	\$0	\$0	
mora combined control	2004	ES Original Bldg.		1,7,0	Communications / Occurry	1.1.00		\$15,429: Replace bell system: current system does		ou.	ψ0.00	φυ	Ψ	
Mora Combined School	1950	South Wing		FAD	Communications / Security	LHSS	L-GOB	not work		ea.	\$0.00	\$0	\$0	
	1000	ES Original Bldg.		1.7.5			- 002	\$13,488: Include replacement of bell system: current		Ju.	ψ0.00	ΨΟ	ΨΟ	
Mora Combined School	1950	North Wing		FAD	Communications / Security	LHSS	L-GOB	system does not work		ea.	\$0.00	\$0	\$0	
	1200	ES MS Org. Gym /		1				,			\$5.30	Ψ	Ψ	
Mora Combined School	1950	Band, K-8		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$18,776		ea.	\$0.00	\$0	\$0	

													TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	dentified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
		ES MS Org. Gym /		•										
Mora Combined School	1950	Band, K-8	F	FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$22,568		ea.	\$0.00	\$0		
Mora Combined School	1965	Cafeteria, K-12	F	FAD	Communications / Security	LHSS	L-GOB	DCU 03-123 \$6,971: No intercom		ea.	\$0.00	\$0	\$0	
		ES Library Phase 3												
Mora Combined School	2001	Const	F	FAD	Communications / Security	LHSS	L-GOB	\$4,427		ea.	\$0.00	\$0	\$0	
Mana Camabina d Cabaal	4005	A alma in /1/2 in all a m	_	- 4 D	C	11100	LCOR	\$12,649 Comm is original: Working but need to			#0.00	Ф.О	Φ0	
Mora Combined School	1995	Admin/Kinder	r	FAD	Communications / Security	LHSS	L-GOB	upgrade		Sī	\$0.00	\$0	\$0	
Mora Combined School	1995	Admin/Kinder	F	FAD	Emergency Light and Power	LHSS	L-GOB	\$2,830		sf	\$0.00	\$0	\$0	
		LIC Original Compt						Doors on the main gym sticking and hard to open:						
Mora Combined School	1974	HS Original Const (gym)		FAD	Exterior Windows & Doors	LHSS	L-GOB	Possible safety problem with exiting the building \$472,155		00	\$0.00	\$0	\$0	
Mora Combined School	1974	(gyiii)	Į.	AD	Exterior Willdows & Doors	LIOS	L-GOB	\$472,133		ea.	φυ.υυ	φυ	Φ0	
		ES Original Bldg.						Exterior doors sticking and hard to open: Possible						
Mora Combined School	1950	South Wing	F	AD	Exterior Windows & Doors	LHSS	L-GOB	safety hazard in need of service \$180.251		ea.	\$0.00	\$0	\$0	
		ES Library Phase 3						Exterior doors sticking and hard to open: Possible			,	, -	, -	
Mora Combined School	2001	Const	F	FAD	Exterior Windows & Doors	LHSS	L-SB9	safety hazard in need of service \$48,849		ea.	\$0.00	\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Update north exit door to ADA complaint		ea.	·	\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Repair window in computer lab 103: it does not lock		ea.		\$0	\$0	
								Upgraded 1998 only in custodian area \$22,568:						
Mora Combined School	1997	MS Main Bldg.	F	FAD	Fire Detection/Alarm	LHSS	L-GOB	Updated 2017	() sf	\$0.00	\$0	\$0	
		HS Original Const												
Mora Combined School	1974	(gym)	F	-AD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$24,249: Updated 2018		sf	\$0.00	\$0	\$0	
			_					Fire alarm and intercom modifications \$30,092:			40.00			
Mora Combined School	1968	HS Main Bldg.		AD	Fire Detection/Alarm	LHSS	L-GOB	Updated 2018		sf	\$0.00	\$0		
Mora Combined School	1991	HS Industrial Arts		FAD	Fire Detection/Alarm	LHSS LHSS	L-GOB	Fire alarm system installed. DCU 03-019 \$7,805 DCU 03-019 \$3,850		sf	\$0.00	\$0	· ·	
Mora Combined School	1991	HS Gym Addition HS Commons	<u> </u>	AD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$3,030		sf	\$0.00	\$0	\$0	
Mora Combined School	2004	Addition	F	AD	Fire Detection/Alarm	LHSS	L-GOB	\$17,498		ef	\$0.00	\$0	\$0	
Word Combined Concor	2004	ES Original Bldg.		/\D	The Betestion, warm	Lileo	L 00B	Ψ17,400		01	ψ0.00	Ψ	ΨΟ	
Mora Combined School	1950	South Wing	l _e	AD	Fire Detection/Alarm	LHSS	L-GOB	\$15,429		sf				
					-						\$0.001	\$0	\$0	
							L 00B	Ψ10,423			\$0.00	\$0	\$0	
Mora Combined School	1950	ES Original Bldg. North Wing		FAD	Fire Detection/Alarm	LHSS	L-GOB	\$13,488		ea.	\$0.00 \$0.00	\$0 \$0		
Mora Combined School	1950	ES Original Bldg.			Fire Detection/Alarm	LHSS				ea.	·	·		
Mora Combined School Mora Combined School	1950 1950	ES Original Bldg. North Wing	F		Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS				ea.	·	·	\$0	
		ES Original Bldg. North Wing ES MS Org. Gym /	F	-AD		LHSS	L-GOB	\$13,488		ea.	\$0.00 \$0.00	\$0	\$0	
Mora Combined School Mora Combined School	1950 2001	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const	F F	FAD FAD	Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS	L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427		sf sf	\$0.00 \$0.00 \$0.00	\$0 \$0 \$0	\$0 \$0 \$0	
Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12	F F F	FAD FAD FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS LHSS	L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971		sf sf sf	\$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder	F F F F	FAD FAD FAD FAD FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018	(sf sf sf ea.	\$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12	F F F F	FAD FAD FAD FAD FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS LHSS	L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered	(sf sf sf	\$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder	F F F F	FAD FAD FAD FAD FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure	(sf sf sf ea.	\$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg.	F F F F	FAD FAD FAD FAD FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391:	(sf sf sf) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder	F F F F	FAD FAD FAD FAD FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm	LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional	(sf sf sf ea.	\$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997 1968	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg.	F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure	(sf sf sf o) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg.	F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional	(sf sf sf) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons	F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713	(sf sf sf) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997 1968	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition	F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure	1	sf sf sf o) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons	F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713	1	sf sf sf) ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg.	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD Oist. FAD Oist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079	1	sf sf sf sf ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004	ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg. North Wing	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD FAD FAD FAD FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered	1	sf sf sf sf ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES MS Org. Gym /	F F F F F F F F F F F F F F F F F F F	FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537	1	sf sf sf sea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES MS Org. Gym / Band, K-8	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD FAD FAD FAD Oist. FAD	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor	1	sf sf sf sea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES MS Org. Gym / Band, K-8 ES Original Bldg.	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD FAD FAD Dist. FAD FAD FAD FAD FAD FAD FAD FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537 Replace wall pads	1	sf sf sf sea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Original Bldg. North Wing	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD FAD FAD Dist. FAD FAD FAD FAD FAD FAD FAD FAD FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537	1	sf sf sf sea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950 1950 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Original Bldg. North Wing ES Original Bldg. North Wing	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD Dist. FAD Dist. FAD Dist. FAD Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Institutional Equipment	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537 Replace wall pads Install ADA signage in all areas	1	sf sf sf sea. ea. ea. ea. ea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	
Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School Mora Combined School	1950 2001 1965 1995 1997 1968 1991 2004 1950 1950	ES Original Bidg. North Wing ES MS Org. Gym / Band, K-8 ES Library Phase 3 Const Cafeteria, K-12 Admin/Kinder MS Main Bldg. HS Main Bldg. HS Gym Addition HS Commons Addition ES Original Bldg. North Wing ES MS Org. Gym / Band, K-8 ES Original Bldg. North Wing	F F F F F F F F F F F F F F F F F F F	FAD FAD FAD FAD Dist. FAD Dist. FAD Dist. FAD Dist. FAD Dist. Dist.	Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Detection/Alarm Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler Fire Sprinkler	LHSS LHSS LHSS LHSS LHSS LHSS LHSS LHSS	L-GOB	\$13,488 DCU 03-019 \$18,776 Completed Dec 2001 \$4,427 DCU 03-019 \$6,971 \$12,649: Updated 2018 Building is not sprinklered NMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: Fully functional NMSFMO recomm. compl. syst. Pressure problematic \$30,713 This is required \$11,079 Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537 Replace wall pads	1	sf sf sf sea. ea. ea. ea. ea. ea.	\$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
		HS Original Const												
Mora Combined School	1974	(gym) ES MS Org. Gym /		FAD	Main Power/Emergency	LHSS	L-GOB	Original \$16,277		sf	\$0.00	\$0	\$0	
Mora Combined School	1950	Band, K-8		FAD	Main Power/Emergency	LHSS	L-GOB	Replaced 1984 \$12,603		sf	\$0.00	\$0	\$0	
Mora Combined School	1974	HS Original Const (gym)		Dist.	Plumbing	LHSS	L-GOB	Upgrade Men's bathroom to ADA complaint		sf		\$0	\$0	
Mora Combined School	1950	ES Original Bldg. South Wing		Dist.	Plumbina	LHSS	L-GOB	Upgrade drinking fountain alcove to ADA complaint		ea.		\$0	\$0	
		oodan viinig		2.01				Poor drainage around the buildings and grounds				Ψ.	ų s	
Mora Combined School	1950	MCS Site		FAD	Z-Landscaping	LHSS	L-GOB	causing damage to exterior walls on the building \$524,513		sf	\$0.00	\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Dist.	Z-Landscaping / Drainage	LHSS	L-GOB	Correct drainage on west side of building outside the band room: water filters through the doors		ea.		\$0	\$0	
Mora Combined School	1950	MCS Site		FAD	Z-Parking Lots	LHSS	L-GOB	Area in poor condition in need of repair due to deterioration and poor drainage around the complex \$1,180,660: District repayed entrance and HS parking lot in 2017		of	\$0.00	\$0	\$0	
					· ·					51	·	**		
Mora Combined School	1950 1968	MCS Site HS Main Bldg.			Z-Site Lighting Z-Site Lighting	LHSS LHSS	L-GOB	Repair / replace wall pack lights on Main HS Building		sf	\$0.00	\$0 \$0	\$0 \$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Z-Site Lighting	LHSS	L-GOB	Install site lighting: there is no lighting in this area Repair / replace one lift station pump: it is not		ST		\$0	\$0	
Mora Combined School	1950	MCS Site		Dist.	Z-Site Utilities	LHSS	L-GOB	working		sf	\$0.00	\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band. K-8		Dist.	Z-Site Utilities	LHSS	L-GOB	Rework drain pipes from ES MS Gym to have one lift station.		ef	,	\$0	\$0	
Word Complified Concor	1000	Buria, it o		Dist.	2 Oile Guillies	LITOO	L-OOB	Walkways in poor condition due to cracks, deterioration and missing concrete. Possible tripping		31		ΨΟ	ψ	
Mora Combined School	1950	MCS Site		FAD	Z-Walkways	LHSS	L-GOB	hazards \$1,459,949		sf	\$0.00	\$0	\$0	
Mora Combined School	1950	ES Original Bldg. South Wing		Dist.	Z-Walkways	LHSS	L-GOB	Repair sidewalk and ramp at south entrance of building		sf		\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Dist.	Z-Walkways	LHSS	L-GOB	Repair sidewalk in north side of building		sf		\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Z-Walkways	LHSS	L-GOB	Repair sidewalk next to the cafeteria		sf		\$0	\$0	
Mora Combined School	1950	Admin/Kinder		Dist.	Ceiling Finishes	PreVent	Prevent	Repair stained ceiling in storage room 117		sf		\$0		
Mora Combined School	1965	Cafeteria, K-12		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in kitchen room		sf		\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Dist.	Ceiling Finishes	PreVent	PreVent	Repair / replace stained ceiling tiles in boys and girls showers		sf		\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Dist.	Ceiling Finishes	PreVent	PreVent	Repair / replace stained ceiling tiles in band room and in classroom 148		sf		\$0	\$0	
		ES MS Org. Gym / Band, K-8			Ceiling Finishes					-f		\$0	\$0	
Mora Combined School	1950	ES Original Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Repair / replace stained ceiling tiles in janitor's closet		SI		\$0	20	
Mora Combined School	1950	North Wing ES Original Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
Mora Combined School	1950	South Wing HS Commons		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
Mora Combined School	2004	Addition		Dist.	Ceiling Finishes	PreVent		Replace stained ceiling tiles in library		sf		\$0		
Mora Combined School	1991	HS Gym Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in storage room		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in teacher's lounge, conference room and in storage room 117		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.	125, 120, 115, 137, 108	Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in science labs and classrooms		sf		\$0	\$0	
Mora Combined School	1974	HS Original Const	,		Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in room next to girls lockers		ef		\$0	\$0	
		(0)	103, 107, 112, 108, 109, 110,					Replace / repair stained ceiling tiles in classrooms		31		φυ		
Mora Combined School	1997	MS Main Bldg.	111, 102	Dist.	Ceiling Finishes	PreVent	PreVent	and computer lab		sf		\$0	\$0	

													TOTAL	
							Funding	540U ITV NEEDO			0007/11/17		PROJECT COST	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	WACC		SUBTOTALS
Mora Combined School	1997	MS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at southwest side of the building		sf		\$0	\$0	
Maria Caratina de Catada	4007	MO Maio Dido		Dist	O different Fire to be a	D	Durit	Repair / replace stained ceiling tiles in corridor in				00	40	
Mora Combined School	1997	MS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	front of classroom 109		st		\$0	\$0	
Mora Combined School	1950	Admin/Kinder		Dist.	Exterior Walls	PreVent	PreVent	Caulk perimeter of building		Sī		\$0	\$0	
Mana Camabinad Cabaal	2004	ES Library Phase 3		Dist	Futorior Walla	D==\/==+	Du-1/	Denois wated studen at north east wall of library				¢ο	Φ0	
Mora Combined School	2001	Const		Dist.	Exterior Walls	PreVent	PreVent	Repair rusted stucco at northeast wall of library		Sī		\$0	\$0	
Mora Combined School	2001	ES Library Phase 3 Const		Dist.	Exterior Walls	PreVent	PreVent	Repair rusted stucco at west corner bead		of		\$0	\$0	
Mora Combined School	2001	ES MS Org. Gym /		DISt.	Exterior waiis	Prevent	Prevent	Repair fusied stucco at west corner bead		SI		Φ0	φ0	
Mora Combined School	1950	Band, K-8		Dist.	Exterior Walls	PreVent	PreVent	Repair wall crack on southeast side of the building		of		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	Caulk perimeter of building		SI If		\$0 \$0	\$0 \$0	
Wora Combined School	1900	110 Mail Blug.		Dist.	Exterior Walls	FIEVEIIL	Fievelit	Repair cracked stucco at west entry and at north	-	11		φυ	φυ	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	entry		cf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	Repair wall outside and inside		of.		\$0 \$0		
Wiora Combined School	1991	ES MS Org. Gym /		Dist.	Exterior Walls	i levelit	i ievent	Repair waii outside and inside		31		ΨΟ	ΨΟ	
Mora Combined School	1950	Band, K-8		Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken windows in band room		ef		\$0	\$0	
Wiora Combined School	1930	ES Original Bldg.		Dist.	Exterior Willdows & Doors	i levelit	i ievent	Treplace broken windows in band room		31		ΨΟ	ΨΟ	
Mora Combined School	1950	North Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken window in classroom 2		sf		\$0	\$0	
Wiora Combined School	1930	ES Original Bldg.		Dist.	Exterior Williams & Bools	i levelit	i ievent	Upgrade exterior windows. Windows are hard to		31		ΨΟ	ΨΟ	
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	Prevent	open		ef		\$0	\$0	
Micra Corribined Corricer	1000	ES Original Bldg.		Diot.	Exterior Williams & Bools	1 TO VOITE	1 TOVOITE	Орен		51		ΨΟ	ΨΟ	
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair window sill		ef		\$0	\$0	
Micra Corribined Correct	1000	ES Original Bldg.		Diot.	Exterior Williams & Bools	1 TO VOITE	i ioveni	Tropul Wildow Sill		51		ΨΟ	ΨΟ	
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair / replace window screens		ea.		\$0	\$0	
Mera Cerribinea Cerreer	1000	ES Original Bldg.		Blot.	Exterior Francisco de Boord	1100011	1107011	Repaint exterior windows' frames: paint is peeling off		ou.		Ψ	Ψ.	
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	of the frames		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair damaged window sill in classroom 107		sf		\$0		
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair window screen in classroom 106		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.			Exterior Windows & Doors	PreVent	PreVent	Reseal all wood window sills		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair all exterior window frames and stucco		ea.		\$0	\$0	
								Assess window settlement; windows are hard to				* -	, -	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	open		ea.		\$0	\$0	
		ES MS Org. Gym /										* -	, -	
Mora Combined School	1950	Band, K-8		Dist.	Floor Finishes	PreVent	PreVent	Replace cracked VCT in boys showers		sf		\$0	\$0	
		ES MS Org. Gym /										·		
Mora Combined School	1950	Band, K-8		Dist.	Floor Finishes	PreVent	PreVent	Replace carpet in band room		sf		\$0	\$0	
		ES MS Org. Gym /										·		
Mora Combined School	1950	Band, K-8		Dist.	Floor Finishes	PreVent	PreVent	Replace cracked VCT in girls restroom		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	Repair carpet in corridor outside computer labs		sf		\$0	\$0	
								Replace / repair cracked VCT and buckled VCT in						
Mora Combined School	1997	MS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	corridors and at north entrance		sf		\$0	\$0	
								Replace / repair cracked VCT at the entrance of						
Mora Combined School	1997	MS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	classroom 112		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	Install vinyl base at west entry		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Foundation / Slab / Structure	PreVent	PreVent	Assess change in floor slope in classroom 108		sf		\$0	\$0	
		ES Library Phase 3						Upgrade HVAC System; there is no heating in this				-		
Mora Combined School	2001	Const		Dist.	HVAC	PreVent	Prevent	area		sf		\$0	\$0	
		ES Library Phase 3					1							
Mora Combined School	2001	Const		Dist.	Institutional Equipment	PreVent	Prevent	Repair plastic laminate at library counter		ea.		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	South Wing		Dist.	Institutional Equipment	PreVent	Prevent	Repair plastic laminate at all classrooms		ea.		\$0	\$0	
		HS Commons												
Mora Combined School	2004	Addition		Dist.	Institutional Equipment	PreVent	Prevent	Replace booths in commons area	5	ea.		\$0	\$0	
		HS Commons												
Mora Combined School	2004	Addition		Dist.	Institutional Equipment	PreVent	Prevent	Replace table arms on auditorium seating	12	ea.		\$0		
Mora Combined School	1968	HS Main Bldg.	107 & 108	Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in classrooms		lf		\$0		
Mora Combined School	1968	HS Main Bldg.		Dist.	Institutional Equipment	PreVent	PreVent	Repair tables in science labs		ea.		\$0	\$0	
						_		Repair plastic laminate in computer lab and						
Mora Combined School	1968	HS Main Bldg.	112, 114, 115,	Dist.	Institutional Equipment	PreVent	Prevent	classrooms		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in classroom 109		ea.		\$0	\$0	

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	PreVent	Prevent	Replace casework in classroom 102		ea.		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Interior Doors	PreVent	PreVent	Repair door in classroom 115: door does not close		ea.		\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band. K-8		Dist.	Interior Walls	PreVent	PreVent	Repair water damage in storage room		sf		\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12			Plumbing	PreVent	Prevent	Repair sink at kitchen		ea.		\$0		
Mora Combined School	1965	Cafeteria, K-12			Wall Finishes	PreVent	PreVent	Repaint exterior walls: paint is peeling off brick		sf		\$0		
Mora Combined School	1965	Cafeteria, K-12		Dist.	Wall Finishes	PreVent	PreVent	Repair wall at kitchen		sf		\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Wall Finishes	PreVent	PreVent	Repair wall due to water damage in dinning room		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair wall hole at north entrance		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.	105, 111, 106, 108, 109, 110	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in classrooms and computer lab		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.	130 & 128	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in councilor and principal offices		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.			Wall Finishes	PreVent	PreVent	Repair wall and ceiling cracks in councilor office and restroom		sf		\$0		
Mora Combined School	1997	MS Main Bldg.	108, 102, 110		Wall Finishes		PreVent	Repair window sill in classrooms		sf		\$0		
Mora Combined School	1997	MS Main Bldg.			Wall Finishes		PreVent	Repair ceiling crack in mechanical room		sf		\$0		
Mora Combined School	1991	Addition		FAD	Technology	Tech	Tech	No system \$1,350: not needed	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	1975	Aud / Band, K-8		FAD	Technology		Tech	Upgraded 1999 \$2,744: Upgraded 2018		ea.	\$0.00	\$0		
Mora Combined School	1965	Cafeteria, K-12		FAD	Technology	Tech	Tech	Upgraded 2000 \$1,019: Upgraded 2018	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	2003	Commons Addition		FAD	Technology	Tech	Tech	New electronic white boards in classrooms \$2,557. Upgraded 2018	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	1991	Industrial Arts High		FAD	Technology	Tech	Tech	Updated 2000 \$1,140: District updated 2018	С	ea.	\$0.00	\$0	\$0	
Mora Combined School	1968	Main Bldg High		FAD	Technology	Tech	Tech	Replaced 2000. New electronic white boards in classrooms (2013). Estimated time frame 2005 \$4,397: Updated 2018	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	1950	Main Bldg Middle		FAD	Technology	Tech	Tech	Updated 2000 \$3,298: District updated 2018		ea.	\$0.00	\$0	\$0	
Mora Combined School	1978	Original Const (gym)		FAD	Technology	Tech	Tech	No system needed \$8,504: Updated 2018	C	ea.	\$0.00	\$0	\$0	
Priority 1 Life-Health-Safe	ty-Security / Ma	intenance / Technol	logy:									\$1,020,735	\$1,020,735	\$1,020,735

District Wide	1950	Campus Wide	Dist.	Communications / Security	LHSS	L-GOB	Update intercom district wide	178,790	sf	\$2.00	\$357,580	\$464,854	
District Wide	1950	Campus Wide	Dist.	Parking Lot	LHSS	L-GOB	Upgrade parking lots	-	ea.	\$750,000.00	\$750,000	\$975,000	
Bistrict Wide	1000	Campus vvide	Diot.	r unting Eot	LITOU	L 00B	Rework drain pipes from ES MS Gym to have one lift	<u>'</u>	cu.	ψ100,000.00	ψ100,000	ψον ο,σσσ	
		ES MS Org. Gym /					station and repair/replace one lift station pump: it is						
District Wide	1950	Band. K-8	Dist.	Z-Site Utilities	LHSS	L-GOB	not working	1	ea.	\$55,000.00	\$55,000	\$71,500	\$1,511,354
Holman ES	1987	HES Addition	FAD	Drain, Waste and Vent	FacRen	BS-SB9			FAD	\$24,395.00	\$24,395	\$31,714	, ,- ,
Holman ES	1987	HES Addition	FAD	Water Distribution	FacRen	BS-GOB		1	FAD	\$24,395.00	\$24,395	\$31,714	\$63,427
Mora Combined School	1995	Admin/Kinder SPED and Nurs	ing Dist.	HVAC	AdqStd	BS-GOB	Upgrade HVAC system: Install heating in nursing and SPED	1,750	sf	\$25.00	\$43,750	\$56,875	
Mora Combined School	1965	Cafeteria, K-12	FAD	HVAC	AdqStd	BS-GOB	\$88,351 Propane rooftop units. Evap cooling	5,600	sf	\$25.00	\$140,000	\$182,000	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8	FAD	HVAC	AdqStd	BS-GOB	Propane rooftop units repl 1984 \$237,966: Upgrade HVAC units: one old unit; newer unit is not working	15,748	sf	\$15.00	\$236,220	\$307,086	
Mora Combined School	1950	ES Original Bldg. North Wing	Dist.	HVAC	AdgStd	BS-GOB	Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the north wing and classrooms are too hot	10,988	sf	\$25.00	\$274,700	\$357,110	
Mora Combined School	1950	ES Original Bldg. South Wing	Dist.	HVAC	AdqStd	BS-GOB	Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the south wing and classrooms are too hot	12,399	sf	\$25.00	\$309,975	\$402,968	
Mora Combined School	1968	HS Main Bldg.	FAD	HVAC	AdqStd	BS-GOB	Original propane rooftop units. No cooling but desired \$381,382: Updated 2003	23,264	sf	\$25.00	\$581,600	\$756,080	
Mora Combined School	1974	HS Original Const (gym)	FAD	HVAC	AdqStd	BS-GOB	Original propane boiler. No cooling but desired \$307,332	16,068	sf	\$25.00	\$401,700	\$522,210	

Sec. 3.1.15

GS Architecture • 2019

								1						
FACILITY NAME	,			Late and Control Design		0.475.0000	Funding	FACILITY NEEDO			0007///		TOTAL PROJECT COST	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	0.00.	CATEGORY	Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	WACC		SUBTOTALS
Mora Combined School	1995	Admin/Kinder		FAD	HVAC Controls	AdqStd	BS-GOB	Beyond Expected Life: Need to upgrade	1	FAD	\$22,378.00	\$22,378	\$29,091	
Mara Cambinad Cabaal	1950	ES MS Org. Gym /			HVAC Controls	A da Ctd	DC COD	Original Describle replaced and ungraded in 1001	4		#22 240 00	#22.040	¢42.402	
Mora Combined School		Band, K-8 HS Gym Addition		FAD FAD	HVAC Controls HVAC Controls	AdqStd	BS-GOB	Original: Possible replaced and upgraded in 1984		FAD FAD	\$33,218.00	\$33,218	\$43,183 \$8,854	
Mora Combined School Mora Combined School	1991	,		FAD		AdqStd	BS-GOB BS-GOB	Original		FAD	\$6,811.00	\$6,811		
Mora Combined School	1991 1968	HS Industrial Arts HS Main Bldg.		FAD	HVAC Controls HVAC Controls	AdqStd	BS-GOB	Original Original \$127,771: Updated 2003			\$13,809.00 \$5.00	\$13,809		
Mora Combined School	1900	HS Original Const		FAD	HVAC CONTOIS	AdqStd	BS-GOB	Original \$127,77 1: Opdated 2003	23,264	SI	\$5.00	\$116,320	\$131,210	
Mora Combined School	1974	(gym)		FAD	HVAC Controls	AdqStd	BS-GOB	Original	1	FAD	\$102,962.00	\$102,962	\$133,851	
Mora Combined School	1974	MS Main Bldg.		FAD	HVAC Controls	AdqStd	BS-GOB	Upgraded 1998		FAD	\$39,926.00	\$39,926		
Wora Combined School	1991	ivio ivialii biug.		FAD	TVAC COILIOIS	Auqoiu	D3-GOD	No gym equipment: Replace some kitchen		FAD	\$39,920.00	φ39,920	\$31,904	
Mora Combined School	1965	Cafeteria, K-12		FAD	Institutional Equipment	AdqStd	BS-GOB	equipment	1	FAD	\$13,405.00	\$13,405	\$17,427	
Mora Combined School	1968	HS Main Bldg.		FAD	Institutional Equipment	AdqStd	BS-GOB	No gym equipment: Updated 2003		FAD	\$57,864.00	\$57,864		
IVIOIA COMBINED SCHOOL	1900	110 Mail Didg.		ו אט	mstitutional Equipment	Augotu	D3-G0D	110 gym equipment. Opdated 2005		ו אט	ψ51,004.00	Ψ37,004	Ψ10,220	
		HS Original Const						Scoreboards/backboards original \$46,629. Half						
Mora Combined School	1974	(gym)		FAD	Institutional Equipment	AdgStd	BS-GOB	bleachers updated 2017; need to replace other half	300	00	\$200.00	\$60,000	\$78,000	
Mora Combined School	1974	ES MS Org. Gym /		FAD	Institutional Equipment	Auqoiu	D3-GOD	Last replaced 1984. Possible replaced in addition in	300	ca.	φ200.00	\$00,000	\$70,000	
Mora Combined School	1950	Band, K-8		FAD	Ceiling Finishes	FacRen	BS-GOB	1984 \$64,759	15,748	ef	\$6.00	\$94,488	\$122,834	
MOIA COMBINED SCHOOL	1900	HS Original Const		י ער	Coming i mishes	i aci\cii	DO-GOD	1007 404, 100	13,740	31	φυ.υυ	φ94,400	φ122,034	
Mora Combined School	1974	(gym)		FAD	Ceiling Finishes	FacRen	BS-SB9	TandG ceiling	1	FAD	\$83,637.00	\$83.637	\$108,728	
Mora Combined School	1950	Admin/Kinder		Dist.	Exterior Walls	FacRen	BS-GOB	Repair stucco	3.600		\$8.00	\$28,800		
Mora Combined School	1930	Admini/Minder		DISt.	Exterior Walls	racinen	D3-GOD	Walls with minor cracks, water damage due to roof	3,000	51	φ0.00	\$20,000	φ31,440	
		ES Library Phase 3						runoff causing water to splash from concrete apron						
Mora Combined School	2001	Const		FAD	Exterior Walls	FacRen	BS-GOB	\$17,205	1,400	cf	\$8.00	\$11,200	\$14,560	
Mora Combined School		ES MS Org. Gym /		FAD	Exterior Walls	racinen	D3-GOD	φ17,203	1,400	51	φ0.00	φ11,200	\$14,500	
Mora Combined School	1950	Band, K-8		Dist.	Exterior Walls	FacRen	BS-GOB	Repair / Upgrade exterior wall finishes	10,000	cf	\$8.00	\$80,000	\$104,000	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Walls	FacRen	BS-GOB	Replace entire building stucco	10,000		\$8.00	\$81,600		
Mora Combined School		ES MS Org. Gym /		DIST.	Exterior Walls	raciten	D3-GOD	Original windows on gym and 1975 windows on	10,200	51	φ0.00	φ01,000	\$100,000	
Mora Combined School	1950	Band, K-8		FAD	Exterior Windows & Doors	FacRen	BS-GOB	addition and doors on gym \$65,283	150	cf	\$175.00	\$26,250	\$34,125	
Mora Combined School	1930	Danu, IX-0		I AD	Exterior Willdows & Doors	I aciteii	D3-G0D	Exterior damage to window sills and drywall, exterior	130	31	ψ173.00	Ψ20,230	ψ54,125	
								doors hard to open and close \$175,766. Reseal all						
Mora Combined School	1997	MS Main Bldg.		FAD	Exterior Windows & Doors	FacRen	BS-GOB	wood window sills;	450	sf	\$175.00	\$78,750	\$102,375	
Word Combined Concor	1001	Wo Wall Blag.	106, 105, 102, 107	1710	Extensi Windows & Books	Tuorton	BC CCB	\$42,497Upgrade carpet in offices and conference	400	51	ψ170.00	φτο,του	ψ102,010	
Mora Combined School	1995	Admin/Kinder	& 109	FAD	Floor Finishes	FacRen	BS-SB9	room	1,500	sf	\$6.00	\$9,000	\$11,700	
Word Combined Concor	1000	/ tarriiri/r tirraci	u 100	1710	Tiedi Tilliones	1 dorton	BC 6B5	Wear and cracking in several areas of the main	1,000	51	ψ0.00	ψ0,000	ψ11,700	
Mora Combined School	1965	Cafeteria, K-12		FAD	Floor Finishes	FacRen	BS-SB9	cafeteria floor \$23,421	2,100	ef	\$6.00	\$12,600	\$16,380	
Mera Cerribilied Cerreer		ES Library Phase 3		17.13	. 1961 1 111161195	i dorton	20 020	541515114 11551 425, 121	2,100	O.	ψ0.00	ψ12,000	\$10,000	
Mora Combined School	2001	Const		FAD	Floor Finishes	FacRen	BS-SB9	Completed Dec 2001 \$14,875	2,200	sf	\$6.00	\$13,200	\$17,160	
		ES MS Org. Gym /		. ,	. 1001 1 111101100		20 020		2,200		ψ0.00	ψ.0,200	\$11,100	
Mora Combined School	1950	Band, K-8		FAD	Floor Finishes	FacRen	BS-GOB	\$63.083	15,000	sf	\$6.00	\$90,000	\$117,000	
		Dania, it o		. ,	. 1661 1 111161166		20 002	\$45,315; Include upgrade carpet in classroom 2 and		0.	ψ0.00	Ψ00,000	\$111,000	
		ES Original Bldg.						replace vinyl base in girls and boys restrooms and						1
Mora Combined School	1950	North Wing		FAD	Floor Finishes	FacRen	BS-GOB	throughout wing.	900	sf	\$15.00	\$13,500	\$17,550	ĺ
		g						\$51,838: Upgrade carpet at all classrooms and			Ţ.1.3 0	Ţ,. .	ţ,300	
							[replace / repair cracked VCT in classroom 18 and in						
		ES Original Bldg.					[corridor and Repair / replace vinyl base in building:						
Mora Combined School	1950	South Wing		FAD	Floor Finishes	FacRen	BS-SB9	base is coming off	7,500	sf	\$6.00	\$45,000	\$58,500	
						1	1	, v	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		Ţ1.3 0	Ţ : z , z o o	, , , , , , , , , , , , , , , , , , , 	
Mora Combined School	1991	HS Industrial Arts		FAD	Floor Finishes	FacRen	BS-GOB	Original. Heavy wear on VCT in classrooms (2013)	1	FAD	\$26,223.00	\$26,223	\$34,090	1
	-			1				Gym flooring replaced 2000 \$81,471: Beyond			, , ,	, , , ==	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
		HS Original Const					[Expected Life: Gym floor is over water table; replace						
Mora Combined School	1974	(gym)		FAD	Floor Finishes	FacRen	BS-GOB	wood floor	9,500	sf	\$30.00	\$285,000	\$370,500	
Mora Combined School	1997	MS Main Bldg.		FAD	Floor Finishes	FacRen	BS-GOB	Replaced 1998 \$75,822	15,000	sf	\$6.00	\$90,000		
		ES MS Org. Gym /		1			1					, , ,		
Mora Combined School	1950	Band, K-8		FAD	Institutional Equipment	FacRen	BS-GOB	Upgraded 1984	1	FAD	\$36,104.00	\$36,104	\$46,935	1
		ES MS Org. Gym /		1	· ·		1	1					,	
Mora Combined School	1950	Band, K-8		FAD	Interior Doors	FacRen	BS-GOB	\$95,596	22	FAD	\$3,000.00	\$66,000	\$85,800	
		ES MS Org. Gym /					1	,,,,,,				, , , , , , , , , , , , , , , , , , , ,		
Mora Combined School	1950	Band, K-8		Dist.	Lighting / Branch Circuits	FacRen	BS-GOB	Replace lights at gym	7,212	sf	\$7.00	\$50,484	\$65,629	1
-	1965	Cafeteria, K-12		FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998		FAD	\$1,560.00	\$1,560		

													TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
TAGILIT NAME		ES MS Org. Gym /	KOOM	lucilinica by	SISILIN	GAILGORI	Cource	TAGILITI NEEDO	QII	ONT	0001/01111	WACC		SOBIOTALS
Mora Combined School	1950	Band, K-8		FAD	Other Electrical Systems	FacRen	BS-SB9	Updated 1984	1	FAD	\$4,201.00	\$4,201	\$5,461	
		, -			,		-				, ,	, , -	, , ,	
Mora Combined School	1991	HS Gym Addition		FAD	Other Electrical Systems	FacRen	BS-SB9	Original	1	FAD	\$861.00	\$861	\$1,119	
Mora Combined School	1991	HS Industrial Arts			Other Electrical Systems		BS-SB9	Original	1	FAD	\$1,746.00	\$1,746	\$2,270	
Mora Combined School	1968	HS Main Bldg.			Other Electrical Systems		BS-SB9	Last upgraded 1991	1	FAD	\$6,733.00	\$6,733	\$8,753	
		HS Original Const			j						Ì	, ,		
Mora Combined School	1974	(gym)		FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1991 w/addition	1	FAD	\$13,022.00	\$13,022	\$16,929	
Mora Combined School	1997	MS Main Bldg.		FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998	1	FAD	\$5,049.00	\$5,049	\$6,564	
								\$53,159 Upgrade bathrooms for ADA. Replace						
Mora Combined School	1965	Cafeteria, K-12		FAD	Plumbing	FacRen	BS-GOB	double oven	250	sf	\$300.00	\$75,000	\$97,500	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Plumbing	FacRen	BS-GOB	Upgraded 1984 \$143,180	800	sf	\$150.00	\$120,000	\$156,000	
	4050	ES Original Bldg.		D: 4	D		DO 00D	Renovate sinks to ADA compliant in girls and boys			# 500.00	*40.000	* 40.000	
Mora Combined School	1950	North Wing HS Industrial Arts		Dist.	Plumbing		BS-GOB	restrooms R/R non operational in need of repair \$85,707		ea.	\$500.00	\$10,000	\$13,000	
Mora Combined School Mora Combined School	1991				Plumbing		BS-GOB		225		\$300.00	\$67,500	\$87,750	
Mora Combined School	1968 1995	HS Main Bldg. Admin/Kinder		FAD FAD	Plumbing Roof		BS-GOB BS-GOB	Original \$229,471 \$87,868: Need to coat metal roof	900 8,236		\$300.00 \$10.00	\$270,000 \$82,360	\$351,000 \$107,068	
Mora Combined School	1995	Admin/Amdei		FAD	Rooi	rachen	D3-GOD	Metal roof replacement 1998 \$48,427: In good	0,230	51	φ10.00	φ02,300	φ107,000	
Mora Combined School	1965	Cafeteria, K-12		FAD	Roof	FacRen	BS-GOB	condition	0	sf	\$0.00	\$0	\$0	
Word Combined Corloci	1000	Garotoria, TC 12		17.0	11001	raditori	DO GOD	Metal roof with several roof leaks into the building		OI .	ψ0.00	ΨΟ	ΨΟ	
								causing damage to ceiling tiles \$501,675: Coat metal						
Mora Combined School	1997	MS Main Bldg.		FAD	Roof	FacRen	BS-GOB	roof.	18,587	sf	\$10.00	\$185,870	\$241,631	
Mora Combined School	1995	Admin/Kinder			Wall Finishes		BS-SB9	Painted 2000: District painted 2007	1	FAD	\$23,937.00	\$23,937	\$31,118	
Mora Combined School	1965	Cafeteria, K-12			Wall Finishes		BS-SB9	Painted 2000 \$13,193	3,500	sf	\$3.50	\$12,250	\$15,925	
		ES Library Phase 3												
Mora Combined School	2001	Const		FAD	Wall Finishes	FacRen	BS-SB9	Completed Dec 2001 \$8,379	3,000	sf	\$3.50	\$10,500	\$13,650	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$35,533.00	\$35,533	\$46,193	
		ES Original Bldg.						Painted 1999; DNS clean and painted 2013 \$25,525;						
Mora Combined School	1950	North Wing		FAD	Wall Finishes	FacRen	BS-SB9	Update wall finish in boys restroom	3,600	sf	\$3.50	\$12,600	\$16,380	
		ES Original Bldg.			l <u>-</u>					_			***	
Mora Combined School	1950	South Wing		FAD	Wall Finishes	FacRen	BS-SB9	\$29,199	6,000	sf	\$3.50	\$21,000	\$27,300	
Manage Constituted Calculation	0004	HS Commons		EAD	NAZ - II. ES-S-S-S-S-S-S-S-S-S-S-S-S-S-S-S-S-S-S-	F D	DO 000	0040 01 0		E 4 D	000 440 00	000 440	040.047	
Mora Combined School Mora Combined School	2004 1991	Addition HS Gym Addition			Wall Finishes Wall Finishes		BS-SB9 BS-SB9	2013: Clean & painted \$7,285	6,000	FAD	\$33,113.00 \$3.50	\$33,113 \$21,000	\$43,047 \$27,300	
Mora Combined School	1991	HS Industrial Arts			Wall Finishes		BS-SB9	Painted 2000. Clean and painted (2013)	0,000	FAD	\$14,771.00	\$14,771	\$19,202	
Mora Combined School	1968	HS Main Bldg.			Wall Finishes		BS-SB9	Painted 2000. Clean and painted (2013)	1	FAD	\$56,948.00	\$56,948	\$74,032	
Mora Combined School	1900	HS Original Const		I AD	Wall I Illistics	aciteii	DO-0D9	l anteu 2000	<u>'</u>	ו אט	ψ30,940.00	Ψ30,940	Ψ14,032	
Mora Combined School	1974	(gym)		FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$45,891.00	\$45,891	\$59,658	
Mora Combined School	1997	MS Main Bldg.			Wall Finishes			Painted 2000		FAD	\$42,709.00	\$42,709		\$6,305,816
Priority 2 Building / Site S				<u> </u>		<u></u>			-		+	\$6,061,998		\$7,880,597
,	, , , , , , , , , , , , , , , , , , , ,											, ,	, ,,	. , ,
Priority 3 Capital Projects	:													
District Support	1950	HS			Athletic Fields		BS-GOB	Redo track surface	1	ea.	\$150,000.00	\$150,000	\$195,000	
District Support	1950	HS	-	Dist.	Athletic Fields	AdqStd	BS-GOB	Install sprinkler system in football field	1	ea.	\$85,000.00	\$85,000	\$110,500	
								Create Softball Field: District has a shared Baseball-						
District Support	1950	HS			Athletic Fields		MP-GOB	Softball field only. Install site lighting at both fields.		ea.	\$350,000.00	\$350,000	\$455,000	
District Support	1950	HS			Athletic Fields			Athletic concessions & restrooms	1,200		\$350.00	\$420,000		
District Support	1950	HS			Site Lighting		MP-GOB	Light Baseball Field		ea.	\$75,000.00	\$300,000	\$390,000	***
District Support	1950	HS			Site Lighting		MP-GOB	Light Softball Field		ea.	\$75,000.00	\$300,000		\$2,086,500
Mora Combined School	1950 1974	Martinez Gym			Renovation		MP-GOB	Renovate Gym Locker/restrooms and Band	3,025		\$200.00 \$250.00	\$605,000	\$786,500 \$812,500	
Mora Combined School Mora Combined School	1974	HS Gym Swimming Pool			Renovation		MP-GOB MP-GOB	Renovate Restrooms and Lobby Repurpose Swimming Pool	2,500 10,547		\$250.00 \$150.00	\$625,000 \$1,582,050		\$3,655,665
		Swirining Pool		ואוטן.	Repurpose	Muyolu	IVIF-GUB	Incharbase ominimility Lool	10,547	21	\$15U.UU	\$1,582,050 \$4,417,050		
Priority 3 Capital Projects		Total Manda						TOTAL						\$5,742,165
Mora Independent Sc	nooi District	rotal Needs:						TOTAL:				\$11,499,783	\$14,643,497	

Estimate of Probable Costs

NEEDS BY FACILITY

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Option 3A														
School Reconfiguration	1950	ES: ES/MS Gym: Café: Admin: Maint		Dist.	Demolish	LocPol		Demolish: ES; Admin; ES/MS Gym; Kitchen- Cafeteria; Maintenance	63,425	5 sf	\$25.00	\$1,585,625	\$2,061,313	
•		ES: ES/MS Gym:						Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing, Cafeteria & Kitchen: Relocate MS into HS & ES into						
School Reconfiguration	1950	Café: Admin: Maint		Dist.	Replace	LocPol	MP-GOB	MS.	24,000) sf	\$300.00	\$7,200,000	\$9,360,000	\$11,421,313
Option 3B														
		ES/MS Gym; Kitchen-Cafeteria;						Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing,						
District Support	1950	Maint		Dist.	Demolish	LocPol	MP-GOB	Cafeteria & Kitchen	28,218	3 sf	\$25.00	\$705,450	\$917,085	<u> </u>
		ES/MS Gym; Kitchen-Cafeteria;						Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing,						
District Support	1950	Maint		Dist.	Replace	LocPol	MP-GOB	Cafeteria & Kitchen	17,500) sf	\$300.00	\$5,250,000	\$6,825,000	\$7,742,08

3.2.1 DEVELOPMENT OF FMP AND PRIORITIZATION PROCESS

Development of FMP Process

Development of the facilities master plan (FMP) process for the Mora Independent School District (MISD) started with a strategic planning meeting. The strategic planning meeting participants were selected by the MISD Superintendent and became participants of the FMP core committee. During this meeting the following items were discussed:

FMP goals and objectives

Roles and responsibilities: decision making process

Participants

Identification of relevant data and methods to obtain data

Type and number of meetings

FMP Schedule

At the conclusion of the strategic planning meeting the MISD FMP process and schedule had been developed and a clear line of communication established.

Information from the strategic planning meeting and the FMP process was shared with the MISD School Board at a regular school board meeting. The MISD School



Board supported the MISD FMP core committee's process and schedule to develop the FMP. This FMP process addresses the specific needs of MISD, supports its educational program and supports:

MISD Mission Mora Independent Schools exists as a concrete foundation to prioritize every student, every day, in every way. We will provide students with the resources necessary to be successful in life. Our school culture will be one of security, respect, honesty, loyalty, accountability, investment, and positivity.

MISD Vision We the leadership of the Mora Independent Schools are committed to a vision in which the roots and values of our broader community shape our school culture and create an environment that is the best place to be, learn, work, grow and enjoy life!

The developed process identified a decision making process for the FMP that consisted of two committees, the FMP core committee and the FMP advisory committee, and the school board. The FMP core committee was entrusted to review and edit all data for accuracy and generate agendas and schedules for upcoming meetings with the FMP advisory committee and the MISD School Board. The FMP advisory committee was entrusted to review data, discuss facility needs and issues, contribute input on facility needs and issues, prioritize the district's needs, and develop a capital

3.2

Prioritization Process and Budgeting

plan which identifies how and when the district will address the priorities. The final approval and adoption of the FMP is the responsibility of the MISD School Board.

The FMP process consisted of two committees:

The FMP Core Committee: Comprised of district administration charged with reviewing data and establishing agendas and schedules for FMP meetings.

The FMP Advisory Committee: Comprised of district administration, staff, principals, teachers and community members.

The FMP process consisted of the following FMP committee meetings:

3 School Board meetings One review of FMP process, schedule, and participants
One review of the District priorities and capital plan
Adoption of the final FMP document

7 FMP Core committee meetings

One Strategic Plan meeting

Six Data review and development of Agenda meetings:

Two of the six meetings were dedicated to review and editing FAD / FMAR Data

3 Advisory committee meetings

One background review meeting
One discussion of district facility needs meeting
One development of recommendations of district priorities and
the capital plan meeting

Mora Independent School District FMP Advisory Committee and Community Input

Mora Independent School District (MISD) understands the importance of having the support of its local community. The district continuously seeks input from the local community and is aware of their concerns related to the future of the district. To assure meaningful community input, MISD developed a FMP advisory committee to be a liaison between the district and the local community for capital projects. The FMP advisory committee members represent the local community and the school district. They were selected by the superintendent and district administration and they are part of the decision making process of the district. The members review data, bring community perspective to the discussions and develop recommendations related to district facility needs for the school board's consideration.

Process and Criteria for Prioritizing District Needs

The prioritization of MISD needs took place over the span of several meetings: three FMP advisory


committee meetings; two meetings with district administration and maintenance staff to review the FAD / FMAR report; and two school board/community meetings to review the FMP process and final recommendations.

The FMP process was based on providing relevant data and engaging in meaningful discussion at each meeting which resulted in knowledgeable, informed decisions by the stakeholders. During the FMP process, the MISD FMP advisory committee, community, and school board were given background information on the district and all identified school and district facility needs.

During the FMP process, the FMP Advisory committee reviewed and discussed the following data:



- Partnerships: District Community State (PSCOC/PSFA)
- District Demographics
- Facilities Assessment Database (FAD)
- Facilities Maintenance Assessment Report (FMAR)
- Enrollment History and Projections
- Existing District and Individual School Size in relation to:
 - Educational Program
 - PSCOC/PSFA Recommended Square Footage per Student
 - State of New Mexico Benchmarks and Measures
 - Adequacy Standards
 - District Policies
- Capacity and Utilization of Schools
- Age and Condition of Schools
- Life Span of Building Systems
- · Preventive Maintenance
- Maintenance Cost per Square Foot per Year
- Size Right School Planning
- Facility Needs at each District Building
- Benefits of a Smaller Footprint
- Efficient and Effective Schools
- Community and School Profiles
- Capital Funding Sources
- 2013 FMP Priorities and Completed Projects



The major concerns of MISD and the FMP Steering committee are:

Life-Health- Safety-Security	Technology	Preventive Maintenance	Student Enrollment		
School Growth	Condition of Facilities	Efficient/Effective Facilities	Equity of Facilities District Wide		
Teacher Retention / Availability	Sustainable Facilities	Availability of Funding	Security		

District Needs Prioritization Criteria

The FMP advisory committee reviewed all district facility needs, capital project funding sources and capabilities for the next five years and beyond. During the prioritization process, the committee discussed the importance of partnerships with PSCOC/PSFA and the local community. Partnership with PSCOC/PSFA is dependent upon aligning future projects with the Facilities Assessment Database (FAD) by identifying facilities that need to be replaced, renovated, have facility and site systems that are past their useful life which could impact student performance and by having access to the local match. Partnership with the local community is dependent on the community understanding and supporting MISD capital project needs and being included in the decision making process. The district is working on restoring its relationship with the local community.

After review and discussion of the data and district issues, the FMP advisory committee developed recommendations and prioritized the district's facility needs. The criteria used by the FMP advisory committee and the district to prioritize capital needs were:

Does it affect Life-Health-Safety-Security? Security was a major area of discussion.

Does it align with the FAD Ranking and support future PSCOC/PSFA partnership?

Does it impact the district's mission and core values?

Does it support proactive instead of reactive maintenance?

Does it support the district's educational program?


Does it promote student success?

Does it align community needs and expectations?

Does it align with New Mexico facility benchmarks, measures & statewide adequacy standards?

Does it align with district policies?

The following chart provides a schematic diagram of the process and the categories that the FMP advisory committee utilized in the prioritization of the identified needs of the district.



Mora Independent School District • 5-Year Facilities Master Plan GS Architecture • 2019

Sec. 3.2.5

This page intentionally left blank

Facilities Master Plan Prioritization Schedule

June 6, 2018: Strategic Planning Meeting

A strategic planning meeting was held June 6, 2018 with district staff to develop the Facilities Master Plan (FMP) process and schedule.

The meeting agenda included:

- FMP PROCESS
- Data:

PSFA FMP Checklist District Background Information Capital Project Funding

• Discussion:

Facility Goals & Objectives
Facility Issues, Concerns & Needs

Decisions:

FMP Decision Making Process FMP Advisory Committee Recommendations School Board Review and Approval

- FMP Schedule
- FMP Committee Members

Meeting Summary: The FMP process and decision making process was established. The FMP schedule was established and there was discussion of district facility goals and objectives for the FMP. Facility issues, concerns and needs were discussed. The relationship between MISD and its local community was discussed. There is an overall lack of trust in the community toward MISD which the district has to overcome prior to being able to pass a much needed GOB. The identified priorities from the last FMP were reviewed and incorporated into the FMP process. Financial considerations and funding sources for the next five years were discussed. FMP tasks were identified and given to district personnel.

June 19, 2018: School Board Meeting

The school board members reviewed the FMP information and provided input on the FMP process, schedule, and committees at their regular meeting.

The meeting agenda included:

- FMP PROCESS
- Data:

PSFA FMP Checklist
District Background Information
Capital Project Funding

Discussion:

Facility Goals & Objectives

Facility Issues, Concerns & Needs

Decisions:

FMP Decision Making Process FMP Advisory Committee Recommendations School Board Review and Approval

- FMP Schedule
- FMP Committee Members

Meeting Summary: The MISD School Board approved of the FMP process and schedule developed by the FMP core committee. Discussion centered on the district needs, issues and concerns. Safety and security was a topic of concern, as was the future of district facilities and the relationship with the local community.

June 26, 2018: 1st FMP Advisory Committee Meeting

The appointed FMP advisory committee met to review information and provide input.

The meeting agenda included:

- Introductions
- FMP PROCESS
- · Data:

PSFA Checklist

District Background Information

Capital Project Funding

Discussion:

Facility Goals & Objectives

Facility Issues, Concerns & Needs

· Decisions:

FMP Decision Making Process

FMP Advisory Committee Recommendations

School Board Review and Approval

- FMP Schedule
- FMP Committee Members

The Committee was presented with several questions for their feedback.

1. What are the positive features of district facilities?

Low Pupil to Teacher Ratio

Focus on technology infrastructure

Vocational program

2. What are the educational challenges faced by MISD schools?

Availability of funding

Technology integration into classrooms

Virtual classrooms

Doing more with less

3.2

Prioritization Process and Budgeting

Limited equipment

Use of existing space

3. What will MISD look like in 5, 10, 15, 50 years?

Better use of existing space

Multiple use facility for 21st century learning, band, cafeteria, and kitchen Increased importance of flexible furniture

4. What is the long range vision of the district in terms of educational program delivery trends?

_

5. In the next five plus years, what are some building systems and features of district facilities that need to change or improve?

Heating and Air Conditioning upgrades

Roof upgrades

Exterior stucco upgrades

6. How do extracurricular activities fit into the FMP?

There are more six different extracurricular activities districtwide with over 180 students participating

State has introduced NM State Gaming

Meeting Summary: The FMP process and schedule were reviewed. District background and relevant information were the main topics of the meeting. The above questions were asked of the FMP advisory committee and they provided input. The facility needs of each school were identified and discussed with input from all committee members. Existing square footage at each district school was reviewed and compared to PSCOC/PSFA recommended square footages. The importance of right sizing district facilities to assure available funds were not being spent to maintain underutilized facilities was discussed. The list of projects identified in the previous FMP was discussed.

August 7, 2018: 2nd FMP Advisory Committee Meeting

The agenda for the second FMP advisory committee meeting was as follows:

- Introductions
- Brief Review of FMP Process
- Brief review of Data:

District Background Information

Capital Project Funding

Facility Goals & Objectives

• Discussion:

Facility Issues, Concerns & Needs Issues for Community Input

Meeting Summary: Enrollment history and projections were discussed as well as utilization of each school. The district student enrollment has been steadily declining for the past several years and projections indicate that this trend will continue. The economic conditions for the local area are

very depressed which has affected the student enrollment. There is no indication as to when there could be an up-turn in the economy. Utilization and capacity analysis of each school was presented to the committee for analysis, consideration and discussion.

The facility needs of each district school was identified and discussed in depth. Holman ES is in good condition and requires preventive maintenance and regular system renewal. The district completed many of the identified needs and projects at the school during the FMP process.

Mora Combined School, which includes Mora ES, Lazaro Garcia MS and Mora HS has been identified by the district and PSCOC/PSFA as the most in need school in the district. The school has many of its building and site systems past their useful life and in need of replacement and/or renewal. The main concern for Mora Combined School is campus and building security.

Mora ES was renovated in 2001 but there are building systems that are close to the end of their useful life or are starting to fail and need to be updated or replaced as soon as possible. Mora ES is the only school at Mora Campus that has been renovated.

Lazaro Garcia MS was built in 1997. The school is in fair condition and requires preventive maintenance; however, it has reached an age where some of its building systems are reaching the end of their useful life and are in need of replacement or renewal such as the wall finishes, floor finishes, and the metal roof at the main building. The ES/MS Gym and band requires HVAC, windows, lighting and walkway upgrades.

Mora High School is a combination of a 1968 and a 2004 building. The school requires preventive maintenance and has some of its building and site systems that are past their useful life and in need of replacement or renewal. The HVAC, floors, and doors are at the end of their life cycle and have been identified to be upgrade at the HS Gym, while the floors have been identified to be updated at the industrial building.

September 11, 2018: 3rd FMP Advisory Committee Meeting

The third FMP advisory committee agenda included:

- Introductions
- Brief Review of FMP Process
- Brief Review of Data:

District Priorities, Capital Plan Recommendations Capital Funding Project

· Discussion:

Capital Recommendations Facility Issues, Concerns & Needs Input on District Needs

Decisions:

Prioritize District Needs

Meeting Summary: All facilities and their needs were reviewed and open for discussion again. The FMP advisory committee selected its priorities to recommend to the school board. The priorities were broken down into three major categories: recurring facility needs, facility/site system renewal, and potential capital projects. Life-Health-Safety-Security-ADA-Code, maintenance and technology fall under the recurring facility needs and was the top priority, reflecting MISD's concern for security district wide. Facility and site system renewal was the second priority. The third priority was major renovation and new construction projects and included the last FMP identified capital projects that have not been completed or are currently in progress. Two options were developed during the FMP process to reorganize the Mora campus and make it more efficient. Both options focused on the need to replace older buildings and consolidate their functions into one efficient building. The district recognized the importance of reducing square footage, but does not know how it will be able to fund a campus reorganization project.

October 16, 2019: School Board Review Meeting

The MISD School Board of Education met in a work session to review input from the FMP advisory committee meetings and discuss the FMP goals, objectives, and priorities put forth by the FMP advisory committee.

Discussed identified district priorities that:

Meet PSCOC/PSFA Requirements

Align with the Facilities Assessment Database (FAD)

Provide Efficient and Effective Use of Existing Facilities

Promote and Enlist Community Partnership

Provide Modern, Well Kept Facilities: Upgraded Facilities and Building Systems

Incorporate items from the last FMP that were not completed

MISD FMP GOALS and OBJECTIVES:

Student Preparation for Life after MISD Schools

Provide Safe and Stimulating Learning Environments

Technology: Keep Current and Upgrade

Maintenance of Existing Facilities

Improve Condition of Existing Facilities

Right Size Facilities

Facility Equity

Partnerships: Community and PSCOC/PSFA

Work within Availability of Funding

Meeting Summary: A full review of the FMP process and its results was shared with the school board in a work session where community members were invited to attend. Underutilized spaces and the two options to right-size the schools were discussed. The school board agreed with the priorities that the FMP Advisory committee recommendations. There was discussion centered on the need for partnering with the local community and PSCOC/PSFA to obtain the much needed funding for capital projects. It is anticipated that there will be limited ability to partner with PSCOC/

PSFA during the life of this FMP due to the lack of funding to provide the district's match; however, MISD will continue to work with its community for support of a future GOB election.

April 24, 2019: School Board Meeting

The final FMP document was presented to the Mora Independent School District community and school board for adoption.

A copy of the sign-in sheets and the presentation of each FMP meeting can be found in the appendix of this document.

FACILITY NEEDS BY CATEGORY

During this FMP process approximately \$14,643,665 in facility needs were identified that are related to eight assessed categories of facility needs: adequacy standards (AdqStd); educational program (EdPro); facility renewal (FacRen); growth; Life-Health-Safety-Security-Code-ADA compliance (LHSS); local policy (LocPol); preventive maintenance and maintenance (PreMaint); and technology (Tech). Due to the possible decline in student population there were no identified needs in the growth category. These identified needs require a combination of funding sources. The district anticipates access to potentially \$4,020,735 in SB-9 and anticipated 2020 GOB funds to address its 2019/2023 facility needs.

ADEQUACY STANDARDS:

\$5,553,194

The district has been actively addressing its adequacy standards issues with its SB-9 funding as available. It is anticipated that the identified FMP adequacy standard needs will require GOB funding; however, there could be some needs that can be addressed with SB-9 funds. The age and condition of existing permanent buildings along with the limited availability of capital funds has made it impossible for MISD to address all adequacy standard issues. As stated above, MISD has been partnering with the community to update its facilities and has made significant improvements to the majority of its schools; however, there are still a number of adequacy standard improvements that need to be addressed.



The majority of MISD schools meets or exceeds the overall New Mexico adequacy standards (NMAS) of the recommended square footage per student in their permanent facilities. A large portion of adequacy standard needs throughout MISD schools identified in this FMP are related to building and site systems and not the need to increase square footage.



HVAC is the primary adequacy standard issue district wide that MISD needs to address. The district has implemented a preventive maintenance plan for its HVAC systems which has resulted in extended life for the majority of its HAVC units; however, due to the number of schools and their age, replacement and renewal of HVAC equipment will remain an on-going process.



The overall square footage of MISD facilities is above state adequacy standards; however, the current Facilities Assessment Database (FAD) identifies spaces at each school that do not meet NM adequacy standards. There are programs housed in spaces that might not meet New Mexico Adequacy Standards; however, there are options within each school for reorganization that would allow the program to be housed in a space that does meet Adequacy Standards. The spaces that do not meet NM adequacy standards do meet the needs of the schools' educational programs. A review of these spaces revealed that some of the FAD information needed to be updated and some of the spaces that were identified as not meeting state adequacy standards actually meet the standards. The spaces that were identified in the FAD as not meeting current NM adequacy standards are:





Holman Elementary School:

- Insufficient Computer Lab Square Footage: Holman ES is a pre-k
 and kindergarten facility. All computer work is accomplished in the
 classroom which eliminates the need for a separate computer lab. The
 school currently meets the needs of the students and there is no plan to
 create a dedicated computer space in this FMP.
- Insufficient Parent Work Space: The district does not have active parent
 participation at the school, but there is space available to house this
 program if it is needed.



- Insufficient Number of Chemical Storage Units: The FAD identifies 2 chemical storage units to meet adequacy standards; Mora HS has one storage unit that meets the needs of the educational program.
- Insufficient Parent Work Space: The district does not have active parent
 participation at the school, but there is space available to house this
 program if it is needed.

The overall square footage of MISD facilities is above state recommended square footage per student. A close look at each of the schools reveals where there is excess square footage. Holman Elementary School exceeds the state adequacy standards by 265 percent, Mora Elementary School by 40 percent, Lazaro Garcia Middle School by 162 percent, and Mora High School exceeds the recommended square footage by 174 percent. The educational program offered at both Lazaro Garcia Middle School and Mora High School requires a relatively large number of specialized instructional spaces; however, due to the decrease in student enrollment, the occupancy of the classrooms is below PED's maximum Pupil to Teacher ratios. This reflects that MISD offers a robust educational program for the number of students at its schools. Any attempt to reduce the permanent square footage of these schools could result in a reduction of its educational program.







3.2

Prioritization Process and Budgeting

While some of the district schools do have an excess of square footage, MISD also realizes the importance of right sizing its facilities to reduce maintenance and utility costs. During this FMP process, discussion of how to further reduce existing square footage and bring the district's facilities even closer to compliance with PSFA recommended adequacy standards related to square footage occurred at each meeting. The discussions centered on the utilization of each of MISD facilities and the cost of maintenance and operations of under-utilized square footage. Two options were developed which would reorganize the Mora campus and could result in a smaller footprint and more efficient facilities. The obstacle to implementing either option is availability of funding.



EDUCATIONAL PROGRAM:

\$0

The district is constantly reviewing its educational program and making adjustments to meet the needs of its students. Currently, the district facilities meet the needs and expectations of its students; however, the lack of students has made it difficult for the district to support a robust educational program, which has resulted in a loss of programs and teachers. There are no educational program related facility needs identified in this FMP.



FACILITY RENEWAL:

\$3,178,214

The majority of the \$3,178,214 reflects upgrades to building and site systems that are past their useful life district wide. There are large scale needs that will require GOB funds, but there are some recurring and maintenance facility needs that can be funded through SB-9. The district has been systematically replacing or upgrading building and site systems at its facilities as funding allows. The building systems to be updated include:



Ceiling Finishes

Drain, Waste, and Vent

Exterior Walls

Exterior Windows and Doors

Floor Finishes

Institutional Equipment

Other Electrical Systems

Plumbing

Roof

Wall Finishes

Water Distribution



The district recognizes that facility renewal is critical in providing a safe, stimulating learning environment; however, capital funding is limited. The district requires more facility renewal than existing or anticipated funds can accommodate in the next five years. There are building and site systems at



each of the existing district schools that are past their useful life and need to be updated. The district has established its priorities to align with the FAD ranking in anticipation of partnering with PSCOC/PSFA. The district could be able to partner with PSCOC/PSFA for building system updates at Mora Combined School during the life of this FMP; however, it has to be able to obtain its match from the local community. The district would like to address the needs at the schools as soon as funding allows and will use a combination of GOB and SB-9 funds and will apply for PSCOC/PSFA funding as schools qualify.



GROWTH: \$0

Mora Independent School District has experienced decline in its enrollment since 2007. The enrollment continues to decline and it is difficult to predict how low it will go before it stabilizes. The expansion of the district's pre-K program should help stabilize the overall enrollment, but the other grades could continue to experience a slow decline. The district realizes the implications of its declining enrollment and will continue to monitor it on a regular basis. If student enrollment continues to decline, MISD will review options for its schools which will center on continuing to create more efficient and effective facilities.



Information regarding the state's "Right Size Initiative" was presented to and discussed by district representatives and the MISD FMP committees. The district was encouraged to include reduction of under-utilized square footage in their long term facilities planning. As a result, the district has identified areas and developed two options where it might be able to reduce square footage in the future. When implemented, either of these options will result in a cost savings of capital funds, maintenance, and utilities; however, the district funds are not sufficient to implement the reduction of square footage at this time. It is recommended that the district continue the discussion of reorganization, building closure, disposal or demolition of under-utilized spaces at each school. There are no funds related to growth at MISD identified in this FMP.



LIFE / HEALTH / SAFETY/SECURITY/CODE: \$1,761,354

The majority of Life-Health-Safety-Security-Code-ADA Compliance needs at MISD facilities are related to security improvements, changes in ADA requirements and the building code due to the age of the facilities, and the condition of existing parking lots. The needs that fall under changes in ADA requirements and the building code are currently grandfathered in. These items have been identified in this FMP to alert the district to the potential impact of these items to future renovation projects, but do not require immediate action or correction. As facilities are replaced or upgraded, the





district might have to address the grandfathered issues, depending on the scope of work identified for a particular facility. The majority of these issues pose no potential impact to school operations at the current time but are identified so they can be included in future projects as needed.

There are some Life-Health-Safety-Security-Code-ADA issues that the district will need to address in the next five years. These issues include upgrade intercom system districtwide, repair windows, complete perimeter fencing, upgrade parking lots, correct walkways, and correct drainage issues. The communication and security systems are major safety needs identified at MISD schools to provide a safe environment for their students. In 2018 PSCOC/PSFA accepted applications for funding security projects at schools throughout the state. Mora Independent School District applied for and received these funds for Mora Combined Campus security projects. Mora Independent School District will continue to align its security projects with PSCOC/PSFA standards and apply for funding as its schools qualify. The district would like to address these needs as soon as funding allows and will use a combination of GOB, SB-9, and PSCOC/PSFA funds.







LOCAL POLICY: \$3,380,000

The district recognizes the importance of providing an environment which is conducive to learning for students and also providing facilities that support student and community needs. Local policy needs are identified needs which do not fall into other categories and exceed adequacy standards, yet they are important to the district's mission and vision and to the community.

The district has been focusing on updating critical needs at its school facilities such as building systems and roofs; however, during this FMP process, the district identified needs that are not critical to the operation of its facilities, but are beneficial to students, community members and will enhance facility operations. These needs were identified at Martinez Gym, the High School Gym, and at district support facilities. Local policy needs will benefit the overall district and include:

- ° Martinez Gym: Renovate gym locker/restrooms and band
- ° HS Gym: Renovate restrooms and lobby
- District Support: Create softball field
- District Support: Create athletic concessions and restrooms
- District Support: Install light at baseball and softball fields

Mora Independent School District will use GOB funds to address its Local Policy needs.



PREVENTIVE MAINTENANCE:

\$520,735

The district recognizes the importance of preventive maintenance. As of December 2018, MISD had a Facilities Maintenance Assessment Report (FMAR) score of 53.42 percent which falls into the poor category. The PSCOC/PSFA has required districts to have an FMAR score of 60 percent or greater prior to awarding project funding. The district is below the 60 percent score which indicates that the district has not been able to implement its preventative maintenance plan. Mora Independent School District has taken a proactive position to improve its preventative maintenance and is seeing results. The district anticipates a substantial increase in its FMAR score by the end of the 2018-19 school year.



Identified preventative maintenance needs are critical to the upkeep of district facilities and have the potential to extend the life of the existing facilities. The district has set in place "School Dude," a system where the facility users can submit a work order identifying when various finishes such as flooring, ceiling tiles, and window coverings need to be replaced; when walls need to be painted; and when building systems are not working properly. This allows the user to have input as to the items that they feel impact their comfort and ability to use the space as intended and allows the district to track the work orders. The major preventive maintenance issues at MISD are:



Ceiling Finishes
Exterior Walls
Exterior Windows and Doors
Floor Finishes
Foundation/Slab/Structure
HVAC
Institutional Equipment
Interior Walls
Plumbing
Wall Finishes



Mora Independent School District will use SB-9 and GOB funds to address its preventive maintenance needs.



MISD Maintenance Effectiveness

The district has worked and is continuing to work with PSFA to incorporate "School Dude" into their maintenance program. The key element for MISD maintenance effectiveness is use of "School Dude" to generate work orders. The district has enabled its schools and district staff to write and submit work orders for any facility maintenance issue that they identify, but implementation of this process has been slow. The work orders are relayed



to MISD maintenance staff and copied to the principal of the school. The maintenance staff reviews the work order and identifies the scope of work required to address the work order. Once the scope of work has been identified the process of ordering materials and assigning the necessary staff takes place. District administration meets with the maintenance supervisor on a regular basis to review the status of each work order which is used to determine the effectiveness of its maintenance staff. Lack of maintenance personnel has been the biggest obstacle in the implementation and progress of the School Dude process.



The other key element in maintenance effectiveness at MISD has been the development of a preventive maintenance plan and implementing the plan. The district recognizes that preventive maintenance is far more economical than deferred maintenance. Preventive maintenance can assist in extending the life of building and site systems. The district has not been able to hold successful general obligation bond elections in recent years which has hindered the district's ability to address major maintenance items that exceed the SB-9 funds. The district relies on an effective maintenance department to address facility issues quickly with limited resources and implement preventive maintenance to extend the life of existing building systems; however, there is limited maintenance staff to provide the necessary manpower.



Anticipated Maintenance Projects that will become Capital Projects:

There is approximately \$7,880,597 of facility and site system renewal projects that have been identified during this FMP process. The district has not established a schedule to address these capital projects; however it anticipates beginning these projects as soon as funds are available. The district anticipates a GOB election in 2020 and will use these funds to address facility and site system renewal projects. A detailed list of these capital projects is identified in the estimate of probable costs needs by category/facility spreadsheet at the end of this section. It identifies capital projects at each district facility and potential funding sources. Currently MISD is anticipating being able to partner with PSCOC/PSFA to assist in funding its maintenance (facility and site system renewal) projects at Mora Combined School that are anticipated to turn into capital projects. Ability to partner with PSCOC/PSFA is contingent upon support from its local community.



These maintenance (facility and site system renewal) projects that could turn into capital projects include:



Holman Elementary School: Drain, Waste, and Vent



3.2

Prioritization Process and Budgeting

Mora Combined School:

Ceiling Finishes

Exterior Walls

Exterior Windows and Doors

Floor Finishes

HVAC

HVAC Controls

Institutional Equipment

Interior Doors

Lighting/Branch Circuits

Plumbing

Roof

Wall Finishes

Districtwide:

Communications/Security

Parking Lots

Site Utilities



The \$250,000 identified to address technology issues is from SB-9 funds and could be supplemented by E-rate. Mora Independent School District has access to E-rate funding and the PSCOC/PSFA Broadband Initiative for technology. The total scope of technology needs could exceed the designated \$250,000 over the next five years and the district is prepared to supplement these funds with E-rate, PSCOC/PSFA Broadband and GOB when necessary. The district is aware of the broadband initiative that PSCOC/PSFA has under taken to provide all New Mexico Public School Districts with affordable and high speed broadband access. The district partnered with PSCOC/PSFA on this initiative to upgrade wireless access, switches and a network router at Mora Campus. The district will continue to monitor its technology system and work with PSFA when it is appropriate and will benefit the district. The district also applies for and receives E-rate funding for its technology program. The district is dedicated to providing its students with access to up-to-date technology. The district has an active technology department that identifies upgrades to technology infrastructure, equipment and software to meet the needs of the schools.

The district continues to upgrade its technology infrastructure to keep up with the newest advancements. Technology is a tool that the district uses extensively in the classroom and for support services which requires a steady funding source. The district applies for e-rate funding and utilizes SB-9 funds to address its technology needs.












Broadband Projects that will become Capital Projects:

During this FMP process no broadband projects for MISD were identified that will become capital projects..


TOTAL DISTRICT CAPITAL NEEDS BY CATEGORY: \$14,643,497

The \$14,643,497 reflects the total needs identified in the above eight categories throughout the district. As shown above, MISD has a potential budget of \$4,020,735 for the next five years from an anticipated 2019 GOB election and SB-9 funds. It is anticipated that the FMP identified needs could span the life a several GOB elections.









						•								
							Funding						TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	_	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
Priority 1 Life-Health-Safe	ety-Security / Ma	aintenance / Techno	logy:				<u> </u>							
								Ceramic tile in this area \$58,787: Replace cracked						
								ceramic tile in commons area and at north entrance						
		HS Commons						of building and Replace / Repair buckled VCT in						
Mora Combined School	2004	Addition		FAD	Floor Finishes	FacRen	BS-GOB	conference room and music room		sf	\$0.00	\$0	\$0	
	4004	110.0 4.11			_,,		DO 00D	Original \$31,041: Replace cracked VCT in lobby			# 0.00	**		
Mora Combined School	1991	HS Gym Addition		FAD	Floor Finishes	FacRen	BS-GOB	area		sf	\$0.00	\$0	\$0	
								Original \$101,101: Replace cracked VCT in						
Mora Combined School	1968	HS Main Bldg.		FAD	Floor Finishes	FacRen	BS-GOB	computer lab 112 and at entrance of classroom 109		sf	\$0.00	\$0	\$0	\$0
Word Combined Concor	1000	He Main Blag.		17.0	Life-Health-Safety-Security-	1 dorton	BC CCB	computer lab 112 and at chitation of oldsstroom 100		OI .	ψ0.00	ΨΟ	ΨΟ	ΨΟ
District Wide					ADA-Code	LHSS	L-SB9	Address life-health-safety-security issues	5	vr.	\$50,000	\$250,000	\$250,000	
		HES Original										•		
Holman ES	1969	Const		FAD	Drain, Waste and Vent	LHSS	L-GOB	\$24.55	1	FAD	\$0.00	\$0	\$0	
								Replace exit classroom doors to ADA compliant,						
Holman ES	1987	HES Addition		FAD	Exterior Doors	LHSS	L-GOB	\$14,098	1	FAD	\$0.00	\$0	'	
Holman ES	2006	HES Addition		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Replace broken front window		ea.		\$0	\$0	
Holman ES	1969	HES Original		EAD	Water Distribution	11100	L COB	\$24,554			#0.00	40	# 0	
Holman ES Holman ES	1969	Const HES Site		FAD Dist.	Z-Fencing	LHSS LHSS	L-GOB L-GOB	\$24,554 Upgrade playground fencing : 2018 In Progress		FAD If	\$0.00	\$0 \$0		
Holman ES	1969	HES Site			Z-Fencing Z-Fencing	LHSS	L-GOB	Repair perimeter fencing: 2018 In Progress		lf		\$0 \$0	1 -	
Holman ES	1969	HES Site		FAD	Z-Parking Lots	LHSS		Beyond expected life by aging \$76,509	v	FAD	\$0.00	\$0		
TIOMIGHT 20	1000	1120 010		17.0	2 r arming 20to	LITOU	LOOB	Redesign Pick-Up/Drop-Off area to separate bus and		1710	Ψ0.00	ΨΟ	ΨΟ	
Holman ES	1969	HES Site		Dist.	Z-Parking Lots	LHSS	L-GOB	parent traffic	_	ea.	\$0.00	\$0	\$0	
Holman ES	1969	HES Site			Z-Site Lighting	LHSS	L-GOB	Install site lighting		ea.	\$0.00	\$0	\$0	
								Create an evacuation route in the back of building.						
Holman ES	2006	HES Addition			Z-Walkways	LHSS	L-GOB	There is only evacuation route in the front.		ea.	\$0.00	\$0	\$0	
Holman ES	1969	HES Site		Dist.	Z-Walkways	LHSS	L-GOB	Replace walkways	300	sf	\$0.00	\$0	\$0	
	4074	HS Original Const						DOLLOG 040 404 040			# 0.00	**		
Mora Combined School	1974	(gym) HS Main Bldg.			Communications / Security Communications / Security	LHSS LHSS	L-GOB	DCU 03-019 \$24,249 DCU 03-019 \$27,677: Updated 2003		ea.	\$0.00 \$0.00	\$0 \$0		
Mora Combined School Mora Combined School	1968 1991	HS Industrial Arts		FAD FAD	Communications / Security	LHSS	L-GOB L-GOB	Intercom installed. DCU 03-019 \$7,805		ea. ea.	\$0.00	\$0 \$0		
Mora Combined School	1991	HS Gym Addition		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$3,850		ea.	\$0.00	\$0	•	
Mora Combined Concor	1001	HS Commons		17.0	Communications / Cecarity	Lileo	LOOD	2 0 0 0 10 ψ0,000		cu.	Ψ0.00	ΨΟ	ΨΟ	
Mora Combined School	2004	Addition		FAD	Communications / Security	LHSS	L-GOB	\$17,498		ea.	\$0.00	\$0	\$0	
		ES Original Bldg.			,			\$15,429: Replace bell system: current system does				·		
Mora Combined School	1950	South Wing		FAD	Communications / Security	LHSS	L-GOB	not work		ea.	\$0.00	\$0	\$0	
		ES Original Bldg.						\$13,488: Include replacement of bell system: current						
Mora Combined School	1950	North Wing		FAD	Communications / Security	LHSS	L-GOB	system does not work		ea.	\$0.00	\$0	\$0	
		ES MS Org. Gym /											**	
Mora Combined School	1950	Band, K-8		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$18,776		ea.	\$0.00	\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$22,568		93	\$0.00	¢0	\$0	
Mora Combined School	1965	Cafeteria, K-12			Communications / Security	LHSS	L-GOB	DCU 03-019 \$22,566 DCU 03-123 \$6,971: No intercom		ea. ea.	\$0.00	\$0 \$0		
mora combined control	1000	ES Library Phase 3		. ,	Communications / Occurry	_, 100	12 000	255 55 125 \$6;61 (. 140 microsm)		Ju.	φ0.00	φυ	φυ	
Mora Combined School	2001	Const		FAD	Communications / Security	LHSS	L-GOB	\$4,427		ea.	\$0.00	\$0	\$0	
MOTA COMBINED SCHOOL	2001	Const		1 AD	Communications / Occurry	L1 100	2-000	\$12,649 Comm is original: Working but need to		ou.	φυ.υυ	φυ	φυ	
Mora Combined School	1995	Admin/Kinder		FAD	Communications / Security	LHSS	L-GOB	upgrade		sf	\$0.00	\$0	\$0	
Mora Combined School	1995	Admin/Kinder			Emergency Light and Power	LHSS	L-GOB	\$2,830		sf	\$0.00	\$0		
					<u> </u>			Doors on the main gym sticking and hard to open:						
		HS Original Const						Possible safety problem with exiting the building						
Mora Combined School	1974	(gym)		FAD	Exterior Windows & Doors	LHSS	L-GOB	\$472,155		ea.	\$0.00	\$0	\$0	
Maria Octable 10 to 1	1050	ES Original Bldg.		EAD	Fortunian Miles I			Exterior doors sticking and hard to open: Possible			22.25			
Mora Combined School	1950	South Wing		FAD	Exterior Windows & Doors	LHSS	L-GOB	safety hazard in need of service \$180,251		ea.	\$0.00	\$0	\$0	
Mora Combined School	2001	ES Library Phase 3		EAD	Exterior Windows & Doors	LHSS	L-SB9	Exterior doors sticking and hard to open: Possible		00	\$0.00	C O	¢ο	
Mora Combined School	1997	Const MS Main Bldg.			Exterior Windows & Doors Exterior Windows & Doors	LHSS	L-SB9	safety hazard in need of service \$48,849 Update north exit door to ADA complaint		ea. ea.	\$0.00	\$0 \$0		
Mora Combined School	1881	IVIO IVIAITI DIUG.		טוסנ.	EXICITOR VALIDONS & DOOLS	LI 100	r-0D3	opuate north exit door to ADA complaint		ca.		φυ	φυ	

													TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
	1007	MO Main Dido		D: 4	Fotonian Windows O. Donne	11100	I 000	Description in description and the description of t				4.0	Φ0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Repair window in computer lab 103: it does not lock Upgraded 1998 only in custodian area \$22,568:		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		FAD	Fire Detection/Alarm	LHSS	L-GOB	Updated 2017) sf	\$0.00	\$0	\$0	
Word Combined Concor	1007	HS Original Const		17.0	The Betestion, warm	LITOU	E 00B	Opadica 2011		7 01	ψ0.00	Ψ	ΨΟ	
Mora Combined School	1974	(gym)		FAD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$24,249: Updated 2018		sf	\$0.00	\$0	\$0	
								Fire alarm and intercom modifications \$30,092:						
Mora Combined School	1968	HS Main Bldg.		FAD	Fire Detection/Alarm	LHSS	L-GOB	Updated 2018		sf	\$0.00	\$0	7 -	
Mora Combined School	1991	HS Industrial Arts		FAD	Fire Detection/Alarm	LHSS	L-GOB	Fire alarm system installed. DCU 03-019 \$7,805		sf	\$0.00	\$0		
Mora Combined School	1991	HS Gym Addition		FAD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$3,850		st	\$0.00	\$0	\$0	
		HS Commons												
Mora Combined School	2004	Addition		FAD	Fire Detection/Alarm	LHSS	L-GOB	\$17,498		ef	\$0.00	\$0	\$0	
Word Combined School	2004	ES Original Bldg.		TAD	The Detection/Alarm	LIIOO	L-GOB	ψ17, 43 0		51	φ0.00	φυ	ΨΟ	
Mora Combined School	1950	South Wing		FAD	Fire Detection/Alarm	LHSS	L-GOB	\$15,429		sf	\$0.00	\$0	\$0	
mora combined conco.		ES Original Bldg.			Detection, na			4 10, 120			ψ0.00	Ψ,	40	
Mora Combined School	1950	North Wing		FAD	Fire Detection/Alarm	LHSS	L-GOB	\$13,488		ea.	\$0.00	\$0	\$0	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$18,776		sf	\$0.00	\$0	\$0	
		ES Library Phase 3												
Mora Combined School	2001	Const		FAD	Fire Detection/Alarm	LHSS	L-GOB	Completed Dec 2001 \$4,427		sf	\$0.00	\$0	7 -	
Mora Combined School	1965	Cafeteria, K-12		FAD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$6,971		sf	\$0.00	\$0		
Mora Combined School	1995	Admin/Kinder		FAD	Fire Detection/Alarm	LHSS	L-GOB	\$12,649: Updated 2018	(ea.	\$0.00	\$0	1 -	
Mora Combined School	1997	MS Main Bldg.		Dist.	Fire Sprinkler	LHSS	L-GOB	Building is not sprinklered NMSFMO recomm. compl. syst. Pressure		ea.		\$C	\$0	
								problematic, only in the custodian area \$79,391:						
Mora Combined School	1968	HS Main Bldg.		FAD	Fire Sprinkler	LHSS	L-GOB	Fully functional		ea.	\$0.00	\$0	\$0	
Mora Combined Concor	1000	Tio Main Blag.		17.0	т по оргинаст	Liloo	L 00B	NMSFMO recomm. compl. syst. Pressure		ou.	ψ0.00	Ψ	ΨΟ	
Mora Combined School	1991	HS Gym Addition		FAD	Fire Sprinkler	LHSS	L-GOB	problematic \$30.713		ea.	\$0.00	\$0	\$0	
		HS Commons						, , ,			, , , , ,		, .	
Mora Combined School	2004	Addition		FAD	Fire Sprinkler	LHSS	L-GOB	This is required \$11,079	1	l ea.	\$0.00	\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	North Wing		Dist.	Fire Sprinkler	LHSS	L-GOB	Building is not sprinklered		ea.	\$0.00	\$0	\$0	
		ES MS Org. Gym /		L				Not needed per UBC and repl. corridor					4.0	
Mora Combined School	1950	Band, K-8		FAD	Fire Sprinkler	LHSS	L-GOB	doors/hardware \$49,537		ea.	\$0.00	\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Dist.	Institutional Equipment	LHSS	L-SB9	Replace wall pads		00		\$0	\$0	
Mora Combined School	1950	ES Original Bldg.		DISt.	Institutional Equipment	LП33	L-3D9	Replace wall paus		ea.		φυ	φυ	
Mora Combined School	1950	North Wing		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage in all areas		ea.		\$0	\$0	
Word Combined Concor	1000	ES Original Bldg.		Diot.	motitutional Equipment	Lileo	L OBO	motali 71571 digitago in ali aroas		cu.		Ψ	ΨΟ	
Mora Combined School	1950	South Wing		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage in all areas		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage		ea.		\$0		
		HS Original Const												
Mora Combined School	1974	(gym)		FAD	Main Power/Emergency	LHSS	L-GOB	Original \$16,277		sf	\$0.00	\$0	\$0	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Main Power/Emergency	LHSS	L-GOB	Replaced 1984 \$12,603		sf	\$0.00	\$0	\$0	
Mana Camabina d Cabaal	1974	HS Original Const		Dist	Plumbing	11100	L-GOB	Upgrade Men's bathroom to ADA complaint				¢.c	\$0	
Mora Combined School	1974	(gym) ES Original Bldg.		Dist.	Plumbing	LHSS	L-GOB	Opgrade Men's pathroom to ADA complaint		SI		\$0	\$0	
Mora Combined School	1950	South Wing		Dist.	Plumbing	LHSS	L-GOB	Upgrade drinking fountain alcove to ADA complaint		ea.		\$0	\$0	
mora Combined Concol	1000	Count willing		15.00.	i idilibiliy	21100	2 005	Poor drainage around the buildings and grounds		ou.		Ψ	ΨΟ	
								causing damage to exterior walls on the building						
Mora Combined School	1950	MCS Site		FAD	Z-Landscaping	LHSS	L-GOB	\$524,513		sf	\$0.00	\$0	\$0	
		ES MS Org. Gym /			. 5			Correct drainage on west side of building outside the						
Mora Combined School	1950	Band, K-8		Dist.	Z-Landscaping / Drainage	LHSS	L-GOB	band room: water filters through the doors		ea.		\$0	\$0	
								Area in poor condition in need of repair due to						
								deterioration and poor drainage around the complex						
Mana Oanskii 101	4050	MOC 0'4-		EAD	7 Dankin v Lata			\$1,180,660: District repayed entrance and HS			00.00	4.0	40	
Mora Combined School	1950	MCS Site		FAD	Z-Parking Lots	LHSS	L-GOB	parking lot in 2017		sf	\$0.00	\$0	\$0	

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Mora Combined School	1950	MCS Site		Dist.	Z-Site Lighting	LHSS	L-GOB	Repair / replace wall pack lights on Main HS Building		sf	\$0.00	\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Z-Site Lighting	LHSS	L-GOB	Install site lighting: there is no lighting in this area		sf	φ0.00	\$0		
Mora Combined Concor	1000	110 1114111 21491		Blot.		21100	2 3 3 2	Repair / replace one lift station pump: it is not		<u> </u>		Ψ		
Mora Combined School	1950	MCS Site		Dist.	Z-Site Utilities	LHSS	L-GOB	working		sf	\$0.00	\$0	\$0	
		ES MS Org. Gym /						Rework drain pipes from ES MS Gym to have one lift			·	·	· ·	
Mora Combined School	1950	Band, K-8		Dist.	Z-Site Utilities	LHSS	L-GOB	station.		sf		\$0	\$0	
								Walkways in poor condition due to cracks,						
								deterioration and missing concrete. Possible tripping						
Mora Combined School	1950	MCS Site		FAD	Z-Walkways	LHSS	L-GOB	hazards \$1,459,949		sf	\$0.00	\$0	\$0	
		ES Original Bldg.						Repair sidewalk and ramp at south entrance of						
Mora Combined School	1950	South Wing		Dist.	Z-Walkways	LHSS	L-GOB	building		sf		\$0	\$0	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8			Z-Walkways	LHSS		Repair sidewalk in north side of building		sf		\$0	¥ -	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Z-Walkways	LHSS	L-GOB	Repair sidewalk next to the cafeteria		sf	MADA 447.00	\$0	¥ -	\$250,000
District Wide	1007	HES Addition		Dist.	Maintenance	PreVent PreVent	Prevent	Preventive and Regular Maintenance needs	5	yr.	\$104,147.00	\$520,735	\$520,735	
Holman ES	1987	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace / repair stained ceiling tiles in corridor		sf		\$0	\$0	
Holman ES	1995	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace / repair stained ceiling tiles in library's exit and in office area		ea.		\$0	\$0	
Holman ES	2006	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Repair ceiling tiles; ceiling bubble in kitchen		sf		\$0		
Holman E3	2000	HES Original		Dist.	Celling Fillishes	i ievent	i le velit	repair ceiling tiles, ceiling bubble in kiterien		31		Ψ	ΨΟ	
Holman ES	1969	Const		Dist.	Ceiling Finishes	PreVent	PreVent	Replace / repair stained ceiling tiles in corridor		sf		\$0	\$0	
rioimari Eo	1000	HES Original		Diot.	Coming 1 misries	1 TO VOIN	1 TO VOITE	replace / repair stained selling thes in serrider		01		Ψ	ΨΟ	
Holman ES	1969	Const		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair water damage in sill at director's office		sf		\$0	\$0	
Holman ES	1987	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Replace / repair cracked VCT in corridor		sf		\$0	· ·	
Holman ES	1995	HES Addition		Dist.	Floor Finishes	PreVent		Repair carpet snag in nurse's office		ea.		\$0		
												·	·	
Holman ES	2006	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Repair / replace cracked VCT outside girls restroom		sf		\$0	\$0	
		HES Original												
Holman ES	1969	Const		Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in reception		ea.		\$0		
Mora Combined School	1950	Admin/Kinder		Dist.	Ceiling Finishes	PreVent	Prevent	Repair stained ceiling in storage room 117		sf		\$0	7 -	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in kitchen room		sf		\$0	\$0	
		ES MS Org. Gym /						Repair / replace stained ceiling tiles in boys and girls						
Mora Combined School	1950	Band, K-8		Dist.	Ceiling Finishes	PreVent	PreVent	showers		sf		\$0	\$0	
	4050	ES MS Org. Gym /		D: 1	O dilitara Findale e	D 1/ /	D 14 4	Repair / replace stained ceiling tiles in band room		1,				
Mora Combined School	1950	Band, K-8		Dist.	Ceiling Finishes	PreVent	PreVent	and in classroom 148		sf		\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band. K-8		Dist.	Ceiling Finishes	PreVent	Dra\/ant	Denair / replace stained sailing tiles in ignitarie algori		sf		\$0	\$0	
Mora Combined School	1950	ES Original Bldg.		DISt.	Celling Finishes	Prevent	PreVent	Repair / replace stained ceiling tiles in janitor's closet		SI		φC	\$0	
Mora Combined School	1950	North Wing		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
Wora Combined School	1930	ES Original Bldg.		Dist.	Celling Fillishes	i ievent	i levelit	Trepair some at both ends of school		31		Ψ	Ψ0	
Mora Combined School	1950	South Wing		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
	.000	HS Commons		2.50	James San			r topum donnt at boar on ab or control				Ψ.	40	
Mora Combined School	2004	Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in library		sf		\$0	\$0	
Mora Combined School	1991	HS Gym Addition		Dist.	Ceiling Finishes	PreVent		Replace stained ceiling tiles in storage room		sf		\$0		
		j						Replace stained ceiling tiles in teacher's lounge,				·		
Mora Combined School	1968	HS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	conference room and in storage room 117		sf		\$0	\$0	
			125, 120, 115,					Replace stained ceiling tiles in science labs and						
Mora Combined School	1968	HS Main Bldg.	137, 108	Dist.	Ceiling Finishes	PreVent	PreVent	classrooms		sf		\$0	\$0	
		HS Original Const		L				Replace stained ceiling tiles in room next to girls		1.				
Mora Combined School	1974	(gym)	100 107 116	Dist.	Ceiling Finishes	PreVent	PreVent	lockers		sf		\$0	\$0	
			103, 107, 112,					Dealers (managinatain at a managinatain at a man						
Mana Canabia at C. I	4007	MO Made Did	108, 109, 110,	Dist	Calling Finishes	Dueldent		Replace / repair stained ceiling tiles in classrooms						
Mora Combined School	1997	MS Main Bldg.	111, 102		Ceiling Finishes	PreVent		and computer lab		sf		\$0		
Mora Combined School	1997	MS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at southwest side of the building		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Diet	Ceiling Finishes	Dro\/ont	Dro\/ont	Repair / replace stained ceiling tiles in corridor in front of classroom 109		sf		Φ.	\$0	
Mora Combined School	1997	Admin/Kinder			Exterior Walls	PreVent PreVent		Caulk perimeter of building		st sf		\$0 \$0		
IVIOTA COMBINICA SCHOOL	1930	ES Library Phase 3		Dist.	LATORIOR VVAIIS	i ieveiit	i ieveni	Saun perimeter or building		31		Φ	, φυ	
Mara Cambinad School	2001	Conet		Diet	Exterior Walls	Pro\/ont	Pro\/ont	Papair rusted stucce at partheast wall of library		of		\$0		

							Funding				0007///		TOTAL PROJECT COST	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	I NOOLOT GOOT	SUBTOTALS
Mora Combined School	2001	ES Library Phase 3 Const		Dist.	Exterior Walls	PreVent	PreVent	Repair rusted stucco at west corner bead		of		\$0	\$0	
Mora Combined School	2001	ES MS Org. Gym /		DISt.	Exterior Walls	Flevelit	Fieveni	Repail Tusted stucco at west comer beau		51		φυ	φυ	
Mora Combined School	1950	Band, K-8		Dist.	Exterior Walls	PreVent	PreVent	Repair wall crack on southeast side of the building		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	Caulk perimeter of building		If		\$0	\$0	
				2.5				Repair cracked stucco at west entry and at north		1		Ţ,	Ψü	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	entry		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent	Repair wall outside and inside		sf		\$0	\$0	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken windows in band room		sf		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	North Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken window in classroom 2		sf		\$0	\$0	
		ES Original Bldg.						Upgrade exterior windows. Windows are hard to						
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	Prevent	open		sf		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair window sill		sf		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair / replace window screens		ea.		\$0	\$0	
		ES Original Bldg.						Repaint exterior windows' frames: paint is peeling off						
Mora Combined School	1950	South Wing			Exterior Windows & Doors	PreVent	PreVent	of the frames		sf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair damaged window sill in classroom 107		sf		\$0	7 -	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair window screen in classroom 106		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.			Exterior Windows & Doors	PreVent	PreVent	Reseal all wood window sills		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair all exterior window frames and stucco		ea.		\$0	\$0	
								Assess window settlement; windows are hard to						
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent	open		ea.		\$0	\$0	
		ES MS Org. Gym /				L								
Mora Combined School	1950	Band, K-8		Dist.	Floor Finishes	PreVent	PreVent	Replace cracked VCT in boys showers		sf		\$0	\$0	
	40-0	ES MS Org. Gym /		5	e. e	_ ,, ,				1, 1			40	
Mora Combined School	1950	Band, K-8		Dist.	Floor Finishes	PreVent	PreVent	Replace carpet in band room		st		\$0	\$0	
Mana Canabina d Caba al	4050	ES MS Org. Gym /		D:-4	Elece Electrica	D	D	Danie a analyst in side marks an				40	ФО.	
Mora Combined School	1950	Band, K-8			Floor Finishes	PreVent	PreVent	Replace cracked VCT in girls restroom		ST		\$0	\$0 \$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	Repair carpet in corridor outside computer labs		ST		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	Replace / repair cracked VCT and buckled VCT in corridors and at north entrance		of		\$0	\$0	
Mora Combined School	1997	IVIS IVIAITI DIUG.		DISt.	FIOOI FIIIISHES	Flevelit	Frevent	Replace / repair cracked VCT at the entrance of		51		φυ	Φυ	
Mora Combined School	1997	MS Main Bldg.		Dist.	Floor Finishes	PreVent	PreVent	classroom 112		ef		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.			Floor Finishes	PreVent	PreVent	Install vinyl base at west entry		ef		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Foundation / Slab / Structure	PreVent	PreVent	Assess change in floor slope in classroom 108		sf		\$0	\$0	
Mora Combined Concor	1000	ES Library Phase 3		Dist.	r canadaon / Clab / Chactare	1 TO VOITE	i ioveni	Upgrade HVAC System; there is no heating in this		01		ΨΟ	ΨΟ	
Mora Combined School	2001	Const		Dist	HVAC	PreVent	Prevent	area		sf		\$0	\$0	
		ES Library Phase 3		2.54.						1		40	7-	
Mora Combined School	2001	Const		Dist.	Institutional Equipment	PreVent	Prevent	Repair plastic laminate at library counter		ea.		\$0	\$0	
		ES Original Bldg.			' '							, -	, -	
Mora Combined School	1950	South Wing		Dist.	Institutional Equipment	PreVent	Prevent	Repair plastic laminate at all classrooms		ea.		\$0	\$0	
		HS Commons					Ī					, .	, ,	
Mora Combined School	2004	Addition		Dist.	Institutional Equipment	PreVent	Prevent	Replace booths in commons area	5	ea.		\$0	\$0	
		HS Commons										,		
Mora Combined School	2004	Addition		Dist.	Institutional Equipment	PreVent	Prevent	Replace table arms on auditorium seating	12	ea.		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.	107 & 108	Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in classrooms		lf		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Institutional Equipment	PreVent	PreVent	Repair tables in science labs		ea.		\$0	\$0	
								Repair plastic laminate in computer lab and						
Mora Combined School	1968	HS Main Bldg.		Dist.	Institutional Equipment	PreVent	Prevent	classrooms		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in classroom 109		ea.		\$0	· ·	
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	PreVent	Prevent	Replace casework in classroom 102		ea.		\$0	\$0	
Mora Combined School	1968	HS Main Bldg.		Dist.	Interior Doors	PreVent	PreVent	Repair door in classroom 115: door does not close		ea.		\$0	\$0	
[<u>.</u>		ES MS Org. Gym /				L	L							
Mora Combined School	1950	Band, K-8		Dist.	Interior Walls	PreVent	PreVent	Repair water damage in storage room		sf		\$0	\$0	

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Mora Combined School	1965	Cafeteria, K-12			Wall Finishes	PreVent	PreVent	Repaint exterior walls: paint is peeling off brick		sf		\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12			Wall Finishes	PreVent	PreVent	Repair wall at kitchen		sf		\$0	7.	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Wall Finishes	PreVent	PreVent	Repair wall due to water damage in dinning room		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair wall hole at north entrance		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.	105, 111, 106, 108, 109, 110	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in classrooms and computer lab		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.	130 & 128	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in councilor and principal offices		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair wall and ceiling cracks in councilor office and restroom		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.	108, 102, 110	Dist.	Wall Finishes	PreVent	PreVent	Repair window sill in classrooms		sf		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair ceiling crack in mechanical room		sf		\$0	\$0	\$520,735
District Wide		District		Dist.	Technology	Tech	Tech	Upgrade technology district wide: Hardware, Software, Training, Broadband	5	yr.	\$50,000.00	\$250,000	\$250,000	
Mora Combined School	1991	Addition		FAD	Technology	Tech	Tech	No system \$1,350: not needed	C	ea.	\$0.00	\$0	\$0	
Mora Combined School Mora Combined School	1975 1965	Aud / Band, K-8 Cafeteria, K-12			Technology Technology	Tech Tech	Tech Tech	Upgraded 1999 \$2,744: Upgraded 2018 Upgraded 2000 \$1,019: Upgraded 2018		ea.	\$0.00 \$0.00	\$0	\$0	
Mora Combined School		Commons Addition			Technology	Tech	Tech	New electronic white boards in classrooms \$2,557. Upgraded 2018		ea.	\$0.00	\$0	\$0	
Mora Combined School	1991	Industrial Arts High		FAD	Technology	Tech	Tech	Updated 2000 \$1,140: District updated 2018	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	1968	Main Bldg High		FAD	Technology	Tech	Tech	Replaced 2000. New electronic white boards in classrooms (2013). Estimated time frame 2005 \$4,397: Updated 2018	C	ea.	\$0.00	\$0	\$0	
Mora Combined School	1950	Main Bldg Middle		FAD	Technology	Tech	Tech	Updated 2000 \$3,298: District updated 2018		ea.	\$0.00	\$0	\$0	
Mora Combined School	1978	Original Const (gym)		FAD	Technology	Tech	Tech	No system needed \$8,504: Updated 2018	C	ea.	\$0.00	\$0	\$0	\$250,000
Priority 1 Life-Health-Safe	Priority 1 Life-Health-Safety-Security / Maintenance / Technology:											\$1,020,735	\$1,020,735	\$1,020,735

Priority 2 Building / Site S	System Upgrad	les:												
	400=							Upgrade HVAC system: Install heating in nursing			40-00	***	4	
Mora Combined School	1995	Admin/Kinder	SPED and Nursing		HVAC	AdqStd	BS-GOB	and SPED	1,750		\$25.00	\$43,750	\$56,875	
Mora Combined School	1965	Cafeteria, K-12		FAD	HVAC	AdqStd	BS-GOB	\$88,351 Propane rooftop units. Evap cooling	5,600	sf	\$25.00	\$140,000	\$182,000	
		ES MS Org. Gym /						Propane rooftop units repl 1984 \$237,966: Upgrade						
Mora Combined School	1950	Band, K-8		FAD	HVAC	AdqStd	BS-GOB	HVAC units: one old unit; newer unit is not working	15,748	sf	\$15.00	\$236,220	\$307,086	
		ES Original Bldg.						Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the			***	40-1-00	40 //0	
Mora Combined School	1950	North Wing		Dist.	HVAC	AdqStd	BS-GOB	north wing and classrooms are too hot	10,988	st	\$25.00	\$274,700	\$357,110	
Mara Cambinad Sahaal	1950	ES Original Bldg. South Wing		Diet	LINVAC	A da Ctd	BS-GOB	Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the south wing and classrooms are too hot	40.200	of	\$25.00	#200 07E	\$402.0GQ	
Mora Combined School	1950	South wing		Dist.	HVAC	AdqStd	BS-GOB	Ü	12,399	SI	\$25.00	\$309,975	\$402,968	
Mora Combined School	1968	HS Main Bldg.		FAD	HVAC	AdqStd	BS-GOB	Original propane rooftop units. No cooling but desired \$381,382: Updated 2003	23,264	sf	\$25.00	\$581,600	\$756,080	
Mora Combined School	1974	HS Original Const		FAD	HVAC	AdqStd	BS-GOB	Original propane boiler. No cooling but desired \$307,332	16,068	of	\$25.00	\$401,700	\$522,210	
Mora Combined School	1974	Admin/Kinder		FAD	HVAC Controls	AdqStd	BS-GOB	Beyond Expected Life: Need to upgrade		FAD	\$22,378.00	\$22,378	\$29,091	
Mora Combined School	1995			FAD	HVAC Controls	Auqsiu	BS-GOB	Beyond Expected Life. Need to appraise		FAD	\$22,370.00	ΦΖΖ,310	\$29,091	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	HVAC Controls	AdgStd	BS-GOB	Original: Possible replaced and upgraded in 1984	1	FAD	\$33,218.00	\$33,218	\$43,183	
Mora Combined School	1991	HS Gym Addition		FAD	HVAC Controls	AdqStd	BS-GOB	Original	1	FAD	\$6,811.00	\$6,811	\$8,854	
Mora Combined School	1991	HS Industrial Arts		FAD	HVAC Controls	AdqStd	BS-GOB	Original	1	FAD	\$13,809.00	\$13,809	\$17,952	
Mora Combined School	1968	HS Main Bldg.		FAD	HVAC Controls	AdqStd	BS-GOB	Original \$127,771: Updated 2003	23,264	sf	\$5.00	\$116,320	\$151,216	
		HS Original Const												
Mora Combined School	1974	(gym)		FAD	HVAC Controls	AdqStd	BS-GOB	Original	1	FAD	\$102,962.00	\$102,962	\$133,851	
Mora Combined School	1997	MS Main Bldg.		FAD	HVAC Controls	AdqStd	BS-GOB	Upgraded 1998	1	FAD	\$39,926.00	\$39,926	\$51,904	
Maria Carrellina d Calacal	4005	Outstants IX 40		EAD	La dia di La Carta da	A .1 Ot .1	DO 00D	No gym equipment: Replace some kitchen		EAD	#40.405.00	#40.405	047.407	
Mora Combined School	1965	Cafeteria, K-12		FAD	Institutional Equipment	AdqStd	BS-GOB	equipment	1	FAD	\$13,405.00	\$13,405	\$17,427	

							Francisco de						TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
Mora Combined School	1968	HS Main Bldg.	ROOM	,	Institutional Equipment	AdgStd	BS-GOB	No gym equipment: Updated 2003		I FAD	\$57,864.00	\$57,864	\$75,223	SUBTUTALS
Mora Combined Concor	1000	Tio Maii Biag.		1712	modular Equipment	rageta	B0 00B	The gym equipment. Opacies 2000		17.5	ψοτ,σοτ.σο	ψο, σο ι	Ψ10,220	
		HS Original Const						Scoreboards/backboards original \$46,629. Half						
Mora Combined School	1974	(gym)		FAD	Institutional Equipment	AdqStd	BS-GOB	bleachers updated 2017; need to replace other half		ea.	\$200.00	\$60,000		\$3,191,029
Holman ES	1987	HES Addition			Drain, Waste and Vent	FacRen	BS-SB9			FAD	\$24,395.00	\$24,395	\$31,714	
Holman ES	1987	HES Addition		FAD	Water Distribution	FacRen	BS-GOB	Last replaced 1984. Possible replaced in addition in	Í	FAD	\$24,395.00	\$24,395	\$31,714	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	Ceiling Finishes	FacRen	BS-GOB	1984 \$64,759	15,748	2 cf	\$6.00	\$94,488	\$122,834	
Wora Combined School	1930	HS Original Const		FAD	Celling Finishes	raciteii	D3-GOD	1904 404,739	13,740	5 51	φ0.00	φ94,400	Ψ122,034	
Mora Combined School	1974	(gym)		FAD	Ceiling Finishes	FacRen	BS-SB9	TandG ceiling	,	I FAD	\$83,637.00	\$83,637	\$108,728	
Mora Combined School	1950	Admin/Kinder			Exterior Walls	FacRen	BS-GOB	Repair stucco	3,600) sf	\$8.00	\$28,800	\$37,440	
								Walls with minor cracks, water damage due to roof						
		ES Library Phase 3						runoff causing water to splash from concrete apron						
Mora Combined School	2001	Const		FAD	Exterior Walls	FacRen	BS-GOB	\$17,205	1,400) sf	\$8.00	\$11,200	\$14,560	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		Diet	Exterior Walls	FacRen	BS-GOB	Repair / Upgrade exterior wall finishes	10,000) of	\$8.00	\$80,000	¢404.000	
Mora Combined School	1997	MS Main Bldg.			Exterior Walls	FacRen	BS-GOB	Replace entire building stucco	10,000		\$8.00	\$81,600	\$104,000 \$106,080	
Mora Combined Cencer	1001	ES MS Org. Gym /		Dist.	Exterior Walls	racitori	DO-00B	Original windows on gym and 1975 windows on	10,200	7 31	ψ0.00	ψ01,000	ψ100,000	
Mora Combined School	1950	Band, K-8		FAD	Exterior Windows & Doors	FacRen	BS-GOB	addition and doors on gym \$65,283	150) sf	\$175.00	\$26,250	\$34,125	
		, -			-			Exterior damage to window sills and drywall, exterior			,	, , , , , , , , , , , , , , , , , , , ,	, , ,	
								doors hard to open and close \$175,766. Reseal all						
Mora Combined School	1997	MS Main Bldg.			Exterior Windows & Doors	FacRen	BS-GOB	wood window sills;	450) sf	\$175.00	\$78,750	\$102,375	
			106, 105, 102, 107					\$42,497Upgrade carpet in offices and conference						
Mora Combined School	1995	Admin/Kinder	& 109	FAD	Floor Finishes	FacRen	BS-SB9	room	1,500) sf	\$6.00	\$9,000	\$11,700	
Mora Combined School	1965	Cafeteria, K-12		FAD	Floor Finishes	FacRen	BS-SB9	Wear and cracking in several areas of the main cafeteria floor \$23,421	2,100	of	\$6.00	\$12,600	\$16,380	
Wiora Combined School	1905	ES Library Phase 3		FAD	Floor Fillishes	raciteii	D3-3D9	Careteria 11001 \$25,421	2,100) 51	φ0.00	φ12,000	φ10,300	
Mora Combined School	2001	Const		FAD	Floor Finishes	FacRen	BS-SB9	Completed Dec 2001 \$14,875	2,200) sf	\$6.00	\$13,200	\$17,160	
		ES MS Org. Gym /							,		,	, ,,		
Mora Combined School	1950	Band, K-8		FAD	Floor Finishes	FacRen	BS-GOB	\$63,083	15,000) sf	\$6.00	\$90,000	\$117,000	
								\$45,315; Include upgrade carpet in classroom 2 and						
	40-0	ES Original Bldg.			e. e			replace vinyl base in girls and boys restrooms and			4	4.0 -00	* 47.550	
Mora Combined School	1950	North Wing		FAD	Floor Finishes	FacRen	BS-GOB	throughout wing. \$51,838: Upgrade carpet at all classrooms and	900) st	\$15.00	\$13,500	\$17,550	
								replace / repair cracked VCT in classroom 18 and in						
		ES Original Bldg.						corridor and Repair / replace vinyl base in building:						
Mora Combined School	1950	South Wing		FAD	Floor Finishes	FacRen	BS-SB9	base is coming off	7,500) sf	\$6.00	\$45,000	\$58,500	
		Ĭ						Ü	,		·	· · ·		
Mora Combined School	1991	HS Industrial Arts		FAD	Floor Finishes	FacRen	BS-GOB	Original. Heavy wear on VCT in classrooms (2013)	1	FAD	\$26,223.00	\$26,223	\$34,090	
								Gym flooring replaced 2000 \$81,471: Beyond						
Mana Canalia a I Calara	4074	HS Original Const		EAD	Elece Electric	F D	DO 00D	Expected Life: Gym floor is over water table; replace	0.500	ي .	#00.00	#005.000	#070 F00	
Mora Combined School Mora Combined School	1974 1997	(gym) MS Main Bldg.			Floor Finishes Floor Finishes	FacRen FacRen	BS-GOB BS-GOB	wood floor Replaced 1998 \$75,822	9,500 15,000		\$30.00 \$6.00	\$285,000	\$370,500 \$117,000	
INIOIA COMBINED SCHOOL	1887	ES MS Org. Gym /		LVD	1 1001 1 111131153	rachen	DO-GOD	ποριαύσα 1990 ψε 3,022	13,000	7 51	\$6.00	\$90,000	φ117,000	
Mora Combined School	1950	Band, K-8		FAD	Institutional Equipment	FacRen	BS-GOB	Upgraded 1984	1	FAD	\$36,104.00	\$36,104	\$46,935	
		ES MS Org. Gym /			1 1			, ,			,	, , , , , , ,	, ,	
Mora Combined School	1950	Band, K-8		FAD	Interior Doors	FacRen	BS-GOB	\$95,596	22	FAD	\$3,000.00	\$66,000	\$85,800	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8			Lighting / Branch Circuits	FacRen	BS-GOB	Replace lights at gym	7,212		\$7.00	\$50,484		
Mora Combined School	1965	Cafeteria, K-12		FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998	1	FAD	\$1,560.00	\$1,560	\$2,028	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	Other Electrical Systems	FacRen	BS-SB9	Updated 1984		FAD	\$4,201.00	\$4,201	\$5,461	
Mora Combined School	1991	HS Gym Addition			Other Electrical Systems	FacRen	BS-SB9	Original		I FAD	\$861.00	\$861	\$1,119	
Mora Combined School	1991	HS Industrial Arts			Other Electrical Systems	FacRen	BS-SB9	Original		FAD	\$1,746.00	\$1,746		
Mora Combined School	1968	HS Main Bldg.			Other Electrical Systems	FacRen	BS-SB9	Last upgraded 1991		FAD	\$6,733.00	\$6,733		
		HS Original Const			•									
Mora Combined School	1974	(gym)			Other Electrical Systems	FacRen	BS-SB9	Upgraded 1991 w/addition	1	FAD	\$13,022.00	\$13,022		
Mora Combined School	1997	MS Main Bldg.			Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998		FAD	\$5,049.00	\$5,049		

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Mora Combined School	1965	Cafeteria. K-12		FAD	Plumbing	FacRen	BS-GOB	\$53,159 Upgrade bathrooms for ADA. Replace double oven	250	cf	\$300.00	\$75,000	\$97,500	
iviora Combined School	1905	ES MS Org. Gym /		FAD	Plumbing	racken	B3-G0B	double over	230	51	φ300.00	\$75,000	φ9 <i>1</i> ,500	
Mora Combined School	1950	Band, K-8		FAD	Plumbina	FacRen	BS-GOB	Upgraded 1984 \$143.180	800	cf	\$150.00	\$120,000	\$156,000	
Wora Combined School	1930	ES Original Bldg.		FAD	Fluiribility	raciteii	D3-GOD	Renovate sinks to ADA compliant in girls and boys	800	31	\$150.00	\$120,000	\$130,000	
Mora Combined School	1950	North Wing		Dist.	Plumbing	FacRen	BS-GOB	restrooms	20	ea.	\$500.00	\$10,000	\$13,000	
Mora Combined School	1991	HS Industrial Arts			Plumbing	FacRen	BS-GOB	R/R non operational in need of repair \$85,707	225		\$300.00	\$67,500	\$87,750	
Mora Combined School	1968	HS Main Bldg.			Plumbing	FacRen	BS-GOB	Original \$229,471	900		\$300.00	\$270,000	\$351,000	
Mora Combined School	1995	Admin/Kinder			Roof	FacRen	BS-GOB	\$87,868: Need to coat metal roof	8,236		\$10.00	\$82,360	\$107,068	
Word Combined Concor	1000	AdminiTallide		IAD	1.001	racitori	DO-00D	Metal roof replacement 1998 \$48,427: In good	0,200	31	ψ10.00	Ψ02,300	ψ107,000	
Mora Combined School	1965	Cafeteria, K-12		FAD	Roof	FacRen	BS-GOB	condition	0	sf	\$0.00	\$0	\$0	
INOTA COMBINED SCHOOL	1905	Odictoria, IX-12		IAD	11001	raciteri	D0-00D	Metal roof with several roof leaks into the building		31	φ0.00	ΨΟ	ΨΟ	
								causing damage to ceiling tiles \$501,675: Coat metal						
Mora Combined School	1997	MS Main Bldg.		FAD	Roof	FacRen	BS-GOB	roof	18,587	cf	\$10.00	\$185,870	\$241,631	
Mora Combined School	1995	Admin/Kinder			Wall Finishes	FacRen	BS-SB9	Painted 2000: District painted 2007		FAD	\$23,937.00	\$23,937	\$31,118	
Mora Combined School	1965	Cafeteria, K-12		FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000. District painted 2007 Painted 2000 \$13.193	3,500		\$23,937.00	\$12,250	\$15,925	
Mora Combined School	1905	ES Library Phase 3		FAD	Wall Fillisties	racken	D3-3D9	Fairted 2000 \$15,195	3,300	51	φ3.50	φ12,230	φ10,920	
Mora Combined School	2001	Const		FAD	Wall Finishes	FacRen	BS-SB9	Completed Dec 2001 \$8,379	3,000	cf	\$3.50	\$10,500	\$13,650	
Mora Combined Scribbi	2001	ES MS Org. Gym /		FAD	Wall Fillisties	racken	D3-3D9	Completed Dec 2001 \$6,379	3,000	51	φ3.30	φ10,500	\$13,000	
Mara Cambinad Sabaal	1050			EAD	Wall Finishes	FaaBan	DC CDO	Dainted 2000	4		#25 522 00	#25 522	¢46 402	
Mora Combined School	1950	Band, K-8		FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$35,533.00	\$35,533	\$46,193	
Maria Caratina di Cata di	4050	ES Original Bldg.		EAD	Mall Finishes	F D	DO 000	Painted 1999; DNS clean and painted 2013 \$25,525;	0.000		#0.50	040.000	¢40 000	
Mora Combined School	1950	North Wing		FAD	Wall Finishes	FacRen	BS-SB9	Update wall finish in boys restroom	3,600	ST	\$3.50	\$12,600	\$16,380	
Maria Caratina di Cata di	4050	ES Original Bldg.		EAD	MAZAR Etailaka	F D	DO 000	\$20,400	0.000		#0.50	#04.000	#07.000	
Mora Combined School	1950	South Wing		FAD	Wall Finishes	FacRen	BS-SB9	\$29,199	6,000	ST	\$3.50	\$21,000	\$27,300	
		HS Commons			=						****	***	440.04	
Mora Combined School	2004	Addition			Wall Finishes		BS-SB9	2013: Clean & painted	1	FAD	\$33,113.00	\$33,113	\$43,047	
Mora Combined School	1991	HS Gym Addition			Wall Finishes		BS-SB9	\$7,285	6,000		\$3.50	\$21,000	\$27,300	
Mora Combined School	1991	HS Industrial Arts			Wall Finishes	FacRen	BS-SB9	Painted 2000. Clean and painted (2013)	1	FAD	\$14,771.00	\$14,771	\$19,202	
Mora Combined School	1968	HS Main Bldg.		FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$56,948.00	\$56,948	\$74,032	
		HS Original Const												
Mora Combined School	1974	(gym)			Wall Finishes		BS-SB9	Painted 2000	1	FAD	\$45,891.00	\$45,891	\$59,658	
Mora Combined School	1997	MS Main Bldg.			Wall Finishes		BS-SB9	Painted 2000		FAD	\$42,709.00	\$42,709	\$55,522	\$3,178,214
District Wide	1950	Campus Wide			Communications / Security	LHSS	L-GOB	Update intercom district wide	178,790	_	\$2.00	\$357,580	\$464,854	
District Wide	1950	Campus Wide		Dist.	Parking Lot	LHSS	L-GOB	Upgrade parking lots	1	ea.	\$750,000.00	\$750,000	\$975,000	
								Rework drain pipes from ES MS Gym to have one lift						
		ES MS Org. Gym /						station and repair/replace one lift station pump: it is					4	
District Wide	1950	Band, K-8		Dist.	Z-Site Utilities	LHSS	L-GOB	not working	1	ea.	\$55,000.00	\$55,000	\$71,500	\$1,511,354
Priority 2 Building / Site S	ystem Upgrade	s:										\$6,061,998	\$7,880,597	\$7,880,597
Priority 3 Capital Projects		1		Ta			Inc. o.s.	In				A · ·	# · · · · ·	
District Support	1950	HS		Dist.	Athletic Fields	AdqStd	BS-GOB	Redo track surface		ea.	\$150,000.00	\$150,000	\$195,000	
District Support	1950	HS			Athletic Fields		BS-GOB	Install sprinkler system in football field		ea.	\$85,000.00	\$85,000	\$110,500	
Mora Combined School	1970	Swimming Pool		Dist.	Repurpose	AdqStd	MP-GOB	Repurpose Swimming Pool	10,547	sf	\$150.00	\$1,582,050	\$2,056,665	\$2,362,165
I						1	1	Create Coffhall Field: Dietrict has a shared Boards !!						
District Comment	4050	110		D: .t	Add at a Cialda	l	MD 005	Create Softball Field: District has a shared Baseball-			#0F0 000 CO	# 050 000	6455 000	
District Support	1950	HS			Athletic Fields	LocPol	MP-GOB	Softball field only. Install site lighting at both fields.		ea.	\$350,000.00	\$350,000	\$455,000	
District Support	1950	HS			Athletic Fields	LocPol	MP-GOB	Athletic concessions & restrooms	1,200		\$350.00	\$420,000	\$546,000	
District Support	1950	HS			Site Lighting	LocPol	MP-GOB	Light Baseball Field		ea.	\$75,000.00	\$300,000	\$390,000	
District Support	1950	HS			Site Lighting	LocPol	MP-GOB	Light Softball Field		ea.	\$75,000.00	\$300,000	\$390,000	
Mora Combined School	1950	Martinez Gym			Renovation	LocPol	MP-GOB	Renovate Gym Locker/restrooms and Band	3,025		\$200.00	\$605,000	\$786,500	
Mora Combined School	1974	HS Gym		Dist.	Renovation	LocPol	MP-GOB	Renovate Restrooms and Lobby	2,500	sf	\$250.00	\$625,000	\$812,500	\$3,380,000
												¢4 447 050	¢E 742 465	\$5,742,165
Priority 3 Capital Projects:		<u></u>										\$4,417,050	\$5,742,165	Ψ3,7 4 2, 100

Mora Independent School District • 5-Year Facilities Master Plan GS Architecture • 2019

NEEDS BY CATEGORY

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Option 1														
School Reconfiguration	1950	ES: ES/MS Gym: Café: Admin: Maint		Dist.	Demolish	LocPol	MP-GOB	Demolish: ES; Admin; ES/MS Gym; Kitchen- Cafeteria: Maintenance	63,425	sf	\$25.00	\$1,585,625	\$2,061,313	
		ES: ES/MS Gym:						Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing, Cafeteria & Kitchen: Relocate MS into HS & ES into						
School Reconfiguration	1950	Café: Admin: Maint		Dist.	Replace	LocPol	MP-GOB	MS.	24,000	sf	\$300.00	\$7,200,000	\$9,360,000	\$11,421,3
Option 2	1	T 50/140 0					•	lo correction with the second		T.			ı	
District Support	1950	ES/MS Gym; Kitchen-Cafeteria; Maint		Dist.	Domolish	LocPol	MP-GOB	Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing, Cafeteria & Kitchen	20 240	of	¢25.00	¢705.450	\$917,085	
District Support	1950	ES/MS Gym; Kitchen-Cafeteria;		DISt.	Demolish	LOCPOI		Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing,	28,218	SI	\$25.00	\$705,450	\$917,085	
District Support	1950	Maint		Dist	Replace	LocPol	MP-GOB	Cafeteria & Kitchen	17 500	sf	\$300.00	\$5 250 000	\$6,825,000	\$7.742.08

3.3.1 PRIORITY CAPITAL IMPROVEMENTS FOR NEXT 5 YEARS

The Mora Independent School District (MISD) 2019-2023 prioritized list of facility needs was developed by the MISD Facilities Master Plan (FMP) advisory committee and adopted by the MISD School Board. The FMP advisory committee identified the facility needs throughout the district during the first committee meeting, discussed the facility needs and their impact on students and the district during the second committee meeting, and prioritized the facility needs during the third committee meeting. The 2019-2023 prioritized list of facility needs for Mora Independent School District is:

MISD FINAL FMP 2019-2023 PRIORITIES

FINAL					
Priority RANK	Priority Description	Funding Source	PSCOC/ PSFA Funding	Schedule	Total Project
1A	Life-Health-Safety-Security	SB-9	1	2019-23	\$250,000
1B	Maintenance/Preventive Maintenance	SB-9		2019-23	\$520,735
1C	Technology	SB-9	1	2019-23	\$250,000
	Priority 1 Subtotal:				\$1,020,735
2	Cabaal Building / Cita Custom Banawali				
2A	School Building / Site System Renewal: LHSS: Communications/Security: Districtwide	BS-GOB	2	2019-23	\$464,854
2B	·			2019-23	
2C	Roofs: Admin, LGMS LHSS: Site Utilities: ES/MS Gym, Lift Stations	BS-GOB BS-GOB	2	2019-23	\$348,699 \$71,500
2D	Plumbing/Water Treatment: MES, MHS, ES/MS Gym	BS-GOB	2	2019-24	\$705,250
2E	HVAC: MES, MHS, LGMS, Admin, ES/MS Gym, HS Gym	BS-GOB	2	2019-25	\$3,020,380
2F	Exterior Walls: MES, LGMS, ES/MS Gym, Admin	BS-GOB	2	2019-26	\$262,080
2G	Parking Lots: Districtwide	BS-GOB	2	2019-23	\$975,000
2H	Miscellaneous Building / Site System Renewals	BS-GOB	2	2019-23	\$2,032,835
	Priority 2 Subtotal:				\$7,880,597
3	Potential Capital Projects:				
3A	Restructure Mora Campus: See Option 1 and 2	GOB	3	2019	
3B	Repurpose Swimming Pool Building	GOB		2021	\$2,056,665
3C	HS Gym Lobby: Renovate concessions and restrooms	GOB	4	2021	\$812,500
3D	Maintenance Building: Replace & Demolish or Renovate (See priority 3A)	GOB		2022	-
3E	ES/MS Gym Restroom Renovation	GOB		2021	\$786,500
3F	New Athletic Event Restrooms and Concessions	GOB		2022	\$546,000
3G	Other Miscellaneous Projects	GOB		2023	\$1,540,500
	Priority 3 Subtotal:				\$5,742,165
	MISD 2019-2023 FMP Priorities TOTAL:				\$14,643,497
	Restructure Mora Campus: Demolish ES Gym,				Γ
	Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building;				
	move MS to HS Building		3		\$11,421,313
Option 1					
Option 1	Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance; build multi-purpose facility for gym, cafeteria/kitchen, band, training and				

The MISD priorities listed above reflect the facility mission and vision of the district to provide a safe, comfortable, stimulating learning environment to all of its students in efficient and effective facilities.

Priority 1, Recurring Needs

\$1,020,735

The first three lines of the above priorities are recurring items that the district has to address to avoid impact to its educational program. They are assigned a priority of 1A, 1B and 1C to indicate that these items will be addressed as needed and as funding is available. These items will be primarily funded through SB-9, GOB and E-rate.

1A: Immediate Life-Health-Safety-Security-Code-ADA Compliance needs will be addressed by the district with SB-9 and GOB funds as the needs arise and funding is available from 2019 to 2023. In 2018 PSCOC/PSFA accepted applications for funding security projects at schools throughout the state. Mora Independent School District applied for and received these funds for Mora Combined Campus security projects. Mora Independent School District will continue to align its security projects with PSCOC/PSFA standards and apply for funding as its schools qualify.

1B: Maintenance and preventive maintenance needs that will be addressed by the district with SB-9 funds as funding is available from 2019 to 2023. Mora Independent School District has worked with the Public Schools Facilities Authority (PSFA) to develop a preventive maintenance plan and is in the process of implementing the plan. Work identified through this plan will be accomplished with SB-9 funds that have the potential to eliminate deferred maintenance and could extend the life of existing building systems; however, limited funding and maintenance staff has made it difficult for MISD to fully implement preventive maintenance to its facilities, thus impacting the life of existing building systems.

1C: Technology needs is also a top priority at MISD. The district is working to update its technology infrastructure, equipment, and broadband width as needed to assure that its students are receiving a relevant educational program and are prepared for life after high school. The district currently uses E-rate and SB-9 funds to fund technology needs. The district partnered with the PSCOC Broadband initiative in 2018 to upgrade wireless access, switches, and a network router at Mora Campus. The district will continue to monitor its technology system and apply for PSCOC Broadband funds when it is appropriate and will benefit the district. Priority 1C will be funded with E-rate, and SB-9 funds from 2019 to 2023 as those funds become available.

Priority 2, Building and Site System Renewal Projects

\$7,880,597

This is a reflection of the district's dedication to maintaining its existing facilities. The building and site system renewal projects have been identified as a high priority because the majority of the MISD facilities have areas where these facility and site systems are past their useful life and have the potential to impact the school's mission. Mora Independent School District understands the importance of addressing the identified needs before they cause collateral damage. Each school was analyzed and physically inspected to identify the needs of the buildings. Mora Independent School District reviewed and updated the existing PSFA Facilities Assessment Database information to more accurately reflect the condition of each district school.

The top facility and site system renewal priorities for the 2019/2023 MISD capital plan are:

- A. Communications/Security Systems: Districtwide
- B. Roofs: Admin, LGMS
- C. Site Utilities: ES/MS Gym, Lift Stations
- D. Plumbing/Water Treatment: MES, MHS, ES/MS Gym
- E. HVAC: MES, MHS, LGMS, Admin, ES/MS Gym, HS Gym
- F. Exterior Walls: MES, LGMS, ES/MS Gym, HS Gym
- G. Parking Lots: Districtwide

Mora Independent School District has identified several buildings for demolition and replacement in Priority 3, capital projects. Prior to updating any building systems at the identified buildings, MISD will review and evaluate the necessity of updating a building system. The district does not want to update a system in a building scheduled for demolition unless not updating the system could impact the mission of the school. Priority 2 needs will be funded with a combination of SB-9 and GOB funds as they are available from 2019 to 2023. The district will continue to review FAD rankings and apply for PSCOC/PSFA funds for district schools that qualify for PSCOC facility and site system renewal projects during the life of this FMP.

Priority 3, Capital Projects.

\$5,742,165

The capital projects listed below are a reflection of the district's dedication to provide safe and secure learning environments for its students and to utilize existing facilities as efficiently and effectively as possible.

- A. Restructure Mora Campus
- B. Repurpose Swimming Pool Building
- C. Renovate HS Gym Lobby: Concessions and Restrooms
- D. Maintenance Building: Replace & Demolish or Renovate (See priority 1 & 2)
- E. Renovation of ES/MS Gym Restrooms
- F. Construction of Athletic Event Facility: Restrooms and Concessions

Priority 3: Capital Projects. The capital projects listed above are a reflection of the district's dedication to provide safe and secure learning environments for its students and to utilize existing facilities as efficiently and effectively as possible.

Capital project 3A refers to the restructure/reorganization of the Mora Campus. Two options were developed for the district's review and consideration. Option 1 is a complete restructure/reorganization of the Mora Campus including demolition of the following buildings: administration building; elementary school building; elementary/middle school gym, band and classroom building; kitchen and cafeteria building; and the maintenance building. The district would relocate elementary school students to the existing middle school building and relocate middle school students to the high school building, creating a 6th – 12th grade school. A new multi-purpose building would be constructed to house district administration, a gymnasium, music program, training program, testing program and the kitchen and cafeteria. Option 2 is a smaller scale capital project which provides limited restructure of the Mora Campus, but no reorganization of students.

3.3

Capital Plan

This option focuses on demolition of the elementary/middle school gym, band and classroom building, kitchen and cafeteria building and the maintenance building. A new multi-purpose building would be constructed to house a gymnasium, music program, training program, testing program and the kitchen and cafeteria. This option does not involve any relocation of students and keep the grade level organization of the schools the same. Option 1 is the preferred option; however, this is the more expensive option and the district has not determined how to fund this large scale capital project. Mora Independent School District will continue to work with its community and PSCOC/PSFA to determine the best way to move forward to an create efficient and effective campus for its students. Either option would mean a reduction of building systems replacements projects identified in priority 2 above.

Priority 3B is the Repurpose of the Swimming Pool Building. The District identified 3 options to address this priority. These options are: repurpose into maintenance building, repurpose into a high school shop program, or repurpose into a multi-purpose building that could be used by the community as well as the school. There was extensive discussion related to each of the options with the conclusion to keep all options open at this time and give MISD the opportunity to engage its community and PSCOC / PSFA to determine the best, long-term option for the students and MISD.

Priority 3C refers to the renovation of the HS gym lobby and restrooms which includes the concessions area located in the 1991 addition and restrooms located in the original 1974 gym building. The district realizes the need to bring these spaces up to current code which would increase the availability at public events to these spaces since the currently availability is extremely limited.

Priority D is directly related to priority 3, options A and B, and consists of options for the maintenance building. The maintenance building is an old facility with many of its systems past their useful life and unsafe for occupation. The district expressed their concern about the issues of this facility and discussed various options to address them. The options include demolition and replacement of the building or renovation of the building. Replacement of the building could mean a new building or relocation into an existing unused building on campus. Renovation of the existing structure appears to cost more than replacement of the building with a new structure. The district will further analyze the available options and decide which of the options is the most viable.

Priority 3E encompasses the renovation of the ES/MS Gym Restrooms. The restrooms are not ADA compliant due to the age of the building and could mean an addition to meet current code requirements.

Priority 3F refers to construction of an athletic event facility: restrooms and concessions which are expected to serve both football and baseball-softball fields.

Mora Independent School District would like to partner with it local community and PSCOC/PSFA on their priority 3 projects. Priority 3, capital projects will need to be funded with GOB and potentially PSCOC/PSFA funds as they are available from 2019 to 2023. Priority 3A Option 1 is

MISD's preferred reorganization/restructure of the Mora Campus; however, the district will need to work closely with its local community and PSCOC/PSFA to determine the best method to fund this project. The \$14,643,497 identified for capital projects does not reflect the probable cost of priority 3A, option 1 or 2. The \$14,643,497 reflects system upgrades to the buildings identified to be demolished in either option. Once the final option has been determined, the probable cost identified for that option has to be incorporated into the capital plan and the building system upgrades for demolished buildings deducted from the capital plan.

Facility Assessment Database

The Facilities Assessment Database (FAD) ranking of MISD educational facilities was shared with, reviewed by and discussed with MISD staff and the MISD FMP advisory committee throughout the FMP process. The condition of facilities and the FAD ranking was considered and became part of the criteria in the MISD FMP advisory committee's prioritization of the district's facility needs. The following FAD ranking was published April 18, 2018.

2018-2019 PSCOC/PSFA RANKING OF MISD Schools

MISD PSFA Facilities Assessment Database (FAD)

School	2018-19 Rank	Weighted NMCI
Holman ES	480	17.82%
Mora Combined School (ES/MS/HS)	73	41.34%

STATE PARTICIPATION IN APPROVED PROJECTS: 32% DISTRICT PARTICIPATION IN APPROVED PROJECTS: 68%

Due to the current FAD ranking of MISD schools, the district could anticipate partnering with PSCOC/PSFA to obtain funding for facility and site system renewal projects and the restructure/reorganization of Mora Campus during the life of this FMP. Mora Independent School District has aligned its priorities with the FAD and will continue to work with PSCOC/PSFA, monitor the FAD rankings, funding procedures, and apply for funding as district schools become eligible.

Facilities Assessment Database (FAD) / Facilities Maintenance Assessment Report (FMAR)

A change in how PSCOC/PSFA can fund a public school capital project was implemented for the 2017/2018 funding process and is now a permanent part of the PSCOC/PSFA funding cycle. PSCOC/PSFA is now funding facility and site system renewal projects and the complete renovation or replacement of a school, depending on the FAD ranking and condition of the school. The facility and site system renewal projects will benefit schools by creating smaller projects thus reducing their share of a PSCOC/PSFA approved project. PSFA has generated a FAD/FMAR report that identifies all of the potential facility and site systems in each school that could be eligible for this funding source. This list of needs was incorporated into the district's overall needs spreadsheet.

In February 2018 the State passed Senate Bill 30 (SB30) which will replace the current state and local match formula in the Public School Capital Outlay Act (PSCOA) for capital outlay awards that the district may pursue. This formula will be implemented over a five year period starting in 2019.

According to the SB30 description, the new formula "adjusts the state and local match to more accurately reflect each school district's ability to pay for public school capital outlay projects. The current calculation is based on the net taxable value for a school district and the number of students enrolled during the immediately preceding year. The new calculation is based on the net taxable value for a school district for the prior five years, the maximum allowable gross square foot per student, the replacement cost per square foot, and the school district population density."

The gradual change in the district and state match is shown in the following table. At the end of the five year implementation period, the state match for MISD will increase to 37 percent and the local match will decrease to 63 percent. This is a gain of five percent in the state's match for MISD.

MISD Change in State/Local Share Five Year Phase

Phase	Local Match	State Match
Phase 1 2017-18	65%	35%
Phase Year 1 (FY 20)	65%	35%
Phase Year 2 (FY 21)	64%	36%
Phase Year 3 (FY 22)	64%	36%
Phase Year 4 (FY 23)	64%	36%
Phase Year 5 Final (FY 24)	63%	37%

2024 STATE SHARE OF AN APPROVED PROJECT: 37% DISTRICT SHARE OF AN APPROVED PROJECT: 63%

The FAD and FMAR reports were reviewed by district administration and the maintenance staff three times during the FMP process. Most schools within MISD have a large portion of building systems that are beyond expected life or are potential mission impact/degraded. The building systems identified in the FAD and FMAR reports are listed in the district's facility needs and capital plan.

Adoption of FMP District Priorities and Capital Plan

The district priorities were reviewed by the MISD School Board of Education on October 16, 2018 and the final FMP document was adopted on April 16, 2019.

3.3.2 MORA INDEPENDENT SCHOOL DISTRICT FINANCIAL STRATEGIES AND ALTERNATIVES

At the conclusion of the 2019-2023 Facilities Master Plan process, priorities were identified and a capital plan was generated that will address the critical needs of MISD for the next five years and

in to the foreseeable future. This is a living document that can and should be reviewed yearly and modified as necessary to reflect the direction of the district.

The district has had the continued support of its local community for SB-9 funds, but it has not held a successful GOB election since 2005. The SB-9 funds have allowed MISD to keep its facilities safe and comfortable for its students and staff; however, there are several major building systems that are in need of renewal before they impact the mission of the district and these systems could require GOB funding. The district is working on its relationship with the local community and will continue to do so until it can hold a successful GOB election.

Unfortunately, there are significantly more capital needs at \$14,643,497, than there are available capital funds. Mora Independent School District has spent the past few months developing their FMP plan, knowing that there would not be enough capital funds to address all of its priority projects. The district anticipates its next GOB election in 2020 for approximately \$3,000,000. Mora Independent School District receives approximately \$204,147 in SB-9 funds to address Life-Health-Safety-Security-ADA-Code and maintenance issues. The district anticipates the next SB-9 election for May 2019. These combined funding sources will provide MISD approximately \$4,020,735 to address its identified \$14,643,497 in facility needs. As these funds become available, MISD will use them and partner with PSCOC/PSFA on qualifying schools to begin addressing the district's most critical needs and the larger capital plan projects. Mora Independent School District has focused on addressing facility and site system renewal projects at all of its schools and focusing on one capital project at a time as funds are available. The district will continue this strategy and use the majority of its 2020 GOB funds to address the capital needs as identified in the above priorities list.

The district has received \$240,000 of direct appropriations from the legislature since 2011. Those funds are not guaranteed, are usually identified for a specific need and will be deducted from any future PSCOC award. With the current state and local match for PSCOC funds it is not beneficial to MISD to seek direct legislative appropriations. The district will continue to seek available funding from various sources.

The MISD community passed a SB-9 election in 2013 which was used to fund life-health-safety-security, general maintenance and preventive maintenance issues. In May 2019 MISD will ask its community to support another SB-9 election to continue funding its life-health-safety-security, general maintenance and preventive maintenance issues.

Mora Independent School District applies for and receives E-rate funding which is applied to technology needs.

Mora Independent School District has not asked its local community to support HB-33 funds and does not anticipate asking for these funds during the life of this FMP.

3.3.3 CAPITAL PLAN

The following pages contain the MISD capital plan and the associated, detailed spreadsheet providing funding information on the projects listed in the capital plan developed to meet the

needs of the district. The capital plan has been developed with the understanding that it is a living document and has flexibility. It is understood that the priorities recommended by the MISD FMP advisory committee to the MISD School Board will be addressed as funding becomes available and will not necessarily be accomplished in the order listed. Other identified district needs may be addressed prior to addressing all of the recommended priorities. Due to the lack of GOB funds at this time, MISD did not established a firm schedule to accomplish its priorities and capital projects in the FMP.

Following the MISD capital plan is an associated spreadsheet with all identified needs sorted by facility then funding source. The following legend will aid in understanding the funding source categories:

Funding Source Legend:

The total 2019/2023 facilities needs have been broken down into eight project types and corresponding funding sources. The eight project types and corresponding funding sources are:

BS-GOB: Building Systems anticipating GOB funding

BS-SB9: Building Systems anticipating SB-9 funding

LHSS-SB9: Life-Health-Safety-Security-Code projects anticipating SB-9 funding

LHSS-GOB: Life-Health-Safety-Security-Code projects anticipating GOB funding

MISC-GOB: Miscellaneous projects anticipating GOB funding

MISC-SB9: Miscellaneous projects anticipating SB-9 funding

PreMaint: Preventive Maintenance projects anticipating SB-9 funding

Tech: Technology projects anticipating E-rate and SB-9 funding

The following table provides a summary of these funding needs.

MISD Project Cost by Funding Source

Project Type	Funding Source	Total Projects Cost	Percentage of Total
Building Systems Upgrades	GOB	\$5,958,111	41%
Building Systems Upgrades	SB-9	\$716,633	5%
Life/Health/Safety/Security/Code Issues	GOB	\$1,511,354	10%
Life/Health/Safety/Security/Code Issues	SB-9	\$250,000	2%
Miscellaneous Projects	GOB	\$5,436,665	37%
Miscellaneous Projects	SB-9	\$0	0%
Preventive Maintenance	SB-9	\$520,735	4%
Technology	GOB & E-Rate	\$250,000	2%
DI	STRICT TOTALS	\$14,643,497	100%

Refer to the following pages for the Mora Independent School District's Capital Plan.

District Priority	Category	Project	Plan Year	GO Bonds	HB33	SB9	Other	Pr	oposed State Share	Total F	Project Cost	Percent Total	State Funding Assistance Priority	District Stat Share Shar	
Holman ES				1											
1A	L/H/S	Life/Health/Safety Issues-GOB	2019-23	\$0				\$	-	\$	-	0%		100%	0%
1A	L/H/S	Life/Health/Safety Issues-SB-9	2019-23			\$.		\$	-	\$	-	0%		100%	0%
1C	EdPro	Technology	2019-23			\$ -				\$	-	0%	1		0%
1B	PreMaint	Preventive Maintenance	2019-23				\$	-		\$	-	0%		65% 3	35%
2	FacRen	Building Systems Upgrades-GOB	2019	\$20,614				\$	11,100	\$	31,714	50%	5	65% 3	35%
2	FacRen	Building Systems Upgrades-SB-9	2019			\$ 20,61	4	\$	11,100	\$	31,714	50%	5	65% 3	85%
	FacRen	Miscellaneous Projects - GOB	2019	\$0				\$	-	\$	-	0%			0%
	FacRen	Miscellaneous Projects - SB-9				\$ -		\$	-	\$	-	0%		100%	0%
	Total			\$ 20,614	\$ -	\$ 20,61	4 \$	- \$	22,199	\$	63,427	100%			
Mora Combin 1A 1A 1C 1B 2 2 3C, 3E	L/H/S L/H/S EdPro PreMaint FacRen FacRen FacRen FacRen	Life/Health/Safety Issues-GOB Life/Health/Safety Issues-SB-9 Technology Preventive Maintenance Building Systems Upgrades-GOB Building Systems Upgrades-SB-9 Miscellaneous Projects-GOB Miscellaneous Projects-SB-9	2019-23 2019-23 2019-23 2019-23 2019 2019 2019	\$3,653,583 \$3,655,665		\$ 445,19	\$	\$ \$ - \$ \$ \$	1,967,314 239,722 -	\$ \$ \$ \$ \$ \$	5,620,897 684,919 3,655,665	0% 0% 0% 0% 56% 7% 37% 0%	1 3 3	100% 100% 65% 3: 65% 3: 100%	0% 0% 0% 85% 85% 0%
	Total			\$ 7,309,248	\$ -	\$ 445,1	98 \$	- \$	2,207,036	\$	9,961,481	100%			
Mora District	vide]											
1A	L/H/S	Life/Health/Safety Issues-GOB	2019-23	\$1,511,354				\$		\$	1,511,354	2383%		100%	0%
1A	L/H/S	Life/Health/Safety Issues-SB-9	2019-23			\$ 250,00	0	\$	-	\$	250,000	394%		100%	0%
1C	EdPro	Technology	2019-23			\$ 250,00	0			\$	250,000	394%	1	100%	0%
1B	PreMaint	Preventive Maintenance	2019-23				\$ 520,7	35		\$	520,735	821%		65% 3	35%
	FacRen	Building Systems Upgrades-GOB	2019	\$0				\$	-	\$	_	0%	5	65% 3.	85%
	FacRen	Building Systems Upgrades-SB-9	2019			\$.		\$	-	\$	-	0%	5		35%
	FacRen	Miscellaneous Projects - GOB	2019	\$0				\$	-	\$	-	0%			0%
	FacRen	Miscellaneous Projects - SB-9				\$ -		\$	-	\$	-	0%			0%
	Total			\$ 1,511,354	\$ -	\$ 500,00	0 \$ 520,73	35 \$	-	\$	2,532,089	3992%			

District Priority Mora District A	Category Administration and S	Project	Plan Year	GO Bonds	HB33	S	5B9		Other	Proposed Stat Share		ital Project Cost	Percent Total	State Funding Assistance Priority	District Share	State Share
1A	L/H/S	Life/Health/Safety Issues-GOB	2019-23	\$0						\$.			0%		100%	0%
1A	L/H/S	Life/Health/Safety Issues-SB-9	2019-23	, , , , , , , , , , , , , , , , , , ,		\$	_			<u>\$</u> \$.			0%		100%	0%
1C	EdPro	Technology	2019-23			Ś				· ·	Ş		0%	1	100%	0%
1B	PreMaint	Preventive Maintenance	2019-23			+		\$	_		Š		0%		65%	35%
2	FacRen	Building Systems Upgrades-GOB	2019	\$198,575				7		\$ 106,92		305,500			65%	35%
	FacRen	Building Systems Upgrades-SB-9	2019	7130,373		Ś	_			\$ 100,52	-		0%	3	65%	35%
3A, 3B, 3D, 3F	FacRen	Miscellaneous Projects-GOB	2019	\$1,781,000		-				<u>\$</u>		1,781,000	85%		100%	0%
371, 30, 30, 31	FacRen	Miscellaneous Projects-SB-9	2013	71,701,000		Ś	-			<u>\$</u>			0%		100%	0%
	Total			\$ 1,979,575	Ś	- \$	-	\$	-	\$ 106,9		2,086,500				
]	Grand Total: Grand Total:	DISTRICT SUPPORT AND DISTRICTWIDE		\$ 7,329,862 \$ 3,490,929		\$	465,811 500,000		520,735	\$ 2,229,23 \$ 106,92		10,024,908 4,618,589				
I	Grand Total:	DISTRICT FACILITIES		\$ 10,820,791	\$ -	\$	965,811	\$	520,735	\$ 2,336,16	50 \$	14,643,497				
	CAPITAL PLAN OP	Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance, Administration, ES; build multi-purpose facility; move ES to MS Building; move MS to HS Building										\$11,421,313		3	65%	35%
	Option 2	Restructure Mora Campus: Demolish ES Gym, Kitchen-Cafeteria, Maintenance; build multi- purpose facility for gym, cafeteria/kitchen, band, training and testing										\$7,742,085		3	65%	35%

							Funding						TOTAL	
FACILITY NAME	AREA-Year	AREA		Identified By	SYSTEM	CATEGORY	Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
Priority 1 Life-Health-Safe	ty-Security / Ma	aintenance / Techno	logy:			T								
								Ceramic tile in this area \$58,787: Replace cracked						
		LIC Commons						ceramic tile in commons area and at north entrance						
Mora Combined School	2004	HS Commons Addition		EAD	Floor Finishes	FooBon	BS-GOB	of building and Replace / Repair buckled VCT in conference room and music room		of	00 00	¢ι	\$0	
Mora Combined School	2004	Addition		FAD	FIOOI FIIIISHES	FacRen	BS-GOB	Original \$31,041: Replace cracked VCT in lobby		SI	\$0.00	\$0	φυ	
Mora Combined School	1991	HS Gym Addition		FAD	Floor Finishes	FacRen	BS-GOB	area		ef	\$0.00	\$0	\$0	
INGIA COMBINEA CONCO	1001	110 Cym 7 tadition		IAD	Tiodi i illiono	racitori	Во-оов	urou		31	ψ0.00	Ψ	ΨΟ	
								Original \$101,101: Replace cracked VCT in						
Mora Combined School	1968	HS Main Bldg.		FAD	Floor Finishes	FacRen	BS-GOB	computer lab 112 and at entrance of classroom 109		sf	\$0.00	\$0	\$0	
		HES Original									,	,	* -	
Holman ES	1969	Const		FAD	Drain, Waste and Vent	LHSS	L-GOB	\$24.55	1	FAD	\$0.00	\$0	\$0	
								Replace exit classroom doors to ADA compliant,						
Holman ES	1987	HES Addition		FAD	Exterior Doors	LHSS	L-GOB	\$14,098	1	FAD	\$0.00	\$0	\$0	
		HES Original												
Holman ES	1969	Const			Water Distribution	LHSS	L-GOB	\$24,554		FAD	\$0.00	\$0		
Holman ES	1969	HES Site			Z-Fencing	LHSS	L-GOB	Upgrade playground fencing : 2018 In Progress		lf		\$0		
Holman ES	1969	HES Site			Z-Fencing	LHSS	L-GOB	Repair perimeter fencing: 2018 In Progress		lf	***	\$0		
Holman ES	1969	HES Site		FAD	Z-Parking Lots	LHSS	L-GOB	Beyond expected life by aging \$76,509		FAD	\$0.00	\$0	\$0	
Halman FC	4000	UEC C:4-		Di-4	7 Davidson Late	11100	LCOD	Redesign Pick-Up/Drop-Off area to separate bus and			#0.00	φc	.	
Holman ES	1969 1969	HES Site HES Site			Z-Parking Lots	LHSS LHSS	L-GOB	parent traffic	1	ea.	\$0.00	\$0 \$0		
Holman ES	1969	HES SILE		Dist.	Z-Site Lighting	LHSS	L-GOB	Install site lighting		ea.	\$0.00	\$ι	\$0	
								Create an evacuation route in the back of building.						
Holman ES	2006	HES Addition		Dist.	Z-Walkways	LHSS	L-GOB	There is only evacuation route in the front.	1	ea.	\$0.00	\$0	\$0	
Holman ES	1969	HES Site			Z-Walkways	LHSS	L-GOB	Replace walkways	300		\$0.00	\$C		
Homan Eo	1000	HS Original Const		Diot.	2 Walkways	LITOU	L 00B	Nopiace waitways		, 51	ψ0.00	Ψ	ΨΟ	
Mora Combined School	1974	(gym)		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$24,249		ea	\$0.00	\$0	\$0	
Mora Combined School	1968	HS Main Bldg.			Communications / Security	LHSS	L-GOB	DCU 03-019 \$27,677: Updated 2003		ea.	\$0.00	\$0	7 -	
Mora Combined School	1991	HS Industrial Arts			Communications / Security	LHSS	L-GOB	Intercom installed. DCU 03-019 \$7,805		ea.	\$0.00	\$0		
Mora Combined School	1991	HS Gym Addition		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$3,850		ea.	\$0.00	\$0	\$0	
		HS Commons			•									
Mora Combined School	2004	Addition		FAD	Communications / Security	LHSS	L-GOB	\$17,498		ea.	\$0.00	\$0	\$0	
		ES Original Bldg.						\$15,429: Replace bell system: current system does						
Mora Combined School	1950	South Wing		FAD	Communications / Security	LHSS	L-GOB	not work		ea.	\$0.00	\$0	\$0	
		ES Original Bldg.						\$13,488: Include replacement of bell system: current						
Mora Combined School	1950	North Wing		FAD	Communications / Security	LHSS	L-GOB	system does not work		ea.	\$0.00	\$0	\$0	
Mana Canakina d Cabaal	4050	ES MS Org. Gym /		EAD	Communications / Committee			DOLL 02 040 040 770			#0.00	Φ.	.	
Mora Combined School	1950	Band, K-8		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$18,776		ea.	\$0.00	\$0	\$0	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	Communications / Security	LHSS	L-GOB	DCU 03-019 \$22.568		00	\$0.00	\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12			Communications / Security	LHSS	L-GOB	DCU 03-123 \$6,971: No intercom		ea.	\$0.00	\$0		
Mora Combined Concor	1303	ES Library Phase 3		IAD	Communications / Occurry	LITOO	L-00B	DOC 00-120 ψ0,071. No Intercent		ca.	ψ0.00	Ψ	ΨΟ	
Mora Combined School	2001	Const		FAD	Communications / Security	LHSS	L-GOB	\$4,427		ea.	\$0.00	\$0	\$0	
		.						\$12,649 Comm is original: Working but need to			70.00		7.0	
Mora Combined School	1995	Admin/Kinder		FAD	Communications / Security	LHSS	L-GOB	upgrade		sf	\$0.00	\$0	\$0	
					•									
Mora Combined School	1995	Admin/Kinder		FAD	Emergency Light and Power	LHSS	L-GOB	\$2,830		sf	\$0.00	\$0	\$0	
		, , , , , , , , , , , , , , , , , , , ,			g	1	1	Doors on the main gym sticking and hard to open:			\$3.30	Ψ	Ψ	
		HS Original Const						Possible safety problem with exiting the building						
Mora Combined School	1974	(gym)		FAD	Exterior Windows & Doors	LHSS	L-GOB	\$472,155		ea.	\$0.00	\$0	\$0	
		ES Original Bldg.						Exterior doors sticking and hard to open: Possible						
Mora Combined School	1950	South Wing		FAD	Exterior Windows & Doors	LHSS	L-GOB	safety hazard in need of service \$180,251		ea.	\$0.00	\$0	\$0	
								Upgraded 1998 only in custodian area \$22,568:						
Mora Combined School	1997	MS Main Bldg.		FAD	Fire Detection/Alarm	LHSS	L-GOB	Updated 2017	C	sf	\$0.00	\$0	\$0	
	40-4	HS Original Const		- 4 5	Fire Data at 101			DOLLOG 040 #04 040 11 11 10040						
Mora Combined School	1974	(gym)		FAD	Fire Detection/Alarm	LHSS	L-GOB	DCU 03-019 \$24,249: Updated 2018		sf	\$0.00	\$0	\$0	

Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0 MMSFMO recomm. compl. syst. Pressure problematic \$30,713 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB Problematic \$30,713 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 LHSS L-GOB Fire Sprinkler LHSS L-GOB This is required \$11,079 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$
FACILITY NAME ARRA-Year ARRA ROM Identified By SYSTEM CATEGORY Source FACILITY NEEDS QTY UNIT COST/UNIT MACC PROJECT CO	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$
Mora Combined School 1988	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$
Mora Combined School 1988	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1991 HS Industrial Arts FAD Fire Detection/Alarm LHSS L-GOB Fire alarm system installed. DCU 03-019 \$7,805 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1991 HS Gym Addition FAD Fire Detection/Alarm LHSS L-GOB DCU 03-019 \$3,850 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 2004 Addition FAD Fire Detection/Alarm LHSS L-GOB \$17,498 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 ES Original Bildg South Wing FAD Fire Detection/Alarm LHSS L-GOB \$15.426 \$f\$ \$5.000 \$0.0000 \$0.000 \$0.000 \$0.000 \$0.000 \$0.000 \$0.000 \$0.000 \$0.	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 South Wing FAD Fire Detection/Alarm LHSS L-GOB \$15.429 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 Roft Wing FAD Fire Detection/Alarm LHSS L-GOB LHSS L	\$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 North Wing FAD Fire Detection/Alarm LHSS L-GOB S13,488 ea. \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 ES MS Org. Gym/ Band, K-8 FAD Fire Detection/Alarm LHSS L-GOB DCU 03-019 \$18,776 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1950 Band, K-8 FAD Fire Detection/Alarm LHSS L-GOB DCU 03-019 \$18,776 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 2001 ES Library Phase 3 Const FAD Fire Detection/Alarm LHSS L-GOB Completed Dec 2001 \$4,427 sf \$0.00 \$0	\$0 \$0 \$0 \$0 \$0 \$0
Mora Combined School 1965	\$0 \$0 \$0 \$0 \$0
Mora Combined School 1965 Cafeteria, K-12 FAD Fire Detection/Alarm LHSS L-GOB DCU 03-019 \$6,971 sf \$0.00 \$0 Mora Combined School 1995 Admin/Kinder FAD Fire Detection/Alarm LHSS L-GOB \$12,649: Updated 2018 0 ea. \$0.00 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0 Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB NMSFMO recomm. compl. syst. Pressure problematic, soly in the custodian area \$79,391: ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB NMSFMO recomm. compl. syst. Pressure problematic, soly in the custodian area \$79,391: ea. \$0.00 \$0 Mora Combined School <	\$0 \$0 \$0 \$0 \$0
Mora Combined School 1995 Admin/Kinder FAD Fire Detection/Alarm LHSS L-GOB \$12,649: Updated 2018 0 ea. \$0.00 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic, 30,713 ea. \$0.00 \$0 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8	\$0 \$0 \$0
Mora Combined School 1995 Admin/Kinder FAD Fire Detection/Alarm LHSS L-GOB \$12,649: Updated 2018 0 ea. \$0.00 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic, 30,713 ea. \$0.00 \$0 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	\$0 \$0 \$0
Mora Combined School 1995 Admin/Kinder FAD Fire Detection/Alarm LHSS L-GOB \$12,649: Updated 2018 0 ea. \$0.00 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic, 30,713 ea. \$0.00 \$0 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	\$0 \$0 \$0
Mora Combined School 1997 MS Main Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0 MMSFMO recomm. compl. syst. Pressure problematic, only in the custodian area \$79,391: FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic \$30,713 ea. \$0.00 \$0 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB Mot needed per UBC and repl. corridor dots/hardware \$49,537 ea. \$0.00 \$0	\$0 \$0
Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic, only in the custodian area \$79,391: BY Commons HS Commons HS Commons Addition FAD Fire Sprinkler LHSS L-GOB Problematic \$30,713 ea. \$0.00 \$0 Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 North Wing Dist. FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 North Wing PAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 North Wing PAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	\$0
Mora Combined School 1968 HS Main Bldg. FAD Fire Sprinkler LHSS L-GOB Fully functional ea. \$0.00 \$0 Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic \$30,713 ea. \$0.00 \$0 HS Commons HS Commons Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1ea. \$0.00 \$0 Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Not needed per UBC and repl. corridor ea. \$0.00 \$0 Solution School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 Solution School \$0.00 \$0 North Wing Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 Solution School \$0.00 \$0 North Wing Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 Solution School \$0.00 \$0 North Wing Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0 Solution School \$0.00 \$0 North Wing Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537	\$0
Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic \$30,713 ea. \$0.00 \$0 HS Commons HS Commons Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1ea. \$0.00 \$0 ES Original Bldg. North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 ES MS Org. Gym / Not needed per UBC and repl. corridor Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	\$0
Mora Combined School 1991 HS Gym Addition FAD Fire Sprinkler LHSS L-GOB problematic \$30,713 ea. \$0.00 \$0 HS Commons HS Commons Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1ea. \$0.00 \$0 ES Original Bldg. North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 ES MS Org. Gym / Not needed per UBC and repl. corridor doors/hardware \$49,537 ea. \$0.00 \$0	
HS Commons Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 ES Original Bldg. North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered Not needed per UBC and repl. corridor Band, K-8 FAD Fire Sprinkler LHSS L-GOB Building is not sprinklered Not needed per UBC and repl. corridor doors/hardware \$49,537 ea. \$0.00 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School 2004 Addition FAD Fire Sprinkler LHSS L-GOB This is required \$11,079 1 ea. \$0.00 \$0 ES Original Bldg. Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 ES MS Org. Gym / Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	,0
ES Original Bldg. Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 \$0 \$0 \$0 \$0 \$0	
Mora Combined School 1950 North Wing Dist. Fire Sprinkler LHSS L-GOB Building is not sprinklered ea. \$0.00 \$0 ES MS Org. Gym / Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0)U
ES MS Org. Gym / Not needed per UBC and repl. corridor Not needed per UBC and repl. corridor ea. \$0.00 \$0	\$0
Mora Combined School 1950 Band, K-8 FAD Fire Sprinkler LHSS L-GOB doors/hardware \$49,537 ea. \$0.00 \$0	50
	\$0
HS Original Const	
Mora Combined School 1974 (gym) FAD Main Power/Emergency LHSS L-GOB Original \$16,277 sf \$0.00 \$0	\$0
ES MS Org. Gym /	
Mora Combined School 1950 Band, K-8 FAD Main Power/Emergency LHSS L-GOB Replaced 1984 \$12,603 sf \$0.00 \$0	\$0
HS Original Const	
Mora Combined School 1974 (gym) Dist. Plumbing LHSS L-GOB Upgrade Men's bathroom to ADA complaint sf \$0	\$0
ES Original Bldg.	*
Mora Combined School 1950 South Wing Dist. Plumbing LHSS L-GOB Upgrade drinking fountain alcove to ADA complaint ea. \$0	\$0
causing damage to exterior walls on the building	
Mora Combined School 1950 MCS Site FAD Z-Landscaping LHSS L-GOB \$524,513 sf \$0.00 \$0	\$0
ES MS Org. Gym / Correct drainage on west side of building outside the	,,,
Mora Combined School 1950 Band, K-8 Dist. Z-Landscaping / Drainage LHSS L-GOB band room: water filters through the doors ea. \$0	\$0
Area in poor condition in need of repair due to	
deterioration and poor drainage around the complex	
\$1,180,660: District repaved entrance and HS	
Mora Combined School 1950 MCS Site FAD Z-Parking Lots LHSS L-GOB parking lot in 2017 sf \$0.00 \$0	\$0
Mora Combined School 1950 MCS Site Dist. Z-Site Lighting LHSS L-GOB Repair / replace wall pack lights on Main HS Building sf \$0.00 \$0	\$0
Mora Combined School 1968 HS Main Bldg. Dist. Z-Site Lighting LHSS L-GOB Install site lighting: there is no lighting in this area sf \$0 Repair / replace one lift station pump: it is not	\$0
Mora Combined School 1950 MCS Site Dist. Z-Site Utilities LHSS L-GOB working sf \$0.00 \$0	\$0
ES MS Org. Gym /	~
Mora Combined School 1950 Band, K-8 Dist. Z-Site Utilities LHSS L-GOB station.	\$0
Walkways in poor condition due to cracks,	
deterioration and missing concrete. Possible tripping	
Mora Combined School 1950 MCS Site FAD Z-Walkways LHSS L-GOB hazards \$1,459,949 sf \$0.00 \$0	4.2
ES Original Bldg. Repair sidewalk and ramp at south entrance of	\$0
Mora Combined School 1950 South Wing Dist. Z-Walkways LHSS L-GOB building sf \$0	\$0 \$0

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	OTV	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
FACILITY NAME	AREA-Tear	ES MS Org. Gym /	ROUM	identified by	SYSTEM	CATEGORT	Source	FACILITY NEEDS	QTY	UNII	COST/UNIT	WACC		SUBTUTALS
Mora Combined School	1950	Band. K-8		Dist.	Z-Walkways	LHSS	L-GOB	Repair sidewalk in north side of building		sf		\$0	0.2	
Mora Combined School	1965	Cafeteria, K-12			Z-Walkways	LHSS	L-GOB	Repair sidewalk in north side of building Repair sidewalk next to the cafeteria		sf		\$C		
Wora Combined School	1905	Caletella, K-12		DISt.	Life-Health-Safety-Security-	LIIOO	L-GOB	Repair sidewark flext to the careteria		51		φι	φυ	
District Wide					ADA-Code	LHSS	L-SB9	Address life-health-safety-security issues	5	vr	\$50,000	\$250.000	\$250,000	\$250,00
Holman ES	2006	HES Addition		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Replace broken front window	<u> </u>	<i>y</i>	\$30,000	+,		
Holman ES	2006			DIST.	Exterior Windows & Doors	LHSS	L-SB9			ea.		\$0	\$0	
Mana Canabin ad Cabaal	0004	ES Library Phase 3		EAD	Fatanian Windows & Danie			Exterior doors sticking and hard to open: Possible			00.00	Φ.		
Mora Combined School	2001	Const		FAD	Exterior Windows & Doors	LHSS	L-SB9	safety hazard in need of service \$48,849		ea.	\$0.00	\$0	'	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Update north exit door to ADA complaint		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Exterior Windows & Doors	LHSS	L-SB9	Repair window in computer lab 103: it does not lock		ea.		\$0	\$0	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		Dist.	Institutional Equipment	LHSS	L-SB9	Replace wall pads		ea.		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	North Wing		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage in all areas		ea.		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	South Wing		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage in all areas		ea.		\$0	\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	LHSS	L-SB9	Install ADA signage		ea.		\$0		
District Wide		me mam brag.		Dist.	Maintenance	PreVent	Prevent	Preventive and Regular Maintenance needs	5	vr.	\$104.147.00	\$520.735	\$520,735	\$520,73
Holman ES	1987	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in corridor		sf	Ψ104,147.00	\$0		Ψ020,70
Hollian ES	1907	TIES Addition		Dist.	Celling I inishes	i ieveni	i ievent	Replace / repair stained ceiling tiles in library's exit		31		Ψ	φυ	
Holman ES	1995	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	and in office area		00		\$0	\$0	
										ea. sf				
Holman ES	2006	HES Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Repair ceiling tiles; ceiling bubble in kitchen		SI		\$0	\$0	
50	4000	HES Original		D	0 "	5	D 1/ /			١,		•		
Holman ES	1969	Const		Dist.	Ceiling Finishes	PreVent	PreVent	Replace / repair stained ceiling tiles in corridor		sf		\$0	\$0	
		HES Original												
Holman ES	1969	Const		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair water damage in sill at director's office		sf		\$0		
Holman ES	1987	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Replace / repair cracked VCT in corridor		sf		\$0		
Holman ES	1995	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Repair carpet snag in nurse's office		ea.		\$0	\$0	
Holman ES	2006	HES Addition		Dist.	Floor Finishes	PreVent	PreVent	Repair / replace cracked VCT outside girls restroom		sf		\$0	\$0	
		HES Original												
Holman ES	1969	Const		Dist.	Institutional Equipment	PreVent	PreVent	Repair plastic laminate in reception		ea.		\$0	\$0	
Mora Combined School	1950	Admin/Kinder		Dist.	Ceiling Finishes	PreVent	Prevent	Repair stained ceiling in storage room 117		sf		\$0	\$0	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in kitchen room		sf		\$0		
Mora Combined Concer	1000	ES MS Org. Gym /		Diot.	Joanning : milerious	1 10 7 0111	i iovone	Repair / replace stained ceiling tiles in boys and girls		O.		Ψ	,	
Mora Combined School	1950	Band. K-8		Dist.	Ceiling Finishes	PreVent	PreVent	showers		sf		\$0	\$0	
Mora Combined School	1930	ES MS Org. Gym /		Dist.	Celling Fillishes	i ieveni	i ievent	Repair / replace stained ceiling tiles in band room		31		Ψ	φυ	
Mora Combined School	1950	Band, K-8		Dist.	Ceiling Finishes	PreVent	Dro\/ont	and in classroom 148		sf		\$0	\$0	
Mora Combined School	1930			DIST.	Celling Finishes	Fieveill	PreVent	and in classicom 146		51		φι	φυ	
Mana Canalian ad Calcad	4050	ES MS Org. Gym /		D:-4	O silita a Finish a s	Durakt	D) / t	Donais (and a section of a sitter with a factor of a section of				0.0	\$0	
Mora Combined School	1950	Band, K-8		Dist.	Ceiling Finishes	PreVent	PreVent	Repair / replace stained ceiling tiles in janitor's closet		sf		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	North Wing		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
		ES Original Bldg.												
Mora Combined School	1950	South Wing		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at both ends of school		sf		\$0	\$0	
		HS Commons												
Mora Combined School	2004	Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in library		sf		\$0	\$0	
Mora Combined School	1991	HS Gym Addition		Dist.	Ceiling Finishes	PreVent	PreVent	Replace stained ceiling tiles in storage room		sf		\$0	\$0	
					<u> </u>			Replace stained ceiling tiles in teacher's lounge,				·		
Mora Combined School	1968	HS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	conference room and in storage room 117		sf		\$0	\$0	
			125, 120, 115,					Replace stained ceiling tiles in science labs and				**	7.0	
Mora Combined School	1968	HS Main Bldg.	137, 108	Dist.	Ceiling Finishes	PreVent	PreVent	classrooms		sf		\$0	\$0	
Micra Combined Concor	1000	HS Original Const	101, 100	Diot.	Coming Timeries	1 10 7 0111	riovone	Replace stained ceiling tiles in room next to girls		<u> </u>		Ψ	, ψο	
Mora Combined School	1974	(gym)		Dist.	Ceiling Finishes	PreVent	PreVent	lockers		sf		\$0	\$0	
iviora Combined School	1974	(9)111)	103, 107, 112,	טוסו.	Coming i iniones	i ievelit	ı ievelil	IOOKOTO		31		φC	φυ	
				1		1		Deplete / repair stained as illian tilen in places						
	460-	MO Mail Bill	108, 109, 110,	D: 4	O alliana Finish an	.	5	Replace / repair stained ceiling tiles in classrooms		١,				
Mora Combined School	1997	MS Main Bldg.	111, 102		Ceiling Finishes	PreVent	PreVent	and computer lab		sf		\$C		
Mora Combined School	1997	MS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	Repair soffit at southwest side of the building		sf		\$0	\$0	
				L		L .		Repair / replace stained ceiling tiles in corridor in		1.				
Mora Combined School	1997	MS Main Bldg.		Dist.	Ceiling Finishes	PreVent	PreVent	front of classroom 109		sf		\$0	\$0	

Arra Correbated School 1950 S.S. Organia Rilidg Dat Deter Windows & Doorn ProVent															
APENINT MANE Mark														TOTAL	
Ave. Combined School	EAGUITY NAME				Identified De	0.40==	CATEGORY	_	EACH ITY NEEDO			0007/11/11			
For Contents (United States)	.,			ROOM	,	0.0.				QTY	UNIT	COST/UNIT	WACC		SUBTUTALS
Average Common Store Common St	Mora Combined School	1950			Dist.	Exterior Walls	PreVent	PreVent	Caulk perimeter of building		sf		\$0	\$0	
Section Committed Sect			-		L		L				_			40	1
Absolution State Dept. Profession	Mora Combined School	2001			Dist.	Exterior Walls	PreVent	PreVent	Repair rusted stucco at northeast wall of library		sf		\$0	\$0	
Accordance Seek Company Seek C					L										1
2000 Combined Shorted 1950 Bean Tick Data Entertor Walls Previous Previous Report and creat on collegend sails of the building 41 50 50	Mora Combined School	2001			Dist.	Exterior Walls	PreVent	PreVent	Repair rusted stucco at west corner bead		sf		\$0	\$0	
Annual Contented School 1959 PS Nam Bibly Ost Schorle Wals Parkent Parke					L										1
Ann. Controlled Stock 1077			, -						1		sf				
Annie Comminded School 1997 MS Plant Bills Dist. Chemist Virallas Privient Praferity Respire and colorisis and instance of the 150 35	Mora Combined School	1968	HS Main Bldg.		Dist.	Exterior Walls	PreVent	PreVent			lf		\$0	\$0	
Ann. Combrook School 1997 M.S. Nam Billig. Ost. Colore White									Repair cracked stucco at west entry and at north						1
Description Combined Shrotol 1950 ES Original Edge Data Care in Windows & Dozes PreVent PreVent Registre tradem windows in latent from of 0.0 0.			5						7		sf				
Annie Combined School 1650 Burr, Krid Oist Carlor Windows & Doors Preferent	Mora Combined School	1997			Dist.	Exterior Walls	PreVent	PreVent	Repair wall outside and inside		sf		\$0	\$0	
Ann Contained Surface 1950 So Cognisis (Ref. 1950															1
Auton Controlled School 1950 North Wing Det Enterior Windows & Doors PreVent PreVent Seglete traviers in descoron 2 d 50 50	Mora Combined School	1950			Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken windows in band room		sf		\$0	\$0	
1960 FS Original Ridg Det. Extorior Windows & Doors Perfect Prevent Original continues Windows are hard to get Det.															1
Actor Combined School 19(0) South Wing Dist Collection Windows & Doors ProVicent Depart windows Dist South Wing Dist Collection Windows & Doors ProVicent Depart windows Doors ProVicent Depart windows Doors ProVicent Depart windows Doors	Mora Combined School	1950	North Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Replace broken window in classroom 2		sf		\$0	\$0	
Proceedings			ES Original Bldg.						Upgrade exterior windows. Windows are hard to						
Advance Contribution School 1950 South Willing Det Edition Windows & Doors Previent P	Mora Combined School	1950			Dist.	Exterior Windows & Doors	PreVent	Prevent	open		sf		\$0	\$0	
Security			ES Original Bldg.												
Annix Combined School 1950 South Wing Dist. Exterior Windows & Doors Previoted Repair regions windows screenes e.a. \$50 \$50	Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair window sill		sf		\$0	\$0	1
SE Original Place Search Windows & Doors PreVent			ES Original Bldg.												
Action Combined School 1950 South Wing Dist Exterior Windows & Doors PreVent PreVent Repetit designed windows \$1 mt designed windows \$2 mt for fire frames \$1 mt for fire for fire frames \$1 mt for fire f	Mora Combined School	1950	South Wing		Dist.	Exterior Windows & Doors	PreVent	PreVent	Repair / replace window screens		ea.		\$0	\$0	1
Action Combined School 1950 South Wing Dist Exterior Windows & Doors PreVent PreVent Repetit designed windows \$1 mt designed windows \$2 mt for fire frames \$1 mt for fire for fire frames \$1 mt for fire f			ES Original Bldg.						Repaint exterior windows' frames: paint is peeling off						
	Mora Combined School	1950			Dist.	Exterior Windows & Doors	PreVent	PreVent			sf		\$0	\$0	
Mora Combined School 1997 M.S. Main Bidg. Dist. Exterior Windows & Doors PreVent Repair window screen in classroom 168 ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	Mora Combined School		HS Main Bldg.		Dist.	Exterior Windows & Doors	PreVent	PreVent			sf		\$0	\$0	
Content Cont			· ·								ea.				
Construction 1997 MS Man Bigg Dist Exterior Windows & Doors PreVent PreV															
Assess window settlement, windows are hard to ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0											ea.		1 -		
Acra Combined School 1997 Ms Main Bldg Dist Ender Windows & Doors PreVent													**	1-	
ESMS Org. Gym/ Bandt, Ke B Ban	Mora Combined School	1997	MS Main Bldg		Dist	Exterior Windows & Doors	PreVent	PreVent			ea		\$0	\$0	1
Adva Combined School 1950 Band, K-8 Dist. Floor Finishes PreVent PreVent PreVent Replace cracked VCT in boys showers sf \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0					2.01.								,	Ų,	
Sem Sorg. Gym / Band, K-8 Dist Floor Finishes PreVent PreVent Replace carpet in band room Sem Sorg. Gym / Band, K-8 Dist Floor Finishes PreVent PreVent Replace carpet in band room Sem Sorg. Gym / Band, K-8 Dist Floor Finishes PreVent PreVent Replace cracked VCT in girls restroom Sem Sorg. Gym / Band, K-8 Dist Floor Finishes PreVent PreVent Replace cracked VCT in girls restroom Sem Sorg. Gym / Band, K-8 Dist Floor Finishes PreVent PreVent Repair carpet in corridor outside computer labs Sem Sorg. Gym / Band Bidg. Dist Floor Finishes PreVent P	Mora Combined School	1950			Dist	Floor Finishes	Pre\/ent	Pre\/ent	Replace cracked VCT in boys showers		c f		\$0	\$0	1
Afora Combined School 1950 Band, K-8 Dist. Floor Finishes PreVent PreVent Replace cracked VCT in girls restroom st 90 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Word Combined Concor	1000			Diot.	Tiest Timeries	1 TO VOITE	1 TO VOIR	Tropiaco cracica vo i in poyo chemero		01		ΨΟ	Ψ	———
ES MS Org. Gym / Dist. Floor Finishes PreVent PreVent Replace cracked VCT in girls restroom sf So So	Mora Combined School	1050	Rand K-8		Diet	Floor Finishes	Pre\/ent	Dre\/ent	Replace carnet in hand room		ef		\$0	\$0	1
Agric Combined School 1958 HS Main Bildg. Dist. Floor Finishes PreVent PreVent Replace cracked VCT in girls restroom sf \$0 \$0	Wora Combined School	1930			Dist.	1 loor 1 misries	i ievent	i ievent	replace carpet in band room		31		ΨΟ	ΨΟ	
	Mora Combined School	1050			Diet	Floor Finishes	Pro\/ont	Pro\/ont	Replace cracked VCT in girls restroom		cf		0.9	\$0	1
Mora Combined School 1997 MS Main Bldg. Dist. Floor Finishes PreVent PreVent Corridors and at north entrance of Replace / repair cracked VCT and buckled VCT in Space or repair cracked VCT at the entrance of Cassroom 112 Cassro			,								of.				
Mora Combined School 1997 MS Main Bildg Dist. Floor Finishes PreVent P	Wora Combined School	1900	i io ivialii biug.		DISt.	1 1001 1 IIIISHES	FIEVEIIL	Fieveni			51		φυ	φυ	
Mora Combined School 1997 MS Main Bidg. Dist. Floor Finishes PreVent PreVent PreVent PreVent Install vinyl base at west entry sf \$ \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$	Mara Cambinad Sabaal	1007	MC Main Dida		Diet	Floor Finishes	Dro\/ont	Dro\/ont	i i		of		¢0	¢0	1
Mora Combined School 1997 MS Main Bildg. Dist. Floor Finishes PreVent PreVent 1997 MS Main Bildg. Dist. Floor Finishes PreVent 1997 MS Main Bildg. Dist. Institutional Equipment PreVent 1998 MS Main Bildg. Dist. Institutional Equipment PreVent 1998 MS Main Bildg. Dist. Institutional Equipment PreVent 1999 MS Main Bildg. Dist. Institutional Equipment PreVent 1999 MS Main Bildg. Dist. Institutional Equipment PreVent PreVent 1999 MS Main Bildg. Dist. Institutional Equipment PreVent PreVent PreVent Repair plastic laminate at library counter ea. \$0.50.50.50.50.50.50.50.50.50.50.50.50.50	Wora Combined School	1997	IVIO IVIAITI DIUG.		DISt.	Floor Fillisties	Fieveni	Frevent			51		φυ	φυ	
Mora Combined School 1997 MS Main Bidg. Dist. Floor Finishes Prevent Prevent Install vinyl base at west entry for Combined School 1968 HS Main Bidg. Dist. Foundation / Slab / Structure Prevent Prevent Prevent Assess change in floor slope in classroom 108 sf \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mana Camphinad Cabaal	4007	MC Main Dida		Dist	Floor Finishes	Due Vent	Due Vant			- 4		φ0	Φ0	1
Mora Combined School 1968 HS Main Bildg. Dist. Foundation / Slab / Structure PreVent PreVent Prevent Assess change in floor slope in classroom 108 ff \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0											SI		· ·	· ·	
Mora Combined School 2001 Const Dist. HVAC PreVent Prevent area Upgrade HVAC System; there is no heating in this area size S Library Phase 3 Const Dist. Institutional Equipment PreVent Prevent Repair plastic laminate at ilbrary counter ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0			3										\$0		
Mora Combined School 2001 Const Dist. HVAC PreVent Prevent area \$\ \text{ES Library Phase 3} \\ \text{Const} \\ \text{Dist.} \\ \text{Institutional Equipment} \\ \text{PreVent} \\ \text{PreVent} \\ \text{Prevent} \\ \text{Repair plastic laminate at library counter} \\ \text{ea.} \\ \text{\$0\$} \\	loonac Combined School	1968			DISt.	roundation / Siab / Structure	Prevent	revent	Ŭ		SI		\$0	\$0	
Mora Combined School 2001 ES Library Phase 3 Const Dist. Institutional Equipment PreVent Prevent Repair plastic laminate at library counter ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mana Canabia 101	0004	-		Dist	10/40	D	D 1	, -						1
Mora Combined School 2001 Const ES Original Bldg. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate at library counter ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	iviora Compined School	2001			DIST.	HVAC	Prevent	revent	area		ST		\$0	\$0	
South Wing Dist. Institutional Equipment PreVent Prevent Repair plastic laminate at all classrooms ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mana Canabia 101	0004			Dist	In attribution of Equipment	D	D 1	Denois pleatic lessingte at 115 services					**	1
Mora Combined School 1950 South Wing Dist. Institutional Equipment PreVent Prevent Repair plastic laminate at all classrooms ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	iviora Combined School	2001			DIST.	ınstitutionai Equipment	Prevent	Prevent	Repair plastic laminate at library counter		ea.		\$0	\$0	
HS Commons Addition Dist. Institutional Equipment PreVent Prevent Replace booths in commons area 5 ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$		46-5				l ere i -	L								1
Mora Combined School 2004 Addition Dist. Institutional Equipment PreVent Prevent Replace booths in commons area 5 ea. \$0 \$0 \$0 HS Commons Addition Dist. Institutional Equipment PreVent Prevent Replace table arms on auditorium seating 12 ea. \$0 \$0 Mora Combined School 1968 HS Main Bldg. 107 & 108 Dist. Institutional Equipment PreVent Repair plastic laminate in classrooms If \$0 \$0 Mora Combined School 1968 HS Main Bldg. Dist. Institutional Equipment PreVent Repair plastic laminate in classrooms If \$0 \$0 Repair plastic laminate in computer lab and classrooms PreVent Prevent Prevent Classrooms PreVent Prevent Classroom PreVent Prevent Prevent Repair plastic laminate in classroom 109 PreVent Repair plastic laminate in classroom 109 PreVent Repair plastic laminate in classroom 109 PreVent PreVent Repair plastic laminate in classroom	Mora Combined School	1950	· ·		Dist.	institutional Equipment	PreVent	Prevent	Repair plastic laminate at all classrooms		ea.		\$0	\$0	
HS Commons Addition Dist. Institutional Equipment PreVent Prevent Replace table arms on auditorium seating 12 ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0						L	L								1
Mora Combined School 2004 Addition Dist. Institutional Equipment PreVent PreVent Replace table arms on auditorium seating 12 ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Mora Combined School	2004			Dist.	Institutional Equipment	PreVent	Prevent	Replace booths in commons area	5	ea.		\$0	\$0	
Mora Combined School 1968 HS Main Bldg. 107 & 108 Dist. Institutional Equipment PreVent PreVent Repair plastic laminate in classrooms If \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0							L							1	1
Mora Combined School 1968 HS Main Bldg. Dist. Institutional Equipment PreVent PreVent Repair tables in science labs Repair plastic laminate in computer lab and Mora Combined School 1968 HS Main Bldg. 112, 114, 115, Dist. Institutional Equipment PreVent Prevent classrooms Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent PreVent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent PreVent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist.									Ĭ	12	ea.				
Mora Combined School 1968 HS Main Bldg. 112, 114, 115, Dist. Institutional Equipment PreVent Prevent classrooms ea. \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0				107 & 108							lf				
Mora Combined School 1968 HS Main Bldg. 112, 114, 115, Dist. Institutional Equipment PreVent Prevent classrooms ea. \$0 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent PreVent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Dist. Institutional Equipment PreVent Prevent Repair plastic laminate in classroom 109 Mora Combined School 1997 MS Main Bldg. Dist. Dist. Dist. Di	Mora Combined School	1968	HS Main Bldg.	·	Dist.	Institutional Equipment	PreVent	PreVent			ea.		\$0	\$0	
Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent PreVent Repair plastic laminate in classroom 109 ea. \$0 \$0 Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 ea. \$0 \$0 \$0 \$0									Repair plastic laminate in computer lab and					<u> </u>	1
Mora Combined School 1997 MS Main Bldg. Dist. Institutional Equipment PreVent Prevent Replace casework in classroom 102 ea. \$0 \$0	Mora Combined School		· ·	112, 114, 115,							ea.				
	Mora Combined School							PreVent			ea.				
	Mora Combined School	1997	MS Main Bldg.		Dist.	Institutional Equipment	PreVent	Prevent	Replace casework in classroom 102		ea.		\$0	\$0	
flora Combined School 1968 HS Main Bldg. Dist. Interior Doors PreVent PreVent Repair door in classroom 115: door does not close ea. \$0 \$0 \$0															
	Mora Combined School	1968	HS Main Bldg.		Dist.	Interior Doors	PreVent	PreVent	Repair door in classroom 115: door does not close	<u></u>	ea.	<u></u>	\$0	\$0	1

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
	7.0.1.2.1.00.1	ES MS Org. Gym /	1100	,	01012			-	٦					0021017120
Mora Combined School	1950	Band, K-8		Dist.	Interior Walls	PreVent	PreVent	Repair water damage in storage room		sf		\$0	\$0	,
Mora Combined School	1965	Cafeteria, K-12		Dist.	Plumbing	PreVent	Prevent	Repair sink at kitchen		ea.		\$(\$0	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Wall Finishes	PreVent	PreVent	Repaint exterior walls: paint is peeling off brick		sf		\$(\$0	
Mora Combined School	1965	Cafeteria, K-12			Wall Finishes	PreVent		Repair wall at kitchen		sf		\$(\$0	
Mora Combined School	1965	Cafeteria, K-12		Dist.	Wall Finishes	PreVent	PreVent	Repair wall due to water damage in dinning room		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair wall hole at north entrance		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.	105, 111, 106, 108, 109, 110	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in classrooms and computer lab		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.	130 & 128	Dist.	Wall Finishes	PreVent	PreVent	Repair wall cracks in councilor and principal offices		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair wall and ceiling cracks in councilor office and restroom		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.	108, 102, 110	Dist.	Wall Finishes	PreVent	PreVent	Repair window sill in classrooms		sf		\$(\$0	
Mora Combined School	1997	MS Main Bldg.		Dist.	Wall Finishes	PreVent	PreVent	Repair ceiling crack in mechanical room		sf		\$(\$0	
								Upgrade technology district wide: Hardware,						
District Wide		District		Dist.	Technology	Tech	Tech	Software, Training, Broadband	5	ō yr.	\$50,000.00	\$250,000	\$250,000	\$250,000
Mora Combined School	1991	Addition		FAD	Technology	Tech	Tech	No system \$1,350: not needed	(ea.	\$0.00	\$(\$0	
		Aud / Band,												
Mora Combined School	1975	K-8		FAD	Technology	Tech	Tech	Upgraded 1999 \$2,744: Upgraded 2018		ea.	\$0.00	\$(7.5	
Mora Combined School	1965	Cafeteria, K-12		FAD	Technology	Tech	Tech	Upgraded 2000 \$1,019: Upgraded 2018	(ea.	\$0.00	\$(\$0	
								New electronic white boards in classrooms \$2,557.						
Mora Combined School	2003	Commons Addition		FAD	Technology	Tech	Tech	Upgraded 2018	(ea.	\$0.00	\$(\$0	
Mora Combined School	1991	Industrial Arts High		FAD	Technology	Tech	Tech	Updated 2000 \$1,140: District updated 2018	(ea.	\$0.00	\$(\$0	
Mora Combined School	1968	Main Bldg High		FAD	Technology	Tech	Tech	Replaced 2000. New electronic white boards in classrooms (2013). Estimated time frame 2005		Dea.	\$0.00	\$(\$0	
IVIOIA COMBINED SCHOOL	1900	iviaiii bidg Higii		FAD	rechilology	i ecri	recii	\$4,397: Updated 2018		Jea.	\$0.00	Ď(\$0	
Mora Combined School	1950	Main Bldg Middle Original Const		FAD	Technology	Tech	Tech	Updated 2000 \$3,298: District updated 2018		ea.	\$0.00	\$0	\$0	
Mora Combined School	1978	(gym)		FAD	Technology	Tech	Tech	No system needed \$8,504: Updated 2018	(ea.	\$0.00	\$(\$0	
Priority 1 Life-Health-Safe	ety-Security / M	aintenance / Techno	logy:									\$1,020,73	\$1,020,735	\$1,020,735

Priority 2 Building / Site S	ystem Upgrad	les:												
Holman ES	1987	HES Addition		FAD	Water Distribution	FacRen	BS-GOB		1	FAD	\$24,395.00	\$24,395	\$31,714	
								Upgrade HVAC system: Install heating in nursing						
Mora Combined School	1995	Admin/Kinder	SPED and Nursing	Dist.	HVAC	AdqStd	BS-GOB	and SPED	1,750) sf	\$25.00	\$43,750	\$56,875	
Mora Combined School	1965	Cafeteria, K-12		FAD	HVAC	AdqStd	BS-GOB	\$88,351 Propane rooftop units. Evap cooling	5,600) sf	\$25.00	\$140,000	\$182,000	
Mora Combined School	1950	ES MS Org. Gym / Band, K-8		FAD	HVAC	AdgStd	BS-GOB	Propane rooftop units repl 1984 \$237,966: Upgrade HVAC units: one old unit; newer unit is not working	15,748	3 sf	\$15.00	\$236,220	\$307,086	
		ES Original Bldg.						Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the	,			. ,	. ,	
Mora Combined School	1950	North Wing		Dist.	HVAC	AdqStd	BS-GOB	north wing and classrooms are too hot	10,988	3 sf	\$25.00	\$274,700	\$357,110	
Mora Combined School	1950	ES Original Bldg. South Wing		Dist.	HVAC	AdqStd	BS-GOB	Upgrade HVAC system: Heating and cooling is a major problem; there is no cooling system in the south wing and classrooms are too hot	12,399) sf	\$25.00	\$309,975	\$402,968	
Mora Combined School	1968	HS Main Bldg.		FAD	HVAC	AdqStd	BS-GOB	Original propane rooftop units. No cooling but desired \$381,382: Updated 2003	23,264		\$25.00	\$581,600	\$756,080	
Mora Combined School	1974	HS Original Const (gym)		FAD	HVAC	AdqStd	BS-GOB	Original propane boiler. No cooling but desired \$307,332	16,068	3 sf	\$25.00	\$401,700	\$522,210	
Mora Combined School	1995	Admin/Kinder		FAD	HVAC Controls	AdqStd	BS-GOB	Beyond Expected Life: Need to upgrade	1	FAD	\$22,378.00	\$22,378	\$29,091	
Mara Cambinad Sabaal	1950	ES MS Org. Gym / Band, K-8		FAD	HVAC Controls	AdaStd	DS COD	Original: Possible replaced and ungraded in 1094		I FAD	\$33,218.00	¢22 240	¢42 192	
Mora Combined School Mora Combined School	1991	HS Gym Addition		FAD	HVAC Controls	AdqStd AdqStd	BS-GOB BS-GOB	Original: Possible replaced and upgraded in 1984 Original		I FAD	\$6,811.00	\$33,218 \$6,811	\$43,183 \$8,854	
Mora Combined School	1991	HS Industrial Arts		FAD	HVAC Controls	AdqStd	BS-GOB	Original		I FAD	\$13,809.00	\$13,809	\$17,952	
Mora Combined School	1968	HS Main Bldg.		FAD	HVAC Controls	AdqStd	BS-GOB	Original \$127,771: Updated 2003	23,264		\$5.00	\$116,320	\$151,216	

													TOTAL	
FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	PROJECT COST	SUBTOTALS
	7 (HS Original Const		,	0.0.12			-	<u></u>	0		10 0		
Mora Combined School	1974	(gym)		FAD	HVAC Controls	AdqStd	BS-GOB	Original	1	FAD	\$102,962.00	\$102,962	\$133,851	
Mora Combined School	1997	MS Main Bldg.		FAD	HVAC Controls	AdqStd	BS-GOB	Upgraded 1998	1	FAD	\$39,926.00	\$39,926	\$51,904	
								No gym equipment: Replace some kitchen						
Mora Combined School Mora Combined School	1965 1968	Cafeteria, K-12 HS Main Bldg.		FAD FAD	Institutional Equipment	AdqStd AdqStd	BS-GOB BS-GOB	equipment		FAD FAD	\$13,405.00 \$57,864.00	\$13,405 \$57,864		
Mora Combined School	1900	no Main blug.		FAD	Institutional Equipment	AuqSiu	BS-GOB	No gym equipment: Updated 2003		FAD	\$57,004.00	\$57,004	\$15,223	
		HS Original Const						Scoreboards/backboards original \$46,629. Half						
Mora Combined School	1974	(gym)		FAD	Institutional Equipment	AdgStd		bleachers updated 2017; need to replace other half	300	ea.	\$200.00	\$60,000	\$78,000	
		ES MS Org. Gym /				1		Last replaced 1984. Possible replaced in addition in			·			
Mora Combined School	1950	Band, K-8			Ceiling Finishes	FacRen		1984 \$64,759	15,748		\$6.00	\$94,488		
Mora Combined School	1950	Admin/Kinder		Dist.	Exterior Walls	FacRen		Repair stucco	3,600) sf	\$8.00	\$28,800	\$37,440	
		FC Library Dhass 2						Walls with minor cracks, water damage due to roof						
Mora Combined School	2001	ES Library Phase 3 Const		FAD	Exterior Walls	FacRen	BS-GOB	runoff causing water to splash from concrete apron \$17.205	1,400	of	\$8.00	\$11,200	\$14,560	
Mora Combined School	2001	ES MS Org. Gym /		FAD	LATERIOR WAIIS	raciteii	B3-GOB	ψ17,203	1,400) 51	φο.υυ	φ11,200	ψ14,300	
Mora Combined School	1950	Band, K-8		Dist.	Exterior Walls	FacRen	BS-GOB	Repair / Upgrade exterior wall finishes	10,000) sf	\$8.00	\$80,000	\$104,000	
Mora Combined School	1997	MS Main Bldg.			Exterior Walls	FacRen		Replace entire building stucco	10,200		\$8.00	\$81,600		
		ES MS Org. Gym /						Original windows on gym and 1975 windows on						
Mora Combined School	1950	Band, K-8		FAD	Exterior Windows & Doors	FacRen		addition and doors on gym \$65,283	150) sf	\$175.00	\$26,250	\$34,125	
								Exterior damage to window sills and drywall, exterior						
Mara Cambinad Cabaal	1997	MS Main Bldg.		FAD	Exterior Windows & Doors	FacBan	BS-GOB	doors hard to open and close \$175,766. Reseal all wood window sills:	450	of	\$175.00	¢70.750	\$102,375	
Mora Combined School	1997	ES MS Org. Gym /		FAD	Exterior Windows & Doors	FacRen	BS-GOB	wood window sills;	450	SI	\$175.00	\$78,750	\$102,375	
Mora Combined School	1950	Band, K-8		FAD	Floor Finishes	FacRen	BS-GOB	\$63.083	15,000) sf	\$6.00	\$90,000	\$117,000	
Word Combined Concor	1000	Barra, re o		17.8	Tion Timorico	1 dorton		\$45,315; Include upgrade carpet in classroom 2 and	10,000	, 01	ψ0.00	Ψ00,000	Ψ111,000	
		ES Original Bldg.						replace vinyl base in girls and boys restrooms and						
Mora Combined School	1950	North Wing		FAD	Floor Finishes	FacRen	BS-GOB	throughout wing.	900) sf	\$15.00	\$13,500	\$17,550	
	4004	1			_,,			\(\sigma_1 \cdot \			***	***	204.000	
Mora Combined School	1991	HS Industrial Arts		FAD	Floor Finishes	FacRen		Original. Heavy wear on VCT in classrooms (2013) Gym flooring replaced 2000 \$81,471: Beyond	1	FAD	\$26,223.00	\$26,223	\$34,090	
		HS Original Const						Expected Life: Gym floor is over water table; replace						
Mora Combined School	1974	(gym)		FAD	Floor Finishes	FacRen	BS-GOB	wood floor	9,500) sf	\$30.00	\$285,000	\$370,500	
Mora Combined School	1997	MS Main Bldg.		FAD	Floor Finishes	FacRen		Replaced 1998 \$75,822	15,000		\$6.00	\$90,000		
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Institutional Equipment	FacRen	BS-GOB	Upgraded 1984	1	FAD	\$36,104.00	\$36,104	\$46,935	
Mana Osmakin ad Oska al	4050	ES MS Org. Gym /		EAD	lated a Decem	F D	DO 00D	\$05.500	0.0		#0.000.00	# 00.000	#05.000	
Mora Combined School	1950	Band, K-8 ES MS Org. Gym /		FAD	Interior Doors	FacRen	BS-GOB	\$95,596	22	FAD	\$3,000.00	\$66,000	\$85,800	
Mora Combined School	1950	Band, K-8		Dist.	Lighting / Branch Circuits	FacRen	BS-GOB	Replace lights at gym	7,212	sf	\$7.00	\$50,484	\$65,629	
		24.14,110		2.01.	_igig /iai.io.i o.i.oai.io			\$53,159 Upgrade bathrooms for ADA. Replace	.,		4.100	φου, .σ.	+ + + + + + + + + + + + + + + + + + + 	
Mora Combined School	1965	Cafeteria, K-12		FAD	Plumbing	FacRen		double oven	250	sf	\$300.00	\$75,000	\$97,500	
		ES MS Org. Gym /												
Mora Combined School	1950	Band, K-8		FAD	Plumbing	FacRen		Upgraded 1984 \$143,180	800) sf	\$150.00	\$120,000	\$156,000	
Mana Camabinad Cabaal	4050	ES Original Bldg.		Dist	Diversities	FaaDan		Renovate sinks to ADA compliant in girls and boys	0.0		# 500.00	¢40.000	¢42.000	
Mora Combined School Mora Combined School	1950 1991	North Wing HS Industrial Arts		Dist. FAD	Plumbing Plumbing	FacRen FacRen	BS-GOB BS-GOB	restrooms R/R non operational in need of repair \$85,707	225	ea.	\$500.00 \$300.00	\$10,000 \$67,500		
Mora Combined School	1968	HS Main Bldg.			Plumbing	FacRen	BS-GOB	Original \$229,471	900		\$300.00	\$270,000	\$351,000	
Mora Combined School	1995	Admin/Kinder			Roof	FacRen		\$87,868: Need to coat metal roof	8,236		\$10.00	\$82,360		
								Metal roof replacement 1998 \$48,427: In good	,					
Mora Combined School	1965	Cafeteria, K-12		FAD	Roof	FacRen	BS-GOB	condition	C) sf	\$0.00	\$0	\$0	
								Metal roof with several roof leaks into the building						
Mara Carabina d Octobro	4007	MC Main Distri			Doof	FooD::		causing damage to ceiling tiles \$501,675: Coat metal	40.505	of .	640.00	#40F 070	#044.004	ΦE 050 044
Mora Combined School Holman ES	1997 1987	MS Main Bldg. HES Addition		FAD FAD	Roof Drain, Waste and Vent	FacRen FacRen	BS-GOB BS-SB9	1001.	18,587	FAD	\$10.00 \$24,395.00	\$185,870 \$24,395		\$5,652,611
I IOIIIIAII EO	1301	HS Original Const		ו עף	Diam, Wasie allu Velit	i acixeii	50-008			IAD	Ψ24,393.00	φ24,393	φ31,114	
Mora Combined School	1974	(gym)		FAD	Ceiling Finishes	FacRen	BS-SB9	TandG ceiling	1	FAD	\$83,637.00	\$83,637	\$108,728	
		100,7	106, 105, 102, 107		-			\$42,497Upgrade carpet in offices and conference						
Mora Combined School	1995	Admin/Kinder	& 109	FAD	Floor Finishes	FacRen	BS-SB9	room	1,500) sf	\$6.00	\$9,000	\$11,700	

FACILITY NAME	AREA-Year	AREA	ROOM Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
	4005		l	E. E	_ 5	DO 0D0	Wear and cracking in several areas of the main	0.400		***	# 40.000	* 40.000	
Mora Combined School	1965	Cafeteria, K-12	FAD	Floor Finishes	FacRen	BS-SB9	cafeteria floor \$23,421	2,100	SŤ	\$6.00	\$12,600	\$16,380	
Mora Combined School	2001	ES Library Phase 3 Const	FAD	Floor Finishes	FacRen	BS-SB9	Completed Dec 2001 \$14,875	2,200	of	\$6.00	\$13,200	\$17,160	
Mora Combined School	2001	Const	FAD	Floor Fillishes	racken	DO-2D9	\$51,838: Upgrade carpet at all classrooms and	2,200	SI	\$6.00	\$13,200	\$17,100	
							replace / repair cracked VCT in classroom 18 and in						
		ES Original Bldg.					corridor and Repair / replace vinyl base in building:						
Mora Combined School	1950	South Wing	FAD	Floor Finishes	FacRen	BS-SB9	base is coming off	7,500	ef	\$6.00	\$45,000	\$58,500	
Mora Combined School	1965	Cafeteria, K-12	FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998	1,500	FAD	\$1,560.00	\$1,560	\$2,028	
Word Combined Concor	1303	ES MS Org. Gym /	IAD	Other Electrical Gysterns	racitori	DO-0D3	opgraded 1000	'	IAD	ψ1,300.00	ψ1,500	ΨΖ,020	
Mora Combined School	1950	Band, K-8	FAD	Other Electrical Systems	FacRen	BS-SB9	Updated 1984	1	FAD	\$4,201.00	\$4,201	\$5,461	
Mora Combined School	1991	HS Gym Addition	FAD	Other Electrical Systems		BS-SB9	Original	1	FAD	\$861.00	\$861	\$1,119	
Mora Combined School	1991	HS Industrial Arts	FAD	Other Electrical Systems	FacRen	BS-SB9	Original	1	FAD	\$1,746.00	\$1,746	\$2,270	
Mora Combined School	1968	HS Main Bldg.	FAD	Other Electrical Systems	FacRen	BS-SB9	Last upgraded 1991	1	FAD	\$6,733.00	\$6,733	\$8,753	
	. 3 6 6	HS Original Const					19			÷5,. 55.66	\$3,.30	45,.30	
Mora Combined School	1974	(gym)	FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1991 w/addition	1	FAD	\$13,022.00	\$13,022	\$16,929	
Mora Combined School	1997	MS Main Bldg.	FAD	Other Electrical Systems	FacRen	BS-SB9	Upgraded 1998	1	FAD	\$5,049.00	\$5,049	\$6,564	
Mora Combined School	1995	Admin/Kinder	FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000: District painted 2007	1	FAD	\$23,937.00	\$23,937	\$31,118	
Mora Combined School	1965	Cafeteria, K-12	FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000 \$13,193	3,500	sf	\$3.50	\$12,250	\$15,925	
		ES Library Phase 3											
Mora Combined School	2001	Const	FAD	Wall Finishes	FacRen	BS-SB9	Completed Dec 2001 \$8,379	3,000	sf	\$3.50	\$10,500	\$13,650	
		ES MS Org. Gym /											
Mora Combined School	1950	Band, K-8	FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$35,533.00	\$35,533	\$46,193	
		ES Original Bldg.					Painted 1999; DNS clean and painted 2013 \$25,525;						
Mora Combined School	1950	North Wing	FAD	Wall Finishes	FacRen	BS-SB9	Update wall finish in boys restroom	3,600	sf	\$3.50	\$12,600	\$16,380	
		ES Original Bldg.											
Mora Combined School	1950	South Wing	FAD	Wall Finishes	FacRen	BS-SB9	\$29,199	6,000	sf	\$3.50	\$21,000	\$27,300	
		HS Commons											
Mora Combined School	2004	Addition	FAD	Wall Finishes		BS-SB9	2013: Clean & painted	1	FAD	\$33,113.00	\$33,113	\$43,047	
Mora Combined School	1991	HS Gym Addition	FAD	Wall Finishes	FacRen	BS-SB9	\$7,285	6,000	sf	\$3.50	\$21,000	\$27,300	
Mora Combined School	1991	HS Industrial Arts	FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000. Clean and painted (2013)	1	FAD	\$14,771.00	\$14,771	\$19,202	
Mora Combined School	1968	HS Main Bldg.	FAD	Wall Finishes	FacRen	BS-SB9	Painted 2000	1	FAD	\$56,948.00	\$56,948	\$74,032	
		HS Original Const											
Mora Combined School	1974	(gym)	FAD	Wall Finishes		BS-SB9	Painted 2000	1	FAD	\$45,891.00	\$45,891	\$59,658	
Mora Combined School	1997	MS Main Bldg.	FAD	Wall Finishes		BS-SB9	Painted 2000	1	FAD	\$42,709.00	\$42,709	\$55,522	\$716,633
District Wide	1950	Campus Wide	Dist.	Parking Lot	LHSS	L-GOB	Upgrade parking lots	1	ea.	\$750,000.00	\$750,000	\$975,000	
							Rework drain pipes from ES MS Gym to have one lift						
		ES MS Org. Gym /					station and repair/replace one lift station pump: it is						
District Wide	1950	Band, K-8	Dist.	Z-Site Utilities	LHSS	L-GOB	not working	1	ea.	\$55,000.00	\$55,000	\$71,500	
District Wide	1950	Campus Wide	Dist.	Communications / Security	LHSS	L-GOB	Update intercom district wide	178,790	sf	\$2.00	\$357,580	\$464,854	\$1,511,354
Priority 2 Building / Site S	System Upgrade	es:									\$6,061,998	\$7,880,597	\$7,880,597
Dulante CO 11 15													
Priority 3 Capital Projects		110	lo: .	I Adulatia Fielda	IA II-OLI	Ino oon	Dada to als audana		1	M450 000 00	#450 000 ¹	#40E 000I	
District Support	1950	HS	Dist.	Athletic Fields		BS-GOB	Redo track surface		ea.	\$150,000.00	\$150,000	\$195,000	#00F F00
District Support	1950	HS	Dist.	Athletic Fields	AdqStd	BS-GOB	Install sprinkler system in football field	1	ea.	\$85,000.00	\$85,000	\$110,500	\$305,500
					1	[Create Softball Field: District has a shared Baseball-						
District Support	1950	HS	Dist.	Athletic Fields	LocPol	MP-GOB	Softball field only. Install site lighting at both fields.	4	00	\$350,000.00	\$350,000	\$455,000	
District Support	1950	HS	Dist.	Athletic Fields	LocPol	MP-GOB	Athletic concessions & restrooms	1,200	ea.	\$350,000.00	\$420,000	\$546,000	
District Support	1950	HS	Dist.	Site Lighting	LocPol	MP-GOB	Light Baseball Field		ea.	\$75,000.00	\$300,000	\$390,000	
District Support	1950	HS	Dist.	Site Lighting		MP-GOB	Light Softball Field		ea.	\$75,000.00	\$300,000	\$390,000	
Mora Combined School	1950	Swimming Pool	Dist.	Repurpose	AdqStd	MP-GOB	Repurpose Swimming Pool	10,547		\$150.00	\$1,582,050	\$2,056,665	
Mora Combined School	1970	Martinez Gym	Dist.	Renovation	LocPol	MP-GOB	Renovate Gym Locker/restrooms and Band	3,025		\$150.00	\$1,582,050	\$2,056,665	
Mora Combined School	1950	HS Gym	Dist.			MP-GOB	Renovate Restrooms and Lobby	2,500		\$200.00	. ,	\$812,500	\$5,436,665
		по буш	IDISI.	Renovation	ILUCFUI	IVIF-GUD	Inchovate restrooms and Loppy	2,500	ы	<u></u> \$∠50.00			
Priority 3 Capital Projects		T (1 N .					TOTAL				\$4,417,050	\$5,742,165	\$5,742,165
Mora Independent So	nool District	lotal Needs:					TOTAL:				\$11,499,783	\$14,643,497	

NEEDS BY FUNDING SOURCE

FACILITY NAME	AREA-Year	AREA	ROOM	Identified By	SYSTEM	CATEGORY	Funding Source	FACILITY NEEDS	QTY	UNIT	COST/UNIT	MACC	TOTAL PROJECT COST	SUBTOTALS
Option 3A														
Орион за	I	T I			ī	T	ī	1		T			ī	
School Reconfiguration	1950	ES: ES/MS Gym: Café: Admin: Maint		Dist.	Demolish	LocPol	MP-GOB	Demolish: ES; Admin; ES/MS Gym; Kitchen- Cafeteria: Maintenance	63,425	Sef	\$25.00	\$1,585,625	\$2,061,313	
ochoor recomigaration	1300			Dist.	Bemoisi	LOCI OI	IVII -GOD	Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing,	00,420	7 31	Ψ20.00	Ψ1,000,020	Ψ2,001,010	
School Reconfiguration	1950	ES: ES/MS Gym: Café: Admin: Maint		Dist.	Replace	LocPol	MP-GOB	Cafeteria & Kitchen: Relocate MS into HS & ES into MS.	24,000) sf	\$300.00	\$7,200,000	\$9,360,000	\$11,421,3°
Option 3B		<u>. </u>		•							· •			
		ES/MS Gym; Kitchen-Cafeteria;						Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing,						
District Support	1950	Maint		Dist.	Demolish	LocPol	MP-GOB	Cafeteria & Kitchen	28,218	3 sf	\$25.00	\$705,450	\$917,085	
District Support	1950	ES/MS Gym; Kitchen-Cafeteria; Maint		Dist.	Replace	LocPol	MP-GOB	Create 21st Century Multi-Purpose Bldg. to replace existing ES/MS Gym, Band, Training, Testing, Cafeteria & Kitchen	17,500) sf	\$300.00	\$5,250,000	\$6,825,000	\$7,742,08