

TUCUMCARI PUBLIC SCHOOLS 5 Year Facilities Master Plan

FINAL • 2019-2023 • # 5368









SECTION 0: INTRODUCTION

Master Plan Team

Executive Summary

- Requirement
- Process and Adoption
- School District Information
- Facilities
- Demographics and Enrollment
- Utilization and Capacity
- District Financial Information
- Technology and Preventive Maintenance
- PSCOC Facilities Assessment Database
- School District Priorities
- School District Capital Plan

Acronyms/Definitions

SECTION 1: FACILITY GOALS/PROCESS

1.1 Goals

- District Mission Statement and Core Values
- District Educational Goals / Program of Instruction
- District Relationship with the Community
- District Facilities Alignment to NMAS
- Long Range District Facility Goals

1.2 Public Process

- Decision Making Authority
- Facilities Master Plan Process
- FMP Prioritization Schedule

1.3 Issues and Findings

SECTION 2: EXISTING & PROJECTED CONDITIONS

2.1 Programs

- 2.1.1 District Information including:
 - Total Enrollment
 - Number of Schools
 - Types of Schools / Grade Configuration
 - School Feeder Chart
 - Pupil to Teacher Ratio
 - School Grades
 - Educational Programs
- 2.1.2 Anticipated Changes in Educational Programs
- 2.1.3 Shared/Joint Use of Facilities

2.2 Sites/ Facilities

- 2.2.1 District Site Information
 - District Site Maps
- 2.2.2 District Facilities Inventory

2.3 District Growth

- District Regional Perspectives
 - Maps of District Region
- Demographic Trends
 - County, District, Town Population Comparisons
 - Median Ages
 - Population Projections
 - County Births to Kindergarten Enrollment
 - Ethnicity
 - Household Types
- Economic and Development Analysis
 - County Industries
 - Occupations and Earnings
 - Poverty Designation

2.4 Enrollment

- Relevant Factors
- Projection Method
- 2.4.1 and 2.4.2 Historic and Projected Enrollment
 - Districtwide Enrollment Trends
 - Elementary School Enrollment
 - Middle School Enrollment
 - High School Enrollment

2.5 Utilization/Capacity

- 2.5.1 Required and Existing Classroom Spaces
- 2.5.2 Special Factors Influencing Facility Use
 - Pupil to Teacher Ratio
 - Special Education Spaces
 - Student Transfers, Magnet and Other Special Programs
 - Boundary Areas
 - Instructional Space Comparisons
- 2.5.3 Utilization and Capacity Analysis
 - Capacity Based on NM Adequacy Standards
 - Maximum and Functional Facility Capacity
 - Instructional Space Capacity
 - Utilization Analysis
- 2.5.4 Strategies to Meet Space Needs
- 2.5.5 Underutilized Spaces

SECTION 3: CAPITAL IMPROVEMENTS PLAN

3.1 Total Capital Needs

- Capital Improvement Project History
- District's Financial Resources
- Anticipated Capital Needs and Funding Sources
- Facility Needs by Facility

3.2 Prioritization Process and Budgeting

- 3.2.1 Development of FMP and Prioritization Process
 - FMP Steering Committee and Community Input
 - Process and Criteria for Prioritizing District Needs
 - FMP Prioritization Schedule
- Facility Needs by Category

3.3 Capital Plan

- 3.3.1 Priority Capital Improvements for Next 5 Years
 - FMP District Priorities
 - Facilities Assessment Database (FAD)
- 3.3.2 Financial Strategies and Alternatives
- 3.3.3 Capital Plan

SECTION 4: MASTER PLAN SUPPORT MATERIALS

4.1 Support Material by School

- 4.1.1 Site/School Details
 - FAD Mark-up/FMAR Reports
 - Executive Summary Report
 - School Details
 - Technology Overview
 - Energy Management Plan Overview
 - School Aerial
 - Construction Dates Plan
 - Building Floor Plans
 - Capacity Plans
 - School Utilization Spreadsheet

4.2 Support Material by District

- 4.2.1 Additional Information for School District
 - Technology Overview
 - Energy Management Plan Overview
 - Preventative Maintenance Plan

Appendix

- Additional Comments/Notes/Support Material
 - Presentations & Meetings

This page intentionally left blank

SECTION

0

Master Plan Team

TUCUMCARI PUBLIC SCHOOLS REPRESENTATIVES

Tucumcari Public Schools Board of Education

Carlos Romero – President Corinne Hayes – Vice President Leif Grey – Secretary Heather Gonzales – Member Fernando Ureste – Member

Superintendent

Aaron McKinney

FMP Core Committee

Aaron McKinney Veronica Hernandez

PUBLIC SCHOOLS FACILITY AUTHORITY REPRESENTATIVES

John Valdez - Facilities Master Planner Jeremy Sanchez - Regional Manager

PLANNING PROFESSIONAL

Greer Stafford / SJCF Architecture

Marilyn Strube, Head Planner Gabriela Ochoa, Planner Jacqueline Zamora, Planner Alyssa Metoyer, Intern



1717 Louisiana Blvd. NE, Suite 205 Albuquerque, NM 87110 505.821.0235 SECTION

0

Master Plan Team

III OS KIELINGIA KIELINGIA

Executive Summary

REQUIREMENT

The Public School Capital Outlay Council (PSCOC)/Public School Facilities Authority (PSFA) require that New Mexico Public School Districts have a Facilities Master Plan as a prerequisite for eligibility to receive state capital outlay assistance (New Mexico Statutes Section [22-25-5 NMSA 1978]). This 5-Year Facilities Master Plan (FMP) was developed utilizing the School District Facilities Master Plan Components and Guidelines issued by Public School Capital Outlay Council/Public School Facilities Authority, October 2016 Revision. It incorporates all public schools within Tucumcari Public Schools (TPS).

PROCESS AND ADOPTION

The following process was followed to conduct the facility assessment and to formulate the FMP. Refer to Section 1.2 for a detailed explanation of the FMP process.

- 1. School Board Review and approve facilities master plan process
- 2. Gather and Formulate data
- 3. FMP Committee Meetings Review, Discuss Data, and Generate Recommendations
- 4. School Board Adoption of Final FMP Document

The Tucumcari Public Schools Board of Education adopted the completed 5-Year Facilities Master Plan on February 18, 2019.

SCHOOL DISTRICT INFORMATION

Address

Tucumcari Public Schools

700 W Amarosa Ave Tucumcari, NM 88401 Phone: 575.461.3910

Mission

Tucumcari Public Schools will prepare students for successful lives.

Vision

Excellence in Education.

Number of Schools 3 Types of Schools






Executive Summary

FACILITIES

Tucumcari Public Schools has three schools. The state identification number is 49130000 and the sites are district owned. The total facility inventory square footage per the floor plans contained in this FMP is 366,727 square feet including administration and support.

There are no portable classrooms in the district. Of the 108 total classrooms, 61 are general use, 28 are special use and 19 are for special education. Total enrollment at 2017/2018 PED 40-Day Count was 976 students. There are approximately 370 square feet per student of district facilities. Total permanent facility square footage of TPS schools according to PSFA is 317,561 square feet. This number does not include administration and support.


DEMOGRAPHICS/ENROLLMENT



Tucumcari Public Schools schools are located in the city of Tucumcari. The district's service area is located in eastern New Mexico in the west side of Quay County.

Quay County has had declines in population since 2000. Population projections from the Bureau of Business and Economic Research (BBER) indicate that the population in the county may continue to steadily decline through 2040.


The graph below shows the population by age of Quay County and the TPS service area. This graph shows that the largest percentage of population for the TPS service area is in the 45 to 54 and the 65 to 74 age ranges. The median age for the TPS Service area was 44 in 2016.



Executive Summary

ENROLLMENT

Schools Tucumcari Public enrollment has been fluctuating between 1,100 and 940 students for the past 11 years. However, it shows mostly a declining trend in the last years. In 2006/2007 district's enrollment was 1,108 students. By 2017/2018 it has declined to approximately 976 students. Projections for the next five years anticipate enrollment to be around 970 students by 2023/2024.



UTILIZATION AND CAPACITY

The table below identifies the 2017/2018 enrollment and available capacity at each TPS school. The Functional Facility Capacity for the district is 1,519 while the N.M. Adequacy Standards recommended capacity for the district based on the existing square footage is 2,723 students. The current enrollment of TPS districtwide is 976 students. The capacity analysis indicates that the district facilities are under capacity and could accommodate additional students. Based on these analyses, the district is under capacity by approximately 570 students.

| | _ | |
|------------------|-------|----------|
| Instructional | Snaco | Canacity |
| IIISII UUUIOIIAI | Space | Capacity |

| School | 2017-18 Enrollment | Maximum Facility Capacity w/Portables | Functional Facility Capacity w/Portables | Instructional Space Capacity w/ Portables @ 67% | NMAS Capacity based on Existing SF/Student |
|-------------------------|-----------------------|--|---|---|---|
| Tucumcari ES | 501 | 973 | 613 | 652 | 972 |
| Elementary Subtotal: | 501 | 973 | 613 | 652 | 972 |
| Tucumcari MS | 222 | 723 | 410 | 484 | 621 |
| Middle School Subtotal: | 222 | 723 | 410 | 484 | 621 |
| Tucumcari HS | 253 | 876 | 496 | 587 | 1,130 |
| High School Subtotal: | 253 | 876 | 496 | 587 | 1,130 |
| DISTRICT TOTALS: | 976 | 2,572 | 1,519 | 1,723 | 2,723 |

PreK enrollment includes only Developmentally Delayed Students. It does not include Typically Developing Students.

The overall Classroom Utilization Rate of TPS is 58 percent. This rate is lower than the PSCOC/PSFA recommended value of between 85 to 95 percent. The overall Facility Utilization Rate of the district is 53 percent which is below the optimal benchmark of 67 percent and indicates that the facilities could be utilized in a more efficient way. Refer to the following table for a detailed breakdown of classroom and facility utilization by school.

Executive Summary

Utilization of Spaces

| School | Grades | 2017-18 Enrollment | Existing # of Classrooms w/Portables | Classroom Utilization Rate | Facility Utilization Rate |
|-------------------------|----------|-----------------------|--------------------------------------|----------------------------------|---------------------------------|
| Tucumcari ES | PreK - 5 | 501 | 48 | 84% | 62% |
| Elementary Subtotal: | | 501 | 48 | 84% | 62% |
| Tucumcari MS | 6-8 | 222 | 28 | 49% | 49% |
| Middle School Subtotal: | | 222 | 28 | 49% | 49% |
| Tucumcari HS | 9-12 | 253 | 31 | 41% | 49% |
| High School Subtotal: | | 253 | 31 | 41% | 49% |
| DISTRICT TOTALS: | | 976 | 107 | 58% | 53% |

TECHNOLOGY

Tucumcari Public Schools has an active technology department that continues to upgrade technology infrastructure, equipment, and software to meet student and staff needs. The district utilizes several modes of transmitting technology, from Windows devices, Chromebooks, computer labs, servers, phones, network printers, and security cameras. The district has incorporated different types of technology in its classrooms including some interactive white boards, overhead projectors, document cameras, iPads, and televisions.

PREVENTATIVE MAINTENANCE PLAN

The district has a preventative maintenance plan in place. Under the 2018 assessment by PSFA of TPS facilities, the combined school facilities currently have an average Facility Maintenance Assessment Report (FMAR) ranking of 90.61 percent and fell into the "outstanding" rated category, indicating that "maintenance activities demonstrate a highly focused and goal driven supported maintenance culture. Facility conditions are exceptionally good and clearly noticeable".

Since the 2018 FMAR assessment, the district is working diligently at keeping and improving the ranking at all TPS schools.

DISTRICT FINANCIAL INFORMATION

| State/District Share: | 69% / 31% | Property Valuations: | \$ 118,464,317 |
|----------------------------------|--------------|----------------------|----------------|
| SB-9 State/District: | \$ 339,413 | Bonding Capacity: | \$ 7,107,859 |
| Last GOB Election (2015): | \$ 3,000,000 | Bonding Debt: | \$ 4,490,000 |
| Anticipated GOB Election (2019): | \$ 3,000,000 | Available Bond: | \$ 2,617,859 |

PSCOC/PSFA Awards since 2005: \$ 20,822,749

PSCOC FACILITIES ASSESSMENT DATABASE

The condition of facilities and the FAD ranking was considered in the FMP committees' prioritization of the district's needs. According to the Facilities Assessment Database (FAD) ranking, it would appear that only one of the TPS district's schools will be eligible for PSCOC/PSFA funding during the life span of this FMP; however, the FAD ranking is subject to change as the database is updated.

Executive Summary

The district should review the ranking periodically to monitor any changes and apply for PSCOC/PSFA funding when appropriate. These FAD ranking were published April 18, 2018.

TPS PSFA Facilities Assessment Database (FAD)

| School | 2018-19 Rank | Weighted NMCI |
|--------------|-----------------|------------------|
| Tucumcari ES | 487 | 17.39% |
| Tucumcari MS | 170 | 33.61% |
| Tucumcari HS | 494 | 17.05% |

State Share 69%, District Share 31% of a PSCOC/PSFA approved project.

SCHOOL DISTRICT PRIORITIES

The FMP advisory committee presented the following district priorities as recommendations to the TPS School Board on November 12, 2018.

TPS FINAL FMP 2019-2023 PRIORITIES

| FINAL | | | PSCOC / | | |
|----------|--|------------------|---------|----------|--------------|
| Priority | | Funding | PSFA | | Total 5 Year |
| RANK | Priority Description | Source | Funding | Schedule | Project |
| 1A | Life-Health-Safety-Security | SB-9 | 1 | 2019-23 | \$603,500 |
| 1B | Maintenance/Preventive Maintenance | SB-9 | 1 | 2019-23 | \$1,093,565 |
| 1C | Technology | SB-9 | 1 | 2019-23 | \$151,250 |
| | Priority 1 Subtotal: | | | | \$1,848,315 |
| | | | | | |
| 2 | Facility / Site System Renewal: | | | | |
| 2A | Tucumcari Middle School | SB-9/GOB* | 2 | 2019-23 | \$5,286,373 |
| 2B | Tucumcari Elementary School | SB-9/GOB | 3 | 2019-23 | \$4,930,623 |
| 2C | Tucumcari High School | SB-9/GOB | 4 | 2019-23 | \$1,490,841 |
| 2D | Mountain View Elementary School | SB-9/GOB | | 2019-23 | \$338,000 |
| | Priority 2 Subtotal: | | | | \$12,045,838 |
| | | | | | |
| 3 | Potential Capital Projects: | | | | |
| 3A | TPS: Create District baseball & softball complex | GOB | | 2019-23 | \$4,875,000 |
| 3B | Demolish Old Maintenance Bldg and build parking lot | GOB | | 2023 | \$369,200 |
| 3C | Demolish part of Mountain View ES and re-roof remaining building | GOB** | | 2023 | \$521,950 |
| 3D | Re-roof Auditorium Flat Roofs | GOB*** | 4 | 2020 | |
| 3E | Install turf at south TES playground | GOB | | 2023 | \$130,000 |
| 3F | TMS: Renovate Home Economics Lab | GOB | 2 | 2023 | \$377,000 |
| 3G | THS: Install campoies at Track & Field | GOB | | 2023 | \$130,000 |
| 3H | THS: Renovate Rattler Field Concessions | GOB | | 2023 | \$24,375 |
| 31 | THS: Create a storefront for customers to buy student vegetables | GOB | | 2023 | \$19,500 |
| | Priority 3 Subtotal: | | | | \$6,447,025 |
| | TPS 2019-2023 FMP Priorities TOTAL: | | | | |
| | this auticinated that DOCOC / DOCA will menticinate in | the Facility / C | 2:4- O4 | Danassal | |
| 2A | *It is anticipated that PSCOC / PSFA will participate in the Facility / Site System Renewal projects for Tucumcari Middle School at approximately 68% but could require closure / \$3,594,734 demolition of the 1970 building. PSCOC / PSFA Share: | | | | |
| 3C | | | | | \$182,000 |
| 3D | ***The probable cost to re-roof the auditorium flat roofs is included in Priority 2C. \$156,000 | | | | |

Executive Summary

SCHOOL DISTRICT CAPITAL PLAN

The district anticipates a potential budget of \$4,848,315 to meet its 2019/2023 facility needs. Tucumcari Public Schools identifies GOB, SB-9, PSCOC/PSFA, and E-rate as available funding sources. When these funds become available they will be used to begin addressing the district's most critical needs, building system upgrades, and the larger capital plan projects. According to the Facilities Assessment Database (FAD) rankings, the district anticipates the possibility to partner with PSCOC/PSFA during the life of this FMP to address the needs of Tucumcari Middle School.

TPS Anticipated Capital Funding

| Funding Source | Project Type | Year | Amount | |
|---|--|-----------|-------------|--|
| SB-9 Funds | Life-Health-Safety-Security-Code, Building System upgrades, and Technology needs | 2019-2023 | \$1,697,065 | |
| GOB Funds | Life-Health-Safety-Security-Code, major Building System upgrades, Preventive Maintenance needs, and Capital projects | 2019 | \$3,000,000 | |
| PLT Funds | Technology Needs | 2019-2023 | \$151,250 | |
| TOTAL TPS Facility Needs Anticipated Budget 2019-2023 | | | | |

The last SB-9 successful election was in 2013. Tucumcari Public Schools will ask its community to support another SB-9 election in 2019 to continue funding its life-health-safety-security, general maintenance, preventive maintenance issues, and building system upgrades. The district receives approximately \$339,413 per year from SB-9.

Tucumcari Public Schools applies for and receives E-rate funding to support its technology needs.

The district can receive direct appropriations granted by the legislature but those funds are not guaranteed and usually not large enough for a capital project. The district has not received any direct appropriations from the legislature since 2009. With current economic conditions, it is unlikely that the district will receive any direct appropriations for capital projects. The district will continue to seek available funding from various sources.

Tucumcari Public Schools has been focused on addressing its priorities and accomplishing one project at a time as funds are available. The district will continue this strategy and use the majority of its anticipated GOB funds to address the capital needs identified in this FMP. The district anticipates its next GOB election for 2019.

Acronyms and Definitions

ADMIN – Administration

ANC – Ancillary

ART - Art

ATD - Attendance Office

AUD – Auditorium **AUX** – Auxiliary

AV - Audio/Video (room, closet)

B – Boy's Toilet

BDCP – Broadband Deficiencies

Corrections Program **BKRM** – Book Room **BLDG** – Building **BR** – Boiler Room **BRK** – Break Room

Building Efficiency – Ratio - NASF/ GSF

BUS – Business

BYOD – Bring Your Own Device

CA – Career Academy **CAF** – Cafeteria

CCSS – Common Core State Standards

CLRM – Classroom CNC – Concessions CNG – Changing Room COMP – Computer Lab CON – Conference

CONF – Conference Room

COR – Corridor **COUN** – Counseling

CSCI – Computer Science (lab, room)

DD Program – Developmentally Delayed

Program

DW – Dish Wash (room, area)

E – Electrical **ENG** – English

EPSS – Educational Plan for Student

Success

EQ – Equipment **F** – File Room

FAD – Facility Assessment Database

FCI – Facility Condition Index (the ratio of need repairs to current replacement value)

FF&E – Furniture, Fixtures and Equipment

FIN – Finance Office

FMP - Facilities Master Plan

FO – Front Office FP – Free Play (area) FS – Food Service

FZ – Freezer **G** – Girl's Toilet

GSF – Gross Square Feet, or the sum of the net assignable square feet plus all other building area that is not assignable.

GYM – Gymnasium

ITV – Interactive TelevisionJ – Janitor's / Custodial Closet

HL – Hall KIT – Kitchen LA – Language Arts

LEA – Local Education Agency

LHSS - Life-Health-Safety-Security-ADA

Code

LIB – Library

LKRM – Lockers (room, area)

LNG – Lounge LOB – Lobby M – Men's Toilet

MACC - Maximum Allowable Construction

Cost

MAT – Material Storage MBPS – Megabits per second

MC – Media Center MECH – Mechanical

MNT – Maintenance (room, area)

MP – Multi-Purpose Room

MS - Media Storage

MT – Math N – Nurse

NASF – Net Assignable Square Feet, or building area that can be assigned to specific task, not including building circulation, wall thickness, mechanical equipment and toilet facilities

NMAS - New Mexico Adequacy Standards

O – Office

PE – Physical Education

PED – Public Education Department

Acronyms and Definitions

PER – Personnel Office

PERM – Permanent building

PLC- Professional Learning Communities

PORT – Portable Building

PSCOC – Public School Capital Outlay

Council

PSFA – Public School Facilities Authority

PTR - Pupil to Teacher Ratio

REF – Refrigerator

SB – Sport's Booth

SCI – Science (room, lab)

SEAT - Seating (area)

SF - Square Feet

SHWR – Shower (area)

SLP – Speech / Language Pathology

SPED – Special Education

SQFT – Square Feet

S/R – Secretary / Receptionist

SRVC – Service (area)

SRVG – Cafeteria Serving (room, area)

SS - Social Studies

State FCI – State Facilities Condition Index

State ID – State Building Identification

Number

STG – Stage

STO - Storage

SUP – Supply (room, closet)

T – Toilet (unisex)

TARE – The area allowing circulation, space

for electrical, mechanical, building and

tech systems, toilets and wall thickness

TES - Tucumcari Elementary School

THS - Tucumcari High School

TMS - Tucumcari Middle School

TPS - Tucumcari Public Schools

V - Vault

VE – Vestibule

VOC – Vocational (room, lab)

W – Women's Toilet

WAIT – Waiting (area, room)

WR – Work Room

WTS - Weight Room

Goals

Tucumcari Public Schools Mission and Vision Statements

Mission

Tucumcari Public Schools will prepare students for successful lives.

Vision

Excellence in Education

TPS Educational Goals

As part of the mission and vision statements by Tucumcari Public Schools, the overall goal is also to prepare all students for the next level of academics, from Kindergarten all the way to their senior year in high school.



TPS Mascot Rattlers

- Tucumcari Elementary School will prepare students for the next level of learning through collaboration of students, families, staff, and community
- Tucumcari Middle School is continuously improving to be a straight A school with academics as priority one, balanced by athletics and activities, and driven by our attitude and accountability. Students are the heart of all that we do!
- Tucumcari High School will provide a learning community that challenges all students to realize their greatest potential.

In order to accomplish these goals, Tucumcari Public Schools will create collaborations between students, families, staff and community. Tucumcari Public Schools will provide all their students with the best possible education by supporting and challenging each students to reach their highest level of potential. Tucumcari Public Schools has developed regulations and rules that are intended to be followed by every student. These rules are intended to drive students to reach deeper, soar higher, and achieve more during their academic years at TPS.

Relationship with TPS Community

Tucumcari Public Schools realizes community partnership is an essential part of the success of the district. The district makes every effort to involve the local community in school functions and programmatic decisions, as well as opening the school facilities for community use. The district is committed to future community involvement in all aspects of TPS. Parents and schools need to work together for the betterment of the students. Parents play an important role in providing support and building the confidence of their children, TPS supports the nurturing these partnerships.

District Facilities Alignment to New Mexico Adequacy Standards

Tucumcari Public Schools is functioning above New Mexico Adequacy Standards (NMAS) recommended square footage per student. The district has reviewed all utilization and capacity at all schools that do not meet NMAS and the issues are addressed in the district's needs and priorities.

1.1

Goals

Long Range Facility Goals

The long range facilities vision of TPS is to provide quality education to all of its students in comfortable and stimulating learning environments that are housed in safe, efficient and effective facilities that support its educational programming.

The identified goals for this Facilities Master Plan are:

- Identify goals and priorities for next General Obligation Bond
- Identify potential partnership opportunities with PSFA

DECISION MAKING AUTHORITY


The board of education commissioned the development of this 5-Year Facilities Master Plan (FMP) to serve as a reference and guide for Tucumcari Public Schools (TPS). It is recommended that this plan be reviewed yearly and modified as necessary to reflect the direction and accomplishments of TPS. It is the responsibility of TPS to review and revise the content of this FMP every five years.

FACILITIES MASTER PLAN PROCESS

Tucumcari Public Schools recognizes that success of this FMP and subsequent projects depend on the district developing strong partnerships between TPS staff, the state of New Mexico and the local community. Each entity plays a vital role in the progress of the district. Without the support of all partners, the district will not be able to move forward with its capital plan.

District and Committee Participation

Tucumcari Public Schools has developed a long, successful relationship with the local community and with the state's PSCOC/PSFA representatives. Tucumcari Public Schools continuously seeks input from



the local community and is aware of their concerns for the future of the district. To serve as a liaison between the FMP core committee, school board and the community, a steering committee was appointed by TPS to assure that all aspects of the district were represented. The committee included members from the state, district administration, faculty, department heads, staff and community.

Utilization of Data in the FMP Process

The driving force behind recommendations made by the steering committee, TPS community and board of education was quality representation of the accumulated data. Through each phase of the process, participants were presented with data and information which they analyzed, discussed and developed recommendations.

Committee members and the community were asked to provide insight behind the data that may be causing certain situations to develop in the Tucumcari area. Community members' insight is crucial in making strong recommendations of how the FMP will use funds towards capital projects that affect TPS.

1.2

Process

District Data

The data presented to partners and stakeholders during the FMP process included:

Enrollment History/Projections based on:

Births

Migration

Housing

Programming Requirements

Historical Enrollment

Community and School Profile based on:

Demographics

Educational programs

Academic Achievement

Financial Information

Educational Facility Assessments based on:

Capacity/Utilization Studies

Profiles

Priorities

Quantitative/Qualitative Analysis

Facilities Assessment Database (FAD) information

Code Review

ADA compliance




FMP Participatory Process

The Greer Stafford planning team conducted interviews with TPS administration and staff. This information along with the data listed above was used by the FMP core committee and the steering committee as a basis for discussion of TPS facilities.

Initially, the FMP steering committee had the task of reviewing information about the Tucumcari Public Schools facilities, understanding the requirements of a facility master plan and generating goals and recommendations for the district's facilities.

As the process advanced, the FMP core committee worked closely with the TPS School Board, reviewed all documents for accuracy, correlated all information acquired during the meetings, and made a final recommendation to the TPS School Board. Ultimately, the school board is responsible for approval of the final FMP.



FMP PRIORITIZATION SCHEDULE

The following is a list of all meetings and agendas in the FMP process. Refer to Section 4.2- Appendix for the sign-in sheets, agendas, and presentations of each FMP meeting.

Tucumcari Public Schools 2019-2023 FMP FMP Process & Schedule


| Participants | Meeting Description | Location | Date | Time |
|---|--|----------|-----------|----------|
| TPS Schools FMP Core Committee | Strategic Planning Meeting: Review PSFA concerns; Establish FMP Process & Schedule; Establish Roles, Responsibilities & Decision Making Process; Establish Committees; Discuss FMP Goals; District Issues, Concerns & Needs | | 13-Apr-18 | 11:30 AM |
| Greer Stafford | Site Assessment / Principal Interviews | | 13-Apr-18 | 1:00 PM |
| TPS Schools Maintenance | Review FAD & FMAR Reports | | 13-Apr-18 | 12:30 PM |
| Greer Stafford | Site Assessment / Principal Interviews | | 5-Jun-18 | 12:00 PM |
| Greer Stafford | Department Interviews | | | |
| TPS Schools Core FMP Committee | Review Site Assessment and Principal Interview Data; Review School Board Presentation; 1st FMP steering Committee Agenda; Discuss FMP Goals; District Issues, Concerns & Needs | | - | |
| TPS Schools School Board & Community | Review of FMP Process and committees; District Issues, Concerns & Needs | | - | |
| TPS Schools Core FMP Committee | Review Data; Review 1st FMP steering Committee presentation; Discuss Use of Surveys; Discuss FMP Goals; Discuss District Issues, Concerns, Needs, Priorities & Options; Develop Agenda for 2nd steering Committee Mtq | | 5-Jun-18 | 11:00 AM |
| 1st TPS Schools FMP steering Committee | Review & Discuss FMP Process & Schedule; Review Data & District Background Info; Review and input on draft Surveys; Input on FMP Goals, Issues, Concerns & Needs | | 5-Jun-18 | 5:00 PM |
| TPS Schools Maintenance | Finalize FAD & FMAR Reports | | 2-Aug-18 | 11:30 AM |
| TPS Schools Core FMP Committee | Review Data & Surveys; Review 1st FMP steering Committee input; Review 2nd FMP steering Committee presentation; Discuss FMP Goals; District Issues, Concerns, Needs, Priorities & Options; Develop Agenda for 3rd steering Committee Mtg | | 2-Aug-18 | 12:30 PM |
| 2nd TPS Schools FMP steering Committee | for 3rd steering Committee Mtg Review & Discuss Data Summary; Discuss & Input on Goals, Issues, Concerns & Needs; Finalize Student & Community Surveys; Discuss Community Meetings | | 2-Aug-18 | 5:00 PM |

| TPS Schools Core FMP Committee | Review 2nd FMP Steering Mtg input. Develop District Options & Priorities; Discuss Community Meetings & 3rd FMP Steering mtg.; Finalize Surveys | - | |
|---|--|-----------|---------|
| TPS Schools Community Meeting | Review & Discuss Data and Background Summary; Discuss & Input on Goals, Issues, Concerns & | - | |
| Greer Stafford | Issue Community Surveys | | |
| TPS Schools Core FMP Committee | Review Community Input and Survey summary; Review 3rd FMP steering Mtg presentation; Discuss and outline Priorities; Options; Discuss Capital Plan and Recommendations | | |
| 3rd TPS Schools FMP steering Committee | Review Community Input and Survey Summary; Review & Discuss Data; Discuss & Input on District Options, Priorities, Capital Plan and Recommendations | | |
| TPS Schools Core FMP Committee | Review of School Board presentation for District Priorities, Capital Plan and Recommendations. | 19-Nov-18 | 4:30 PM |
| TPS Schools School Board and Community | Review of District Priorities, Capital Plan and Recommendations. | 19-Nov-18 | 6:00 PM |
| TPS Schools School Board | Adopt FMP | 18-Feb-19 | |

Conclusion

The process of participation for the TPS FMP reflects the level of commitment of the TPS community to its students. This process was possible because of the groundwork for engagement already established by the district. The FMP document contains the priorities, objectives and goals the committees put forth.

The following page contains a graphic representation of each stage of the process to arrive at a final FMP document.




Tucumcari Public Schools • 5-Year Facilities Master Plan GS Architecture • 2019

This page intentionally left blank

Issues and Findings

ISSUES, CONCERNS AND NEEDS OF THE DISTRICT

- Security: This issue has gained more importance lately throughout all of the state's districts. Tucumcari Public Schools (TPS) has security as its top priority, as part of providing a comfortable and secure environment for staff and students. During the process of this FMP, the district reviewed different aspects related to security that would help TPS establishing districtwide security standards.
- Best Use of Existing Classroom Space: Tucumcari Public Schools is currently functioning above N.M. Adequacy Standards. The total facilities of the district exceed by 46.7 percent the recommended NMAS square footage. The district would like to address this issue to better utilize its facilities.
- *Facility Funding:* Tucumcari Public Schools passed GOB elections on 2003 and 2011. The district receives approximately \$344,839 per year from SB-9 funds. Since 2005 PSCOC/PSFA has awarded TPS \$20,822,749.
- Facility Condition: Funds have not been sufficient to maintain all TPS facilities. Yet the district has done an extraordinary job maintaining its facilities with the available funds. Currently, TPS has a Facilities Maintenance Assessment Report score of 90.61 percent. The district will continue working to improve the condition of its facilities.
- Integration of Technology into Educational Program: The district is working to improve technology districtwide, but technology evolves so fast that the district is concerned about integrating newer technologies into classrooms and have the technology resources to support its educational programs.
- Enrollment: The enrollment has been in decline for the last 12 years.
 The growing concern for Tucumcari Public Schools is that this trend
 might continue, particularly affecting the enrollment in elementary
 and middle school.
- Teacher Retention / Housing: Loss of enrollment in past years has made it difficult for the district to retain their well-qualified teaching staff and has become a concern for the district.
- State Mandated pre-K: Eastern Plains C.A.A. is the direct provider of Head Start pre-K services for children in disadvantaged households in the Tucumcari area. The state of New Mexico is working toward making pre-K education mandatory for all children. This will change the capacity needs of TPS and potentially terminate the Head Start program. The district will need to address capacity needs if this state mandated program gets approved.



1.3


Issues and Findings

This page intentionally left blank

2.1.1 OVERVIEW OF CURRENT EDUCATIONAL PROGRAMS AND FACILITIES

| 2017-18 Enrollment | 976 Students |
|--|----------------------------------|
| Number of Schools | 3 Schools |
| Types of Schools | 1 High School: 9th - 12th |
| | 1 Middle School: 6th - 8th |
| | 1 Elementary School: pre-K - 5th |
| Average TPS Pupil to Teacher Ratio (PTR) | Elementary School = 18:1 |
| | Middle School = 13:1 |
| | High School = 14:1 |
| State Charter Schools operating in TPS | None |
| Alternative Schools operating in TPS | None |
| Private Schools Operating within TPS | None |

Feeder Chart for Tucumcari Public School



SCHOOL GRADES

The Public Education Department (PED) uses a school grading system for each school across the State of New Mexico. The following are the 2017/2018 grades for TPS schools:

| Tucumcari ES | С |
|--------------|---|
| Tucumcari MS | В |
| Tucumcari HS | С |

EDUCATIONAL PROGRAMS

Federal Programs

Tucumcari Public Schools participates in and receives federal monies from the following programs:

Title I - Rural / Low Income Schools

Title II - Professional Development

Title III - English Language Acquisition

School Programs

Tucumcari Public Schools provides its students with a diverse and comprehensive package of educational programs that supplement academics.

Tucumcari Public Schools provides the following programs and services to its students throughout the district:

Special Education

Response Through Intervention(RTI)

Tutoring

Bilingual Programs

Reading First Programs

N.M. pre-K and District pre-K programs

Tucumcari Public Schools provides the following programs to Middle and High School:

Advanced Placement (AP) -

English

Math

Science

Gifted Programs

Fine Arts

Technology

Languages

Distance on-line and Interactive Television (ITV) Courses

Career Academy

Advanced Placement College Credit Programs

Extracurricular Programs

Clubs:

Football

Basketball

Volleyball

Softball

Baseball

Soccer

Track and Field

Cross Country

Cheer

Band

Other

Golf

Wrestling

Future Farmers of America (FFA)

Family, Career and Community Leaders of America (FCCLA)

2.1.2 ANTICIPATED CHANGES IN EDUCATIONAL PROGRAMS

Tucumcari Public Schools did not identify any anticipated changes in their educational programs during the time of this Facility Master Plan.

2.1.3 SHARED / JOINT USE OF FACILITIES


Tucumcari Public Schools does not have joint or shared use with any other private or public entities and does not have any plans to increase shared or joint use in the near future.

William Willia


2.2.1 MAPS

Tucumcari Public Schools Boundaries

Tucumcari Public Schools (TPS) is located in the eastern part of New Mexico in Quay County, and district schools are located in the city of Tucumcari, New Mexico. The district shares borders with Logan, San Jon, Grady, Melrose, House, Santa Rosa, and West Las Vegas School Districts. The district incorporates 996 square miles. The map of New Mexico School Districts below shows the location of Tucumcari Public Schools district in the state.




The map below shows Tucumcari Public Schools boundaries in relation to Quay County. Most of the district's students live in the City of Tucumcari and in the surrounding rural areas.



Tucumcari Public Schools Locations

In the following map each TPS school location is depicted. The district has three schools that are all located in the City of Tucumcari. The longest distance between schools is .8 miles (from the middle school to the elementary school).



0

0

0.25

0.4

0.5

8.0

Schools

- Tucumcari ES
- Tucumcari MS
- Tucumcari HS
- Tucumcari Central Office


1 mi

1.6 km

This page intentionally left blank



Tucumcari Public Schools Sites



Source: Google Maps

Tucumcari Public Schools • 5-Year Facilities Master Plan GS Architecture • 2019

This page intentionally left blank

2.2.2 FACILITY INVENTORY

Tucumcari Public Schools Facility Inventory

Tucumcari Public Schools (TPS) has three schools: one elementary, one middle, and one high school. The state identification number is 49130 and the sites are district owned. The total facility inventory square footage is 366,727 square feet. This number includes administration and support buildings.

There are no portable classrooms at TPS. Of the 108 total classrooms, 61 are general use, 28 are special use and 19 are special education. Total enrollment at the 2017/2018 PED 40-day count was 976 students. There are approximately 370 square feet per student of district facilities. Total educational facility square footage according to PSFA is 317,561 square feet. However, based on current drawings the actual total is 319,589 square feet.

FAD Ranking

The following table contains the FAD Ranking for all district schools:

TPS PSFA Facilities Assessment Database (FAD)

| School | 2018-19 Rank | Weighted NMCI |
|--------------|-----------------|------------------|
| Tucumcari ES | 487 | 17.39% |
| Tucumcari MS | 170 | 33.61% |
| Tucumcari HS | 494 | 17.05% |

The following page contains the Tucumcari Public Schools Facility Inventory Table.

Sites / Facilities

This page intentionally left blank



Sites / Facilities

TUCUMCARI PUBLIC SCHOOLS FACILITY INVENTORY 2019-2023

| Facility Name | State ID | Address | Open Date | Age (Years) | Dates of Major Additions and Renovations | State FCI | Replacement Value from State Database | Weighted NMCI | Site Acreage | Owned or Leased | Total Permanent Bldg Area | | Total Bldg Area (GSF) | Grades | Current Year Enrollment (40 day) | No. of General Classrooms | No. of Special Ed Classrooms | | | Single | Port CR % of Total | GSF Per Student |
|----------------------------|----------|---|--------------|----------------|---|-----------|---|------------------|-----------------|--------------------|---------------------------------|---|--------------------------|----------|--|---------------------------------|------------------------------------|-----|-----|--------|-----------------------|--------------------|
| Elementary | _ | | | | | | | | | | | | | | | | | | | | | |
| Tucumcari ES | 49371053 | 1623 S. Ninth St. Tucumcari, NM 88401 | 2000 | 18 | 1998, 99, 2000, 02, 06 | 52.11% | \$20,641,014 | 17.39% | 20.56 | Owned | 102,448 | 0 | 102,448 | PreK - 5 | 501 | 32 | 10 | 6 | 48 | 0 | 0% | 204 |
| | <u> </u> | | | | Sub-totals | n/a | \$20,641,014 | n/a | 20.56 | n/a | 102,448 | 0 | 102,448 | n/a | 501 | 32 | 10 | 6 | 48 | 0 | 0% | 204 |
| Middle School | | | | | | | • | | | • | | • | • | | | | • | | | | | |
| Tucumcari MS | 49371163 | 1000 S. Fifth St. Tucumcari, NM 88401 | 1970 | 48 | 1932, 1949, 1980 | 69.99% | \$14,665,778 | 33.61% | 5.40 | Owned | 83,269 | 0 | 83,269 | 6-8 | 222 | 16 | 3 | 9 | 28 | 0 | 0% | 375 |
| | | | | | Sub-totals | n/a | \$14,665,778 | n/a | 5.40 | n/a | 83,269 | 0 | 83,269 | n/a | 222 | 16 | 3 | 9 | 28 | 0 | 0% | 375 |
| High School | | | | | | | | | | | | | | | | | | | | | | |
| Tucumcari HS | 49371164 | 1001 S. Seventh St. Tucumcari, NM 88401 | 1962 | 56 | 1962, 68, 96, 2006, 11 | 52.77% | \$23,142,513 | 17.05% | 37.00 | Owned | 133,872 | 0 | 133,872 | 9-12 | 253 | 12 | 6 | 13 | 31 | 0 | 0% | 529 |
| | | | | | Sub-totals | n/a | \$23,142,513 | n/a | 37.00 | n/a | 133,872 | 0 | 133,872 | n/a | 253 | 12 | 6 | 13 | 31 | 0 | 0% | 529 |
| | | | | | School Totals | n/a | \$58,449,305 | n/a | 62.96 | n/a | 319,589 | 0 | 319,589 | n/a | 976 | 60 | 19 | 28 | 107 | 0 | 0% | 370 |
| Closed Schools | | | | | | | | | | | | | | | | | | | | | | |
| Mountain View ES | 49130000 | 1608 S. Rock Island St. Tucumcari, NM 88401 | unk. | | | n/a | \$0 | n/a | 0.00 | Owned | 22,440 | 0 | 22,440 | n/a | 0 | 0 | 0 | 0 | 0 | 0 | 0% | 0 |
| | | | | | Sub-totals | n/a | \$0 | n/a | 0.00 | n/a | 22,440 | 0 | 22,440 | n/a | 0 | 0 | 0 | 0 | 0 | 0 | 0% | 0 |
| Administrative and Support | | | | | | | | | | | | | | | | | | | | | | |
| Administration Building | 49130000 | 700 W. Amarosa Ave. Tucumcari, NM 88401 | 1965 | 53 | 2001 | n/a | n/a | n/a | 3.0 | Owned | 14,900 | 0 | 14,900 | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a |
| Maintenance (2) | 49130000 | 1019 S. Fifth St. Tucumcari, NM 88401 | unk. | | | n/a | n/a | n/a | On HS | Owned | 14,542 | 0 | 14,542 | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a |
| Transportation (2) | 49130000 | 413 W. Barnes Ave. Tucumcari, NM 88401 | unk. | | | n/a | n/a | n/a | On HS | Owned | 17,696 | 0 | 17,696 | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a | n/a |
| | | | | | Sub-totals | n/a | \$0 | n/a | 3.00 | n/a | 47,138 | 0 | 47,138 | n/a | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| | | | | | District Totals | n/a | \$58,449,305 | n/a | 65.96 | n/a | 366,727 | 0 | 366,727 | 0 | 976 | 60 | 19 | 28 | 107 | 0 | 0% | 370 |

Note

The Facility Sq.Ft. Including Portables is from the FMP drawings and it might differ from the sq.ft. identified on the FAD.

Sites / Facilities

This page intentionally left blank

This District Growth Analysis takes a look at the demographic and economic factors affecting the region of the Tucumcari Public Schools (TPS). In this section relevant demographic information regarding populations living in Quay County and the TPS service area will be documented. The first part of this section focuses on demographic factors affecting TPS, the second part focuses on economic and development factors that may contribute to growth within the district.

Data Resources

Data used in this District Growth Analysis was primarily obtained from the Bureau of Business and Economic Research (BBER), and both American Community Survey (ACS) data and U.S. Census Bureau data. The 2012-2016 ACS provides estimates regarding demographic profiles including population and economic characteristics of geographic areas in the United States. American Community Survey data is collected in one year and five year periods and provide a more detailed analysis of a given population than 10-year census data. The population estimates of the ACS do not match the official counts of the 2010 census but instead provide a reliable outlook regarding the demographic conditions of a particular geographic area. State and county data resources are also used throughout this section, please see source information in each subheading for details.


New Mexico Department of Health Statistics and Quay County data is used for detailed county wide analysis. All data is used interchangeably to yield a thorough interpretation of the demographic factors affecting Quay County and the TPS service area.

Tucumcari Public Schools Service Area Regional Perspective Quay County

The county of Quay is located in the northeastern portion of the State of New Mexico bordering Texas. The region encompassing the TPS service area is located in the western corner of Quay County

and its central facilities located within the city of Tucumcari. The region's economic development is diverse, with jobs in accommodation, food service, health care and social assistance, followed by retail trade. The largest population center in the district is the city of Tucumcari. Quay County boundaries include the communities of Endee, Forrest, Glenrio, McAlister, Montoya, Quay, Wheatland and the villages of House, Logan and San Jon. Its adjacent counties are Curry, De Baca, Guadalupe, Harding, Union and Roosevelt, Tucumcari Public Schools boundaries are shown on the map to the right.

The city of Tucumcari can be accessed traveling 176 miles east on Interstate 40 from Albuquerque. The districts estimated acreage is 637,440. Quay County has recreation options for residents and tourists alike, including the famous Route 66, the




Mesalands Dino museum, larger-than-life murals, Ute lake and Conchas Lake state park. These attractions make Tucumcari and its sister communities a prime destination for those wishing to raise a family within a small town culture while having the option to travel to the adjacent border states of Texas and Oklahoma as a point of commerce or tourism. While the unemployment rate remains higher than the overall rate for the State of New Mexico, efforts by the County and the Economic Development Center have shown this rate to be improving.

DEMOGRAPHIC TRENDS


Tucumcari Public Schools Service Area Population Comparisons


According to the 2016 American Community Survey, median age in Quay County was 47 years. The median age for the TPS Service area was 44. The Quay County age range is slightly higher than the New Mexico median age of 37 (source: ACS 5-Year Estimates, 2012-2016).



In the TPS service area, the percentage of the population that is school age is approximately 26.67 percent. The TPS service area has a high percentage of wage earning age populations, as well as a large percentage of older age categories. This is a strong sign of growth in district enrollment which

relies on the increase of families in the district to keep enrollment robust (source: ACS 5-Year Estimates, 2012-2016).






New Mexico County Median Age Comparison Map

The map to the left compares the median age per county across New Mexico in 2016. Quay County's median age is shown at 46.5, which is higher than the median age for the state of New Mexico (source: ACS 5-Year Estimates, 2012-2016).

Quay County Historic and Projected Population Estimates

Population in Quay County denoted a 3.79 percent decrease in population from 2010 to 2015. Population projections for New Mexico counties from the present through 2040 show that Quay County population will experience a boost by 2020 and begin a slight decline in population starting in 2020 through 2040 (source: UNM Geospatial and Population Studies, New Mexico County Projections July 1, 2010 to July 1, 2040; Bureau Business and Economic Research, UNM. Released Oct. 2012).



Population Growth Comparisons


Population grown comparisons between New Mexico, Quay County, the TPS service area and TPS enrollment show that the populations in Quay County and TPS enrollment have decreased slightly while the population in the TPS service area had a modest increase between 2011 and 2016. Quay County declined by the largest percentage and may be an indication of out-migration by young families possibly looking for more employment opportunities.

| Total Population | 2011 | 2016 | % Change |
|-------------------------|-----------|-----------|----------|
| New Mexico | 2,037,136 | 2,082,669 | 2.24% |
| Quay County | 9,000 | 8,555 | -4.94% |
| TPS Service Area | 6,636 | 6,737 | 1.52% |
| TPS Enrollment | 1,022 | 976 | -4.50% |

In 2011, district enrollment constituted approximately 11.36 percent of the county population, and in 2016 the percentage of enrollment increased slightly to 11.41 percent. However, the county's population decreased by 4.94 percent. The TPS service area grew a little, gaining approximately 1.52 percent population since 2011(source: ACS 5-Year Estimates, 2007-2011, 2012-2016; PED 40-Day Count Enrollment Trends, 2016-17). It must be emphasized that since the completion of this study, TPS has reported a rise in enrollment count by the year 2018.


Quay County Births

The following graph depicts the historic births in Quay County for the last 12 years. These births provide a point of reference for the number of entering kindergarten students. The graph shows that an average of 101 children were born annually from 2006 to 2017. In 2012 there were 120 births; this number provides us with an estimate of the number of entering kindergarten students in the 2017/2018 school year (source: N.M. Department of Health, 2017).



Kindergarten Enrollment

In the next chart, births to kindergarten enrollment are compared in two separate seven-year periods (the top coordinate represents the number of births in Quay County and the bottom coordinate represents the number of enrolled kindergarten students). The relationship between the two sets are analyzed so that the number of births in a given year are an indicator of the number of kindergarten enrollment five years later. For example, Year 1 of birth (2006) corresponds to Year 1 of kindergarten enrollment (2011) because a child who was born in 2006 will attend kindergarten in 2011.




The average number of Quay County births from 2006 to 2012 was 112 per year. Kindergarten enrollment at TPS included about 78.5 percent of the share of births in the county. In the Year 1 period shown above (e.g. kindergarten enrollment in 2011 at TPS, [95]; County births, [121]). This ratio decreased to 68.3 percent by Year 7 of the related period (source: PED 40-Day Count, Fall 2017; N.M. Department of Health, 2017). The change shows that TPS retains only about 70 percent of births by rate from Quay County. This comparison chart also shows a fluctuating births to enrollment comparison that is expected to remain the same in following years.

Race and Ethnicity


The following two charts represent the expressed racial and ethnic identities of the TPS service area population.

The first chart on the right reveals that 88 percent of the TPS area population identifies as white and the second largest at 5.94 percent identifies as some other race, leaving the population of black or African American at 2.5 percent (source: ACS 5-Year Estimates, 2012-2016).



Because populations that identify their ethnic origin as Hispanic or Latino can be from any race, the U.S. Census provides a category to measure Hispanic or Latino ethnic identity.

The chart on the right represents the population that identifies as Hispanic and the population that does not. It shows that 52 percent in the TPS service area population identify as Hispanic and 48 percent identify themselves as Not Hispanic or Latino (source: ACS 5-Year Estimates, 2012-2016).



TPS Service Area Household Types

There are 2,412 households in the TPS service area. Of these number, 21.3 percent have one or more children under 18 compared to 58.60 percent of households which have one or more people over 60 (source: ACS 5-Year Estimates, 2012-2016). These numbers show that the older population is larger than the younger population and this could alter the enrollment for TPS in the coming years.


| Total family households | 1,290 |
|--|-------|
| Average family size | 4.01 |
| Total Households | 2,412 |
| Average household size | 2.77 |
| Households with one or more people under 18 years | 21.3% |
| Households with one or more people 60 years and over | 58.6% |

ECONOMIC AND DEVELOPMENT ANALYSIS


Quay County and TPS Service Area Occupations

The primary industries in Quay County are in accommodation and food services followed by

retail trade and educational Services (source: N.M. Department of Workforce Solutions, 2nd Quarter 2017). Most of the industry is fueled by the economic development in the city of Tucumcari.




The TPS service area population primary occupations are management, business, science and arts, sales and office occupations, and service occupations. There are approximately 2,226 people 16 years old and older employed in the TPS service area (source: ACS 5-Year Estimates, 2012-2016).



Quay County and TPS Service Area Earnings and Incomes


According to the U.S. Census, earnings refer to the direct compensation workers collect from their occupation; while income refers to earnings as well as income derived from alternative sources such as investments, retirement/pension, and social security insurance programs. The following graph expresses the median income comparison between Quay County, the TPS service area, and the State of New Mexico.



The median income for the TPS service area in 2016 was \$26,255; the median income for Quay County which was \$28,159. Both are less than the median income for the State of New Mexico which is \$45,674. This gives a clear presentation of the limited economic advantages within the city of Tucumcari, the County and TPS service area (source: ACS 5-Year Estimates, 2012-2016).


Quay County Unemployment Rate

Unemployment rate for Quay County in 2010 was 9.4 percent. This was slightly higher than the general unemployment rate for New Mexico. Since 2010 this rate has decreased to a rate of 7.2 percent, which is still higher than the overall state unemployment rate of 6.7 percent as of 2017. A lower unemployment rate can contribute to the overall population stability for the TPS district (source: Statistics by County, UNM Bureau of Business and Economic Research, 2010-2017).



TPS Boundary Area Poverty Designation

The U.S. Census has determined that 1,440 of the total population of 6,737 residing in the TPS service area are designated as living below poverty level. Population below poverty level under 18 years is approximately 470. The largest population count living below poverty level range between the ages of 18 to 64 (source: ACS 5-Year Estimates, 2012-2016). According to the district, TPS is approved for 100 percent free lunch as part of the assistance to supplement the nutritional conditions of a low-income population.



The following charts represents the poverty designation comparison between the state of New Mexico, Quay County and Tucumcari Public Schools (source: ACS 5-Year Estimates, 2012-2016).

| 2016 | Total Population | Population Below Poverty Level | Percent Below Poverty Level |
|-------------|-------------------------|--------------------------------|--------------------------------|
| New Mexico | 2,082,669 | 426,814 | 20.49% |
| Quay County | 8,555 | 1,638 | 19.1% |
| TPS | 6,737 | 1,440 | 21.37% |

2.3

District Growth

Demographic Summary

The District Growth Analysis for TPS shows that Quay County, the city of Tucumcari and TPS enrollment have experienced a steady decline in population and school enrollment. In contrast to that decline, the TPS service area continues to reflect an increase in population, this could be attributed to the variety of employment opportunities offered in Quay County and the proximity to a post-secondary educational institution, Mesalands Community College. The city of Tucumcari is one of New Mexico's most sought after recreational options for its nature footprint and easy access to the Texas and Oklahoma state line, however the absence of a more diverse economic landscape and further career development could be the influencing factors that drive young families out of the TPS service area.

This page intentionally left blank

RELEVANT FACTORS

Tucumcari Public Schools (TPS) is located in the north-central seat of Quay County, it shares a southern border with Curry and Roosevelt counties, to the west are De Baca and Guadalupe counties, and at the northern border are Union, Harding and San Miguel counties. The State of Texas is to the east of Quay County. District enrollment is derived from the city of Tucumcari and adjacent rural areas. Population growth within the district is dependent on economic factors that influence in-migration and out-migration of Tucumcari and the TPS service area. The district is experiencing a decline in population and future plateau partly because of its remote location, a dynamic seen in many small cities in the State of New Mexico. The county has not seen significant economic development to encourage young parents to grow their families and to remain in the TPS service area.

PROJECTION METHOD

There are several methods of projecting student enrollment for school districts. The most common is the cohort-survival method. In this method, the numbers of students in a cohort (a group of students of a certain age who move together through one grade level to the next) are tracked through past grades. Based on historical enrollment data, survival rates (ratios of the number of students who remain from one year to the next) are calculated. Prevailing birth rates for kindergarten and average survival rates for other grades are used to calculate future enrollment. Ratios can be adjusted to reflect major factors identified during the growth analysis. Since the cohort-survival method addresses students who are currently in the system, it tends to be accurate for five to seven years.

The population method is another projection technique. This method uses information about a known population (usually derived from U.S. Census data) and actual attendance from the area. Projected enrollment is calculated based on the ratio of students attending classes to the general population, multiplied by the projected change for the population in the general area.

These methods were combined to project the enrollment for Tucumcari Public Schools. Overall student enrollment was calculated at the district level using the population method. This number is used as a control total for detailed cohort-survival projections at the school level. Smaller school districts can often rely on close monitoring of development activity to identify changes in student population.

2.4.1 & 2.4.2 HISTORICAL AND PROJECTED ENROLLMENT TABLES

Tucumcari Public Schools Districtwide Enrollment Trends

In 2006/2007 district enrollment was 1,108 students. Enrollment declined to 948 students during the 2014/2015 school year. Enrollment has appeared to stabilize remaining around 960 students since 2015/2016 (source: NM PED Official 40-Day Count). The declines may have multiple factors, including families moving out of the Tucumcari Public Schools service area for increased employment opportunities.

Enrollment projections for TPS anticipate that overall student enrollment will increase in the following year and then steadily decline for the next five years, remaining near the 970 student range through 2023/2024 school year. These enrollment projections were reached after analyzing the following factors:

- Enrollment trends showing a slow decline of student enrollment
- Out-migration of young families from the TPS service area
- Declining birth rates in Quay County
- Limited growth in crucial economic sectors


The following page contains tables for historical and projected enrollment and a trend graph comparing TPS districtwide enrollment trends over time.

TPS Districtwide Historical Enrollment

| Grade Level | 2006-07 | 2007-08 | 2008-09 | 2009-10 | 2010-11 | 2011-12 | 2012-13 | 2013-14 | 2014-15 | 2015-16 | 2016-17 | 2017-18 |
|-------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|
| Pre-K | 37 | 40 | 49 | 47 | 0 | 36 | 29 | 35 | 25 | 28 | 25 | 40 |
| KN | 96 | 84 | 87 | 86 | 92 | 95 | 94 | 76 | 78 | 76 | 84 | 82 |
| 1st | 86 | 97 | 87 | 84 | 89 | 85 | 99 | 102 | 77 | 77 | 76 | 82 |
| 2nd | 94 | 82 | 101 | 90 | 79 | 85 | 73 | 79 | 83 | 74 | 76 | 71 |
| 3rd | 80 | 94 | 81 | 93 | 95 | 82 | 82 | 71 | 84 | 83 | 71 | 73 |
| 4th | 66 | 78 | 87 | 86 | 97 | 96 | 82 | 80 | 67 | 81 | 83 | 69 |
| 5th | 72 | 64 | 73 | 82 | 81 | 90 | 87 | 77 | 72 | 73 | 80 | 84 |
| 6th | 69 | 80 | 69 | 79 | 81 | 74 | 82 | 78 | 75 | 74 | 70 | 74 |
| 7th | 81 | 71 | 69 | 59 | 76 | 78 | 77 | 78 | 78 | 75 | 79 | 73 |
| 8th | 105 | 71 | 65 | 79 | 66 | 76 | 70 | 68 | 73 | 75 | 70 | 75 |
| 9th | 121 | 103 | 87 | 84 | 93 | 83 | 78 | 86 | 72 | 74 | 74 | 71 |
| 10th | 82 | 97 | 92 | 80 | 70 | 75 | 61 | 55 | 67 | 61 | 65 | 69 |
| 11th | 63 | 64 | 70 | 81 | 54 | 54 | 67 | 51 | 51 | 61 | 59 | 59 |
| 12th | 56 | 39 | 60 | 61 | 69 | 49 | 51 | 54 | 46 | 52 | 55 | 54 |
| TOTAL | 1,108 | 1,064 | 1,077 | 1,091 | 1,042 | 1,058 | 1,032 | 990 | 948 | 964 | 967 | 976 |
| w/out PreK | 1,071 | 1,024 | 1,028 | 1,044 | 1,042 | 1,022 | 1,003 | 955 | 923 | 936 | 942 | 936 |

TPS Districtwide Projected Enrollment

| Grade Level | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 |
|-------------|---------|---------|---------|---------|---------|---------|
| Pre-K | 39 | 35 | 36 | 33 | 32 | 30 |
| KN | 70 | 73 | 72 | 70 | 71 | 70 |
| 1st | 93 | 70 | 73 | 72 | 70 | 71 |
| 2nd | 83 | 91 | 70 | 72 | 72 | 69 |
| 3rd | 75 | 82 | 90 | 70 | 71 | 72 |
| 4th | 69 | 74 | 81 | 90 | 69 | 71 |
| 5th | 72 | 67 | 72 | 80 | 89 | 69 |
| 6th | 85 | 71 | 66 | 72 | 79 | 88 |
| 7th | 72 | 84 | 70 | 65 | 71 | 77 |
| 8th | 79 | 70 | 82 | 69 | 65 | 69 |
| 9th | 104 | 88 | 78 | 91 | 77 | 73 |
| 10th | 65 | 99 | 73 | 72 | 85 | 70 |
| 11th | 69 | 60 | 96 | 62 | 68 | 76 |
| 12th | 57 | 64 | 56 | 86 | 58 | 65 |
| TOTAL | 1,032 | 1,029 | 1,016 | 1,004 | 977 | 970 |
| w/out PreK | 993 | 994 | 980 | 971 | 945 | 940 |



Tucumcari Public Schools Elementary Enrollment

Tucumcari Public Schools has one elementary school, Tucumcari Elementary (TES) for grades pre-K through fifth.

Historical enrollment data shows an average of 78 percent of corresponding births in Quay County are enrolled in pre-K. The school has historically averaged a peak of 569 enrolled students in 2011/2012 school year.

Projected elementary enrollment is expected to remain around 500 students until the 2019/2020 school year before beginning a gradual decrease through 2022/2023.


The following page contains historical and projected enrollment tables and an enrollment trends graph for TES.

Tucumcari Elementary School Historical Enrollment Data

| Grade Level | 2006-07 | 2007-08 | 2008-09 | 2009-10 | 2010-11 | 2011-12 | 2012-13 | 2013-14 | 2014-15 | 2015-16 | 2016-17 | 2017-18 |
|-------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|
| Pre-K | 37 | 40 | 49 | 47 | 0 | 36 | 29 | 35 | 25 | 28 | 25 | 40 |
| KN | 96 | 84 | 87 | 86 | 92 | 95 | 94 | 76 | 78 | 76 | 84 | 82 |
| 1st | 86 | 97 | 87 | 84 | 89 | 85 | 99 | 102 | 77 | 77 | 76 | 82 |
| 2nd | 94 | 82 | 101 | 90 | 79 | 85 | 73 | 79 | 83 | 74 | 76 | 71 |
| 3rd | 80 | 94 | 81 | 93 | 95 | 82 | 82 | 71 | 84 | 83 | 71 | 73 |
| 4th | 66 | 78 | 87 | 86 | 97 | 96 | 82 | 80 | 67 | 81 | 83 | 69 |
| 5th | 72 | 64 | 73 | 82 | 81 | 90 | 87 | 77 | 72 | 73 | 80 | 84 |
| TOTAL | 531 | 539 | 565 | 568 | 533 | 569 | 546 | 520 | 486 | 492 | 495 | 501 |

Tucumcari Elementary School Projected Enrollment

| Grade Level | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 |
|-------------|---------|---------|---------|---------|---------|---------|
| Pre-K | 39 | 35 | 36 | 33 | 32 | 30 |
| KN | 70 | 73 | 72 | 70 | 71 | 70 |
| 1st | 93 | 70 | 73 | 72 | 70 | 71 |
| 2nd | 83 | 91 | 70 | 72 | 72 | 69 |
| 3rd | 75 | 82 | 90 | 70 | 71 | 72 |
| 4th | 69 | 74 | 81 | 90 | 69 | 71 |
| 5th | 72 | 67 | 72 | 80 | 89 | 69 |
| TOTAL | 501 | 493 | 495 | 487 | 475 | 452 |



Middle and High School Enrollment

Middle School

The district has one middle school; Tucumcari Middle School (TMS) for grades six through eight.

Middle school enrollment shows minor decreases in enrollment in-line with districtwide enrollment. Tucumcari Middle School enrollment has historically stayed between 200 and 250 students. It is projected to stay in the low 200s, indicating a potential stability in enrollment.

High School

The district has one high school; Tucumcari High School (THS) for grades nine through twelve.


High school enrollment has declined in-line with districtwide enrollment. Overall high school enrollment has maintained in the low-to-mid 200 student range. Projections for high school enrollment anticipate that this trend will have a few peak increases during the 2019/2020 and 2021/2022 school years, eventually leveling back to the mid-200s through 2023/2024.

Tucumcari Middle School Enrollment History

| Grade Level | 2006-07 | 2007-08 | 2008-09 | 2009-10 | 2010-11 | 2011-12 | 2012-13 | 2013-14 | 2014-15 | 2015-16 | 2016-17 | 2017-18 |
|-------------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|---------|
| 6th | 69 | 80 | 69 | 79 | 81 | 74 | 82 | 78 | 75 | 74 | 70 | 74 |
| 7th | 81 | 71 | 69 | 59 | 76 | 78 | 77 | 78 | 78 | 75 | 79 | 73 |
| 8th | 105 | 71 | 65 | 79 | 66 | 76 | 70 | 68 | 73 | 75 | 70 | 75 |
| TOTAL | 255 | 222 | 203 | 217 | 223 | 228 | 229 | 224 | 226 | 224 | 219 | 222 |

Tucumcari Middle School Enrollment Projection

| Grade Level | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 |
|-------------|---------|---------|---------|---------|---------|---------|
| 6th | 85 | 71 | 66 | 72 | 79 | 88 |
| 7th | 72 | 84 | 70 | 65 | 71 | 77 |
| 8th | 79 | 70 | 82 | 69 | 65 | 69 |
| TOTAL | 236 | 225 | 218 | 206 | 215 | 234 |




Tucumcari High School Enrollment History

| 12th | 56 322 | 39 303 | 60 30 9 | 61 30 6 | 69 286 | 49 261 | 51 257 | 54 24 6 | 46 23 6 | 52 248 | 55 253 | 54 253 |
|-------------|------------------|------------------|-------------------|-------------------|------------------|------------------|------------------|-------------------|-------------------|------------------|------------------|------------------|
| 11th | 63 | 64 | 70 | 81 | 54 | 54 | 67 | 51 | 51 | 61 | 59 | 59 |
| 10th | 82 | 97 | 92 | 80 | 70 | 75 | 61 | 55 | 67 | 61 | 65 | 69 |
| 9th | 121 | 103 | 87 | 84 | 93 | 83 | 78 | 86 | 72 | 74 | 74 | 71 |
| Grade Level | 2006-07 | 2007-08 | 2008-09 | 2009-10 | 2010-11 | 2011-12 | 2012-13 | 2013-14 | 2014-15 | 2015-16 | 2016-17 | 2017-18 |

Tucumcari High School Enrollment Projection

| Grade Level | 2018-19 | 2019-20 | 2020-21 | 2021-22 | 2022-23 | 2023-24 |
|-------------|---------|---------|---------|---------|---------|---------|
| 9th | 104 | 88 | 78 | 91 | 77 | 73 |
| 10th | 65 | 99 | 73 | 72 | 85 | 70 |
| 11th | 69 | 60 | 96 | 62 | 68 | 76 |
| 12th | 57 | 64 | 56 | 86 | 58 | 65 |
| TOTAL | 295 | 311 | 303 | 311 | 288 | 284 |



2.5.1 REQUIRED AND EXISTING CLASSROOM SPACES

The following table shows the **minimum** number of classrooms required to accommodate the current enrollment at Tucumcari Public Schools (TPS); the **minimum** number of classrooms that are projected to be required in the next five years for projected enrollment at TPS; and the number of **existing** classrooms per school.

For the 2017/2018 school year, a minimum of 66 classrooms were required to accommodate the year's enrollment; while a minimum of 64 classrooms are projected to be required for the 2023/2024 projected enrollment. The district has 108 existing classrooms.


| | 2017-18 | | 2023-24 | | |
|-------------------------|----------------------------|------------------------------------|------------------------------|------------------------------------|---------------------------|
| School | Total Current Enroll | 2017-18 Minimal Clrms Rqd | Total Projected Enroll | 2023-24 Minimal Clrms Rqd | # of Existing Clrms |
| Tucumcari ES | 501 | 38 | 452 | 34 | 48 |
| Elementary Subtotal: | 501 | 38 | 452 | 34 | 48 |
| Tucumcari MS | 222 | 14 | 234 | 14 | 29 |
| Middle School Subtotal: | 222 | 14 | 234 | 14 | 29 |
| Tucumcari HS | 253 | 14 | 284 | 16 | 31 |
| High School Subtotal: | 253 | 14 | 284 | 16 | 31 |

Minimum Number of Classrooms Required

Number of existing classrooms is based upon existing permanent and portable classrooms.

The enrollment numbers identified in the previous table only reflect the number of "developmentally delayed" students (DD) in pre-K and do not include the "typically developing" students that TPS supports in its pre-K program. TPS has to provide adequate space to support all pre-K students.

The number of classrooms identified in the table reflects the minimal number of classrooms required to house students but does not take into consideration the educational programs offered at each school. The middle school and high school of TPS provide robust class offerings to their students which could require additional classrooms to adequately support their programs.



As noted in the previous tables, the district overall has more classrooms than it required for the current enrollment. As for individual schools, each TPS school has more than the minimum required number of classrooms for both the existing and projected student enrollment. The middle school and the high school each have twice the minimum number of required classrooms. During the FMP process, the district discussed options to utilize existing square footage more efficiently if enrollment continues to decrease over the next five years.

2.5.2 SPECIAL FACTORS INFLUENCING FACILITY USE

To get an overall picture of the utilization of a school it is important to take a look at how the instructional spaces are being utilized and the different factors that can influence their use. These factors include the Pupil Teacher Ratios (PTRs), special programs, student transfers, boundary areas, and other special and magnet programs. Analysis and identification of these factors will help determine their impact on the facility use of spaces.

Lower than state required PTRs

The Pupil Teacher Ratios (PTRs), determined by the New Mexico Public Education Department (PED), indicates the maximum number of students that should be assigned to each teacher in a classroom. A school's average PTR is based on department's pupil-to-teacher ratio by grade level. It is important to consider this factor since it can influence the number of teachers and classrooms required for a given facility.

The following is the allowable PTR by grade level from PED:

| Pre - K | 8 - 12 with aides |
|--------------|---|
| Kindergarten | 15 without an aide; 20 with an aide |
| 1st - 3rd | 22 |
| 4th - 6th | 24 |
| 7th - 8th | Max English class size; 27 or 150 / teacher / day |
| 9th - 12th | Max English class size: 30 or 150 / teacher / day |

The table on the following page compares the district PTR to the department's allowable PTR. The sixth column of the table shows the average PTRs of each school in the district and the average PED PTR by school level. These values are calculated based on the total current enrollment of each school and divided by the total number of assigned classrooms/teachers. The fifth column shows the average allowable PED PTR based on the grade configuration of each school.

According to the results shown on the table, the elementary schools have an average PTR of 17.78 which is close to the department's allowable PTR of 21. The middle school PTR is 13.98 and the department's allowable PTR is 27. The high school has a PTR of 14.06 and the department's allowable PTR is 30. The district overall has an average PTR of 15.27 compared to the department's allowable PTR of 26. The middle and high school values are low compared to the allowable department's allowable PTR which indicates that there are more teachers and classrooms than are required. However, this may also reflect a robust educational program in those schools.

Pupil Teacher Ratios

| School | Grades | 2017-18 Enrollment | 2017-18 # of TPS Assigned Teachers / Classrooms | PED PTR | 2017-18 TPS PTR w/ Existing Classrooms |
|-------------------------|----------|-----------------------|--|---------|---|
| Tucumcari ES | PreK - 5 | 501 | 28 | 21 | 17.78 |
| Elementary Subtotal: | | 501 | 28 | 21 | 17.78 |
| Tucumcari MS | 6-8 | 222 | 16 | 27 | 13.98 |
| Middle School Subtotal: | | 222 | 16 | 27 | 13.98 |
| Tucumcari HS | 9-12 | 253 | 18 | 30 | 14.06 |
| High School Subtotal: | | 253 | 18 | 30 | 14.06 |
| DISTRICT TOTALS: | | 976 | 62 | 26 | 15.27 |

PreK enrollment includes only Developmentally Delayed Students. It does not include Typically Developing Students.

Special Education Spaces

The Special Education (SPED) program must be reviewed whenever determining the capacity and utilization of facilities. It is important to understand the impact that special education programs have on each school. The following table identifies the

SPED Enrollment Comparisons

| School | 2017-18 Enrollment | Special Ed Enrollment | Special Ed as % of Total |
|-------------------------|-----------------------|--------------------------|-----------------------------|
| Tucumcari ES | 501 | 34 | 7% |
| Elementary Subtotal: | 501 | 34 | 7% |
| Tucumcari MS | 222 | 29 | 13% |
| Middle School Subtotal: | 222 | 29 | 13% |
| Tucumcari HS | 253 | 18 | 7% |
| High School Subtotal: | 253 | 18 | 7% |
| DISTRICT TOTALS: | 976 | 81 | 8% |

number of students at TPS that are eligible to receive C and D levels of special education instruction but do not include A and B levels from gifted and pre-school. Eight percent of the total student population receive C and D levels of special education instruction at TPS.

Student Transfers, Magnet Programs, and Other Special Programs

The district has very low student transfers into and out of the district and it does not have any other special or magnet programs at this time. This has not had an adverse effect on the district.

Boundary Areas

The district does not have any school level attendance boundaries within it.

Instructional Space Comparisons

When calculating capacity and utilization it is necessary to know how many general instruction, special education and special use spaces are located within a school in order to determine how the spaces are being utilized. General instruction classrooms are those spaces dedicated to regular education, while special use spaces are those spaces used for career, art, music, physical education, computer, science labs, which require specialized spaces.

The following two tables identify the number of instructional spaces in the three different categories. The first table shows the number of spaces that are used for general instruction, special education, and special use, while the second table shows the percentage of the overall facility.

Instructional Space Comparisons


| School | # of General Use Classrooms | # Special Ed Classrooms | # Special Use Classrooms | Total Instructional Spaces | Portable Classrooms Total # of Instructional Spaces |
|-------------------------|-----------------------------------|----------------------------|-----------------------------|----------------------------------|---|
| Tucumcari ES | 32 | 10 | 6 | 48 | 0 |
| Elementary Subtotal: | 32 | 10 | 6 | 48 | 0 |
| Tucumcari MS | 17 | 3 | 9 | 29 | 0 |
| Middle School Subtotal: | 17 | 3 | 9 | 29 | 0 |
| Tucumcari HS | 12 | 6 | 13 | 31 | 0 |
| High School Subtotal: | 12 | 6 | 13 | 31 | 0 |
| District Totals: | 61 | 19 | 28 | 108 | 0 |

The above table shows that the district has 108 permanent instructional spaces. There are no portables in the district. Of the 108 spaces, 61 instructional spaces are for general use, 19 instructional spaces are for special education, and 28 instructional spaces are for special use. Percentage wise, this corresponds to 56 percent general use spaces, 18 percent special education spaces, and 26 percent special use spaces as shown in the following table.

Instructional Space Usage as a Percent

| School | General Use % of Total Classrooms | Special Ed % of Total Classrooms | Special Use % of Total Classrooms |
|-------------------------|---|--|---|
| Tucumcari ES | 67% | 21% | 13% |
| Elementary Subtotal: | 67% | 21% | 13% |
| Tucumcari MS | 59% | 10% | 31% |
| Middle School Subtotal: | 59% | 10% | 31% |
| Tucumcari HS | 39% | 19% | 42% |
| High School Subtotal: | 39% | 19% | 42% |
| District Totals: | 56% | 18% | 26% |

Additionally, the following graph has a line at 67 percent which serves as a **benchmark** of the ideal amount of assigned spaces in a school. Only Tucumcari Elementary School is at the 67 percent benchmark. Tucumcari Middle School and Tucumcari High School have lower percentages at 59 percent and 39 percent correspondingly. Overall, the district has a percentage of 56 percent of assigned spaces there is still some room for improvement for space utilization at the middle and high schools.



2.5.3 UTILIZATION AND CAPACITY ANALYSIS

School utilization and capacity are not stationary numbers; they can change from year to year depending on the educational programs available at the school, the Pupil to Teacher Ratio, scheduling, and special needs of the students. Special programs that the district provides to meet the needs of its students can have a dramatic impact on the capacity and utilization of educational facilities. For that reason, it is recommended that the utilization and capacity of the facilities be reviewed annually and updated as necessary to realize the most effective use of the buildings and to enable the district to effectively plan for the future.

The methodology used to determine facility capacity can be slightly different for each school type due to their educational programs and use of facilities. For this Facilities Master Plan, capacities were analyzed using three different capacity calculation methods to provide a comprehensive look at school capacities. The first method is based on N.M. Adequacy Standards (NMAS) which is based on the permanent square footages of schools. The second is Functional Facility Capacity which is based on the number of instructional spaces and educational programming of each school. The third method is Instructional Space Capacity which is based on the number of instructional spaces at each school and is used as a benchmark. All three capacity analyses are based on existing facilities. The capacities are calculated for permanent plus portable facilities. The square footage used in these calculations is based on the square footage identified in the floor plans for each school. It is important to mention that the floor plans in this FMP have been updated and reflect changes to school facilities that PSFA might have not recorded.

New Mexico Adequacy Standards (NMAS) Capacity Methodology

The first capacity calculation method is based on the comparison of the existing square feet of each school to the NMAS recommended square feet per student for a new school as calculated by the New Mexico Public Schools Facility Authority (PSFA) recommendations.

The authority recommendations for overall square footage of a school are based on student population and derived from the Maximum Building Gross Square Foot Calculator located on the PSFA website. Recommended square footage per student in the NMAS is intended to functionally support all of a school's educational programs, yet encourage multi-use spaces.

In determining the capacity that the Public Schools Capital Outlay Council (PSCOC) and Public School Facilities Authority (PSFA) anticipates for a new school, the overall square footage of the school is compared to square footages in the Maximum Building Gross Square Foot Calculator and the capacity associated with that square footage. Existing schools were not originally designed utilizing today's standards, but this comparison provides insight into the capacity of existing schools and provides a benchmark.

The NMAS recommended square feet per student provides insight to student capacity of existing school facilities based on the existing square feet of each school, both permanent and portable. This method of calculating capacity provides a look at how the existing school compares to NMAS. The square footage per student is based solely on NMAS square footage and does not take into consideration the number of existing instructional spaces or the educational program of the school.

Maximum and Functional Facility Capacity Methodology

This method is based partly on the New Mexico Public Education Department (PED) Pupil to Teacher Ratio (PTR) and partly on the number of existing classrooms including portables and the educational program. This capacity method looks at the Maximum Facility Capacity and the Functional Facility Capacity of each school. These two capacities are explained in greater detail below.

Maximum Facility Capacity: This capacity is the **maximum** number of students that can be assigned to each classroom or instructional space. The maximum number of students that can be assigned to each instructional space including classrooms, gymnasiums, computer labs, and multi-purpose rooms, is based upon the PED standard for PTR or the NMAS for minimum square feet required per student, whichever is more restrictive. When calculating Maximum Facility Capacity, consideration is based solely on how many students are allowed in each instructional space. It does not take into consideration the educational program delivered at the school and how the classrooms are used. It is understood that this is not a realistic capacity for a school but serves to identify a facility's **maximum capacity.**

Functional Facility Capacity: This is the potential **best use** of classrooms or instructional spaces based on the school's educational program and facility design. Unlike Maximum Facility Capacity, this calculation includes only spaces that have assigned classes functioning within; however, it excludes specialized instructional spaces such as science labs, art, music, computer labs, specialty labs, and certain special education spaces that are not assigned classrooms. Similar to Maximum Facility Capacity, the number of students that can be assigned to each classroom is based upon the PED standard for PTR or the NMAS for square feet per student, whichever is more restrictive. This calculation of capacity allows for the distinct **functional** uses of the facility based on the number of classrooms and educational programming.

When analyzing Functional Facility Capacity of a school it is important to remember that schools with excess classrooms may convert these classrooms into 'other' use rooms such as storage, meeting rooms or may leave them as vacant classrooms. In that case, those classrooms will not show up in the final Functional Facility Capacity number. This will reduce the school's overall capacity numbers and may not be a realistic representation of the school's capacity, but rather a reflection of the current use of the instructional spaces at each school.

For elementary schools, only the general use classrooms are counted for Functional Facility Capacity. The special use rooms such as art, music, computer, and gym are not counted. Except for level D or DD classrooms, special education classrooms are not included in the functional capacity count. The functional capacity calculation accounts for the potential to fill classrooms that function as "homeroom instruction" for students.

For middle and high schools the only rooms deducted from the Functional Facility Capacity are rooms identified as special education or unassigned support labs such as computer labs, science labs, specialty labs, etc. unless they have assigned classes functioning in the space. The exclusion of special use and support classrooms provides a more realistic capacity that reflects the educational program of the school.

Instructional Space Capacity Methodology

This capacity method, also known as the 67 Percent Instructional Space Capacity, is based partly on the New Mexico Public Education Department (PED) Pupil to Teacher Ratio (PTR) and partly on the number and size of existing classrooms including portables.

The 67 Percent Instructional Space Capacity is a BENCHMARK based on the Instructional Space Capacity calculations to provide insight to TPS. It is based on the premises that a benchmark school capacity of 67 percent of its maximum capacity is an ideal capacity. An overall instructional capacity of 67 percent should be attainable for schools. The majority of elementary, middle and high schools in New Mexico are able to achieve this rate. If a school is below the benchmark capacity of 67 percent, the district needs to review the educational program of the school and develop a plan to increase the utilization and efficiency of the school.

Capacity Analysis Based on the New Mexico Adequacy Standards (NMAS) Method

The following table shows the current TPS enrollment and the NMAS recommended square feet per student per school. The NMAS recommended facility square footage is based on the current enrollment and the NMAS current recommended square feet per student. The differences between existing school square footages and NMAS recommended facility square footages are shown in the subsequent columns for comparison. The table also contains the NMAS recommended student capacity based on the existing square footage of each school in the district. The total combined NMAS totals are calculated across the bottom of the table.

Tucumcari Public Schools has three schools with a 2017/2018 student population of 976 and an overall square footage of permanent and portable facilities of 319,589 according to the FMP floor


plans. This square footage is comprised of 108 permanent and portable instructional spaces.

NMAS Recommended Square Footage

| School | 2017-18 Enrollment | NMAS CURRENT Rcmd SF/Student | NMAS Rcmd Facility SF | Actual Facility SF (w/Portables) | Difference | Ratio of Existing SF to Rcmd SF |
|-------------------------|-----------------------|---------------------------------------|-----------------------------|--|------------|---------------------------------------|
| Tucumcari ES | 501 | 128 | 63,910 | 102,448 | 38,538 | 160% |
| Elementary Subtotal: | 501 | | 63,910 | 102,448 | 38,538 | 160% |
| Tucumcari MS | 222 | 159 | 35,331 | 83,269 | 47,938 | 236% |
| Middle School Subtotal: | 222 | | 35,331 | 83,269 | 47,938 | 236% |
| Tucumcari HS | 253 | 197 | 49,805 | 133,872 | 84,067 | 269% |
| High School Subtotal: | 253 | | 49,805 | 133,872 | 84,067 | 269% |
| DISTRICT TOTALS: | 976 | | 149,046 | 319,589 | 170,543 | 214% |

The NMAS recommended square footage for the three schools based on 976 students is 149,046 square feet. This recommendation is 170,543 square feet less than the existing square footage of 319,589. Tucumcari Elementary School exceeds NMAS recommendations by 38,538 square feet. The middle school exceeds the recommendations by 47,938 square feet. The high school exceeds NMAS recommended square footage by 84,067 square feet. The NMAS recommendations do not include full-size gymnasiums for elementary schools, or auxiliary gymnasiums and performing arts centers for middle and high schools.

The next figure shows the NMAS recommended and existing square footages for each school level as well as the difference between the two.



The following table shows the NMAS recommended student capacity which is based on the existing square footage of each school in the district including portables. The NMAS recommended overall district capacity for the three schools is based on a total of 319,589 square feet and the NMAS calculator. The recommended capacity is approximately 2,723 students. This is 1,747 students more than the 2017/2018 student population of 976.

NM Adequacy Standards Capacity

| School | Grades | 2017-18 Enrollment | NMAS Rcmd Facility SF | Actual Facility SF (w/Portables) | NMAS Capacity |
|-------------------------|----------|-----------------------|-----------------------------|--|------------------|
| Tucumcari ES | PreK - 5 | 501 | 63910 | 102,448 | 972 |
| Elementary Subtotal: | | 501 | 63,910 | 102,448 | 972 |
| Tucumcari MS | 6-8 | 222 | 35,331 | 83,269 | 621 |
| Middle School Subtotal: | | 222 | 35,331 | 83,269 | 621 |
| Tucumcari HS | 9-12 | 253 | 49,805 | 133,872 | 1,130 |
| High School Subtotal: | _ | 253 | 49,805 | 133,872 | 1,130 |
| DISTRICT TOTALS: | | 976 | 149,046 | 319,589 | 2,723 |

These capacities are based upon square foot per student and include portables.

Based on this method all TPS schools are under capacity. Tucumcari Elementary School has a NMAS capacity of 972 students. It's 2017/2018 enrollment is 501 students. Tucumcari Middle School has a NMAS capacity of 621, and it's enrollment is 222 students. Tucumcari High school has a NMAS capacity of 1,130 and has an enrollment of 253. The results of this method show that there is room for improvement to utilize square footage more efficiently at all TPS schools, especially at the high school which has a capacity that is significantly higher than its enrollment compared.

Capacity Analysis Results Based on the Functional Facility Capacity Method

The following table shows Maximum Facility Capacity and Functional Facility Capacity. This analysis indicates that the district's Maximum Facility Capacity with portables is 2,572 students and its Functional Facility Capacity with portables is 1,519 students. Tucumcari Public Schools 2017/2018 enrollment is 976 which is 543 students less than the Functional Facility Capacity.

Functional Facility Capacity Compared to Maximum Facility Capacity

| School | Grades | 2017-18 Enrollment | Existing # of Classrooms w/ Portables | Maximum Facility Capacity w/Portables | Functional Facility Capacity w/Portables |
|-------------------------|----------|-----------------------|---|--|---|
| Tucumcari ES | PreK - 5 | 501 | 48 | 973 | 613 |
| Elementary Subtotal: | | 501 | 48 | 973 | 613 |
| Tucumcari MS | 6-8 | 222 | 28 | 723 | 410 |
| Middle School Subtotal: | | 222 | 28 | 723 | 410 |
| Tucumcari HS | 9-12 | 253 | 31 | 876 | 496 |
| High School Subtotal: | | 253 | 31 | 876 | 496 |
| DISTRICT TOTALS: | | 976 | 107 | 2,572 | 1,519 |

These capacities are based upon the number of classrooms in the District and the educational program.

The Functional Facility Capacity results show that all TPS schools are under capacity. Tucumcari Elementary School has a functional capacity of 613 and it enrollment is 501. Tucumcari Middle School has a functional capacity of 410 and its enrollment is 222. Tucumcari High School has a functional capacity of 496 and its enrollment is 253.

Based on the functional capacity, the district could accommodate an additional 543 students with the current educational program and still remain under the Functional Facility Capacity threshold.

Capacity Analysis Results Based on the Instructional Space Capacity Method

The following table shows the results of the third method of analysis, the 67 Percent Instructional Space Capacity. This method serves as a benchmark and can be used to validate the values obtained from the other two capacity methods.

Instructional Space Capacity - 67%

| School | Grades | 2017-18 Enrollment | Existing # of Classrooms w/Portables | Instructional Space Capacity w/ Portables @ 67% |
|-------------------------|----------|-----------------------|--|---|
| Tucumcari ES | PreK - 5 | 501 | 48 | 652 |
| Elementary Subtotal: | | 501 | 48 | 652 |
| Tucumcari MS | 6-8 | 222 | 28 | 484 |
| Middle School Subtotal: | | 222 | 28 | 484 |
| Tucumcari HS | 9-12 | 253 | 31 | 587 |
| High School Subtotal: | | 253 | 31 | 587 |
| DISTRICT TOTALS: | | 976 | 107 | 1,723 |

PreK enrollment includes only Developmentally Delayed Students. It does not include Typically Developing Students.

According to the results, the district's Instructional Space Capacity is 1,723 students which is 747 students more than its current enrollment of 976. All of TPS schools are under capacity. Tucumcari High School has a capacity of 587 and could accommodate 334 additional students. Tucumcari Middle School has a capacity of 484 and could accommodate 262 additional students. Tucumcari Elementary School has a capacity of 652 and could accommodate 151 additional students.

Capacity Analysis Summary

The table in the following page shows a summary of the three capacity methods used for TPS: **NM Adequacy Standards Capacity**, **The Maximum Facility Capacity** / **Functional Facility Capacity** and the **67 Percent Instructional Space Capacity**. According to the results of all three methods, the capacities exceed the current student population of the schools. The capacities show that all the schools at TPS are oversized.


The Functional Facility Capacity and the 67 Percent Capacity methods are better indicators of facility capacity than the NMAS capacity method because they take into consideration gymnasiums, closed portable classrooms, and other support spaces that significantly increase the available space.

Instructional Space Capacity

| School | 2017-18 Enrollment | Maximum Facility Capacity w/Portables | Functional Facility Capacity w/Portables | Instructional Space Capacity w/ Portables @ 67% | NMAS Capacity based on Existing SF/Student |
|-------------------------|-----------------------|--|---|---|---|
| Tucumcari ES | 501 | 973 | 613 | 652 | 972 |
| Elementary Subtotal: | 501 | 973 | 613 | 652 | 972 |
| Tucumcari MS | 222 | 723 | 410 | 484 | 621 |
| Middle School Subtotal: | 222 | 723 | 410 | 484 | 621 |
| Tucumcari HS | 253 | 876 | 496 | 587 | 1,130 |
| High School Subtotal: | 253 | 876 | 496 | 587 | 1,130 |
| DISTRICT TOTALS: | 976 | 2,572 | 1,519 | 1,723 | 2,723 |

PreK enrollment includes only Developmentally Delayed Students. It does not include Typically Developing Students.

Finally, the graph below shows a comparison of the district total capacities of all three methods of analysis. Based on the current square footage of existing facilities, the current educational program, and the number of instructional spaces, the district can accommodate at least 543 additional students. From this number, around 112 students correspond to the elementary school, 188 to the middle school, and 243 to the high school.




Utilization Studies

There are two indicators of space utilization, **Classroom Utilization Rate** and **Facility Utilization Rate**. The first indicator, Classroom Utilization Rate, is based on the percentage rate of assigned classroom occupancy. Whereas the second indicator, Facility Utilization Rate, is the percentage of assigned spaces compared to unassigned classroom spaces during a typical school day. Both indicators are explained in greater detail on the following pages.


Classroom Utilization Rate Indicator


The Classroom Utilization Rate indicator is based on the percentage rate of assigned classroom occupancy and does not include instructional support spaces. The State of New Mexico strives for an optimal instructional space utilization of 95 to 100 percent of general use classrooms for elementary schools and an optimal rate of 80 to 95 percent for middle and high schools. These utilization percentages are not to be confused with the capacity studies just discussed in this FMP. The 95 to 100 percent utilization rate identified for elementary schools and the 80 to 95 percent utilization rate identified for middle and high schools refers




to utilization of the scheduled and assigned classrooms or instructional spaces. For example, if an elementary classroom / instructional space has a capacity of 22 students, the state anticipates 21 to 22 students to occupy that space, or a utilization rate of 95 to 100 percent.

Tucumcari Public Schools has an average Classroom Utilization Rate of 58 percent districtwide. This rate is considerably below the 80 to 95 percent NMAS recommended rate. Tucumcari Elementary School has a classroom utilization rate of approximately 84 percent, the middle school rate is 49 percentand the high school rate is 49 percentand the high school rate is 41 percent. The TPS schools Classroom Utilization Rates are not consistent with the N.M. utilization guidelines of 80 to 95 percent. This indicates room for improvement in the use of assigned classrooms at all TPS schools. These results are shown graphically in the next figure.









Facility Utilization Rate Indicator


The Facility Utilization Rate indicator is the percentage that indicates the number of assigned and unassigned classroom spaces during a typical school day. The Facility Utilization Rate separates classrooms that are assigned on a given school day and the number of classrooms that are used for support spaces or are unassigned.

An optimal benchmark for facility utilization for schools is 67 percent of its maximum capacity. For example, a school with 12 total classrooms at 67 percent capacity would have eight assigned classrooms and no more than




four unassigned classrooms. Elementary school unassigned classrooms for support are different from the middle and high school levels.

67% Capacity of a 12 Classroom School



The chart on the right shows the percentage of assigned classroom spaces support spaces of the overall district. District students occupy 53 percent of the instructional spaces during the school day. The 53 percent overall Facility Utilization Rate does not reflect the capacity of students in the classroom spaces, only that 53 percent of those spaces are used during the day by any number of students.


Currently, the elementary school has a facility utilization rate of 62 percent, the middle school has a rate of 49 percent and the high school has a rate of 49 percent.



All the schools have facility utilization rates that are below the 67 percent benchmark. This indicates that there is an excess of instructional spaces and an above average number of instructional spaces that are not assigned and being used as support spaces in the school.







Utilization Studies Summary


The following table shows each TPS school, their Classroom Utilization Rate and their Facility Utilization Rate.

Utilization of Spaces


| School | Grades | 2017-18 Enrollment | Existing # of Classrooms w/Portables | Classroom Utilization Rate | Facility Utilization Rate |
|-------------------------|----------|-----------------------|--------------------------------------|----------------------------------|---------------------------------|
| Tucumcari ES | PreK - 5 | 501 | 48 | 84% | 62% |
| Elementary Subtotal: | | 501 | 48 | 84% | 62% |
| Tucumcari MS | 6-8 | 222 | 28 | 49% | 49% |
| Middle School Subtotal: | | 222 | 28 | 49% | 49% |
| Tucumcari HS | 9-12 | 253 | 31 | 41% | 49% |
| High School Subtotal: | | 253 | 31 | 41% | 49% |
| DISTRICT TOTALS: | | 976 | 107 | 58% | 53% |

PreK enrollment includes only Developmentally Delayed Students. It does not include Typically Developing Students.

In addition, the following graphs present a comparison of each school utilization rates to the recommended rates. The first graph shows that none of the TPS schools have a classroom utilization rate that complies with the state's recommended values of 95 to 100 percent or 80 to 95 percent. Tucumcari Elementary School has the highest classroom utilization rate at 84 percent. This value is not far from the recommended rate. The middle school and the high school have classroom utilization rates that are below the recommended rate of 80 percent to 95 percent. Tucumcari High School is the school that has the lowest classroom utilization rate at 41 percent. Tucumcari Middle school classroom utilization rate is 49 percent.



In regard to the Facility Utilization Rates, all TPS schools have rates that are below the 67 percent optimal benchmark rate. Tucumcari Elementary School is the school with the highest facility utilization rate at 62 percent while both Tucumcari Middle School and Tucumcari High School have the lowest rate at 49 percent. Low facility utilization rates indicate that there is an excess of instructional spaces and the facilities are under-utilized at these schools; however, this could also indicate a robust educational program in these schools.



Utilization and Capacity

Utilization and Capacity Summary

Tucumcari Public Schools (TPS) has experienced declines in its enrollment over the past 10 years. As a result, declining enrollment has left TPS schools under capacity. The previous analyses indicate that the overall district is under capacity and has a low classroom utilization rate.

The district has reported an increase in its enrollment for the 2018 fall period, but the forecasted economic conditions in the local area could cause the student enrollment to continue its declining trend in the next 5 years.

The three capacity methods showed that the district can accommodate ,at a minimum, approximately 543 additional students. From this number, around 112 students correspond to the elementary school, 188 to the middle school, and 243 to the high school. However, demographic and enrollment analyses indicate that the overall student population of TPS may decrease in the coming years, which may increase the under-utilized spaces in the district. The TPS school that has the highest under utilized space is Tucumcari High School.

Regarding the utilization studies, the district is below the recommended rates in both indicators. The elementary school shows the highest classroom utilization rate at 84 percent which is still below the recommended 95 percent rate. The middle school has a classroom utilization rate of 49 percent and the high school of 41 percent. Both schools have classroom utilization rates that are significantly below the 80 percent to 95 percent recommended rate.

The facility utilization rates also indicate that the facilities in the district are underutilized. Tucumcari ES is the school that shows the highest facility utilization rate at 62 percent which is close to the optimal benchmark rate of 67 percent indicating that the school is close to a good balance between assigned classrooms and support or unassigned classrooms. On the contrary, the middle school and the high school show values that are low compared to the benchmark rate of 67 percent. Both schools have a facility utilization rate of 49 percent. Low values of facility utilization indicate that the facilities could be utilized in a more efficient way.

Tucumcari Public Schools does not have plans to reduce any permanent square footage on the schools. The district identified the possibility to dispose of the old maintenance building and a portion of Mountain View ES building which will reduce square footage at the district facilities. At the high school level, the district does not have any plans to reduce square footage so the school can maintain its robust educational program; however, if enrollment continues to decline the district will revisit the utilization of the school and take appropriate measures to provide efficient utilization.

During the FMP process, TPS acknowledged that the majority of its facilities are under-utilized and discussed the importance of reducing square footage in order to meet adequacy standards and reduce maintenance costs of district facilities. Unfortunately, the availability of funding has made it difficult for the District to address the excess of space. Tucumcari Public Schools will continue to monitor its declining enrollment and will make adjustments as necessary and as funds allow it in order to keep effective utilization.

Utilization and Capacity

2.5.4 STRATEGIES TO MEET SPACE NEEDS

Tucumcari Public Schools realizes the need to reduce square footage in district's facilities because the majority of the schools are oversized and under capacity since the enrollment has been declining for the past 10 years and it may continue to decline. During the FMP process, the district discussed and identified different strategies that could be implemented to reduce square footage and to reduce maintenance costs.

At the present time, TPS does not have any plans to reduce square footage at any of its schools in order to maintain their robust educational program; however, if the enrollment continues to decrease, the district would need to take appropriate measures to provide efficient utilization of all its schools.

The district has identified portion of Mountain View ES facility for demolition. This school closed years ago, but the district leases the property to a head start school; however, TPS is still in charge of the maintenance and operation of the building. The district would like to demolish the majority of the building and keep the section where the head start program is housed.

Tucumcari Public Schools also identified the old maintenance building for demolition since the building is an old facility that would require a significant amount of upgrades to extend its useful life.

2.5.5 UNDER-UTILIZED SPACES

Tucumcari Public Schools has identified and discussed some of the available options to address the under-utilized facilities in the district; however, availability of funds is a concern to the district and makes it difficult to implement these strategies.

As previously mentioned, Tucumcari High School is the school that has the most underutilized space and could accommodate around 240 additional students; however, the school also has a robust educational program and requires a large number of classrooms to adequately support its programs. Currently, TPS does not have any plans to reduce square footage at this school so it can maintain its educational program. If the enrollment continues to decrease, the district would need to revise the utilization of the facilities and take appropriate measures to provide efficient utilization of the school.

As identified above, the District would like to demolish the old maintenance's building and a section of the Mountain View ES facility to address underutilized space. Tucumcari Public Schools would like to perform this action as soon as funding allows. This actions will result in a reduction of square footage and reduction of maintenance and operation costs.

Utilization and Capacity

Lils of the state of the state

Total Capital Needs

CAPITAL IMPROVEMENT PROJECT HISTORY

Tucumcari Public Schools (TPS) has developed capital improvement plans that address the highest priorities as funds have been available. The district has been successful in partnering with the local community and the state's Public School Capital Outlay Council (PSCOC). The local community has shown its support of the district by passing General Obligation Bonds (GOB) and Senate Bill-9 (SB-9) mill levies. With the support of the local community, TPS has been successful in partnering with PSCOC on qualifying projects. The district continues to maintain their facilities through prudent use of available funding. The following list shows a history of GOB bond elections for TPS since 2003.

| Bond Election Date | Election Amount |
|---------------------------|-----------------|
| February, 2003 | \$750,000 |
| February, 2011 | \$2,000,000 |
| February, 2015 | \$3,000,000 |
| Total | \$5,750,000 |

As the chart above shows, the community has supported TPS by passing General Obligation Bonds (GOB) for a total of \$5,750,000. The district anticipates its next GOB election in 2019.

The last successful SB-9 mill levy election was held in 2013. The next SB-9 election will be held in 2019. The district receives approximately \$339,413 per year from SB-9.

The district has also received PSCOC/PSFA awards for a total of \$20,822,749 since 2005. The majority of these funds were for the Tucumcari High School replacement project.

Using funds from these sources, the district has been able to accomplish various capital projects throughout the district. The following table shows the capital projects that the district has completed since 2005 and the funding source of each project.

TPS Capital Projects since 2005

| Year | School | Project | Funding Source |
|------|--------------|----------------------------------|------------------|
| 2006 | Tucumcari ES | Kindergarten Addition | GOB |
| 2006 | Tucumcari HS | Phase 1 | GOB & PSCOC/PSFA |
| 2010 | Rhoades Gym | Total Renovation | GOB |
| 2010 | Rhoades Gym | New Rubber Floor | GOB |
| 2011 | Tucumcari HS | Phase 2 | GOB & PSCOC/PSFA |
| 2011 | Tucumcari HS | Rattler Gym Renovation | GOB |
| 2012 | Tucumcari ES | New Evaporative Cooling | SB-9 |
| 2012 | Tucumcari ES | Roof Replacement | GOB & PSCOC/PSFA |
| 2012 | Green House | Total Renovation For Hydroponics | GOB |
| 2016 | Tucumcari ES | Lighting Upgrade | SB-9 |
| 2016 | Tucumcari MS | Lighting Upgrade | SB-9 |
| 2017 | Tucumcari ES | Parking Lots Upgrade | SB-9 |
| 2018 | Tucumcari MS | Roof Replacement | GOB |
| 2018 | Tucumcari MS | HVAC System Upgrade | GOB |

Total Capital Needs

CURRENT AND ANTICIPATED FINANCIAL RESOURCES

General Obligation Bonds (GOB)

The 2018 assessed land valuation of TPS was \$118,464,317. The TPS maximum bonding capacity at 6.00 percent of its 2018 assessed valuation was approximately \$7,107,859. As of June 2018, the district is bonded 63.2 percent to capacity which is \$4,490,000. The current tax rate is one that is sustainable by the community; therefore, the district does not anticipate increasing the tax rate at this time. Currently TPS bonding capacity is \$2,617,859. The district anticipates its next GOB election in 2019 for \$3,000,000, which will maintain the current tax rate.

Mill Levies

Tucumcari Public Schools has a two mill levy in place to take advantage of state matching funds under the N.M. Senate Bill 9 (SB-9) program. SB-9 revenues provided approximately \$339,413 for the 2017/2018 school year for general maintenance and small projects. The levy is subject to renewal through an election every six years. The last SB-9 successful election was in 2013, the next SB-9 election is scheduled for 2019.

The district does not have a mill levy in place allowed under N.M. House Bill 33 (HB33). HB33 funding is generally used for renovation, additions to existing facilities and technology. Mill levies under HB33 must be approved through an election every five years.

Deficiencies Correction Unit Funding

N.M. House Bill 31 (HB31) was a funding program that was established to provide additional funding to New Mexico Public School Districts to primarily address health and safety needs. The district has received funding under HB31 to address health and safety needs at all school campuses within the district. All identified projects receiving funds from this source have been completed. The fund was administered by the New Mexico Department of Education Deficiencies Correction Unit (DCU) which has evolved into the Public School Facilities Authority (PSFA). The PSFA / DCU provided funds to TPS for addressing health and safety needs throughout the district. The exact amount of funds provided to the district could vary slightly based upon the final project completion cost. There is no additional funding available for school districts through this program at this time.

Broadband Deficiencies Correction Program

The state created a broadband deficiencies correction program in 2016 which provides funding to assist New Mexico Public School districts in increasing their broadband or technology capabilities. This program works with funds from the district, E-rate and PSCOC and is overseen by PSFA. Tucumcari Public Schools has not applied for funding through this program, but could apply in the future.

School Security Funding

The state created a school security program in 2018 which provides funding to assist New Mexico public school districts in upgrading security at school campuses as needed. This program is funded through PSCOC and overseen by PSFA. Tucumcari Public Schools did not apply for school security funding in 2018, but could apply in the future. This funding through PSCOC for school security projects could require a district funding match.

Total Capital Needs

Legislative Appropriations

Tucumcari Public Schools can receive special appropriations granted by the legislature. Amounts appropriated can vary or can be zero. The amount of money from legislative appropriations accepted by the district will be deducted from critical capital outlay funds. The district has not received any legislative appropriations since 2009. Currently, the district has an offset of \$0.

Federal Impact Aid

Tucumcari Public Schools does not receive PL874 Federal Impact Aid funds. Federal Impact Aid funds are provided to school districts in lieu of local property taxes for students residing on federal lands within their service area. This includes Native American lands, military installments, federal public domain, and national forest lands.

Grants/E-Rate

Tucumcari Public Schools is an E-rate funded district and receives a variable amount of funding every year for technology and broadband projects through the E-rate program. The district uses SB-9 funds to supplement its technology program.

Payment in Lieu of Taxes

Tucumcari Public Schools receives approximately \$30,250 from wind farms annually. It can be allocated to any TPS need. The money is received in lieu of taxes. Private wind generation companies pay the county a yearly sum for the lease of land and air space to operate electricity generating windmills that are located on school district property. The county appropriates \$30,250 to TPS yearly.

Public School Capital Outlay Act

Effective September 1, 2003 any school district can apply for capital outlay regardless of its percentage of indebtedness. Priorities for funding of school projects are determined by using the ranking of each public school in the state. The rankings are generated from information in the facilities assessment database which is based on the statewide adequacy standards. All districts must present their needs before the PSCOC which is comprised of nine members. The following or their designees are identified in statute: the Governor, the Secretary of the Department of Finance and Administration, the Director of the Construction Industries Division of the Regulation and Licensing Department, the Secretary of Education, the President of the State Board of Education, the President of the State School Boards Association, and the Directors of the Legislative Education Study Committee, Legislative Finance Committee, and the Legislative Council Services.

The Council shall establish criteria to be used in public school capital outlay projects that receive grant assistance including the feasibility of using design, build and finance arrangements; the potential use of more durable construction materials; and any other financing or construction concept that may maximize the dollar effect of the state grant assistance.

No more than 10 percent of the combined total of grants in a funding cycle shall be used for retrofitting existing facilities for technology infrastructure. No application for grant assistance shall be approved unless the Council determines that: the project is needed and included in the school district's five-year

Total Capital Needs

facilities plan; the school district has used its capital resources in a prudent manner; the school district has provided insurance for buildings; the school district has submitted a five-year facilities master plan that includes enrollment projections, a current preventive maintenance plan, and projections for the facilities needed in order to maintain a full-day kindergarten program; the school district is willing and able to pay any portion of the total cost not funded with grant assistance from the fund; the application includes the capital needs of any charter schools located in the district; and the school district has agreed to comply with reporting requirements.

Tucumcari Public Schools must compete with all other New Mexico public school districts for this funding. As of April 2018, TPS's match for this funding source is 34% and the state's match is 66%. Since 2005 TPS has received \$20,822,749 from PSCOC for capital projects. Refer to the page 3.1.1 for a list of TPS capital projects that have received PSCOC funds.

TPS TOTAL 2019/2023 ANTICIPATED CAPITAL NEEDS AND FUNDING SOURCES

The total 2019/2023 facilities needs identified for TPS during the FMP process is approximately \$20,368,308. This is the total needs of all district facilities including Tucumcari Elementary School, Tucumcari Middle School, Tucumcari High School, Mountain View Elementary School, and all district support facilities.

The 2019/2023 facility needs of TPS has been broken down into eight funding categories to identify the type of need and potential funding source to address that type of need:

- 1. BS-GOB: Building Systems Upgrades–GOB: Identified building/site systems upgrades anticipated to be funded by GOB.
- 2. BS-SB9: Building Systems Upgrades–SB-9: Identified building/site systems upgrades anticipated to be funded by SB-9.
- 3. L-GOB: Life-Health-Safety-Security–GOB: Identified life, health, safety, security, code and ADA needs anticipated to be funded by GOB.
- 4. L-SB9: Life-Health-Safety-Security–SB-9: Identified life, health, safety, security, code and ADA needs anticipated to be funded by SB-9.
- 5. MP-GOB: Miscellaneous Capital Projects–GOB: Identified miscellaneous capital projects, not related to building system upgrades, anticipated to be funded by GOB.
- 6. MP-SB9: Miscellaneous Capital Projects–SB-9: Identified miscellaneous capital projects, not related to building system upgrades, anticipated to be funded by SB-9.
- 7. PreVent: Preventive Maintenance: Identified miscellaneous preventive maintenance projects anticipated to be funded by SB-9.
- 8. Tech: Technology: Identified technology projects anticipated to be funded by E-rate, PLT and SB-9 funds.

The table on the following page lists the sources of funding that the school utilizes to address maintenance needs, capital projects, and broadband:

Total Capital Needs

TPS Funding Sources

| Sources of Funding for: | GOB | SB-9 | E-Rate | PLT |
|---|-----|------|--------|-----|
| Life/Health/Safety/Security/Code Issues | | ✓ | | |
| Maintenance / Preventive Maintenance | | ✓ | | |
| Technology / Broadband | | | ✓ | ✓ |
| Building Systems Upgrades | ✓ | ✓ | | |
| Capital Projects | ✓ | | | |

The following table summarizes the type of need, its potential funding source, and probable costs.

TPS Project Cost by Funding Source

| Project Type | Funding Source | Total Projects Cost | Percentage of Total |
|---|-------------------|------------------------|---------------------|
| Building Systems Upgrades | GOB | \$5,228,392 | 26% |
| Building Systems Upgrades | SB-9 | \$2,202,191 | 11% |
| Life/Health/Safety/Security/Code Issues | GOB | \$3,915,051 | 19% |
| Life/Health/Safety/Security/Code Issues | SB-9 | \$1,303,703 | 6% |
| Miscellaneous Projects | GOB | \$6,447,025 | 32% |
| Miscellaneous Projects | SB-9 | \$0 | 0% |
| Preventive Maintenance | SB-9 | \$1,093,565 | 5% |
| Technology | GOB & E-Rate | \$151,250 | 1% |
| DIS | STRICT TOTALS | \$20,341,178 | 100% |

To meet the 2019-2023 facilities needs of TPS based on the above funding categories, the district anticipates a potential budget of \$4,848,315, which does not include any funds from PSCOC.

TPS Anticipated Capital Funding

| Funding Source | Project Type | Year | Amount | | | | | | | |
|--|--|--------------|-------------|--|--|--|--|--|--|--|
| SB-9 Funds | Life-Health-Safety-Security-Code, Building System upgrades, and Technology needs | 2019-2023 | \$1,697,065 | | | | | | | |
| Life-Health-Safety-Security-Code, major GOB Funds Building System upgrades, Preventive Maintenance needs, and Capital projects | | | | | | | | | | |
| PLT Funds Technology Needs 2019-2023 | | | | | | | | | | |
| TC | TAL TPS Facility Needs Anticipated Budge | et 2019-2023 | \$4,848,315 | | | | | | | |

The potential budget for TPS identifies SB-9, GOB, PLT, and E-rate as available funding sources to address its facility needs. At this time, due to the current Facilities Assessment Database (FAD) ranking of district facilities, TPS anticipates being able to partner with PSCOC / PSFA for the identified facility needs at Tucumcari Middle School and possibly Tucumcari Elementary School during the life of this FMP. This project partnership would substantially increase the district's to fund capital projects. The

Total Capital Needs

district will continue to work with PSFA, monitor FAD ranking of all district schools and apply for PSCOC / PSFA funding as they qualify and their funding match is available.

FACILITY NEEDS BY FACILITY

The district identified capital needs cover ALL district schools and support buildings. The district identified capital needs at each of its facilities as follows:



TUCUMCARI ELEMENTARY SCHOOL: \$5,060,623

Tucumcari Elementary School (TES) is located on the west side of the city of Tucumcari. The school is located next to a residential area and is an active part of community life. The original construction was in 1998 and there have been four phases of additions to it. The school does not have any portables on site.



The majority of needs identified at Tucumcari Elementary are related to preventive maintenance, with some Life- Health-Safety-Security-ADA-Code (LHSS) needs, facility and site renewal, and adequacy standards needs. The majority of the LHSS needs

at the school are related to safety issues and security improvements that the district would like to implement at the school. The facility renewal needs are related to building systems that are past their useful life and need to be replaced, and the needs related to adequacy standards are related to the HVAC systems which are beyond their expected life. The majority of the issues related to preventive maintenance are related to water infiltration, settlement issues, and movement of walls. There is evidence of settlement throughout the school. It is recommended that a structural assessment of the school be completed.



The district has been addressing the facility needs as funding is available, keeping the facilities safe and comfortable for use, and will continue to do so. The Tucumcari Elementary School major building system needs that could require GOB funds to address are:



Communications/Security
Exterior Doors
Fire Sprinklers
Floor Finishes
HVAC
Interior Walls
Fencing
Landscaping/Drainage
Playground equipment
Walkways

Total Capital Needs





- There are no areas of TES that have been identified to be replaced at this time.
- There are no areas of TES that have been identified for major renovation at this time.
- There are building systems that have been identified to be updated at TES. See above.
- There are no areas of TES that have been scheduled for minor renovation at this time.
- All sections of TES require general maintenance.
- All sections of TES require continued preventive maintenance.
- There are no areas of TES that has been identified for demolition.
- There are no portables on TES campus that have been identified for disposal.
- There are no instructional spaces of TES that are under consideration for closure at this time.
- There is no plan to consolidate TES with any other district school at this time.





\$6,032,573

Tucumcari Middle School (TMS) is located near the center of the city of Tucumcari. The original building opened in 1970 with an addition to the main building in 1996. The cafeteria was added in 1972 and the gym in 1980. There have not been any major renovations to the school. There are no portable instructional buildings on campus. The Tucumcari Middle School kitchen provides food service to Tucumcari High School.





The 1970 facility is in need of a major renovation and/or substantial facility and site system renewal. Unfortunately, the enrollment at TMS has been declining and the school is underutilized. The district is monitoring the student enrollment and developing options to address the utilization of the school. The district has discussed relocating middle school students to the high school, but it was determined that relocation to the high school would not be beneficial for middle school students. If the student enrollment continues to decline the district could close or demolish the 1970 facility and house all middle school students in the

1996 addition. This is preferable to relocating middle school students to the high school.

Tucumcari Middle School is an older school with many of its building systems past their useful life. It has been identified as the district's most in need school. The majority of needs at Tucumcari Middle School are related to Life-Health-Safety-Security-ADA-Code (LHSS), facility and site

Total Capital Needs



system renewal, and preventive maintenance. The facility and site system renewal needs of the middle school are due to building systems that have exceed their useful life and need to be replaced while other building systems continue to need preventive maintenance to extend their useful life. The majority of the LHSS needs at this school is due to the age of the building and has been grandfathered in and do not require immediate attention; however, any major renovation of this school would require that the grandfathered items be corrected.



The district has been addressing the facility needs as funding is available, keeping the facilities safe and comfortable for use, and will continue to do so. Tucumcari Middle School facility and site system needs that could require GOB funds to address are:



Ceiling Finishes

Communications/Security

Fire Detection/Alarm

Fire Sprinklers

Floor Finishes

HVAC

HVAC Controls

Institutional Equipment

Plumbing

Water Distribution


Fencing

Site Specialties

Parking Lots

Walkways





- The 1970 portion of TMS would benefit from major renovation.
- There are major building systems that have been identified to be updated at TMS. See above.
- The home economics lab at TMS has been identified for minor renovation.
- All areas of TMS require continued general maintenance.
- All areas of TMS require continued preventive maintenance.
- There are no areas of TMS that has been identified for demolition at this time.
- There are no portables on TMS campus that have been identified for disposal.



Total Capital Needs



- If student enrollment continues to decline at TMS, portions or all of the 1970 facility could be closed or demolished.
- There has been discussion of relocating middle school students to the high school, but this is not a preferred option and would be a last resort.



TUCUMCARI HIGH SCHOOL:

\$6,539,717

Tucumcari High School (THS) is located near the center of the city of Tucumcari. The school opened in 1946 and has had several additions since then including the band and choir building, library, field house, auditorium, vocational building, and additional classrooms. The majority of the main building was replaced in two phases, 2006 and in 2011. There are no portable instructional buildings on campus.



The majority of facility needs at THS are related to Facility Renewal and Life-Health-Safety-Security-ADA-Code (LHSS) of the older buildings. The facility renewal needs of the high school are due to buildings systems that have exceed their useful life and need to be replaced before they impact the mission of the school. The majority of the LHSS needs at this school are related to security improvements that the district would like to implement.



The district has been addressing the facility needs as funding is available, keeping the facilities safe and comfortable for use, and will continue to do so. Tucumcari High School building system needs that could require GOB funds to address are:





- There are no areas of THS that have been identified to be replaced at this time.
- There are no areas of THS that have been identified for major renovation.

Total Capital Needs



- The THS Rhodes Field House concessions have been has been scheduled for minor renovation.
- There are major building systems that have been identified to be updated at THS. See above.
- All areas of THS need continued general maintenance.
- All areas of THS need continued preventive maintenance.
- There are no areas of THS that has been identified for demolition.
- There are no portables on THS campus that have been identified for disposal.
- There are no instructional spaces of THS that are under consideration for closure at this time.
- There is no plan to consolidate THS with any other district school at this time.



MOUNTAIN VIEW ELEMENTARY SCHOOL: \$859,950

Tucumcari Public Schools closed Mountain View Elementary School (MVES) closed in 2000, but TPS still owns and maintains the building. The school is located near Tucumcari Middle School is currently leased to the local Head Start program. There are no portables on the site.



It is the intention of TPS to demolish the portion of the building that is not being leased by the Head Start program as soon as funding for demolition is available. The district is going to replace the roof over the area that is being leased by Head Start.

TPS anticipates upgrading the parking lot at MVES for safety. These are the only facility needs identified for MVES at this time.



Demolition

Roofs

Parking Lots



- There are no areas of MVES that have been identified to be replaced at this time.
- There are no areas of MVES that have been identified for major renovation at this time.
- There are major building systems that have been identified to be updated at MVES. See above.
- There are no areas of MVES that need to be scheduled for minor renovation.
- All areas of MVES need continued general maintenance.


Total Capital Needs

- All areas of MVES need continued preventive maintenance.
- The portion of MVES that is not being leased by Head Start has been identified for disposal or demolition.
- There are portables on MVES campus that have been identified for disposal.
- There are no instructional spaces of MVES that may be under consideration for closure at this time.
- There is no plan to consolidate MVES with any other district school at this time.

District School Facilities Total: \$18,492,863
District Support Facilities / District Wide Needs: \$1,848,315

District Total Facility Needs: \$20,341,178

The chart and graph below illustrate the probable cost of the needs at each facility. Refer to the NEEDS spreadsheet sorted by FACILITY at the end of this section for a detailed list of TPS needs related to the facilities identified above.



Total Capital Needs

This page intentionally left blank

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|--------------|---------------------------|--------------|-----------------------|-----------|--------------|---------------------------------|--------------------|------------------|---|----------|----------|---------------|-------------|----------------------------|------------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| Priority 1 I | Life-Health-Safety-Se | curity / Mai | intenance / Ted | chnology: | • | | | • | | | | | | | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| 1A | District Wide | | | | Dist | Code | LHSS | L-SB9 | Address life-health-safety-security issues | į. | 5 yr | \$120,700 | \$603,500 | \$603,500 | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| | District Wide | | | | Dist | Code | LHSS | L-SB9 | Install vehicle barracades at front of each school | | | 0010 710 00 | * | * 4.000 * 00 | |
| 1B | District Wide | | | | Dist. | Maintenance | PreVent | BS-SB9 | Preventive and Regular Maintenance needs | | 5 yr | \$218,713.00 | \$1,093,565 | \$1,093,565 | |
| 1C | District Wide | | | | Dist | Technology | Tech | Tech | Upgrade IT equipment, software, training district wide | | 5 vr | \$30,250.00 | \$151,250 | \$151,250 | \$1,848,31 |
| 10 | District Wide | | | | Dist | Technology | TECH | Tecn | Install ramp in steep hill to access west playground | • | уу | \$30,230.00 | \$131,230 | \$131,230 | ψ1,040,31 |
| | Tucumcari ES | 1998 | Site | | Dist | Z-Walkways | LHSS | L-GOB | and basketball courts | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Interior Doors | LHSS | L-SB9 | Replace door lock in janitor's room | | ea | | \$0 | \$0 | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| | Tucumcari ES | | | | Dist | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| | Tucumcari ES | | | | Dist | Code | LHSS | L-SB9 | Install security cameras: inside and outside | | | | | | |
| | | | . | | | | | | Correct ponding in courtyard between gym and the | | | | • | • | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | PreK-2nd grade building | | ea | | \$0 | \$0 | |
| | Т | 2002 | Dhaas 4 | | Diet | Cailing Finishes | Due Vent | DC CDC | Replace ceiling tiles due to water damage in | , | | # C 00 | ¢o. | ¢o. | |
| | Tucumcari ES | 2002 | Phase 4 Phase 2 | | Dist | Ceiling Finishes | PreVent | BS-SB9 | corridor next to gym | (|) sf | \$6.00 | \$0 | \$0 | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace water stained ceiling tiles | (|) sf | \$6.00 | \$0 | \$0 | |
| | rucumcan Lo | 1999 | Phase 4 | | Dist | Celling Finishes | i ievent | DO-0D9 | Replace water stained ceiling tiles in classroom 22 | <u>'</u> |) 31 | ψ0.00 | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Ceiling Finishes | PreVent | BS-SB9 | and office next to it | (|) sf | \$6.00 | \$0 | \$0 | |
| | racamoun 20 | 2002 | Glacorocinic | | 2.00 | Coming Finances | 1 10 1011 | 20 020 | Repair damage due to water at top corner of North | | J 0. | ψ0.00 | Ψυ | ΨΟ | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Ceiling Finishes | PreVent | BS-SB9 | entrance | (|) sf | \$6.00 | \$0 | \$0 | |
| | | | | Special | | | | | | | | · | · | · | |
| | | | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Office | Dist | Exterior Doors | PreVent | BS-SB9 | Repair door frame separation | (|) ea | \$2,500.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Exterior Walls | PreVent | BS-SB9 | Repair wall cracks in north wall of gym | (|) ea | \$2,500.00 | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari ES | 2006 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT in Special Ed classroom 24 | | sf | | \$0 | \$0 | |
| | | | Phase 2 | 0, 00 | . . | E. E | 5 | 50.050 | Replace cracked VCT at the entrance of the | | 1. | | • | Φ0 | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 22 | Dist | Floor Finishes | PreVent | BS-SB9 | classroom | | st | | \$0 | \$0 | |
| | Tucumcari ES | 1998 | Phase 1 Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace damaged VCT in admin section | | of | | \$0 | \$0 | |
| | rucumcan ES | 1998 | Phase 1 | | DIST | Floor Finishes | Prevent | 82-289 | Replace damaged VCT in admin section | | SI | | \$0 | Φυ | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair heavy damage in VCT outside of restrooms | | ef | | \$0 | \$0 | |
| | racamean Lo | 1990 | Phase 1 | | Dist | r loor r inigries | i ievent | DO-0D9 | Repair cracked VCT in classroom 9 and in corridor | | 31 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | outside classroom | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | 2.00 | | 1.1010 | 20 020 | Repair VCT separation in classroom 14 and in | | 0. | | ų v | 7- | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | corridor outside the classroom | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair / replace VCT at the entrance of Gym | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair / replace VCT at west entrance of cafeteria | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT at the entrance of library | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT in corridor next to gym | | sf | | \$0 | \$0 | |
| | Turner = = 150 | 0000 | Di C | | Dist. | Floor Finish | Dest. | DO 050 | Deplete all VOT in a south as wide VOT 1 1 12 11 | | | | * - | ^ | |
| | Tucumcari ES | 2000 | Phase 3 | 1 | Dist | Floor Finishes | PreVent | BS-SB9 | Replace all VCT in south corridor. VCT is bubbling | | ST of | | \$0 \$0 | \$0 \$0 | |
| | Tucumcari ES Tucumcari ES | 2000 2000 | Phase 3 Phase 3 | | Dist Dist | Floor Finishes Floor Finishes | PreVent PreVent | BS-SB9 BS-SB9 | Replace / repair cracked VCT in commons area Replace / repair damaged VCT in storage room | | sf sf | | \$0 \$0 | \$0 \$0 | |
| | rucumcan ES | 2000 | Phase 3 Phase 1 | 1 | ופוח | I IOOI I IIIISIIUS | rieveni | PO-9DA | Correct settlement issues of slab between PreK- | | 51 | - | \$0 | Φ0 | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | 2nd grade building and Gym | | sf | | \$0 | \$0 | |
| | r dodinodn EO | 1330 | Ciacolocino | | Dist | - Sandation, Slab, Structure | i iovoni | 20 003 | Address movement in expansion joints in north and | | JI | | φυ | ΨΟ | |
| | | | | | | | | | west walls of the gym; Assess settlement in wall | | | | | | |
| | | | | | | | | | between gym and the PreK-2nd grade building; | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | walkway has dropped 2 to 3 inches | | ea | | \$0 | \$0 | |
| | | | Phase 2 | | İ | | | | | | | | , , | ** | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | HVAC | PreVent | BS-SB9 | Repair / replace rusted radiators in restrooms | | ea | | \$0 | \$0 | |

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|----------|---------------------------|--------------|------------------------------|-------------|------------|----------------------------------|--------------------|------------------|---|-----|----------|------------------|------------|---------------|-----------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | | | PreK-2nd Grade | | | | 1 | | | | | | | | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Institutional Equipment | PreVent | BS-SB9 | Repair plastic laminate in Lounge | | ea | | \$0 | \$0 | |
| | | | PreK-2nd Grade | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Interior Doors | PreVent | BS-SB9 | Correct door in book room. Door binds in frame. | | ea | | \$0 | \$0 | |
| | Tucumcari ES | 1999 | Phase 2 | | Dist | Interior Doors and Partitions | PreVent | BS-SB9 | Deplete rusted metal partition in hour restrators | | | | \$0 | \$0 | |
| | rucumcan ES | 1999 | Classrooms PreK-2nd Grade | | DIST | Interior Doors and Partitions | Prevent | DO-9D9 | Replace rusted metal partition in boys restrooms | | ea | | Φ0 | \$0 | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Interior Walls | PreVent | BS-SB9 | Repair water damage in electrical room | | sf | \$1.00 | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | 7 | 7. | 7. | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 16 | Dist | Interior Walls | PreVent | BS-SB9 | Repair damage on East wall of the classroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | Repair cracked walls in boys and girls restrooms, | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | and in room behind restrooms | | sf | | \$0 | \$0 | |
| | Tugumgari FC | 2002 | Dhoos 4 | | Diet | Interior Walls | Dro\/ont | DC CDO | Correct water damage and movement in walls due | | of | | ΦΩ. | ¢ο | |
| | Tucumcari ES Tucumcari ES | 2002 2002 | Phase 4 Phase 4 | Gymnasium | | Interior Walls | PreVent PreVent | BS-SB9 BS-SB9 | to water infiltration in corridor next to gym Repair split face cracking in north wall of gym | | sf sf | | \$0 \$0 | \$0 \$0 | |
| | rucumcan Lo | 2002 | Phase 4 | Cymnasium | Dist | interior vvans | i ievent | DO-0D9 | repair split face cracking in north wall of gym | | 31 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | Repair wall cracks in classrooms | | sf | | \$0 | \$0 | |
| | | | PreK-2nd Grade | | | | | | Investigate and address standing water in corridor | | | | * - | * - | |
| | Tucumcari ES | 1998 | Bldg | | | U | PreVent | BS-SB9 | by administration | 1 | sf | \$0.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Gym | | Dist | Roof | PreVent | BS-SB9 | Correct roof leaks | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | . | D (| | | | | ١, | | • | • | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Roof | PreVent | BS-SB9 | Repair water filtration in skylites | | st | | \$0 | \$0 | |
| | Tucumcari ES | 1998 | Phase 1 Classrooms | Lounge | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | | | | | |
| | rucumcan L5 | 1990 | Phase 2 | Lourige | Dist | 1001 | Fievent | DO-009 | Nepali Celling leaks | | | | | | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | * | · | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Roof | PreVent | BS-SB9 | Correct damage due to water filtration in skylites | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 17 | Dist | Wall Finishes | PreVent | BS-SB9 | Repair window sill in classroom | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 1998 | Phase 1 Classrooms | | Dist | Wall Finishes | PreVent | BS-SB9 | Correct loose tile on planter in commons area | | of | | 0.9 | \$0 | |
| | Tucumcan ES | 1996 | Classioonis | Special | DISL | Wall Fillisties | Prevent | DO-9D9 | Correct loose tile on planter in commons area | | sf | | \$0 | ΦΟ | |
| | | | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Office | Dist | Wall Finishes | PreVent | BS-SB9 | Repair crack at window and cracked walls | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Wall Finishes | PreVent | BS-SB9 | Repair wall damage in library | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Cafeteria | | | | PreVent | | Repair base of wall in custodian room | | sf | | \$0 | \$0 | |
| | Tucumcari ES Tucumcari ES | 2000 2000 | Phase 3 Phase 3 and 4 | | | Wall Finishes Z-Walkways | PreVent PreVent | BS-SB9 BS-SB9 | Repair wall damage due to water in restrooms Recaulk perimeter of building | | sf | \$2.00 | \$0 \$0 | \$0 \$0 | |
| | Tucumcan L3 | 2000 | Phase 1 | | DIST | Z-vvaikways | Fieveni | D3-3D9 | Necault perimeter of building | | III | φ2.00 | φυ | φυ | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Air/Ventilation Equipment | Tech | Tech | Install split system for cooling in server room | (| ea | \$7,500.00 | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | | | Tech | Tech | Install split system for cooling in IT room | | ea | \$7,500.00 | \$0 | | \$ |
| | | | | | | Life-Health-Safety-Security-ADA | - | | | | | · | · | | · |
| | Tucumcari HS | | | | | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Other Equipment | LHSS | L-SB9 | Replace stage curtain | | ea | \$1.00 | \$0 | \$0 | |
| | | | _, | | | | l | | Install fence between Rattler Gym and Football | | 1. | | | . | |
| | Tucumcari HS | 1946 | Site | | Dist | Z-Fencing | LHSS | L-SB9 | Field | | sf | \$1.00 | \$0 | \$0 | |
| | | | _, | | | | l | | | | 1. | | | . | |
| | Tucumcari HS | 1946 | Site | | | Z-Walkways | LHSS | L-SB9 | Install ADA ramp to practice field | (| sf | \$1.00 | \$0 | \$0 | |
| | Tucumcari HS Tucumcari HS | 1946 | Rattler Gym | | | Ceiling Finishes Other Equipment | PreVent | BS-SB9 BS-SB9 | Repair hard ceiling in women's locker restroom Install netting and screens on cooling side | | 100 | \$1.00 \$0.00 | \$0 \$0 | | |
| | i ucumcan no | | GreenHouse Ag/Welding | | חופו | Oner Equipment | PreVent | PO-9D8 | mistali netting and screens on cooling side | | ea | φυ.υυ | \$0 | \$0 | |
| | Tucumcari HS | 1990 | Shop | | FAD | Technology | Tech | Tech | | | ea | \$1,187.00 | \$0 | \$0 | |
| | Tucumcari HS | 1946 | Rattler Gym | | | | Tech | Tech | | | ea | \$4,772.00 | \$0 | | |
| | Tucumcari HS | 1985 | Auditorium | | | Technology | Tech | Tech | | | ea | \$3,702.00 | \$0 | | \$ |
| | Tucumcari MS | 1980 | Trojan Gym | - | Dist | Plumbing | FacRen | BS-SB9 | Repair showers in men's lockers | (| ea | \$12,500.00 | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | Classroom 9 | Dist | Plumbing | FacRen | BS-SB9 | Replace sink and casework in classroom 9 | | ea | | \$0 | \$0 | |

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|-----------------|--------------------------|-------------|-------------------|--------------|------------|---------------------------------|----------|---------|---|-----|------|-----------|-------------|---------------|-------------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | LHSS | L-SB9 | Replace ADA signage | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | LHSS | L-SB9 | Repair locker frame | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | | Interior Doors | LHSS | L-SB9 | Upgrade door in admin section; not ADA hardware | | ea | | \$0 | \$0 | |
| | | | | | | Interior Doors, Partitions, | | | Repair ladder to roof in boiler room. Ladder is | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | | Stairs, Elevators | LHSS | L-SB9 | detached from wall | | ea | | \$0 | \$0 | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| | Tucumcari MS | | | | Dist | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | | | | | | | | | Correct drainage in area between Cafeteria and | | | | | | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Landscaping / Drainage | LHSS | | Rattler Gym | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | Correct ponding next to north courtyard | | ea | | \$0 | \$0 | |
| | | | | | | | | | Correct drainage at main entry; water drains off | | | | | | |
| | Tucumcari MS | 1996 | Addition | | | Z-Landscaping / Drainage | LHSS | | roof onto entry slab | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | | Z-Walkways | LHSS | L-SB9 | Repair sidewalk by Cafeteria and Gym | | sf | | \$0 | 7 - | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Walkways | LHSS | L-SB9 | Correct tripping hazard at entry sidewalk | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | | Ceiling Finishes | | BS-SB9 | Replace stained ceiling tiles in classroom 5 | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | | Ceiling Finishes | | | Replace stained ceiling tiles throughout building | | sf | | \$0 | | |
| | Tucumcari MS | 1996 | Addition | | | Ceiling Finishes | | | Repair hole in ceiling in boys restroom | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair cracked ceiling at girls restroom | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair frame of exterior door in wood shop; frame | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Exterior Doors | PreVent | BS-SB9 | is rusted | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | Room 1 | Dist | Floor Finishes | PreVent | BS-SB9 | Repair interior water damage (6x6 AVT) | | sf | | \$0 | \$0 | |
| | | | | | | | | | Replace / repair cracked VCT in classrooms and | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Floor Finishes | PreVent | BS-SB9 | corridors | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair / replace cracked VCT in corridor outside | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | boys restrooms | | sf | | \$0 | \$0 | |
| | T | 4000 | A statitions | | | Floor Finish or | | | Repair / replace cracked VCT in the lounge's | | 1. | | . . | • | |
| | Tucumcari MS | 1996 | Addition | | 2.00 | Floor Finishes | | BS-SB9 | restroom | | st | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | PreVent | BS-SB9 | Replace plastic laminate in girls restroom | | ea | | \$0 | \$0 | |
| | | | [| | | | | | Repair cracked walls in classroom 9 and outside | | 1. | | | <u> </u> | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Interior Walls | PreVent | BS-SB9 | room 1 | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair cracked walls in classrooms, wood shop | | 1. | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Interior Walls | PreVent | BS-SB9 | and lounge | | sf | | \$0 | \$0 | |
| | | 40=0 | [| . | | [_ | | | <u> </u> | | 1. | | . . | <u> </u> | |
| | Tucumcari MS | 1970 | Original Building | | | Wall Finishes | | BS-SB9 | Repair wall due to water damage in classroom 9 | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | | Classroom 16 | | Wall Finishes | PreVent | BS-SB9 | Repair window sill in classroom 16 | | sf | | \$0 | | \$0 |
| Priority 1 Life | fe-Health-Safety-Securit | y / Mainten | ance / Technolog | y Total Need | s: | | | | | | | | \$1,848,315 | \$1,848,315 | \$1,848,315 |

| Priority 2 Building / S | ite System Upgra | ades: | | | | | | | | | | | | | |
|-------------------------|------------------|-------|----------------|----------------------------------|------|------------------|--------|--------|--|--------|-----|-------------|-------------|-------------|-----------|
| Mountain Vie | ew ES | | | | Dist | Roof | FacRen | BS-GOB | Replace Roof | 7,000 | sf | \$20.00 | \$140,000 | \$182,000 | |
| Mountain Vie | ew ES | | | | Dist | Z-Parking Lots | FacRen | BS-GOB | Resurface parking lot | 30,000 | sf | \$4.00 | \$120,000 | \$156,000 | \$338,000 |
| | | P | PreK-2nd Grade | | | | | | | | | | | | |
| Tucumcari E | S 199 | 8 | Bldg | | FAD | HVAC | AdqStd | BS-GOB | | 1 | FAD | \$82,559.00 | \$82,559 | \$107,327 | |
| Tucumcari E | S 200 | 6 | Kind Addition | | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 2,367 | ea | \$20.00 | \$47,340 | \$61,542 | |
| | | F | PreK-2nd Grade | | | | | | | | | | | | |
| Tucumcari E | S 199 | 8 | Bldg | | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 22,339 | ea | \$20.00 | \$446,780 | \$580,814 | |
| | | | Phase 2 | | | | | | | | | | | | |
| Tucumcari E | S 199 | 9 | Classrooms | | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 77,301 | ea | \$20.00 | \$1,546,020 | \$2,009,826 | |
| Tucumcari E | S 200 | 6 | Kind Addition | 23 and 24 | FAD | Ceiling Finishes | FacRen | BS-SB9 | In rooms 23 and 24 | 1 | FAD | \$5,006.00 | \$5,006 | \$6,508 | |
| | | | 3rd and 4th | | | | | | Doors opened and closed properly in this asset | | | | | | |
| Tucumcari E | S 200 | 0 | Grade Bldg | | FAD | Exterior Doors | FacRen | BS-SB9 | \$41,937: Replace all exterior doors and frames | 1 | FAD | \$41,937.00 | \$41,937 | \$54,518 | |
| Tucumcari E | S 199 | 9 | Campus wide | | Dist | Exterior Doors | FacRen | BS-SB9 | Replace all exterior doors and frames | 50 | ea | \$5,000.00 | \$250,000 | \$325,000 | |
| Tucumcari E | S 200 | 12 | Phase 4 | Library & Special Programs | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in library and Special Programs Offices | 5,427 | sf | \$6.00 | \$32,562 | \$42,331 | |

| MADELITY NAME Page | DISTRICT | | ADEA | | | lalamtifical | | | From alling as | | | | | | TOTAL PROJECT | |
|--|--|---------------|-------|---------------|------|--------------|---------------------------|----------|----------------|---|--------|----------------|-----------------------|--------------------|-----------------|-------------|
| Summer LS | DISTRICT | EACH ITY NAME | AREA- | ADEA | POOM | Identified | CVCTEM | CATEGORY | Funding | EACILITY NEEDS | OTV | LINIT | COST/LINIT | MACC | TOTAL PROJECT | CUDTOTALC |
| Recurrent ES 2000 Classrooms Data Rec Finches Seation | PRIORITI | FACILITY NAME | Tear | | ROOM | Бу | STSTEM | CATEGORT | Source | FACILITY NEEDS | QIT | UNII | COST/ONIT | MACC | COST | SUBTUTALS |
| Texamen Column | | Tucumcari ES | 2002 | | | Diet | Floor Finishes | FacRen | RS-SR0 | Ungrade carnet in classrooms and computer lab | 2 500 | ef | \$6.00 | \$15,000 | \$19 500 | |
| Tournest E 1988 Chapter 1988 Chapter 1988 Fabrus | | racamean Eo | 2002 | Olassioonis | | Dist | 1 1001 1 111131103 | racitori | DO 0D3 | opgrade carpet in classrooms and computer lab | 2,500 | 31 | ψ0.00 | ψ10,000 | ψ10,000 | |
| Household Bill 2001 Red Addroin Pall Prince Prince Section Bill State To Gain and Johnson Pall State To Gain and Johnson Pall State To Gain and Johnson Pall To Gain | | | | Phase 1 | | | | | | Upgrade carpet in classrooms, computer lab and | | | | | | |
| Transcer PS | | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | FacRen | BS-SB9 | offices. Carpet is in good condition in classroom 8 | 5,750 | sf | \$6.00 | \$34,500 | \$44,850 | |
| Tournest E9 | | Tucumcari ES | 2006 | Kind Addition | | FAD | Floor Finishes | FacRen | BS-SB9 | | | | \$12,201.00 | | \$15,861 | |
| Textures FS | | | | | | | | | | TPO and metal pitched roof. Roof was in good | | | | | | |
| Tuestool ES | | | | | | | | | | | 0 | FAD | | \$0 | \$0 | |
| Tourneal ES 1999 Literative PAD Communication / Security Literature PAD 1990 Communication / Security Commu | | Tucumcari ES | 2002 | | | Dist | Z-Landscaping / Drainage | FacRen | BS-SB9 | Replace sprinkler system: valves and pipes | 1 | ea | \$75,000.00 | \$75,000 | \$97,500 | |
| Tucument ES | | | | | | | | | | | | | | | | |
| Tournest ES | | | | | | | | | | | | | | | T - | |
| Tourneari ES 1998 Classocome Data File Epimblers L15S L-COB The the part does localized by the floors. Dustin is Authoriting around the floor in the part of | | Tucumcari ES | 2002 | | | FAD | Communications / Security | LHSS | L-GOB | System was in good condition | 0 | FAD | \$4,221.00 | \$0 | \$0 | |
| Tourneal ES 1999 Liber STRD NAD Poor Pinitage Liber STRD | | T | 4000 | | | D' | Fine On sinkle se | | | Duthing to a storagical depend | 00.040 | | # 40.00 | # 000 400 | #000 447 | |
| Tuumcail ES | | Tucumcari ES | 1998 | Classrooms | | Dist | Fire Sprinklers | LHSS | L-GOB | | 22,319 | ST | \$10.00 | \$223,190 | \$290,147 | |
| Tournoat ES | | | | Cofotorio/ | | | | | | | | | | | | |
| Tournest ES 1986 Pock-2nd Goodle Pock-2n | | Tucumcari ES | 1000 | | | EAD | Floor Finishos | 1 400 | LCOR | | 1 | EAD | \$100.035.00 | \$100 035 | \$130.046 | |
| Trummark ES | - | Tucumcan Lo | 1999 | | | FAD | Floor Finishes | LIIOO | L-GOB | | | IAD | \$100,033.00 | \$100,033 | \$130,040 | |
| Tuburidar ES 1998 Bidg FAD Interior Walls L+SS L-GOB Filing cracks and monitoring the sales of the FAD \$138,706,500 \$138,706 \$100,000 \$24,000 \$100 | | Tucumcari ES | 1998 | | | FAD | Floor Finishes | LHSS | L-GOR | | 1 | FAD | \$156 782 00 | \$156 782 | \$203.817 | |
| Trucment ES | | - acamoun EC | 1000 | , | | IND | 1.1001 1 111101100 | LI 100 | _ 505 | | | אוו | ψ100,702.00 | ψ100,702 | Ψ203,017 | |
| Tourneam ES | | Tucumcari ES | 1998 | | | FAD | Interior Walls | LHSS | L-GOB | | 1 | FAD | \$138 705 00 | \$138 705 | \$180 317 | |
| Tourneal ES | - | | | | | | | | | | | | +, | | | |
| Tournean ES | | | | | | | | | | | | | , | +, | | |
| Tucument S | | | | | | | | | | | | | | | | |
| Tucumcari HS 1998 Site FAD Z-Walkways LHSS LS89 monitored for further damage by the desirct 1 FAD \$315,170,00 \$315,170 \$499,721 \$4,930,623 Tucumcari HS 1970 House Dat HVAC AdqStd 85-GDB Install Air Conditioning 12,713 at \$20,00 \$3254,266 \$330,636 Tucumcari HS 1985 Auditorium Dat Rock Rock Replace auditorium flat rock 6,000 d \$20,00 \$3250,00 \$315,000 \$31 | | | 1000 | | | | | | | | | | + ==,===== | +==,=== | | |
| Tucumani HS | | Tucumcari ES | 1998 | Site | | FAD | Z-Walkwavs | LHSS | L-SB9 | | 1 | FAD | \$315,170.00 | \$315.170 | \$409.721 | \$4.930.623 |
| Tucumean HS | | | | | | | | | | 3 / | | | · | . , | , , | , , , |
| Tucumean HS | | Tucumcari HS | 1970 | House | | Dist | HVAC | AdqStd | BS-GOB | Install Air Conditioning | 12,713 | sf | \$20.00 | \$254,260 | \$330,538 | |
| Trucumcant HS | | Tucumcari HS | 1985 | Auditorium | | Dist | Roof | FacRen | | Replace auditorium flat roofs | | | \$20.00 | \$120,000 | \$156,000 | |
| Tucumcai HS | | Tucumcari HS | 1962 | Main Bldg | | FAD | Water Distribution | FacRen | BS-GOB | Bldg replaced in 2006 | 0 | FAD | \$209,879.00 | \$0 | \$0 | |
| Tucumcari HS | | Tucumcari HS | 1946 | Rattler Gym | | FAD | Water distribution | FacRen | BS-GOB | | 1 | FAD | \$91,331.00 | \$91,331 | \$118,730 | |
| Tucumcari HS | | | | Rhodes Field | | | | | | | | | | | | |
| Tocumcant HS | | | | | | | | FacRen | | | | | . , | . , | | |
| Tocumean HS | | | | | | | | | | | | | | | | |
| Tucumcari HS | | | | | | | | | | | | | | | \$134,703 | |
| Tucumcari HS | | | | | | | , | | | Bldg replaced in 2006 | | | | Ψυ | \$0 | |
| Tucumcari HS | | Tucumcari HS | 1946 | | | FAD | Drain, Waste and Vent | FacRen | BS-SB9 | | 1 | FAD | \$91,331.00 | \$91,331 | \$118,730 | |
| Tucumcari HS 1985 Auditorium FAD Drain, Waste and Vent FacRen BS-SB9 1 FAD \$70,848 0.0 \$70,848 \$92,102 | | | | | | | | | | | | | ********* | ** | *** | |
| Tucumcari HS | | | | | | | | | | | | | | | | |
| Tucumcari HS | | | | | | | , | | | | | | . , | | | |
| Tucumcari HS | | | | | | | | | | | | | | | | |
| Tucumcari HS 1985 Auditorium Dist Institutional Equipment FacRen BS-SB9 Install presentation system 1 ea \$50,000 00 \$50,000 \$65,000 | - | | | | | | | | | | | | | | | |
| Tucumcari HS | | | | | | | | | | Install presentation system | | | | | | |
| Tucumcari HS 1985 Auditorium Dist Lighting / Branch Circuits FacRen BS-SB9 Update stage lighting 1,000 sf \$8.00 \$10,400 Update electrical on stage to provide more power outlets outle | | | | | | | | | | | | | ' ' | | | |
| Tucumcari HS 1985 Auditorium Dist Main Power/Emergency FacRen BS-SB9 outlets outlets 1,000 sf \$8.00 \$10,400 \$1 | | | | | | | | | | | | | | | 7 - | |
| Tucumcari HS | | | | aitoriairi | | 1 | gg , Dianon Should | | | | 1,000 | † " | Ψ0.00 | ψ0,000 | Ψ10,π00 | |
| Tucumcari HS 1985 Auditorium Dist Plumbing FacRen BS-SB9 restroom 1 ea \$5,000.00 \$5,000 \$6,500 Tucumcari HS 1990 GreenHouse Dist Roof FacRen BS-SB9 Replace green house roof 800 sf \$20.00 \$16,000 \$20,800 Tucumcari HS 1962 Main Bldg FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$0.00 \$0.00 \$0.00 Tucumcari HS 1968 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 0 FAD \$50,229.00 \$0.0 | | Tucumcari HS | 1985 | Auditorium | | Dist | Main Power/Emergency | FacRen | BS-SB9 | | 1.000 | sf | \$8.00 | \$8.000 | \$10.400 | |
| Tucumcari HS | | | 1.555 | | | 1 | | | | | .,550 | ĺ. | Ψ0.00 | ψο,οοο | ψ.0,.00 | |
| Tucumcari HS 1990 GreenHouse Dist Roof FacRen BS-SB9 Replace green house roof 800 sf \$20.00 \$16,000 \$20,800 Tucumcari HS 1962 Main Bldg FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$0.00 \$0 \$0 Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 Beyond Expected Life: Bldg was replaced in 2006 1 FAD \$86,046.00 \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 Beyond Expected Life: District installed all new heating units in 2002. District needs air conditioning. Installed 2018 Units were in good condition \$197,007. Install air | 1 | Tucumcari HS | 1985 | Auditorium | | Dist | Plumbing | FacRen | BS-SB9 | | 1 | ea | \$5,000.00 | \$5,000 | \$6,500 | |
| Tucumcari HS 1962 Main Bldg FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$0.00 \$0 \$0 Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 0 FAD \$50,229.00 \$0 \$0 \$1,490,841 Beyond Expected Life: District installed all new heating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 Units were in good condition \$197,007. Install air | | | | | | | ŭ | | | | | | | | . , | |
| Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 0 FAD \$50,229.00 \$0 \$0 \$1,490,841 Beyond Expected Life: District installed all new heating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 Units were in good condition \$197,007. Install air | | | | | | | | | | | | | | | | |
| Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 Tucumcari HS 1962 Main Bldg FAD Main Power/Emergency LHSS L-GOB Bldg replaced in 2006 0 FAD \$50,229.00 \$0 \$0 \$1,490,841 Beyond Expected Life: District installed all new heating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 Units were in good condition \$197,007. Install air | 1 | Tucumcari HS | 1962 | Main Bldg | | FAD | Fire Sprinklers | LHSS | L-GOB | Beyond Expected Life: Bldg was replaced in 2006 | 0 | FAD | \$0.00 | \$0 | \$0 | |
| Beyond Expected Life: District installed all new heating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 Units were in good condition \$197,007. Install air | | | 1946 | Rattler Gym | | FAD | Fire Sprinklers | LHSS | | Beyond Expected Life | | | \$86,046.00 | \$86,046 | \$111,860 | |
| Beyond Expected Life: District installed all new heating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 Units were in good condition \$197,007. Install air | | Tucumcari HS | 1962 | Main Bldg | | FAD | | | L-GOB | | 0 | FAD | \$50,229.00 | | | \$1,490,841 |
| Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$ | | | | | | | | | | Beyond Expected Life: District installed all new | | | | | | <u> </u> |
| Units were in good condition \$197,007. Install air | 1 | | |] | | | I | 1 | | | | | | | | |
| | | Tucumcari MS | 1970 | Original Bldg | | FAD | HVAC | AdqStd | BS-GOB | | 0 | FAD | \$1,063,074.00 | \$0 | \$0 | |
| Tucumcari MS 1980 Trojan Gym FAD HVAC AdqStd BS-GOB conditioning in gym 15,800 sf \$20.00 \$316,000 \$410,800 | | | | | | | | | | | | | | | | |
| | | Tucumcari MS | 1980 | Trojan Gym | | FAD | HVAC | AdqStd | BS-GOB | conditioning in gym | 15,800 | sf | \$20.00 | \$316,000 | \$410,800 | |

NEEDS BY FACILITY

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | TOTAL PROJECT | |
|----------|---------------------------|--------------|-------------------------|------|--------------|---|------------------|----------------|---|------------------------|-------------------|-----------------------|------------------------|-----------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Bv | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| _ | Tucumcari MS | 1972 | Cafeteria | ROOM | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in cafeteria | 15,800 sf | \$20.00 | \$316,000 | \$410,800 | OODIOTALO |
| | Tucumcari MS | 1996 | Clrm Addition | | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning. Completed 2018 | 0 sf | \$20.00 | \$310,000 | \$410,800 \$0 | |
| | T dodinodni WO | 1330 | Olimitadition | | Dist | 11177.0 | Λαγοια | Во сов | install all conditioning. Completed 2010 | 0 31 | | ΨΟ | ΨΟ | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | HVAC Controls | AdqStd | BS-GOB | System was in use. Vent covers are old and worn | 0 FAD | \$148,470.00 | \$0 | \$0 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | HVAC Controls | AdqStd | BS-GOB | System was in good condition. | 1 FAD | \$27,514.00 | \$27,514 | \$35,768 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Roof | FacRen | BS-GOB | Beyond Expected Life: Replaced 2018 | 0 FAD | \$242,907.00 | \$0 | \$0 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | 1 FAD | \$34,944.00 | \$34,944 | \$45,427 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | 1 FAD | \$97,288.00 | \$97,288 | \$126,474 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | 1 FAD | \$2,941.00 | \$2,941 | \$3,823 | |
| | | | | | | | | | Beyond Expected Life \$197,512: Repave west | | | | | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Parking Lots | FacRen | BS-GOB | parking lot | 30,000 sf | \$6.00 | \$180,000 | \$234,000 | |
| | | | | | | | | | | | | | | |
| | T : 140 | | 0 | | | | | | Replace ceiling tiles throughout building in | | | ^ | 0.45 400 | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Ceiling Finishes | FacRen | BS-SB9 | classrooms. Ceiling Tiles replaced in corridor 2002. | 14,759 sf | \$6.00 | \$88,554 | \$115,120 | |
| | | | | | | | | | Tiles in locker rooms, offices and store rooms were | | | | | |
| | Tucumcari MS | 1000 | Traign Cum | | FAD | Cailing Finishes | FooDoo | BS-SB9 | in good condition. Ceiling over the gym was in good condition. | 1 FAD | \$53,594.00 | \$50.504 | \$69,672 | |
| | Tucumcari MS | 1980 1972 | Trojan Gym Cafeteria | | FAD | Ceiling Finishes Drain, Waste and Vent | FacRen FacRen | BS-SB9 | good condition. | 1 FAD | \$33,594.00 | \$53,594 \$34,944 | \$45.427 | |
| | Tucumcari MS | 1972 | Original Bldg | | FAD | Drain, Waste and Vent | FacRen | BS-SB9 | | 1 FAD | \$97,822.00 | \$97,822 | \$127,169 | |
| | Tucumcari MS | 1980 | Trojan Gym | | | Drain, Waste and Vent | FacRen | BS-SB9 | | 1 FAD | \$43,508.00 | \$43,508 | \$56,560 | |
| | r dedificali MO | 1300 | riojan Oyin | | IAD | Diam, waste and vent | Taciton | DO 0D3 | Exterior doors are original: New exterior door at | TIAD | ψ+3,300.00 | ψ+3,300 | ψ30,300 | |
| | | | | | | | | | entry only. Upgrade exit door to courtyard in | | | | | |
| | | | | | | | | | vestibule: Door is original. Upgrade north exterior | | | | | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Exterior Doors | FacRen | BS-SB9 | doors: not ADA compliant | 1 FAD | \$56,605.00 | \$56,605 | \$73,587 | |
| | | | | | | | | | Doors were in good condition: District replaced 2 | | | | , í | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Exterior Doors | FacRen | BS-SB9 | double doors at entry | 1 FAD | \$25,176.00 | \$25,176 | \$32,729 | |
| | | | | | | | | | Front doors are original; all doors in kitchen new, | | | | | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Exterior Doors | FacRen | BS-SB9 | except for 2 exit doors | 0 FAD | \$20,220.00 | \$0 | \$0 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Exterior Windows | FacRen | BS-SB9 | Replace all windows | 1 FAD | \$20,220.00 | \$20,220 | \$26,286 | |
| | | | | | | | | | The old portion would be locker rooms floors. | | | | | |
| | | | | | | | | | Floors were in good condition. Wood floor replaced | | | | | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Floor Finishes | FacRen | BS-SB9 | 2011. \$62,700 | 2,500 sf | \$6.00 | \$15,000 | \$19,500 | |
| | | | | | | | | | Barrand Francisco de de Maria | | | | | |
| | Tucumcari MS | 1070 | Original Building | | Diet | Floor Finishes | FacRen | BS-SB9 | Beyond Expected Life: upgrade carpet in middle corridors, reception area and classroom 14 | 2,750 sf | \$6.00 | \$46 F00 | \$21,450 | |
| | Tucumcan ws | 1970 | Original Building | | Dist | Floor Finishes | racken | DO-2D9 | condors, reception area and classroom 14 | 2,750 Si | Φ0.00 | \$16,500 | \$21,450 | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Floor Finishes | FacRen | BS-SB9 | Replace asbestos floor tile in 4 north classrooms | 3,771 sf | \$20.00 | \$75,420 | \$98,046 | |
| | Tucumcan Wo | 1370 | Original Dallaling | | Dist | 1 loor 1 lilistics | Taciton | DO-003 | Replace assestes floor the fit 4 flortif classicoms | 5,771 51 | Ψ20.00 | Ψ10,420 | ψ50,040 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in classrooms and computer lab | 15,000 sf | \$6.00 | \$90,000 | \$117,000 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Institutional Equipment | FacRen | BS-SB9 | opg.ado sarpor in ciacordo ino ana comparer ias | 1 FAD | \$67,230.00 | \$67,230 | \$87,399 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Institutional Equipment | FacRen | BS-SB9 | | 1 FAD | \$29,901.00 | \$29,901 | \$38,871 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Lighting / Branch Circuits | FacRen | BS-SB9 | | 1 FAD | \$69,612.00 | \$69,612 | \$90,496 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Lighting / Branch Circuits | FacRen | BS-SB9 | Beyond Expected Life: Updated to LED in 2016 | 0 FAD | \$97,437.00 | \$0 | \$0 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Lighting / Branch Circuits | FacRen | BS-SB9 | Split system for original branch circuits \$43,337 | 15,800 sf | \$3.00 | \$47,400 | \$61,620 | |
| | Tucumcari MS | 1996 | Addition | | FAD | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 27,520 sf | \$2.50 | \$68,800 | \$89,440 | |
| | Tucumcari MS | 1970 | Main Bldg | | Dist | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 30,150 sf | \$2.50 | \$75,375 | \$97,988 | |
| | Tucumcari MS | 1972 | Cafeteria | | Dist | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 15,800 sf | \$2.50 | \$39,500 | \$51,350 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Communications / Security | LHSS | L-GOB | There is no intercom in this building | 15,800 sf | \$2.50 | \$39,500 | \$51,350 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Fire Detection / Alarm | LHSS | L-GOB | No fire alarm in this building | 15,800 sf | \$3.50 | \$55,300 | \$71,890 | |
| | Tucumcari MS | 1996 | Addition | | FAD | Fire Detection/Alarm | LHSS | L-GOB | \$32,182 | 27,520 sf | \$3.50 | \$96,320 | \$125,216 \$127,193 | |
| | Tucumcari MS | 1970 | Original Bldg | | Dist | Fire Detection/Alarm Fire Detection/Alarm | LHSS LHSS | L-GOB | | 30,150 sf | \$3.50 \$3.50 | \$105,525 \$55,300 | \$137,183 \$71,890 | |
| | Tucumcari MS Tucumcari MS | 1972 1980 | Cafeteria Trojan Gym | | Dist Dist | Fire Sprinkler | LHSS | L-GOB L-GOB | The building is not sprinklered | 15,800 sf 15,800 sf | \$3.50 \$10.00 | \$55,300 \$158,000 | \$71,890 \$205,400 | |
| | i dodinoan ivio | 1300 | Hojan Gyili | | Dist | i iic opiiikiei | LITOS | L-00B | The ballaling is not sprinklered | 13,000 81 | φ10.00 | φ100,000 | φ200,400 | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 30,150 sf | \$10.00 | \$301,500 | \$391,950 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 27,520 sf | \$10.00 | \$275,200 | \$357,760 | |
| | Tucumcari MS | 1970 | Original Bldg | | | Fire Sprinkler | LHSS | L-GOB | Required by UBC. Grandfathered in \$70,780 | 30,150 ea | \$10.00 | \$301,500 | | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 FAD | \$8,363.00 | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 FAD | \$23,411.00 | \$0 | \$0 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 FAD | \$10,413.00 | \$0 | \$0 | |
| | | | | | | | | | Upgrade staff and students restrooms to ADA | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Plumbing | LHSS | L-GOB | compliant | 400 sf | \$300.00 | \$120,000 | \$156,000 | |

| DISTRICT PRIORITY | FACILITY NAME | AREA- Year | AREA | ROOM | Identified By | SYSTEM | CATEGORY | Funding Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | TOTAL PROJECT COST | SUBTOTALS |
|---------------------|--------------------------|---------------|-------------------|------|------------------|------------------------|-----------|-------------------|---|--------|-------|----------------|--------------|-----------------------|--------------|
| | | | | | | | | | Beyond Expected Life: Upgrade restrooms in | | | | | | |
| | | | | | | | | | cafeteria to ADA compliant; restrooms alcoves not | | | | | | |
| | Tucumcari MS | 1972 | Cafeteria | | | Plumbing | LHSS | L-GOB | ADA | 300 | | \$300.00 | | \$117,000 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Fencing | LHSS | L-GOB | Complete perimeter fencing | 2,500 | | \$100.00 | | \$325,000 | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Playground Equipment | LHSS | L-GOB | No playground equipment | 0 | FAD | \$66,835.00 | | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Site Specialties | LHSS | L-GOB | Install solar traffic signs | 2 | ea ea | \$2,500.00 | . , | \$6,500 | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Walkways | LHSS | L-SB9 | The facility has lots of spalding and cracking | 1 | FAD | \$223,448.00 | \$223,448 | \$290,482 | \$5,286,373 |
| Priority 2 B | uilding / Site System Up | grades Tot | tal Needs: | | | | | | | | | | \$9,266,029 | \$12,045,838 | \$12,045,838 |
| Priority 3 | Capital Projects: | I | | | | | | 1 | Demolish part of bldg. / keep part of bldg. for Head. | | I | | | | |
| | | | | | | | | | Demolish part of bldg. / keep part of bldg. for Head | | | | | | |
| 3 | Mountain View ES | | | | | Demolition | AdqStd | MP-GOB | Start Program | 16,060 | | \$25.00 | | \$521,950 | \$521,950 |
| 5 | Tucumcari ES | | Site | | | New Construction | EdPro | MP-GOB | Install Turf at South ES playground | 12,500 | _ | \$8.00 | \$100,000 | \$130,000 | \$130,000 |
| 8 | Tucumcari HS | | 1948 | | | Renovation | FacRen | MP-GOB | Renovate Rattler Field Concessions | 250 |) sf | \$75.00 | + -, | \$24,375 | |
| 7 | Tucumcari HS | | Site | | | New Construction | LocPol | MP-GOB | Install canopies at Track & Field | 4 | ea | \$25,000.00 | \$100,000 | \$130,000 | |
| | Turan and HC | | Site | | | New Construction | l a a Dal | MD COD | Create district baseball and softball field complex: lighted fields, concessions, restrooms, irrigated | 4 | | \$2.750.000.00 | ¢2.750.000 | ¢4.975.000 | |
| 1 | Tucumcari HS | | Site | | | New Construction | LocPol | MP-GOB | grass, bleachers, pressbox | i i | ea | \$3,750,000.00 | \$3,750,000 | \$4,875,000 | |
| 9 | Tucumcari HS | | Vo.Ag. Bldg. | | | New Construction | LocPol | MP-GOB | Create a storefront (small building) for customers to buy student vegetables | 120 | sf | \$125.00 | \$15,000 | \$19,500 | \$5,048,875 |
| 2 | Tucumcari MS | | Site | | | Demolition | AdqStd | MP-GOB | Demolish old maintenance bldg. across from MS and create new parking lot with site lighting | 22,720 | sf | \$12.50 | \$284,000 | \$369,200 | |
| 6 | Tucumcari MS | 1970 | Original Builidng | | | Renovation | EdPro | MP-GOB | Renovate Home Economics Lab | 1,450 | sf | \$200.00 | \$290,000 | \$377,000 | \$746,200 |
| Priority 3 C | apital Projects Total Ne | eds: | | | | | | | | | | | \$4,959,250 | \$6,447,025 | \$6,447,025 |
| | ri Public Schools To | | s: | | | | | | TOTAL: | | | | \$16,073,594 | \$20,341,178 | |

Tucumcari Public Schools • 5-Year Facilities Master Plan

3.2.1 DEVELOPMENT OF FMP AND PRIORITIZATION PROCESS

Development of FMP Process

Development of the facilities master plan (FMP) process for the Tucumcari Public Schools (TPS) started with a strategic planning meeting. The strategic planning meeting participants were selected by the TPS Superintendent and became the FMP core committee. During this meeting the following items were discussed:

FMP goals and objectives
Roles and Responsibilities: decision
making process
Participants
Identification of relevant data and
methods to obtain data
Type and number of Meetings
FMP Schedule

At the conclusion of the strategic planning meeting the TPS FMP process and schedule had been developed and a clear line of communication established.

Information from the strategic planning meeting and the FMP process was shared with the TPS School Board at a regular



School Board meeting. The TPS School Board supported the TPS FMP Core committee's process and schedule to develop the FMP. This FMP process addresses the specific needs of TPS, supports its educational program and supports the:

TPS Mission Tucumcari Public Schools will prepare students for successful lives.

TPS Vision Excellence in Education.

The developed process identified a decision making process for the FMP that consisted of two committees, the FMP core committee and the FMP steering committee; and the School Board. The FMP core committee was entrusted to review and edit all data for accuracy and generate agendas and schedules for upcoming meetings with the FMP steering committee and the TPS School Board. The FMP steering committee was entrusted to review data, discuss facility needs and issues, contribute input on facility needs and issues, prioritize the district's needs, and develop a capital plan which identifies how and when the district will address the priorities. The final approval and adoption of the FMP is the responsibility of the TPS School Board.

The FMP process consisted of two committees:

• The FMP Core Committee: Comprised of district administration.

 The FMP Steering Committee: Comprised of district administration, staff, principals, teachers and community members.

The FMP process consisted of the following FMP meetings:

2 School Board meetings

One review of the District priorities and capital plan Adoption of the final FMP document

6 FMP Core committee meetings

One Strategic Plan meeting

Five Data review and development of Agenda meetings:

Two of the six meetings were dedicated to review and

editing FAD / FMAR Data

2 Steering committee meetings

One background review meeting
One discussion of district facility needs and development of recommendations of district priorities and the capital plan meeting

Tucumcari Public Schools FMP Steering Committee and Community Input

Tucumcari Public Schools has developed a long, successful relationship with the local community and their PSCOC/PSFA representatives. Tucumcari Public Schools continuously seeks input from the local community and is aware of their concerns about the future of the district. To assure meaningful community input, TPS developed a FMP steering committee to be a liaison between the district and the local community for capital projects. The FMP steering committee members represent the local community and the school district. They were selected by the superintendent and district administration and they are part of the decision making process of the district. The members review data, bring community perspective to the discussions and develop recommendations related to district facility needs for the school board's consideration.

Process and Criteria for Prioritizing District Needs

The prioritization of TPS needs took place over the span of several meetings: two FMP steering committee meetings; two meetings with district administration and maintenance staff to review the FAD/FMAR report; and one school board meeting to review the final recommendations.

The FMP process was based on providing relevant data and engaging in meaningful discussion which resulted in knowledgeable, informed decisions. During the FMP process, the TPS FMP steering committee, community, and school board were given background information on the district and all identified school and district facility needs.



During the FMP process, the FMP Steering committee reviewed and discussed the following data:

- District Vision and Mission
- Partnerships: District Community State (PSCOC/PSFA)
- · District Demographics
- Facilities Assessment Database (FAD)
- Facilities Maintenance Assessment Report (FMAR)
- Enrollment History and Projections
- Existing District and Individual School Size in relation to:
- Educational Program
- PSCOC/PSFA Recommended Square Footage per Student
- State of New Mexico Benchmarks and Measures
- Adequacy Standards
- District Policies
- Capacity and Utilization of Schools
- Age and Condition of Schools
- Life Span of Building Systems
- Preventive Maintenance
- Maintenance Cost per Square Foot per Year
- Size Right School Planning
- Facility Needs at each District Building
- Benefits of a Smaller Footprint
- Efficient and Effective Schools
- Community and School Profiles
- Capital Funding Sources
- 2013 FMP Priorities and Completed Projects

The major concerns of TPS and the FMP Steering committee are:



District Needs Prioritization Criteria

The FMP steering committee reviewed all district facility needs, capital project funding sources, and capabilities for the next five years and beyond. During the prioritization process, the committee discussed the importance of partnerships with PSCOC/PSFA and the local community. Partnership with PSCOC/PSFA is dependent upon aligning future projects with the Facilities Assessment Database (FAD) and identifying facilities that need to be replaced, renovated, or have facility and site systems that are past their useful life which could impact student performance. Partnership with the local community is dependent on the community understanding and supporting TPS capital project needs and being included in the decision making process.

After review and discussion of the data and district issues, the FMP steering committee developed recommendations and prioritized the district's facility needs. The criteria used by the FMP steering committee and the district to prioritize capital needs were:

Does it affect Life-Health-Safety-Security?

Does it align with the FAD Ranking and support future PSCOC/PSFA partnership?

Does it impact the district's mission and core values?

Does it support proactive instead of reactive maintenance?

Does it support the district's educational program?


Does it promote student success?

Does it support community needs and expectations?

Does it align with New Mexico facility benchmarks, measures & statewide adequacy standards?

Does it align with district policies?

The following chart provides a schematic diagram of the process and the categories that the FMP steering committee utilized in the prioritization of the identified needs of the district.



This page intentionally left blank

Facilities Master Plan Prioritization Schedule

April 4, 2018: Strategic Planning Meeting

A strategic planning meeting was held April 4, 2018 with district staff to develop the Facilities Master Plan (FMP) process and schedule.

The meeting agenda included:

- FMP PROCESS
- Data:

PSFA FMP Checklist District Background Information Capital Project Funding

• Discussion:

Facility Goals & Objectives Facility Issues, Concerns & Needs

Decisions:

FMP Decision Making Process FMP Steering Committee Recommendations School Board Review and Approval

- FMP Schedule
- FMP Committee Members

Meeting Summary: The FMP process and decision making process was established. The FMP schedule was established and there was discussion of district facility goals and objectives for the FMP. Facility issues, concerns and needs were discussed. The relationship between TPS and its local community was discussed. The community has shown its support of the district by passing all recent general obligation bond elections. The district passed a GOB election in 2015 which identified several capital projects to be accomplished with GOB funds. This list was reviewed and incorporated into the FMP process. Financial considerations and funding sources for the next five years were discussed. Facility Master Plan tasks were identified and given to district personnel.

June 5, 2018: 1st FMP Steering Committee Meeting

The appointed FMP steering committee met to review information and provide input.

The meeting agenda included:

- Introductions
- FMP PROCESS
- Data:

PSFA Checklist
District Background Information
Capital Project Funding

Discussion:

Facility Goals & Objectives

Prioritization Process and Budgeting

Facility Issues, Concerns & Needs

Decisions:

FMP Decision Making Process FMP Steering Committee Recommendations School Board Review and Approval

- FMP Schedule
- FMP Committee Members

The Committee was presented with several questions for their feedback:

1. What are the positive features of district facilities?

Overall district has a low PTR

Storage at the middle school

2. What are the educational challenges faced by TPS schools?

Hiring qualified teachers

Parents are not participating into children's education

3. What will education in TPS look like in 5, 10, 15, 50 years?

More distance based learning

More vocational programs

Mesalands Community College will increase vocational

Dual credits for 11th and 12th grades

4. What is the long range vision of the district in terms of educational program delivery trends?

Interaction with Mesalands Community College

5. In the next five plus years, what are some building systems and features of district facilities that need to change or improve?

Tucumcari Elementary: Evaporative cooling, playground equipment, boilers
Tucumcari Middle School: Air conditioning at cafeteria; lockers at the gym need to
be replaced

6. How do extracurricular activities fit into the FMP?

The district needs baseball and softball games

Address safety issues at games

The district just installed auditorium sound system

Meeting Summary: The FMP process and schedule were reviewed. District background and relevant information were the main topics of the meeting. The above questions were asked of the FMP steering committee and they provided input. The facility needs of each school were identified and discussed with input from all committee members. Existing square footage at each district school was reviewed and compared to PSCOC / PSFA recommended square footages. The importance of right sizing district facilities to assure available funds were not being spent to maintain underutilized facilities was discussed.

Prioritization Process and Budgeting

August 2, 2018: 2nd FMP Steering Committee Meeting

The agenda for the second FMP steering committee meeting was as follows:

- Introductions
- Brief Review of FMP Process
- Brief review of Data:

District Background Information

Capital Project Funding

Facility Goals & Objectives

Facility Issues, Concerns & Needs

Input on District Needs

District Priorities, Capital Plan Recommendations

Capital Funding Project

Discussion:

Capital Recommendations

Facility Issues, Concerns & Needs

Input on District Needs

Decisions:

Prioritize District Needs

Meeting Summary: Enrollment history and projections were discussed as well as utilization of each school. The district student enrollment has been steadily declining for the past several years and projections indicate that this trend will continue. Utilization and capacity analysis of each school was presented to the committee for analysis, consideration and discussion.

The facility needs of each district school were identified and discussed in depth. Tucumcari Elementary School is in good condition and requires preventive maintenance and regular system renewal. The major identified issues at the school are the water filtrations from the roofs even though the district is constantly repairing it and settlement issues that need to be addressed in different sections of the building. Tucumcari Middle School has been identified by the district and PSCOC/PSFA as the most in-need school in the district. The school has many of its building and site systems past their useful life and in need of replacement or renewal. The middle school is underutilized and the district is considering its options to increase the utilization at TMS. Tucumcari High School is a relatively new facility with the main building being replaced in 2006 and in 2011. The sections of the school that were not replaced are in good condition, but require preventive maintenance and regular facility and site system renewal. Tucumcari Public Schools owns the property of Mountain View Elementary School. This school has been closed, but a portion of the building is currently leased for Head Start Program. The district would like to demolish the part of the building that is not being leased and has identified the need to replace the roof and the resurface the parking lot for the portion of building that is being leased.

Due to the size of the district, all FMP steering committee members were very familiar with the

facility conditions at each school. The FMP steering committee was able to select its priorities to recommend to the school board at the end of the second FMP steering committee meeting. The priorities were broken down into three major categories: recurring facility needs, facility/site system renewal, and potential capital projects. Life-health-safety-security, maintenance and technology fall under the recurring facility needs and was the top priority. Facility/site system renewal was the second priority. The third priority was major renovation and new construction projects and TMS facility needs and district athletic needs.

November 19, 2018: School Board Review Meeting

The TPS School Board of Education met to review input from the FMP steering committee meetings and discuss the FMP goals, objectives, and priorities put forth by the FMP steering committee.

Discussed identified district priorities that:

Meet PSCOC/PSFA Requirements

Align with the Facilities Assessment Database (FAD)

Provide Efficient and Effective Use of Existing Facilities

Promote and Enlist Community Partnership

Provide Modern, Well Kept Facilities: Upgraded Facilities and Building Systems

TPS FMP GOALS and OBJECTIVES:

Student Preparation for Life after TPS Schools

Provide Safe and Stimulating Learning Environments

Technology: Keep Current and Upgrade

Maintenance of Existing Facilities

Improve Condition of Existing Facilities

Right Size Facilities

Facility Equity

Partnerships: Community and PSCOC/PSFA

Work within Availability of Funding

Meeting Summary: A full review of the FMP process was shared with the school board in a regular meeting where community members were invited to attend. The board agreed with the priorities that the FMP Steering committee recommended. There was discussion centered on the need for partnering with the local community and PSCOC/PSFA to obtain the much needed funding for capital projects.

January 21, 2019: School Board Meeting

The final FMP document was presented to the TPS community and school board for adoption.

A copy of the sign-in sheets and the presentation of each FMP meeting can be found in the appendix of this document.

FACILITY NEEDS BY CATEGORY

During this FMP process approximately \$20,341,178 in facility needs were identified that are related to eight assessed categories of facility needs: adequacy standards (AdqStd); educational program (EdPro); facility renewal (FacRen); growth; Life-Health-Safety-Security-Code-ADA compliance (LHSS); local policy (LocPol); preventive maintenance/maintenance (PreMaint); and technology (Tech). Due to the decline in student population there were no identified needs in the growth category. These identified needs require a combination of funding sources. The district anticipates access to potentially \$4,848,315 in SB-9, PLT and an anticipated GOB funds to address its 2019/2023 facility needs.



ADEQUACY STANDARDS:

\$4,838,565

The district has been actively addressing its adequacy standards issues with its SB-9 and GOB funding as available. The majority of adequacy standard needs identified in this FMP will require GOB funding; however, there are some that can be addressed with SB-9 funds. The age and condition of existing permanent buildings along with the limited availability of capital funds has made it impossible for TPS to address all adequacy standard issues. As stated above, TPS has been partnering with the community and PSCOC/PSFA to update its facilities and has made significant improvements to the majority of its schools; however, there are still a number of adequacy standard improvements that need to be addressed.



The majority of TPS schools meet or exceed the overall New Mexico adequacy standards (NMAS) of the recommended square footage per student in their permanent facilities. The primary adequacy standard needs throughout the district identified in this FMP are related to building systems and not the need to increase square footage. HVAC is the primary adequacy standard issue district wide that TPS needs to address. The district has implemented a preventive maintenance plan for its HVAC systems which has resulted in extended life for the majority of its HAVC units; however, due to the number of schools and their age, replacement and renewal of HVAC equipment will remain an on-going process.



The overall square footage of TPS facilities is above state adequacy standards; however, the current Facilities Assessment Database (FAD) identifies individual spaces at each school that do not meet New Mexico adequacy standards. There are programs housed in spaces that might not meet New Mexico adequacy standards; however, there are options within each school for reorganization that would allow the program to be housed in a space that does meet adequacy standards. There are also



spaces that do not meet New Mexico adequacy standards, but meet the needs of the schools' educational programs. A review of these spaces revealed that some of the FAD information needed to be updated and some of the spaces that were identified as not meeting state adequacy standards actually meet the standards. The spaces that were identified in the FAD as not meeting current N.M. adequacy standards are:



Tucumcari Elementary School:

Insufficient Parent Work Space: The district does not have active parent
participation at the school, but there is space available to house this
program if it is needed.





- Insufficient Parent Work Space: There is existing space available to house this program if it is needed.
- Insufficient Number of Chemical Storage Units: The existing science labs do have the required separate storage space, but do not have chemical storage units for each lab. There is no plan to increase the number of chemical storage units in this FMP.



Tucumcari High School:

• Insufficient Parent Work Space: There is existing space available to house this program if it is needed.







While the district schools do have an excess of square footage, TPS also



realizes the importance of right sizing its facilities to reduce maintenance and utility costs. During this FMP process, discussion of how to further reduce existing square footage and bring the district's facilities even closer to compliance with PSFA recommended adequacy standards related to square footage occurred at each meeting. The discussions centered on the utilization of each of TPS facilities and the cost of maintenance and operations of under-utilized square footage. The district is monitoring student enrollment at TMS and could close or demolish a portion of the 1970 building. The district would like to demolish the old maintenance building and portion of Mountain View Elementary which is currently leased to the local Head Start program. The district would like to address these needs as soon as GOB funding allows.



EDUCATIONAL PROGRAM:

\$507,000

The \$507,000 reflects the need to modify existing facilities to meet the desired educational program of TPS. The district is constantly reviewing its educational program and making adjustments to meet the needs of its students. There are two educational program related projects included in this FMP. The educational program needs were identified at Tucumcari Elementary School and Tucumcari Middle School. The elementary school has identified the need to install turf at the south playground and the middle school identified the need to renovate the home economics lab. The district would like to address these needs as soon as funding allows and will use GOB funds to address them.



FACILITY RENEWAL:

\$3,523,792

The majority of the \$3,523,792 reflects upgrades to building and site systems that are past their useful life district wide. There are large scale needs that will require GOB funds, but there are recurring and maintenance facility needs that will be funded through SB-9. The district has been systematically replacing or upgrading building and site systems at its facilities as funding allows. The building systems to be updated include:



Ceiling Finishes

Drain, Waste, and Vent

Exhaust Ventilation System

Exterior Windows and Doors

Floor Finishes

Institutional Equipment

Lighting/Branch Circuits

Main Power/Emergency

Plumbing

Roof

Water Distribution

Landscaping/Drainage



Prioritization Process and Budgeting

Parking Lots

GROWTH:

The district recognizes that facility renewal is critical in providing a safe, stimulating learning environment; however, capital funding is limited. The district requires more facility renewal than existing or anticipated funds can accommodate in the next five years. There are building and site systems at each of the existing district schools that are past their useful life and need to be updated. The district has established its priorities to align with the FAD ranking in anticipation of partnering with PSCOC/PSFA on these building and site system upgrade projects when the projects qualify for state funding assistance. The district anticipates being able to partner with PSCOC/PSFA for building system updates at TMS and possibly TES during the life of this FMP. The district would like to address the needs at their other schools as soon as funding allows and will use a combination of GOB and SB-9 funds and will apply for PSCOC/PSFA funding as schools qualify.





\$0

The district has experienced a decline in student enrollment since 2009. The enrollment continues to decline and it is difficult to predict how low it will go before it stabilizes. The district realizes the implications of its declining enrollment and will continue to monitor it on a regular basis. Both classroom and facility utilization in the overall district are lower than state recommended values. If student enrollment continues to decline, TPS will review options for its schools which will center on continuing to create more efficient and effective facilities.



Information regarding the state's "Right Size Initiative" was presented to and discussed by district representatives and the TPS FMP committees. The district was encouraged to include reduction of under-utilized square footage in their long term facilities planning. As a result, the district has identified areas where it might be able to reduce square footage in the future. When implemented, these initiatives will result in a cost savings of capital funds, maintenance, and utilities; however, the district funds are not sufficient to implement the reduction of square footage at this time. It is recommended that the district continue the discussion of closure, disposal or demolition of under-utilized spaces at each school. There are no funds related to growth at TPS identified in this FMP.



LIFE / HEALTH / SAFETY/SECURITY/CODE: \$5,218,756

The majority of Life-Health-Safety-Security-Code-ADA Compliance needs at TPS facilities are related to security improvements, and changes in ADA requirements and the building code due to the age of the facilities. The needs that fall under changes in ADA requirements and the building code are currently grandfathered in. These items have been identified in this



FMP to alert the district to the potential impact of these items to future renovation projects, but do not require immediate action or correction. As facilities are replaced or upgraded, the district might have to address the grandfathered issues, depending on the scope of work identified for a particular facility. The majority of these issues pose no potential impact to school operations at the current time but are identified so they can be included in future projects as needed.




There are some Life-Health-Safety-Security-Code-ADA compliance issues that the district will need to address in the next five years. These issues include upgrade intercom system at the middle school, upgrade security entries, install security cameras and install fire sprinklers, correct settlement issues at the elementary school, complete perimeter fencing, correct walkways, and correct drainage issues. The communication and security systems are major safety needs identified at TPS schools to provide a safe environment for TPS students. These upgrades are needed mainly at TMS.



The district would like to address these needs as soon as funding allows and will use a combination of GOB, SB-9, and PSCOC/PSFA funds.

LOCAL POLICY: \$5,024,500





The district has been partnering with PSCOC/PSFA and focusing on updating critical needs at its school facilities such as building systems and roofs; however, during this FMP process, the district identified needs that are not critical to the operation of its facilities, but are beneficial to students, community members and will enhance facility operations. These needs were identified at THS but will benefit the overall district. Local policy needs include:



Tucumcari HS: Install canopies at Track & Field
Tucumcari HS: Create district baseball and softball field complex: lighted
fields, concessions, restrooms, irrigated grass, bleachers, and press box
Tucumcari HS: Create a storefront (small building) for customers to buy
student vegetables



TPS will use GOB funds to address its local policy needs.

3.2

Prioritization Process and Budgeting

PREVENTIVE MAINTENANCE:

\$1,093,565

The district recognizes the importance of preventive maintenance and has implemented a PSFA approved Preventive Maintenance Plan. As of September 2017, TPS had a Facilities Maintenance Assessment Report (FMAR) score of 90.61 percent which falls into the good category. The PSCOC/PSFA has required districts to have an FMAR score of 60 percent or greater prior to awarding project funding. The district is above the 60 percent score which indicates that the district has implemented its preventative maintenance plan and is taking the necessary steps to extend the life of existing building and site systems.



Identified preventative maintenance needs are critical to the upkeep of district facilities and have the potential to extend the life of the existing facilities. The district has set in place "School Dude," a system where the facility users can submit a work order identifying when various finishes such as flooring, ceiling tiles, and window coverings need to be replaced; when walls need to be painted; and when building systems are not working properly. This allows the user to have input as to the items that they feel impact their comfort and ability to use the space as intended and allows the district to track the work orders. The major preventive maintenance issues at TPS are:



Ceiling Finishes

Exterior Doors

Floor Finishes

Foundation/Slab/Structure

HVAC

Institutional Equipment

Interior Doors and Partitions

Interior Walls

Other Equipment

Plumbing

Roof

Wall Finishes

Walkways



Tucumcari Public Schools will use SB-9 and GOB funds to address its preventive maintenance needs.



TPS Maintenance Effectiveness

The district has worked with PSFA to incorporate "School Dude" into their maintenance program. The key element for TPS maintenance effectiveness is use of "School Dude" to generate work orders. The district has enabled



3.2

Prioritization Process and Budgeting

its schools and district staff to write and submit work orders for any facility maintenance issue that they identify. The work orders are relayed to TPS maintenance staff and copied to the principal of the school. The maintenance staff reviews the work order and identifies the scope of work required to address the work order. Once the scope of work has been identified the process of ordering materials and assigning the necessary staff takes place. District administration meets with the maintenance supervisor on a regular basis to review the status of each work order which is used to determine the effectiveness of its maintenance staff.



The other key element in maintenance effectiveness at TPS has been the development of a preventive maintenance plan and implementing the plan. The district recognizes that preventive maintenance is far more economical than deferred maintenance. Preventive maintenance can assist in extending the life of building systems. The district has been able to hold successful general obligation bond elections which allow it to address major maintenance items that exceed the SB-9 funds. The district relies on an effective maintenance department to address facility issues quickly with limited resources and implement preventive maintenance to extend the life of existing building systems.



Anticipated Maintenance Projects that will become Capital Projects:

There is approximately \$12,045,838 of facility / site system renewal projects that have been identified during this FMP process. The district has not established a schedule to address these capital projects; however it anticipates beginning these projects as soon as funds are available. The district anticipates a GOB election in 2019 and will begin to address these needs with these funds. A detailed list of these capital projects is identified in the estimate of probable costs needs by funding source/facility spreadsheet at the end of Section 3.3. It identifies capital projects at each district facility and potential funding sources. Currently TPS is anticipating a partnership with PSCOC / PSFA to assist in funding its maintenance (facility and site system renewal) projects at Tucumcari Middle School and possibly Tucumcari Elementary School that are anticipated to turn into capital projects.



These maintenance (facility and site system renewal) projects that could turn into capital projects include:



Tucumcari Elementary School:

Exterior Doors
Floor Finishes
Landscaping/Drainage
Tucumcari Middle School



Prioritization Process and Budgeting

Ceiling Finishes Drain, Waste, and Vent **Exterior Doors Exterior Windows** Floor Finishes Institutional Equipment Lighting/Branch Circuits Parking Lots Water Distribution Tucumcari High School Drain, Waste, and Vent Roof **Parking Lots** Water Distribution









The \$151,250 identified to address technology issues is payment in lieu of taxes (PLT) funds that TPS has designated to address these issues. The total scope of technology needs could exceed the designated \$151,250 over the next five years and the district is prepared to supplement these funds with SB-9 and E-rate funds when necessary. The district is aware of the broadband initiative that PSCOC/PSFA has under taken to provide all New Mexico Public School Districts with affordable and high speed broadband. The district has not partnered with PSCOC/PSFA on this initiative; however the district will continue to monitor its technology system and work with PSFA when it is appropriate and will benefit the district. The district also applies for and receives E-rate funding for its technology program. The district is dedicated to providing its students with access to up-to-date technology. The district has an active technology department that identifies upgrades to technology infrastructure, equipment and software to meet the needs of the schools.







The district continues to upgrade its technology infrastructure to keep up with the newest advancements. Technology is a tool that the district uses extensively in the classroom and for support services which requires a steady funding source. The district applies for E-rate funding and utilizes PLT funds to address its technology needs.



Broadband Projects that will become Capital Projects:

During this FMP process no broadband projects for TPS were identified that will become capital projects.


Prioritization Process and Budgeting

TOTAL DISTRICT CAPITAL NEEDS BY CATEGORY:

\$20,341,178

The \$20,341,178 reflects the total needs identified in the above eight categories throughout the district. As shown above, TPS has a potential budget of \$4,848,315 for the next five years from SB-9 and PLT funds, and an anticipated 2019 GOB election. It is anticipated that the FMP identified needs could span the life a several GOB elections.

The following chart illustrates the probable cost of the needs as they fall into the above identified categories. Refer to the NEEDS spreadsheet sorted by CATEGORY in this section for a detailed list of TPS needs related to the categories identified above.



Prioritization Process and Budgeting

This page intentionally left blank

| DIOTRICT | | T 4854 | ı | | I., | | | 1 - " | | | | | | TOTAL DDG IFOT | |
|------------|-----------------------|--------|-------------|-------------|--------------|------------------------------|-------------|---------|---|-----|----------|----------------------|------------|--------------------------|------------|
| DISTRICT | FACILITY NAME | AREA- | | 2001 | Identified | 0.407514 | CATECORY | Funding | EACH ITY NEEDS | OTV | | COST/UNIT | | TOTAL PROJECT | OUDTOTAL O |
| PRIORITY | | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| Priority 1 | Life-Health-Safety-Se | | | echnology: | | | | | | | | | | | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Plumbing | FacRen | BS-SB9 | Repair showers in men's lockers | (|) ea | \$12,500.00 | \$0 | \$0 | |
| | | | Original | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Building | Classroom 9 | | Plumbing | FacRen | BS-SB9 | Replace sink and casework in classroom 9 | | ea | | \$0 | \$0 | \$0 |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | LHSS | L-SB9 | Replace ADA signage | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | LHSS | L-SB9 | Repair locker frame | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Interior Doors | LHSS | L-SB9 | Replace door lock in janitor's room | | ea | | \$0 | \$0 | |
| | | | Original | | | | | | Upgrade door in admin section; not ADA | | | | | | |
| | Tucumcari MS | 1970 | Building | | Dist | Interior Doors | LHSS | L-SB9 | hardware | | ea | | \$0 | \$0 | |
| | | 1.0-0 | Original | | . | Interior Doors, Partitions, | | | Repair ladder to roof in boiler room. Ladder is | | | | • | • | |
| | Tucumcari MS | 1970 | Building | | Dist | Stairs, Elevators | LHSS | L-SB9 | detached from wall | | ea | | \$0 | \$0 | |
| 4.0 | D: . : | | | | 5 | Life-Health-Safety-Security- | | | | _ | _ | #400 7 00 | 4000 500 | # 000 5 00 | |
| 1A | District Wide | | | | Dist | ADA-Code | LHSS | L-SB9 | Address life-health-safety-security issues | ţ | yr | \$120,700 | \$603,500 | \$603,500 | |
| | D: . : | | | | D: . | Life-Health-Safety-Security- | | | | | | | | | |
| | District Wide | 1 | | | Dist | ADA-Code | LHSS | L-SB9 | Install vehicle barracades at front of each school | | | | | | |
| | | | | | D: . | Life-Health-Safety-Security- | | | | | | | | | |
| | Tucumcari ES | 1 | | | Dist | ADA-Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | | | | | . | Life-Health-Safety-Security- | | | | | | | | | |
| | Tucumcari ES | | | | Dist | ADA-Code | LHSS | L-SB9 | Install security cameras: inside and outside | | | | | | |
| | T :110 | | | | D: / | Life-Health-Safety-Security- | | | | | | | | | |
| | Tucumcari HS | 1 | | | Dist | ADA-Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | T | | | | Di-t | Life-Health-Safety-Security- | | 1 000 | 0 | | | | | | |
| | Tucumcari MS | 4005 | A | | Dist | ADA-Code | LHSS | L-SB9 | Create secure entry | | - | 0 4.00 | | # 0 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Other Equipment | LHSS | L-SB9 | Replace stage curtain | | ea | \$1.00 | \$0 | \$0 | |
| | T | 4040 | 014- | | Di-t | 7 Familia e | | 1 000 | Install fence between Rattler Gym and Football | | | 64.00 | C O | (C) | |
| | Tucumcari HS | 1946 | Site | | Dist | Z-Fencing | LHSS | L-SB9 | Field | | Sī | \$1.00 | \$0 | \$0 | |
| | T | 0000 | DI 4 | | Di-t | 7 Landarania a / Daria a a | | 1 000 | Correct ponding in courtyard between gym and | | | | C O | (C) | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | the PreK-2nd grade building | | ea | | \$0 | \$0 | |
| | To a company of MO | 4070 | 014- | | Di-t | 7 Landa annin n / Dunin ann | | 1 000 | Correct drainage in area between Cafeteria and | | | | C O | (C) | |
| | Tucumcari MS | 1970 | Site | | | Z-Landscaping / Drainage | LHSS | L-SB9 | Rattler Gym | | ea | | \$0 | \$0 \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | Correct ponding next to north courtyard | | ea | | \$0 | \$0 | |
| | Turning of MC | 4000 | Addition | | Di-t | 7 Landasanina / Dusinasa | | 1 000 | Correct drainage at main entry; water drains off | | | | C O | ¢ο | |
| | Tucumcari MS | 1996 | Addition | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | roof onto entry slab Install ramp in steep hill to access west | | ea | | \$0 | \$0 | |
| | Tucumcari ES | 1998 | Site | | Diet | Z-Walkways | LHSS | L-GOB | · · · · · · · · · · · · · · · · · · · | | of | | ¢ο | ¢0 | |
| | Tucumcari HS | 1996 | Site | | Dist Dist | Z-Walkways | LHSS | L-SB9 | playground and basketball courts Install ADA ramp to practice field | |) sf | \$1.00 | \$0 \$0 | \$0 \$0 | |
| | Tucumcari MS | 1940 | Site | | Dist | Z-Walkways | LHSS | L-SB9 | Repair sidewalk by Cafeteria and Gym | , |) 51 | φ1.00 | \$0 \$0 | \$0 \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Walkways | LHSS | L-SB9 | Correct tripping hazard at entry sidewalk | | of of | | \$0 \$0 | T - | \$603,500 |
| | rucumcan ivio | 1970 | Site | + | Dist | Z-vvaikways | LI 100 | L-3D9 | Replace ceiling tiles due to water damage in | | 51 | | φυ | ΨΟ | φουσ,σου |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Ceilina Finishes | PreVent | BS-SB9 | corridor next to gym | (|) sf | \$6.00 | \$0 | \$0 | |
| | rucumcan L3 | 2002 | Phase 2 | | Dist | Celling Finishes | Fievent | DO-2D9 | Corridor flext to gym | , |) 51 | φ0.00 | ΨΟ | ΨΟ | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace water stained ceiling tiles | (|) sf | \$6.00 | \$0 | \$0 | |
| | rucumcan Lo | 1999 | Phase 4 | | Dist | Celling Fillishes | Fievent | D3-3D9 | Replace water stained ceiling tiles Replace water stained ceiling tiles in classroom | , |) 51 | φ0.00 | φυ | φυ | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Ceiling Finishes | PreVent | BS-SB9 | 22 and office next to it | (|) sf | \$6.00 | \$0 | \$0 | |
| | r dediffical i ES | 2002 | Classiconis | | Dist | Celling Finishes | Fievent | D3-3D9 | Repair damage due to water at top corner of | , |) 51 | φ0.00 | φυ | ΨΟ | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Ceiling Finishes | PreVent | BS-SB9 | North entrance | (|) sf | \$6.00 | \$0 | \$0 | |
| | rucumcan Lo | 2000 | T Hase 5 | | Dist | Celling Finishes | i ievent | DO-0D9 | North entrance | • |) 31 | ψ0.00 | ΨΟ | ΨΟ | |
| | Tucumcari HS | 1946 | Rattler Gym | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair hard ceiling in women's locker restroom | | | \$1.00 | \$0 | \$0 | |
| | rucumcarrio | 1340 | Original | | Dist | Celling Finishes | i ievent | DO-0D9 | Trepair flard ceiling in women's locker restroom | | | Ψ1.00 | ΨΟ | ΨΟ | |
| | Tucumcari MS | 1970 | Building | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace stained ceiling tiles in classroom 5 | | cf | | \$0 | \$0 | |
| | racamean we | 1910 | Dullulity | + | ادات | Coming i mioneo | i iovent | 20.009 | Tropiace stained ceiling thes in diassiooni 3 | | JI . | | φυ | φυ | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace stained ceiling tiles throughout building | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair hole in ceiling in boys restroom | | sf | | \$0 \$0 | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair cracked ceiling at girls restroom | | of | | \$0 | | |
| | 1 addition into | 1330 | , iddition | Special | D131 | Coming i inionos | 1 TO V GITE | 50 000 | Tropali ordonod coning at gine restroom | | 31 | | φυ | ΨΟ | |
| | | 1 | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Exterior Doors | PreVent | BS-SB9 | Repair door frame separation | (|) ea | \$2,500.00 | \$0 | \$0 | |
| | 1 addition LO | 2002 | 1 11430 7 | Cilioc | 5100 | EXIONO BOOK | 7 10 7 0110 | 50 050 | Repair frame of exterior door in wood shop; | | , 04 | Ψ2,000.00 | ΨΟ | ΨΟ | |
| | Tucumcari MS | 1996 | Addition | | Dist | Exterior Doors | PreVent | BS-SB9 | frame is rusted | | sf | | \$0 | \$0 | |
| - | Tucumcari ES | 2002 | Phase 4 | Gymnasium | | Exterior Walls | PreVent | | Repair wall cracks in north wall of gym | (| ea | \$2,500.00 | \$0 | | |
| <u> </u> | racamean Lo | 2002 | 1 11a36 4 | Oymmasiuill | וטוטנ | EAGIOI WAIIS | I ICACIII | בחם סרי | propan wan oraono in norui wan di gyin | | , ca | Ψ2,500.00 | φυ | φυ | |

| | | | | | | | | 1 | | | | | | | |
|----------|---------------|-------|-----------------------|-----------|------------|-------------------------------|-----------|---------|--|-----|------------|-----------|------------|---------------|-----------|
| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | | | | | | | | | Replace cracked VCT in Special Ed classroom | | | | | | |
| | Tucumcari ES | 2006 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | 24 | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | Replace cracked VCT at the entrance of the | | | | | 4 | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 22 | Dist | Floor Finishes | PreVent | BS-SB9 | classroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | L | | | | | | ١. | | | 4- | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace damaged VCT in admin section | | sf | | \$0 | \$0 | |
| | T | 4000 | Phase 1 | | D: . | Floor Finish on | D 14 4 | DO 000 | Repair heavy damage in VCT outside of | | ١, | | 00 | C O | |
| | Tucumcari ES | 1998 | Classrooms Phase 1 | | Dist | Floor Finishes | PreVent | BS-SB9 | restrooms Repair cracked VCT in classroom 9 and in | | Sī | | \$0 | \$0 | |
| | Tugumgari FC | 1998 | | | Dist | Floor Finishes | DroVont | BS-SB9 | corridor outside classroom | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 1996 | Classrooms Phase 2 | | DISL | Floor Finishes | PreVent | D3-3D9 | Repair VCT separation in classroom 14 and in | | SI | | Φυ | ΦU | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | corridor outside the classroom | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair / replace VCT at the entrance of Gym | | sf | | \$0 \$0 | \$0 | |
| | Tucumcan Lo | 2002 | Phase 2 | | Dist | 1 loor 1 littisties | i ievent | DO-0D9 | Repair / replace VCT at the entrance of | | 31 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Floor Finishes | PreVent | BS-SB9 | cafeteria | | sf | | \$0 | \$0 | |
| | racamean Eo | 1999 | Odicicia | | Dist | 1 loor 1 misries | i ievent | DO-0D9 | careteria | | 31 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT at the entrance of library | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT in corridor next to gym | | sf | | \$0 | \$0 | |
| | radamoan Eo | 2002 | 1 11450 4 | | Dist | 1 leaf i miones | 1 TO VOIR | BC 0B0 | Replace all VCT in south corridor. VCT is | | 01 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | bubbling | | sf | | \$0 | \$0 | |
| | radamean Ed | 2000 | 1 11466 6 | | D.O. | 1 loor 1 micrios | 11010111 | 20 020 | | | 0. | | ΨΟ | Ψ | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace / repair cracked VCT in commons area | | sf | | \$0 | \$0 | |
| | | 2000 | | | Biot | . 1001 1 111101100 | 1 10 VOIR | 20 020 | Tropiado / Topan eradica to tim delimiteno area | | 0. | | ΨΟ | Ψ** | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace / repair damaged VCT in storage room | | sf | | \$0 | \$0 | |
| | | | Original | | | | | | l l l l l l l l l l l l l l l l l l l | | | | ** | 7.2 | |
| | Tucumcari MS | 1970 | Building | Room 1 | Dist | Floor Finishes | PreVent | BS-SB9 | Repair interior water damage (6x6 AVT) | | sf | | \$0 | \$0 | |
| | | | Original | | | | | | Replace / repair cracked VCT in classrooms and | | | | ** | * - | |
| | Tucumcari MS | 1970 | Building | | Dist | Floor Finishes | PreVent | BS-SB9 | corridors | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair / replace cracked VCT in corridor outside | | | | · | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | boys restrooms | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair / replace cracked VCT in the lounge's | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | restroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | Correct settlement issues of slab between PreK- | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | 2nd grade building and Gym | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | | | | | | | | | Address movement in expansion joints in north | | | | | | |
| | | | | | | | | | and west walls of the gym; Assess settlement in | | | | | | |
| | | | | | | | | | wall between gym and the PreK-2nd grade | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | building; walkway has dropped 2 to 3 inches | | ea | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | 4 | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | HVAC | PreVent | BS-SB9 | Repair / replace rusted radiators in restrooms | | ea | | \$0 | \$0 | |
| | | | PreK-2nd | | L. | l <u></u> . | L | | | | | | | 4- | |
| | Tucumcari ES | 1998 | Grade Bldg | | Dist | Institutional Equipment | PreVent | BS-SB9 | Repair plastic laminate in Lounge | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | PreVent | BS-SB9 | Replace plastic laminate in girls restroom | | ea | | \$0 | \$0 | |
| | | | PreK-2nd | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Grade Bldg | ļ | Dist | Interior Doors | PreVent | BS-SB9 | Correct door in book room. Door binds in frame. | | ea | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | Interior Doors and Partitions | PreVent | BS-SB9 | Replace rusted metal partition in boys restrooms | | ea | | \$0 | \$0 | |
| | | | PreK-2nd | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Grade Bldg | <u> </u> | Dist | Interior Walls | PreVent | BS-SB9 | Repair water damage in electrical room | | sf | \$1.00 | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 16 | Dist | Interior Walls | PreVent | BS-SB9 | Repair damage on East wall of the classroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | Repair cracked walls in boys and girls restrooms, | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | and in room behind restrooms | | sf | | \$0 | \$0 | |
| | | | | | | | | 1 | Correct water damage and movement in walls | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Interior Walls | PreVent | BS-SB9 | due to water infiltration in corridor next to gym | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Interior Walls | PreVent | BS-SB9 | Repair split face cracking in north wall of gym | | sf | | \$0 | \$0 | |
| | | | Phase 4 | | L | l | L | | | | l <u>.</u> | | | | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | Repair wall cracks in classrooms | | sf | | \$0 | \$0 | |
| | | | Original | | | l | | | Repair cracked walls in classroom 9 and outside | | ١, | | <u>.</u> | * - | |
| | Tucumcari MS | 1970 | Building | l | Dist | Interior Walls | PreVent | BS-SB9 | room 1 | | sf | | \$0 | \$0 | |

NEEDS BY CATEGORY

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|----------|------------------------|---------------|-----------------|---------------|------------|---------------------------|----------|---------|--|-----|-------|--------------|-------------|---------------|-------------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | | | | | | | | | Repair cracked walls in classrooms, wood shop | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Interior Walls | PreVent | BS-SB9 | and lounge | | sf | | \$0 | \$0 | |
| | District Wide | | | | Dist. | Maintenance | PreVent | BS-SB9 | Preventive and Regular Maintenance needs | 5 | 5 yr | \$218,713.00 | \$1,093,565 | \$1,093,565 | |
| | Tucumcari HS | | GreenHouse | | Dist | Other Equipment | PreVent | BS-SB9 | Install netting and screens on cooling side | 1 | l ea | \$0.00 | \$0 | \$0 | |
| | | | PreK-2nd | | | | | | Investigate and address standing water in | | | | | | |
| | Tucumcari ES | 1998 | Grade Bldg | | Dist | Plumbing | PreVent | BS-SB9 | corridor by administration | 1 | l sf | \$0.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Gym | | Dist | Roof | PreVent | BS-SB9 | Correct roof leaks | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Roof | PreVent | BS-SB9 | Repair water filtration in skylites | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | Lounge | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | | | | | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Roof | PreVent | BS-SB9 | Correct damage due to water filtration in skylites | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 17 | Dist | Wall Finishes | PreVent | BS-SB9 | Repair window sill in classroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Wall Finishes | PreVent | BS-SB9 | Correct loose tile on planter in commons area | | sf | | \$0 | \$0 | |
| | | | | Special | | | | | | | | | | | |
| | | | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Office | Dist | Wall Finishes | | BS-SB9 | Repair crack at window and cracked walls | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Wall Finishes | PreVent | BS-SB9 | Repair wall damage in library | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Wall Finishes | PreVent | BS-SB9 | Repair base of wall in custodian room | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Wall Finishes | PreVent | BS-SB9 | Repair wall damage due to water in restrooms | | sf | | \$0 | \$0 | |
| | | | Original | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Building | Classroom 9 | | Wall Finishes | PreVent | BS-SB9 | Repair wall due to water damage in classroom 9 | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | | Classroom 16 | | Wall Finishes | | BS-SB9 | Repair window sill in classroom 16 | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 and 4 | | Dist | Z-Walkways | PreVent | BS-SB9 | Recaulk perimeter of building | | lf | \$2.00 | \$0 | \$0 | \$1,093,565 |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Air/Ventilation Equipment | Tech | Tech | Install split system for cooling in server room | C | ea ea | \$7,500.00 | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Air/Ventilation Equipment | Tech | Tech | Install split system for cooling in IT room | C | ea ea | \$7,500.00 | \$0 | \$0 | |
| | | | | | | | | | Upgrade IT equipment, software, training district | | | | | | |
| 1C | District Wide | | | | Dist | Technology | Tech | Tech | wide | 5 | yr | \$30,250.00 | \$151,250 | \$151,250 | |
| | | | Ag/Welding | | | | | | | | | | | | |
| | Tucumcari HS | 1990 | Shop | | FAD | Technology | Tech | Tech | | | ea | \$1,187.00 | \$0 | \$0 | |
| | Tucumcari HS | 1946 | Rattler Gym | | FAD | Technology | Tech | Tech | | | ea | \$4,772.00 | \$0 | \$0 | |
| | Tucumcari HS | 1985 | Auditorium | | FAD | Technology | Tech | Tech | | | ea | \$3,702.00 | \$0 | \$0 | \$151,250 |
| D | ife-Health-Safety-Secu | rity / Mainto | nance / Technol | ony Total Nee | rde. | | | | | | | | \$1,848,315 | \$1,848,315 | \$1,848,315 |

Priority 2 Building / Site System Upgrades: PreK-2nd Tucumcari ES Grade Bldg FAD HVAC \$82,559.00 \$82,559 1998 Install air conditioning in all classroom Tucumcari ES 2006 Kind Addition Dist HVAC AdqStd BS-GOB 2,367 ea \$20.00 \$47,340 \$61,542 PreK-2nd HVAC AdqStd BS-GOB \$446,780 \$580,814 Tucumcari ES 1998 Grade Bldg Dist Install air conditioning in all classroom 22,339 ea \$20.00 Phase 2 1999 Classrooms HVAC BS-GOB Install air conditioning in all classroom 77,301 ea \$20.00 \$1,546,020 \$2,009,826 Tucumcari ES Dist AdqStd Rhodes Field Tucumcari HS 1970 HVAC AdqStd BS-GOB Install Air Conditioning 12,713 sf \$20.00 \$254,260 \$330,538 Beyond Expected Life: District installed all new eating units in 2002. District needs air Tucumcari MS 1970 Original Bldg FAD HVAC AdqStd BS-GOB conditioning. Installed 2018 0 FAD \$1,063,074.00 Units were in good condition \$197,007. Install ai 1980 HVAC Trojan Gym FAD AdqStd BS-GOB conditioning in gym \$20.00 \$316,000 \$410,800 Tucumcari MS 15,800 sf Cafeteria HVAC BS-GOB Tucumcari MS 1972 Dist AdqStd Install air conditioning in cafeteria 15,800 sf \$20.00 \$316,000 \$410,800 Install air conditioning. Completed 201 Tucumcari MS 1996 CIrm Addition Dist HVAC AdqStd BS-GOB Tucumcari MS Original Bldg HVAC Controls AdqStd BS-GOB System was in use. Vent covers are old and worn \$148,470.00 FAD \$27,514.00 \$35,768 HVAC Controls \$27,514 \$3,947,415 Tucumcari MS 1980 Trojan Gym AdqStd BS-GOB System was in good condition. 1 FAD

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|--|---------------|-------|----------------------|------------|------------|----------------------------|-----------|---------|--|--------|----------|-----------------|-------------------------|--------------------------|-----------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Bv | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | Tucumcari ES | 2006 | Kind Addition | | | Ceiling Finishes | | BS-SB9 | In rooms 23 and 24 | | FAD | \$5,006.00 | \$5,006 | \$6,508 | |
| | | | | 20 0110 21 | 17.0 | | T GOTTOTT | 20 020 | Replace ceiling tiles throughout building in | | 17.0 | ψο,σσσ.σσ | φο,σσσ | \$0,000 | |
| | | | Original | | | | | | classrooms. Ceiling Tiles replaced in corridor | | | | | | |
| | Tucumcari MS | 1970 | Building | | Dist | Ceiling Finishes | FacRen | BS-SB9 | 2002. | 14,759 |) sf | \$6.00 | \$88,554 | \$115,120 | |
| | | | | | | - | | | Tiles in locker rooms, offices and store rooms | | | | | | |
| | | | | | | | | | were in good condition. Ceiling over the gym was | | | | | | |
| | Tucumcari MS | 1980 | Trojan Gym | | | Ceiling Finishes | | BS-SB9 | in good condition. | | FAD | \$53,594.00 | \$53,594 | \$69,672 | |
| | Tucumcari HS | 1962 | Main Bldg | | | Drain, Waste and Vent | | BS-SB9 | Bldg replaced in 2006 | | FAD | \$209,879.00 | \$0 | \$0 | |
| | Tucumcari HS | 1946 | Rattler Gym | | FAD | Drain, Waste and Vent | FacRen | BS-SB9 | | 1 | FAD | \$91,331.00 | \$91,331 | \$118,730 | |
| | | | Rhodes Field | | | | | | | | | | | | |
| | Tucumcari HS | 1970 | House | | | Drain, Waste and Vent | | BS-SB9 | | | FAD | \$24,397.00 | \$24,397 | \$31,716 | |
| | Tucumcari HS | 1985 | Auditorium | | | Drain, Waste and Vent | | BS-SB9 | | | FAD | \$70,848.00 | \$70,848 | \$92,102 | |
| | Tucumcari MS | 1972 | Cafeteria | | | Drain, Waste and Vent | | BS-SB9 | | | FAD | \$34,944.00 | \$34,944 | \$45,427 | |
| | Tucumcari MS | 1970 | Original Bldg | | | Drain, Waste and Vent | | BS-SB9 | | | FAD | \$97,822.00 | \$97,822 | \$127,169 | |
| | Tucumcari MS | 1980 | Trojan Gym | | | Drain, Waste and Vent | | BS-SB9 | | | FAD | \$43,508.00 | \$43,508 | \$56,560 | |
| | Tucumcari HS | 1985 | Auditorium | | | Exhaust Ventilation System | | BS-SB9 | | | FAD | \$40,731.00 | \$40,731 | \$52,950 \$52,900 | |
| - | Tucumcari HS | 1985 | Auditorium | | FAD | Exterior Doors | FacRen | BS-SB9 | Exterior doors are original: New exterior door at | 1 | FAD | \$40,997.00 | \$40,997 | \$53,296 | |
| | | | | | | | | | entry only. Upgrade exit door to courtyard in | | | | | | |
| | | | | | | | | | vestibule: Door is original. Upgrade north exterior | | | | | | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Exterior Doors | FacRen | BS-SB9 | doors: not ADA compliant | 1 | FAD | \$56,605.00 | \$56,605 | \$73,587 | |
| | Tucumcan ivis | 1970 | Original blug | | FAD | Exterior Doors | racken | D3-3D9 | Doors were in good condition: District replaced 2 | | ITAD | \$50,005.00 | φ30,003 | φ <i>1</i> 3,36 <i>1</i> | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Exterior Doors | FacRen | BS-SB9 | double doors at entry | 1 | FAD | \$25,176.00 | \$25,176 | \$32,729 | |
| | Tucumcan Wo | 1900 | 110jaii Oyiii | | IAD | Exterior Doors | raciten | DO-0D9 | double doors at entry | ' | | Ψ23,170.00 | Ψ23,170 | Ψ32,129 | |
| | | | 3rd and 4th | | | | | | Doors opened and closed properly in this asset | | | | | | |
| | Tucumcari ES | 2000 | Grade Bldg | | FAD | Exterior Doors | FacRen | BS-SB9 | \$41,937: Replace all exterior doors and frames | 1 | FAD | \$41,937.00 | \$41,937 | \$54,518 | |
| | Tucumcari ES | 1999 | Campus wide | | | Exterior Doors | | BS-SB9 | Replace all exterior doors and frames | | ea | \$5,000.00 | \$250,000 | \$325,000 | |
| | racamean EC | 1000 | Campac wac | | Biot | Exterior Degre | racran | 20 020 | Front doors are original; all doors in kitchen new, | | Jou | φο,σσσ.σσ | Ψ200,000 | ψ020,000 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Exterior Doors | FacRen | BS-SB9 | except for 2 exit doors | 0 | FAD | \$20,220.00 | \$0 | \$0 | |
| | Tucumcari HS | 1985 | Auditorium | | | Exterior Windows | | BS-SB9 | | | FAD | \$40,997.00 | \$40,997 | \$53,296 | |
| | Tucumcari MS | 1972 | Cafeteria | | | Exterior Windows | | BS-SB9 | Replace all windows | | FAD | \$20,220.00 | \$20,220 | \$26,286 | |
| | | | | Library & | | | | | | | | . , | . , | | |
| | | | | Special | | | | | Upgrade carpet in library and Special Programs | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Programs | Dist | Floor Finishes | FacRen | BS-SB9 | Offices | 5,427 | r sf | \$6.00 | \$32,562 | \$42,331 | |
| | | | Phase 4 | | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in classrooms and computer lab | 2,500 |) sf | \$6.00 | \$15,000 | \$19,500 | |
| | | | | | | | | | Upgrade carpet in classrooms, computer lab and | | | | | | |
| | | | Phase 1 | | | | | | offices. Carpet is in good condition in classroom | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | | Floor Finishes | | BS-SB9 | 8 | 5,750 | | \$6.00 | \$34,500 | \$44,850 | |
| | Tucumcari ES | 2006 | Kind Addition | | FAD | Floor Finishes | FacRen | BS-SB9 | Tiles and carpet were in good condition | 1 | FAD | \$12,201.00 | \$12,201 | \$15,861 | |
| | | | | | | | | | The old portion would be locker rooms floors. | | | | | | |
| | | 4000 | - | | 5.5 | | | 50.050 | Floors were in good condition. Wood floor | 0.500 | | | 0.15 000 | #40 =00 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Floor Finishes | FacRen | BS-SB9 | replaced 2011. \$62,700 | 2,500 |) ST | \$6.00 | \$15,000 | \$19,500 | |
| | | | Out at the set | | | | | | Davis and Even acted Life, we would be a seemed in 1999. | | 1 | | | | |
| | T | 4070 | Original | | D: . | Eleca Elejakoa | E 5 | DO 000 | Beyond Expected Life: upgrade carpet in middle | 0.750 | | # 0.00 | # 40 F 00 | CO4 450 | |
| - | Tucumcari MS | 1970 | Building | | Dist | Floor Finishes | FacRen | BS-SB9 | corridors, reception area and classroom 14 | 2,750 |) SI | \$6.00 | \$16,500 | \$21,450 | |
|] | Tucumoori MS | 1970 | Original Building | | Dist | Floor Finishes | FacPon | BS-SB9 | Poplace ashestes floor tile in 4 porth alcores | 3,771 | ef | ¢20.00 | ¢75 400 | ¢00.040 | |
| | Tucumcari MS | 1970 | Duliding | | חופו | I IOOI FIIIISHES | FacRen | DO-0D8 | Replace asbestos floor tile in 4 north classrooms | 3,771 | 51 | \$20.00 | \$75,420 | \$98,046 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in classrooms and computer lab | 15,000 | ef | \$6.00 | \$90,000 | \$117,000 | |
| | Tucumcari HS | 1985 | Auditorium | | | Institutional Equipment | | BS-SB9 | Install presentation system | | ea | \$50,000.00 | \$50,000 | \$65,000 | |
| | Tucumcari HS | 1985 | Auditorium | | | Institutional Equipment | | BS-SB9 | Update sound system: Completed | | ea ea | \$30,000.00 | \$30,000 | \$0 | |
| | Tucumcari MS | 1970 | Original Bldg | | | Institutional Equipment | | BS-SB9 | Special Sound System. Completed | | FAD | \$67,230.00 | \$67,230 | \$87,399 | |
| | Tucumcari MS | 1980 | Trojan Gym | | | Institutional Equipment | | BS-SB9 | | | FAD | \$29,901.00 | \$29,901 | \$38,871 | |
| | Tucumcari HS | 1985 | Auditorium | | | Lighting / Branch Circuits | | BS-SB9 | Update stage lighting | 1,000 | | \$8.00 | \$8,000 | \$10,400 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Lighting / Branch Circuits | | BS-SB9 | | | FAD | \$69,612.00 | \$69,612 | \$90,496 | |
| | | | | | | <u> </u> | | | | | | , , , , , , , , | +,-· - | 722, 300 | |
| [| Tucumcari MS | 1970 | Original Bldg | | FAD | Lighting / Branch Circuits | FacRen | BS-SB9 | Beyond Expected Life: Updated to LED in 2016 | 0 | FAD | \$97,437.00 | \$0 | \$0 | |
| | | | | | | | | | · | | | | | | |
| ŀ | Tucumcari MS | 1980 | Trojan Gym | | FAD | Lighting / Branch Circuits | FacRen | BS-SB9 | Split system for original branch circuits \$43,337 | 15,800 |) sf | \$3.00 | \$47,400 | \$61,620 | |

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|----------|---------------------------|--------------|------------------------|------|-------------|---------------------------|------------------|------------------|---|--------|------------|-------------------------|------------|-----------------------|------------|
| PRIORITY | FACILITY NAME | | ADEA | DOOM | | | CATEGORY | _ | FACILITY NEEDS | OTV | UNIT | COST/UNIT | | COST | CUPTOTALO |
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | | QTY | UNII | COST/UNIT | MACC | COST | SUBTOTALS |
| | - : | 4005 | A 114 1 | | D: . | L. 5 /5 | | DO 000 | Update electrical on stage to provide more power | |] . | *** | | 040.400 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Main Power/Emergency | FacRen | BS-SB9 | outlets | 1,000 | st | \$8.00 | \$8,000 | \$10,400 | |
| | - : | 4005 | A 114 1 | | D: . | B | | DO 000 | Replace missing sink in backstage women's | | | # 5 000 00 | Φ= 000 | #0.500 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Plumbing | FacRen | BS-SB9 | restroom | | ea | \$5,000.00 | \$5,000 | \$6,500 | |
| | Mountain View ES | 1 | Dual Coad | | Dist | Roof | FacRen | BS-GOB | Replace Roof | 7,000 | ST | \$20.00 | \$140,000 | \$182,000 | |
| | Turning and FC | 4000 | PreK-2nd Grade Bldg | | | Doof | FaaDaa | DC CDO | TPO and metal pitched roof. Roof was in good | , | | ¢400,007,00 | \$0 | ¢o. | |
| | Tucumcari ES Tucumcari HS | 1998 1985 | Auditorium | | FAD Dist | Roof Roof | FacRen FacRen | BS-SB9 BS-GOB | condition Replace auditorium flat roofs | 6,000 | FAD | \$162,087.00 \$20.00 | \$120,000 | \$156,000 | |
| | Tucumcari HS | 1900 | GreenHouse | | Dist | Roof | FacRen | BS-SB9 | Replace green house roof | 800 | | \$20.00 | \$120,000 | \$20,800 | |
| | Tucumcari MS | 1990 | Original Bldg | | FAD | Roof | FacRen | BS-GOB | Beyond Expected Life: Replaced 2018 | | FAD | \$242,907.00 | \$16,000 | \$20,800 | |
| | Tucumcari HS | 1962 | Main Bldg | | FAD | Water Distribution | FacRen | BS-GOB | Bldg replaced in 2006 | | FAD | \$242,907.00 | \$0 \$0 | ΦO | |
| | Tucumcari HS | 1946 | Rattler Gym | | FAD | Water distribution | FacRen | BS-GOB | Blug Teplaced III 2000 | | FAD | \$91,331.00 | \$91,331 | \$118,730 | |
| | Tucumcan no | 1940 | Rhodes Field | | IAD | Water distribution | i acixeii | D3-G0B | | | I AD | ψ91,331.00 | φ91,331 | \$110,730 | |
| | Tucumcari HS | 1970 | House | | FAD | Water Distribution | FacRen | BS-GOB | | | FAD | \$24,397.00 | \$24,397 | \$31,716 | |
| | Tucumcari HS | 1985 | Auditorium | | FAD | Water Distribution | FacRen | BS-GOB | | | FAD | \$70,848.00 | \$70,848 | \$92,102 | |
| - | Tucumcari MS | 1972 | Cafeteria | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | | FAD | \$34,944.00 | \$34,944 | \$45,427 | |
| | Tucumcari MS | 1972 | Original Bldg | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | | FAD | \$97,288.00 | \$97,288 | \$126,474 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | | FAD | \$2,941.00 | \$2,941 | \$3,823 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Z-Landscaping / Drainage | FacRen | BS-SB9 | Replace sprinkler system: valves and pipes | | ea | \$75,000.00 | \$75,000 | \$97,500 | |
| | Mountain View ES | 2002 | 1 11a36 4 | | Dist | Z-Parking Lots | FacRen | BS-GOB | Resurface parking lot | 30,000 | | \$4.00 | \$120,000 | \$156,000 | |
| | Tucumcari HS | 1946 | Site | | FAD | Z-Parking Lots | FacRen | BS-GOB | Beyond Expected Life Portion | | FAD | \$103,618.00 | \$103,618 | \$134,703 | |
| | Tucumcan no | 1940 | Site | | IAD | Z-Faiking Lois | i aciveii | D3-G0B | Beyond Expected Life Fortion Beyond Expected Life \$197,512: Repave west | | I AD | \$103,010.00 | \$103,010 | \$134,703 | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Parking Lots | FacRen | BS-GOB | parking lot | 30,000 | of | \$6.00 | \$180,000 | \$234,000 | \$3,483,16 |
| | Tucumcan wo | 1970 | Cafeteria/ | | IAD | Z-Faiking Lois | i aciveii | D3-G0B | parking lot | 30,000 | 51 | φ0.00 | \$100,000 | \$234,000 | φ3,403,10 |
| | Tucumcari ES | 1999 | Library/SPED | | FAD | Communications / Security | LHSS | L-GOB | System was in good working condition | (| FAD | \$29,762.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Gym | | FAD | Communications / Security | LHSS | L-GOB | System was in good working condition | | FAD | \$4,221.00 | \$0 \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | FAD | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 27,520 | | \$2.50 | \$68,800 | \$89,440 | |
| | Tucumcari MS | 1970 | Main Bldg | | Dist | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 30,150 | | \$2.50 | \$75,375 | \$97,988 | |
| | Tucumcari MS | 1970 | Cafeteria | | Dist | Communications / Security | LHSS | L-GOB | Upgrade intercom \$32,182 | 15,800 | | \$2.50 | \$39,500 | \$51,350 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Communications / Security | LHSS | L-GOB | There is no intercom in this building | 15,800 | | \$2.50 | \$39,500 | \$51,350 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Fire Detection / Alarm | LHSS | L-GOB | No fire alarm in this building | 15,800 | | \$3.50 | \$55,300 | \$71,890 | |
| | Tucumcari MS | 1996 | Addition | | FAD | Fire Detection/Alarm | LHSS | L-GOB | \$32,182 | 27,520 | | \$3.50 | \$96,320 | \$125,216 | |
| | Tucumcari MS | 1970 | Original Bldg | | Dist | Fire Detection/Alarm | LHSS | L-GOB | Ψ32,102 | 30,150 | | \$3.50 | \$105,525 | \$137,183 | |
| | Tucumcari MS | 1970 | Cafeteria | | Dist | Fire Detection/Alarm | LHSS | L-GOB | | 15,800 | | \$3.50 | \$55,300 | \$71,890 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 15,800 | | \$10.00 | \$158,000 | \$205,400 | |
| | Tucumcan wo | 1900 | Original | | Dist | l lie Spillikiei | LITOO | L-00B | The building is not sprinklered | 13,000 | 7 31 | Ψ10.00 | ψ130,000 | Ψ203, 4 00 | |
| | Tucumcari MS | 1970 | Building | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 30,150 | of | \$10.00 | \$301,500 | \$391,950 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 27,520 | | \$10.00 | \$275,200 | \$357,760 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Fire Sprinkler | LHSS | L-GOB | Required by UBC. Grandfathered in \$70.780 | 30,150 | | \$10.00 | \$301,500 | \$391,950 | |
| | Tucumcan WC | 1370 | Phase 1 | | IAD | i ne oprinkler | LITOU | LOOD | required by ODO. Grandiamered in \$70,700 | 50,150 | Ca | ψ10.00 | ψ301,300 | ψ001,000 | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Fire Sprinklers | LHSS | L-GOB | Building is not sprinklered | 22,319 | ef | \$10.00 | \$223,190 | \$290,147 | |
| | racamean Lo | 1330 | Olassioonis | | Dist | i iie opiiiikieis | LITOU | LOOD | Building is not sprinklered | 22,010 | / JOI | Ψ10.00 | ΨΖΖΟ,130 | Ψ230,147 | |
| | Tucumcari HS | 1962 | Main Bldg | | FAD | Fire Sprinklers | LHSS | L-GOB | Beyond Expected Life: Bldg was replaced in 2006 | (| FAD | \$0.00 | \$0 | \$0 | |
| - | Tucumcari HS | 1946 | Rattler Gym | | FAD | Fire Sprinklers | LHSS | L-GOB | Beyond Expected Life Beyond Expected Life | | FAD | \$86,046.00 | \$86,046 | \$111,860 | |
| | i ucumcan Ho | 1340 | Namer Gym | | I AD | i iio opiiiikieis | LI 100 | E-00B | To the b side doors leading to the floors. District | | IAD | ΨΟΟ,040.00 | φου,υ40 | φ111,000 | |
| | | | Cafeteria/ | | | | | | is monitoring. The remaining areas are in good | | | | | | |
| | Tucumcari ES | 1999 | Library/SPED | | FAD | Floor Finishes | LHSS | L-GOB | condition | 1 | FAD | \$100,035.00 | \$100,035 | \$130,046 | |
| | racamean Lo | 1555 | PreK-2nd | | IAD | 1 loor i misries | LITOO | L-00B | Correction of tiles in the hallways and in the | | ו אט | ψ100,033.00 | Ψ100,033 | Ψ130,040 | |
| | Tucumcari ES | 1998 | Grade Bldg | | FAD | Floor Finishes | LHSS | L-GOB | classrooms due to the settlement of the asset | 4 | FAD | \$156,782.00 | \$156,782 | \$203,817 | |
| — | r dodinican EO | 1330 | PreK-2nd | | I AD | 1 IOOI I IIIIGIIOG | 11100 | _ 000 | Filling cracks and monitoring the areas of the | | I AD | Ψ100,702.00 | Ψ130,702 | Ψ203,017 | |
| | Tucumcari ES | 1998 | Grade Bldg | | FAD | Interior Walls | LHSS | L-GOB | cracks in this asset | 4 | FAD | \$138,705.00 | \$138,705 | \$180,317 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | | FAD | \$8,363.00 | \$138,703 | \$100,517 | |
| - | Tucumcari MS | 1972 | Original Bldg | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | | FAD | \$23,411.00 | \$0 | | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | | FAD | \$10,413.00 | \$0 | | |
| | Tucumcari HS | 1962 | Main Bldg | | FAD | Main Power/Emergency | LHSS | L-GOB | Bldg replaced in 2006 | | FAD | \$50,229.00 | \$0 \$0 | | |
| | - abamban Ho | 1302 | Original | | IAD | Main i owon Emorgonoy | LI 100 | _ 555 | Upgrade staff and students restrooms to ADA | | ואט | Ψου,ΖΖΘ.00 | ΨΟ | ΨΟ | |
| | Tucumcari MS | 1970 | Building | | Dist | Plumbing | LHSS | L-GOB | compliant | 400 | sf | \$300.00 | \$120,000 | \$156,000 | |
| | i dodinodii MO | 1070 | Dunung | | 2.30 | l ambing | L. 100 | _ 005 | Beyond Expected Life: Upgrade restrooms in | 400 | , <u> </u> | ψ500.00 | Ψ120,000 | ψ100,000 | |
| 1 | | | | | 1 | | | | cafeteria to ADA compliant; restrooms alcoves | | | | | | |
| | Tucumcari MS | 1972 | Cafeteria | | Dist | Plumbing | LHSS | L-GOB | not ADA | 300 | ef | \$300.00 | \$90,000 | \$117,000 | |
| | . acamoun mo | 1072 | Jaiotolia | | 12.00 | amang | 1200 | | | 500 | , . | Ψ000.00 | Ψ50,000 | Ψ117,000 | |

NEEDS BY CATEGORY

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|---------------------|---------------------------|-------------|----------------------|------|------------|------------------------|----------|---------|---|--------|-------|----------------|--------------|---------------|--------------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | Tucumcari ES | 1998 | Site | | Dist | Z-Fencing | LHSS | L-GOB | Complete perimeter fencing | 2,000 |) If | \$100.00 | \$200,000 | \$260,000 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Fencing | LHSS | L-GOB | Complete perimeter fencing | 2,500 |) If | \$100.00 | \$250,000 | \$325,000 | |
| | Tucumcari ES | 1998 | Site | | Dist | Z-Playground Equipment | LHSS | L-GOB | Replace west playground | 1 | ea | \$50,000.00 | \$50,000 | \$65,000 | |
| | Tucumcari ES | 1998 | Site | | Dist | Z-Playground Equipment | LHSS | L-GOB | Install swings at the old playground | 1 | ea | \$20,000.00 | \$20,000 | \$26,000 | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Playground Equipment | LHSS | L-GOB | No playground equipment | C |) FAD | \$66,835.00 | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Site Specialties | LHSS | L-GOB | Install solar traffic signs | 2 | ea | \$2,500.00 | \$5,000 | \$6,500 | |
| | Tucumcari ES | 1998 | Site | | FAD | Z-Walkways | LHSS | L-SB9 | Could split as there is large fine sections. Being monitored for further damage by the district | | FAD | \$315,170.00 | \$315,170 | \$409,721 | |
| | Tucumcari MS | 1970 | Site | | FAD | Z-Walkways | LHSS | L-SB9 | The facility has lots of spalding and cracking | 1 | FAD | \$223,448.00 | \$223,448 | \$290,482 | \$4,615,255 |
| Priority 2 B | Building / Site System U | lpgrades To | tal Needs: | | | | | | | | | | \$9,266,029 | \$12,045,838 | \$12,045,838 |
| | | | | | | | | | | | | | | | |
| Priority 3 | Capital Projects: | | | | | | | | | | | | | | |
| | | | | | | | | | Demolish part of bldg. / keep part of bldg. for | | | | | | |
| 3 | Mountain View ES | | | | | Demolition | AdqStd | MP-GOB | Head Start Program | 16,060 |) sf | \$25.00 | \$401,500 | \$521,950 | |
| 2 | Tucumcari MS | | Site | | | Demolition | AdqStd | MP-GOB | Demolish old maintenance bldg. across from MS and create new parking lot with site lighting | 22,720 | _ | \$12.50 | \$284,000 | \$369,200 | \$891,150 |
| 5 | Tucumcari ES | | Site | | ļ | New Construction | EdPro | MP-GOB | Install Turf at South ES playground | 12,500 |) st | \$8.00 | \$100,000 | \$130,000 | |
| | Tucumcari MS | 1970 | Original Builidng | | | Renovation | EdPro | MP-GOB | Renovate Home Economics Lab | 1,450 | | \$200.00 | \$290,000 | \$377,000 | \$507,000 |
| | Tucumcari HS | | 1948 | | | Renovation | FacRen | MP-GOB | Renovate Rattler Field Concessions | 250 | | \$75.00 | \$18,750 | \$24,375 | \$24,375 |
| 7 | Tucumcari HS | | Site | | | New Construction | LocPol | MP-GOB | Install canopies at Track & Field | 4 | l ea | \$25,000.00 | \$100,000 | \$130,000 | |
| 1 | Tucumcari HS | | Site | | | New Construction | LocPol | MP-GOB | Create district baseball and softball field complex: lighted fields, concessions, restrooms, irrigated grass, bleachers, pressbox | 1 | ea | \$3,750,000.00 | \$3,750,000 | \$4,875,000 | |
| 9 | Tucumcari HS | | Vo.Ag. Bldg. | | | New Construction | LocPol | MP-GOB | Create a storefront (small building) for customers to buy student vegetables | 120 |) sf | \$125.00 | \$15,000 | \$19,500 | \$5,024,500 |
| Priority 3 C | Capital Projects Total No | eeds: | | | | | | | | | | | \$4,959,250 | \$6,447,025 | \$6,447,025 |
| Tucumca | ari Public Schools T | otal Need | s: | | | | | | TOTAL: | | | | \$16,073,594 | \$20,341,178 | |

Tucumcari Public Schools • 5-Year Facilities Master Plan

3.3.1 PRIORITY CAPITAL IMPROVEMENTS FOR NEXT 5 YEARS

The Tucumcari Public Schools (TPS) prioritized list of facility needs for the next five years was developed by the TPS Facilities Master Plan (FMP) steering committee and adopted by the TPS School Board. The FMP steering committee had completed some preliminary work prior to starting the FMP process which enabled them to complete their tasks in a streamlined process. The FMP steering committee identified the facility needs throughout the district during the first committee meeting, discussed the facility needs and their impact on students and the district, and prioritized the facility needs during the second committee meeting. The prioritized list of Tucumcari Public Schools for 2019 to 2023 facility needs is:

TPS FINAL FMP 2019-2023 PRIORITIES

| FINAL Priority RANK | Priority Description | Funding Source | PSCOC / PSFA Funding | Schedule | Total 5 Year Project |
|---------------------------|--|-------------------|----------------------------|----------|-------------------------|
| 1A | Life-Health-Safety-Security | SB-9 | 1 | 2019-23 | \$603,500 |
| 1B | Maintenance/Preventive Maintenance | SB-9 | 1 | 2019-23 | \$1,093,565 |
| 1C | Technology | SB-9 | 1 | 2019-23 | \$151,250 |
| | Priority 1 Subtotal: | | | | \$1,848,315 |
| | | | | | |
| 2 | Facility / Site System Renewal: | | | | |
| 2A | Tucumcari Middle School | SB-9/GOB* | 2 | 2019-23 | \$5,286,373 |
| 2B | Tucumcari Elementary School | SB-9/GOB | 3 | 2019-23 | \$4,930,623 |
| 2C | Tucumcari High School | SB-9/GOB | 4 | 2019-23 | \$1,490,841 |
| 2D | Mountain View Elementary School | SB-9/GOB | | 2019-23 | \$338,000 |
| | Priority 2 Subtotal: | | | | \$12,045,838 |
| | | | | | |
| 3 | Potential Capital Projects: | | | | |
| 3A | TPS: Create District baseball & softball complex | GOB | | 2019-23 | \$4,875,000 |
| 3B | Demolish Old Maintenance Bldg and build parking lot | GOB | | 2023 | \$369,200 |
| 3C | Demolish part of Mountain View ES and re-roof remaining building | GOB** | | 2023 | \$521,950 |
| 3D | Re-roof Auditorium Flat Roofs | GOB*** | 4 | 2020 | |
| 3E | Install turf at south TES playground | GOB | | 2023 | \$130,000 |
| 3F | TMS: Renovate Home Economics Lab | GOB | 2 | 2023 | \$377,000 |
| 3G | THS: Install campoies at Track & Field | GOB | | 2023 | \$130,000 |
| 3H | THS: Renovate Rattler Field Concessions | GOB | | 2023 | \$24,375 |
| 31 | THS: Create a storefront for customers to buy student vegetables | GOB | | 2023 | \$19,500 |
| | Priority 3 Subtotal: | | | | \$6,447,025 |
| | TPS 2019-2023 FMP Priorities TOTAL: | | | | \$20,341,178 |
| | *It is anticipated that PSCOC / PSFA will participate in | the Facility / S | Site System | Renewal | |

| 2A | *It is anticipated that PSCOC / PSFA will participate in the Facility / Site System Renewal projects for Tucumcari Middle School at approximately 68% but could require closure / demolition of the 1970 building. PSCOC / PSFA Share: | \$3,594,734 |
|----|--|-------------|
| 3C | **The probable cost to re-roof Mountain View Elementary School is included in Priority 2D. | \$182,000 |
| 3D | ***The probable cost to re-roof the auditorium flat roofs is included in Priority 2C. | \$156,000 |

The TPS priorities listed above reflect the facility mission and vision of the district to provide a safe, comfortable, stimulating learning environment to all of its students in efficient and effective facilities.

3.3

Capital Plan

Priority 1, Recurring Needs

\$1,848,315

The first three lines of the above priorities are recurring items that the district has to address to avoid impact to its educational program. They are assigned a priority of 1A, 1B and 1C to indicate that these items will be addressed as needed and as funding is available. These items will be primarily funded through SB-9, Payment in Lieu of Taxes and E-rate.

1A: Immediate Life-Health-Safety-Security-Code-ADA Compliance needs will be addressed by the district with SB-9 and GOB funds as the needs arise and funding is available from 2019 to 2023.

1B: Maintenance and preventive maintenance needs that will be addressed by the district with SB-9 and GOB funds as funding is available from 2019 to 2023. Tucumcari Public Schools has worked with the Public Schools Facilities Authority (PSFA) to develop a preventive maintenance plan, funded through SB-9 funds that has the potential to eliminate deferred maintenance and could extend the life of existing building systems; however, limited funding has made it difficult for TPS to fully implement its preventive maintenance plan, thus impacting the life of existing building systems.

1C: Technology needs, even though Tucumcari Public Schools does not have a documented technology plan, are a priority. The district is working to update its technology infrastructure, equipment, and broadband width as needed to assure that its students are receiving a relevant educational program and are prepared for life after high school. The district currently uses e-rate and PLT funds to fund technology needs. The district has not applied for PSCOC Broadband initiative, but realizes this is an option for TPS in the future. The district will continue to monitor its technology system and apply for PSCOC Broadband funds when it is appropriate and will benefit the district. Priority 1C will be funded with E-rate, SB-9 and PLT funds from 2019 to 2023.

Priority 2, Building and Site System Renewal Projects

\$12,045,838

This is a reflection of the district's dedication to maintaining its existing facilities. The building and site system renewal projects have been identified as a high priority because some if not all of the TPS facilities have areas where these facility/site systems are past their useful life and have the potential to impact the school's mission. Tucumcari Public Schools understands the importance of addressing the identified needs before they cause collateral damage. Each school was analyzed and physically inspected to identify the needs of the buildings. Based on the data obtained from the analysis and inspection of the facilities, the FMP steering committee reviewed the information of each facility and voted to assign a facility/site system renewal priority rank for each school. The priorities were assigned as follows:

- 1. Tucumcari Middle School
- 2. Tucumcari Elementary School
- 3. Tucumcari High School
- 4. Mountain View Elementary School

The table on the following page shows the facility and site systems renewal priorities identified at each TPS school for the 2019/2023 capital plan:

3.3

Capital Plan

| Building Systems Upgrades (Priority 2) | TES | TMS | THS | MVES |
|---|-----|-----|-----|------|
| Air / Ventilation Equipment | | | | |
| Ceiling Finishes | х | х | | |
| Communications / Security | | х | | |
| Drain, Waste and Vent | | х | Х | |
| Exhaust Ventilation System | | | Х | |
| Exterior Walls | | | | |
| Exterior Windows & Doors | х | х | Х | |
| Fire Detection / Alarm | | х | | |
| Fire Sprinklers | х | х | Х | |
| Floor Finishes | х | х | | |
| Foundation / Slab / Structure | | | | |
| HVAC: Equipment & Controls | х | х | Х | |
| Institutional Equipment: Kitchen Equip & Casework | | х | Х | |
| Interior Doors, Partitions, Stairs, Elevators | | | | |
| Interior Walls | Х | | | |
| Lighting / Branch Circuits | | х | Х | |
| Main Power / Emergency | | | Х | |
| Other Electrical Systems | | | | |
| Other Equipment | | | | |
| Plumbing / District Water Treatment | | х | Х | |
| Roofs | | | Х | Х |
| Wall Finishes | | | | |
| Water Distribution | | | Х | |
| Athletic Fields | | | | |
| Fencing | Х | Х | | |
| Landscaping Drainage | Х | | | |
| Parking Lots: Asphalt | | Х | Х | Х |
| Playground Equipment | Х | | | |
| Site Lighting | | | | |
| Site Specialties | | Х | | |
| Site Utilities | | | | |
| Walkways | Х | Х | | |

Priority 2 needs will be funded with a combination of SB-9 and GOB funds as they are available from 2019 to 2023. Tucumcari Public Schools could apply for PSCOC/PSFA funds for Tucumcari Middle School and any other district school that qualifies PSCOC facility and site system renewal during the life of this FMP.

Priority 3: Capital Projects.

\$6,447,025

The capital projects listed below are a reflection of the district's dedication to provide safe and secure learning environments for its students and to utilize existing facilities as efficiently and effectively as possible. Capital project 3A refers to the construction of a districtwide baseball and softball complex. Currently the district utilizes the city's complex for baseball and softball events.

The city does not have the resources to adequately maintain the baseball and softball complex to provide a safe environment for students. The district is working with the City of Tucumcari to acquire the complex and have it be the district's responsibility to maintain the complex. Priority 3B is the demolition of the old maintenance building which is beyond repair and not being used. The district would like to dispose of the building and create a parking lot in this space. This parking lot will serve TMS, and both Trojan and Rattler Gyms. Priority 3C refers to demolishing the unleased portion of Mountain View Elementary School building. The district leases a portion of this facility to the local Head Start program. The district will keep the leased portion and demolish the other portion of the building. As part of priority 3C, TPS has identified the need to re-roof the portion of the building that will remain. Priority 3D will re-roof the flat roofs of the auditorium. Priority 3E is to install turf at the south playground of Tucumcari Elementary School. Priority 3F is the renovation of the home economics lab at Tucumcari Middle School. Priorities 3G, 3H and 3I are all related to Tucumcari High School. Priority 3G refers to installing canopies at the track and field; priority 3H refers to renovation of Rattler field concessions, and priority 3I is the creation of a storefront for customers to buy student-grown vegetables that are harvested in the high school greenhouse.

The identified Priority 3 capital projects for the 2019/2023 TPS FMP are:

- A. Create district baseball and softball complex
- B. Demolish old maintenance building and build parking lot
- C. Demolish part of Mountain View Elementary School and re-roof remaining of building
- D. Re-roof auditorium flat roofs
- E. Tucumcari Elementary School: Install turf at south playground
- F. Tucumcari Middle School: Renovate home economics lab
- G. Tucumcari High School: Install canopies at track and field
- H. Tucumcari High School: Renovate Rattler field concessions
- I. Tucumcari High School: Create a storefront for customers to buy student vegetables

Priority 3 capital projects will be funded with the next District GOB funds election, which is anticipated to be held in 2019. The district would like assistance from PSCOC/PSFA on the demolition of the old maintenance building and part of Mountain View Elementary School since these priorities identify the district's determination to reduce excess square footage of district facilities thus reducing maintenance and operation costs.

Facility Assessment Database

The Facilities Assessment Database (FAD) ranking of TPS educational facilities was shared with and reviewed by the TPS FMP steering committee throughout the FMP process. The condition of facilities and the FAD ranking was considered and became part of the criteria in the TPS FMP steering committee's prioritization of the district's facility needs. The following FAD ranking was published April 18, 2018.

2018-2019 PSCOC/PSFA RANKING OF TPS Schools

TPS PSFA Facilities Assessment Database (FAD)

| School | 2018-19 Rank | Weighted NMCI |
|--------------|-----------------|------------------|
| Tucumcari ES | 487 | 17.39% |
| Tucumcari MS | 170 | 33.61% |
| Tucumcari HS | 494 | 17.05% |

STATE PARTICIPATION IN APPROVED PROJECTS: 66% DISTRICT PARTICIPATION IN APPROVED PROJECTS: 34%

Due to the current FAD ranking of TPS schools, the district anticipates to partner with PSCOC/PSFA to obtain funding for the identified facility needs at Tucumcari Middle School during the life of this FMP. Tucumcari Public Schools has aligned its priorities with the FAD and will continue to work with PSCOC/PSFA, monitor the FAD rankings, funding procedures, and apply for funding as district schools become eligible.

Facilities Assessment Database (FAD) and Facilities Maintenance Assessment Report (FMAR)

A change in how the PSCOC/PSFA can fund a public school capital project was implemented for the 2017-2018 funding process and is anticipated to be in effect for the 2018-19 PSCOC/PSFA funding cycle. The PSCOC/PSFA is now funding building system replacements and the complete renovation of a school, depending on the FAD ranking and condition of the school. This will benefit schools by creating smaller projects thus reducing their share of a PSCOC/PSFA approved project. The Public Schools Facility Authority has generated a FAD/FMAR report that identifies all of the potential building systems in each school that could be eligible for this funding source.

In February 2018 the State passed the Senate Bill 30 (SB30) which will replace the current state and local match formula in the Public School Capital Outlay Act (PSCOA) for capital outlay awards that the district may pursue. This formula will be implemented in a five year period starting in 2019.

According to the SB30 description, the new formula "adjusts the state and local match to more accurately reflect each school district's ability to pay for public school capital outlay projects. The current calculation is based on the net taxable value for a school district and the number of students enrolled during the immediately preceding year. The new calculation is based on the net taxable value for a school district for the prior five years, the maximum allowable gross square foot per student, the replacement cost per square foot, and the school district population density."

The gradual change in the district and state match is shown in table on the next page. At the end of the five year implementation period, the state match for TPS will increase to 70 percent and the local match will decrease to 30 percent. This is a gain in state's match of 4 percent for TPS.

TPS Change in State/District Share Five Year Phase

| Phase | Local Match | State Match |
|----------------------------|-------------|-------------|
| Phase 1 2017-18 | 31% | 69% |
| Phase Year 1 (FY 20) | 31% | 69% |
| Phase Year 2 (FY 21) | 31% | 69% |
| Phase Year 3 (FY 22) | 30% | 70% |
| Phase Year 4 (FY 23) | 30% | 70% |
| Phase Year 5 Final (FY 24) | 30% | 70% |

2024 STATE SHARE OF AN APPROVED PROJECT: 70% DISTRICT SHARE OF AN APPROVED PROJECT: 30%

The FAD and FMAR reports were reviewed by district administration and the maintenance staff twice during the FMP process. Most schools within TPS have a large portion of building systems that are beyond expected life or are potential mission impact/degraded. The building systems identified in the FAD and FMAR reports are listed in the district's facility needs and capital plan.

Adoption of FMP District Priorities and Capital Plan

The district priorities were reviewed by the TPS School Board of Education on November 12, 2018 and the final FMP document was adopted on January 21, 2019.

3.3.2 TPS FINANCIAL STRATEGIES AND ALTERNATIVES

At the conclusion of the 2019-23 Facilities Master Plan process, priorities were identified and a capital plan was generated that will address the critical needs of TPS for the next five years and in to the foreseeable future. This is a living document that can and should be reviewed yearly and modified as necessary to reflect the direction of the district.

The district has had the continued support of its local community and passed a \$3,000,000 GOB in February of 2015 allowing it to keep its facilities safe and comfortable for its students and staff. The majority of the 2015 GOB was used for upgrading the parking lots and lighting of Tucumcari Elementary School, upgrades to the floor and doors at Trojan Gym, and to upgrade the lighting at Tucumcari Middle School. The remainder will be used to replace Tucumcari Middle School roofs.

Even with the completion of these capital projects, there are significantly more capital needs at \$20,341,178, than there are available capital funds. Tucumcari Public Schools has spent the past few months developing their FMP plan, knowing that there would not be enough capital funds to address all of its priority projects. The district anticipates a 2019 GOB for approximately \$3,000,000 for capital projects, \$1,697,065 in SB-9 funds to address Life-Health-Safety-Security-ADA Code and maintenance issues, and a minimum of \$151,250 to address technology needs from PLT. This will provide TPS approximately \$4,848,315 to address its identified \$20,341,178 in facility needs. As these funds become available, TPS will use them and partner with PSCOC/PSFA on qualifying

3.3

Capital Plan

schools to begin addressing the district's most critical needs and the larger capital plan projects. Tucumcari Public Schools has focused on addressing facility and site system renewal projects at all of its school and focusing on one capital project at a time as funds are available. The District will continue this strategy and use the majority of its 2019 GOB funds to address the capital needs as identified in the above priorities list with emphasis on Tucumcari Middle School facility and site system renewal.

The district has not received any direct appropriations from the legislature since 2009; however, those funds are not guaranteed, are usually identified for a specific need and will be deducted from and future PSCOC award. With current economic conditions, it is unlikely that TPS will receive any direct appropriations. The district will continue to seek available funding from various sources.

The TPS community passed a SB-9 election in 2013 which was used to fund life-health-safety-security, general maintenance and preventive maintenance issues. In 2019 TPS will ask its community to support another SB-9 election to continue funding its Life-Health-Safety-Security-ADA Code, general maintenance and preventive maintenance issues.

Tucumcari Public Schools applies for and receives E-rate funding which is applied to technology needs.

Tucumcari Public Schools receives Payment in Lieu of Taxes (PLT) funding due to windmill farms that are located within district boundaries. The district receives approximately \$30,250 per year from PLT. These funds are not enough for capital projects.

Tucumcari Public Schools has not asked its local community to support HB-33 funds and does not anticipate asking for these funds during the life of this FMP.

3.3.3 CAPITAL PLAN

The following pages contain the TPS capital plan and the associated, detailed spreadsheet providing funding information on the projects listed in the capital plan developed to meet the needs of the district. The capital plan has been developed with the understanding that it is a living document and has flexibility. It is understood that the priorities recommended by the TPS FMP steering committee to the TPS School Board will be addressed as funding becomes available and will not necessarily be accomplished in the order listed. Other identified district needs may be addressed prior to addressing all of the recommended priorities. Due to the lack of GOB funds at this time, TPS did not established a firm schedule to accomplish its priorities and capital projects in the FMP.

Following the TPS capital plan is an associated spreadsheet with all identified needs sorted by facility then funding source. The following legend will aid in understanding the funding source categories:

Funding Source Legend:

The total 2019-2023 facilities needs have been broken down into eight project types and

corresponding funding sources. The eight project types and corresponding funding sources are:

BS-GOB: Building Systems anticipating GOB funding

BS-SB9: Building Systems anticipating SB-9 funding

LHSS-SB9: Life-Health-Safety-Security-Code projects anticipating SB-9 funding

LHSS-GOB: Life-Health-Safety-Security-Code projects anticipating GOB funding

MISC-GOB: Miscellaneous projects anticipating GOB funding

MISC-SB9: Miscellaneous projects anticipating SB-9 funding

PreMaint: Preventive Maintenance projects anticipating SB-9 funding

Tech: Technology projects anticipating e-rate, PLT and SB-9 funding

The table below provides a summary of these funding needs:

TPS Project Cost by Funding Source

| Project Type | Funding Source | Total Projects Cost | Percentage of Total |
|---|-------------------|------------------------|---------------------|
| Building Systems Upgrades | GOB | \$5,228,392 | 26% |
| Building Systems Upgrades | SB-9 | \$2,202,191 | 11% |
| Life/Health/Safety/Security/Code Issues | GOB | \$3,915,051 | 19% |
| Life/Health/Safety/Security/Code Issues | SB-9 | \$1,303,703 | 6% |
| Miscellaneous Projects | GOB | \$6,447,025 | 32% |
| Miscellaneous Projects | SB-9 | \$0 | 0% |
| Preventive Maintenance | SB-9 | \$1,093,565 | 5% |
| Technology | GOB & E-Rate | \$151,250 | 1% |
| DIS | STRICT TOTALS | \$20,341,178 | 100% |

Refer to the following pages for the Tucumcari Public Schools' Capital Plan.

| | | | | | | | | | | | State | | |
|--------------|----------|--------------------------------|-----------|--------------|------|---|-------|----------------|--------------------|---------|------------|---------|-------|
| | | | | | | | | | | | Funding | | |
| District | | | | | | | | Proposed State | | Percent | Assistance | | State |
| Priority | Category | Project | Plan Year | GO Bonds | HB33 | SB9 | Other | Share | Total Project Cost | Total | Priority | Share S | Share |
| T :50 | | | | 1 | | | | | | | | | |
| Tucumcari ES | | Luc tu tu to c | 2010.00 | 4 | | _ | T | T | l | | | 1001 | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$1,155,326 | | | | \$ - | \$ 1,155,326 | | | 100% | 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | | | \$ 409,721 | | \$ - | \$ 409,721 | 8% | | 100% | 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ - | | | \$ - | 0% | 1 | 100% | 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | | \$ - | | \$ - | 0% | | 34% | 66% |
| 2B | FacRen | Building Systems Upgrades-GOB | 2019 | \$938,233 | | | | \$ 1,821,276 | | | 3 | 34% | 66% |
| 2B | FacRen | Building Systems Upgrades-SB-9 | 2019 | | | \$ 206,063 | | \$ 400,005 | \$ 606,068 | | 3 | 34% | 66% |
| 3E | FacRen | Miscellaneous Projects - GOB | 2019 | \$130,000 | | | | \$ - | \$ 130,000 | 3% | | 100% | 0% |
| | FacRen | Miscellaneous Projects - SB-9 | | | | \$ - | | \$ - | \$ - | 0% | | 100% | 0% |
| | Total | | | \$ 2,223,559 | \$ - | \$ 615,784 | \$ - | \$ 2,221,280 | \$ 5,060,623 | 100% | | | |
| | | | • | | | | | | | | | • | |
| Tucumcari MS | | | | | | | | | | | | | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$2,647,866 | | | | \$ - | \$ 2,647,866 | | | 100% | 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | | | \$ 290,482 | | \$ - | \$ 290,482 | 6% | | 100% | 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ - | | | \$ - | 0% | 1 | 100% | 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | | \$ - | | \$ - | 0% | | 34% | 66% |
| 2A | FacRen | Building Systems Upgrades-GOB | 2019 | \$430,812 | | | | \$ 836,281 | \$ 1,267,093 | 25% | 2 | 34% | 66% |
| 2A | FacRen | Building Systems Upgrades-SB-9 | 2019 | | | \$ 367,517 | | \$ 713,415 | \$ 1,080,932 | 21% | 2 | 34% | 66% |
| 3B, 3F | FacRen | Miscellaneous Projects - GOB | 2019 | \$746,200 | | | | \$ - | \$ 746,200 | 15% | 2 | 100% | 0% |
| | FacRen | Miscellaneous Projects - SB-9 | | | | \$ - | | \$ - | \$ - | 0% | | 100% | 0% |
| | Total | | | \$ 3,824,878 | \$ - | \$ 657,999 | \$ - | \$ 1,549,696 | \$ 6,032,573 | 119% | | | |
| | | | | | | | | | | | | | |
| Tucumcari HS | | | | | | | | | | | | | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$111,860 | | | | \$ - | \$ 111,860 | 2% | | 100% | 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | | | \$ - | | \$ - | \$ - | 0% | | 100% | 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ - | | | \$ - | 0% | 1 | 100% | 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | | \$ - | | \$ - | 0% | | 34% | 66% |
| 2C, 3D | FacRen | Building Systems Upgrades-GOB | 2019 | \$293,689 | | | | \$ 570,102 | \$ 863,790 | 17% | 4 | 34% | 66% |
| 2C | FacRen | Building Systems Upgrades-SB-9 | 2019 | , | | \$ 175,165 | | \$ 340,026 | \$ 515,191 | 10% | 4 | 34% | 66% |
| 3A, 3G, 3H | FacRen | Miscellaneous Projects - GOB | 2019 | \$5,048,875 | | | | \$ - | \$ 5,048,875 | | | 100% | 0% |
| , , | FacRen | Miscellaneous Projects - SB-9 | | . , , - | | \$ - | | \$ - | \$ - | 0% | | 100% | 0% |
| | Total | | | \$ 5,454,423 | \$ - | \$ 175,165 | \$ - | \$ 910,128 | \$ 6,539,716 | 129% | | | |
| | | | | | | , | | , - | | | | | |

Tucumcari Public Schools • 5-Year Facilities Master Plan GS Architecture • 2019

| District Priority | Category | Project | Plan Year | GO Bonds | HB33 | | SB9 | Other | Pro | oposed State Share | Total | Project Cost | Percent Total | State Funding Assistance Priority | District State Share Share |
|----------------------|-------------------------|--------------------------------|-----------|---------------|------|--------------|-----------|-------|------|-----------------------|-------|--------------|------------------|--|-------------------------------|
| | v ES (Head Start) | 1 | | | | | | 7 | | ı | | | | | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$0 | | | | | \$ | - | \$ | - | 0% | | 100% 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | | | \$ | - | | \$ | - | \$ | - | 0% | | 100% 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ | - | | | | \$ | - | 0% | 1 | 100% 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | | | \$ - | | | \$ | - | 0% | | 34% 66% |
| 2D | FacRen | Building Systems Upgrades-GOB | 2019 | \$114,920 | | | | | \$ | 223,080 | \$ | 338,000 | 39% | | 34% 66% |
| | FacRen | Building Systems Upgrades-SB-9 | 2019 | | | \$ | - | | \$ | - | \$ | - | 0% | | 34% 66% |
| 3C | FacRen | Miscellaneous Projects-GOB | 2019 | \$521,950 | | | | | \$ | - | \$ | 521,950 | 61% | | 100% 0% |
| | FacRen | Miscellaneous Projects-SB-9 | | | | \$ | - | | \$ | - | \$ | - | 0% | | 100% 0% |
| | Total | | | \$ 636,870 | \$ | - \$ | - | \$ | - \$ | 223,080 | \$ | 859,950 | 100% | | |
| Tucumcari Dist | trictwide | | |] | | | | | | | | | _ | · | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$0 | | | | | \$ | - | \$ | - | 0% | | 100% 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | · | | \$ | 603,500 | | \$ | - | \$ | 603,500 | 33% | | 100% 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ | 151,250 | | | | \$ | 151,250 | 8% | 1 | 100% 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | | , | \$ - | | | \$ | - | 0% | | 34% 66% |
| | FacRen | Building Systems Upgrades-GOB | 2019 | \$0 | | | | | \$ | - | \$ | - | 0% | | 34% 66% |
| 2A, 2B, 2C | FacRen | Building Systems Upgrades-SB-9 | 2019 | · | | Ś | 371,812 | | \$ | 721,753 | | 1,093,565 | 59% | 2 | 34% 66% |
| , , - | FacRen | Miscellaneous Projects-GOB | 2019 | \$0 | | <u> </u> | | | Ś | - | Ś | - | 0% | | 100% 0% |
| | FacRen | Miscellaneous Projects-SB-9 | | | | \$ | - | | \$ | - | \$ | - | 0% | | 100% 0% |
| | Total | | | \$ - | \$ | - \$ | 1,126,562 | \$ | - \$ | 721,753 | \$ | 1,848,315 | 100% | | |
| Tucumcari Dist | trict Administration. S | Support and Districtwide | | 1 | | | | | | | | | | | |
| 1A | L/H/S | Life/Health/Safety Issues-GOB | 2019-23 | \$0 | | | | | \$ | - | \$ | _ | 0% | | 100% 0% |
| 1A | L/H/S | Life/Health/Safety Issues-SB-9 | 2019-23 | γo | | \$ | | | \$ | _ | \$ | | 0% | | 100% 0% |
| 1C | EdPro | Technology | 2019-23 | | | \$ | _ | | | | \$ | | 0% | 1 | 100% 0% |
| 1B | PreMaint | Preventive Maintenance | 2019-23 | | | , | | \$ - | | | \$ | _ | 0% | <u> </u> | 34% 66% |
| 10 | FacRen | Building Systems Upgrades-GOB | 2019 | \$0 | | | | 7 | \$ | _ | \$ | _ | 0% | | 34% 66% |
| | FacRen | Building Systems Upgrades-SB-9 | 2019 | 70 | | Ś | | | \$ | _ | \$ | _ | 0% | | 34% 66% |
| | FacRen | Miscellaneous Projects-GOB | 2019 | \$0 | | ۲ | | | \$ | _ | \$ | | 0% | | 100% 0% |
| | FacRen | Miscellaneous Projects-SB-9 | 2019 | 30 | | Ś | _ | | Ś | _ | \$ | | 0% | | 100% 0% |
| | Total | Wilsonian Court Tojecto OB 5 | | \$ - | \$ | - \$ | _ | \$ | - \$ | - | \$ | _ | 0% | | 10070 070 |
| | 10141 | | | Y | Ψ | Y | | Ψ | Υ. | | Υ | | 070 | | |
| | Grand Total: | SCHOOLS | | \$ 11,502,860 | \$ - | \$ | 1,448,948 | \$ - | \$ | 4,681,105 | \$ | 18,492,863 | | | |
| I | Grand Total: | DISTRICTWIDE | | \$ - | \$ - | \$ | - | \$ - | \$ | - | \$ | 1,848,315 | | | |
| I | Grand Total: | DISTRICT SUPPORT | | \$ - | \$ - | \$ | - | \$ - | \$ | - | \$ | - | | | |

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|----------|---------------------------|--------------|--------------------|--|------------|-------------------------------|--------------------|---------|--|-----|------------|--------------------|-------------------|---------------|-----------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | By | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | | | | | Бу | STSTEM | CATEGORT | Source | FACILITY NEEDS | QIT | UNII | COST/ONLI | WACC | CO31 | SUBTUTALS |
| | Life-Health-Safety-Sec | curity / Mai | intenance / Tec | nnology: | In: / | Ind-1-day and a | In v | DO 000 | D | | | #040 740 00 | 04 000 505 | \$4,000 F0F | |
| 1B | District Wide | | | | Dist. | Maintenance | PreVent | BS-SB9 | Preventive and Regular Maintenance needs | į | yr | \$218,713.00 | \$1,093,565 | \$1,093,565 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace ceiling tiles due to water damage in | (| sf | \$6.00 | \$0 | \$0 | |
| | Tucumcan ES | 2002 | Phase 2 | | DISL | Celling Finishes | Flevent | D3-3D9 | corridor next to gym | , |) 51 | φ0.00 | Φυ | Φ0 | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace water stained ceiling tiles | (| sf | \$6.00 | \$0 | \$0 | |
| | Tucumcan Lo | 1999 | Phase 4 | | Dist | Celling Finishes | i ievent | D0-0D9 | Replace water stained ceiling tiles Replace water stained ceiling tiles in classroom 22 | | 7 31 | ψ0.00 | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Ceiling Finishes | PreVent | BS-SB9 | and office next to it | (| sf | \$6.00 | \$0 | \$0 | |
| | Tuodinodii Eo | 2002 | Oldooroomo | | Dist | Coming 1 miorics | 1 10 VOIII | DO 000 | Repair damage due to water at top corner of North | | 7 01 | ψ0.00 | ΨΟ | ΨΟ | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Ceiling Finishes | PreVent | BS-SB9 | entrance | (| sf | \$6.00 | \$0 | \$0 | |
| | | | | Special | 1 | | | | | | 1 | 40.00 | 7.0 | 7- | |
| | | | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Office | Dist | Exterior Doors | PreVent | BS-SB9 | Repair door frame separation | (| ea | \$2,500.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Exterior Walls | PreVent | BS-SB9 | Repair wall cracks in north wall of gym | (| ea 💮 | \$2,500.00 | \$0 | \$0 | |
| | | | | | | | | | , | | | | · | · | |
| | Tucumcari ES | 2006 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT in Special Ed classroom 24 | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | Replace cracked VCT at the entrance of the | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 22 | Dist | Floor Finishes | PreVent | BS-SB9 | classroom | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace damaged VCT in admin section | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair heavy damage in VCT outside of restrooms | | sf | | \$0 | \$0 | |
| | | | Phase 1 | | | | | | Repair cracked VCT in classroom 9 and in corridor | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | outside classroom | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | Repair VCT separation in classroom 14 and in | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | Floor Finishes | PreVent | BS-SB9 | corridor outside the classroom | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Floor Finishes | PreVent | BS-SB9 | Repair / replace VCT at the entrance of Gym | | sf | | \$0 | \$0 | |
| | | | Phase 2 | | . | | 5 | | | | | | | • | |
| | Tucumcari ES | 1999 | Cafeteria | 1.9 | Dist | Floor Finishes | PreVent | BS-SB9 | Repair / replace VCT at west entrance of cafeteria | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT at the entrance of library | | sf sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace cracked VCT in corridor next to gym | | Sī | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace all VCT in south corridor. VCT is bubbling | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace / repair cracked VCT in commons area | | sf | | \$0 \$0 | \$0 \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Floor Finishes | PreVent | BS-SB9 | Replace / repair cracked VCT in commons area Replace / repair damaged VCT in storage room | | sf | | \$0 \$0 | \$0 \$0 | |
| | Tucumcan Lo | 2000 | Phase 1 | | Dist | 1 loor 1 inisites | i ievent | D0-0D9 | Correct settlement issues of slab between PreK- | | 31 | | ΨΟ | ΨΟ | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | 2nd grade building and Gym | | ef | | \$0 | \$0 | |
| | Tuodinodii 20 | 1000 | Ciacordonio | | Dist | | 1 TO VOITE | DO 000 | Address movement in expansion joints in north and | | OI . | | ΨΟ | ΨΟ | |
| | | | | | | | | | west walls of the gym; Assess settlement in wall | | | | | | |
| | | | | | | | | | between gym and the PreK-2nd grade building; | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | Gymnasium | Dist | Foundation/Slab/Structure | PreVent | BS-SB9 | walkway has dropped 2 to 3 inches | | ea | | \$0 | \$0 | |
| | | | Phase 2 | | | | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | HVAC | PreVent | BS-SB9 | Repair / replace rusted radiators in restrooms | | ea | | \$0 | \$0 | |
| | | | PreK-2nd Grade | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Institutional Equipment | PreVent | BS-SB9 | Repair plastic laminate in Lounge | | ea | | \$0 | \$0 | |
| | | | PreK-2nd Grade | | | | | | | | | | | | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Interior Doors | PreVent | BS-SB9 | Correct door in book room. Door binds in frame. | | ea | | \$0 | \$0 | |
| | | | Phase 2 | | <u>_</u> . | <u> </u> | | | | | | | | | |
| | Tucumcari ES | 1999 | Classrooms | | Dist | Interior Doors and Partitions | PreVent | BS-SB9 | Replace rusted metal partition in boys restrooms | | ea | | \$0 | \$0 | |
| | T | 4000 | PreK-2nd Grade | 1 | . | Lataria a NATA | . | DO 05 - | Description description in the state of | | 1. | | | * - | |
| | Tucumcari ES | 1998 | Bldg | <u> </u> | Dist | Interior Walls | PreVent | BS-SB9 | Repair water damage in electrical room | | sf | \$1.00 | \$0 | \$0 | |
| | T | 4000 | Phase 2 | Olmor 40 | D:-4 | listaria s Malla | Due) / s = t | DC CDC | Denois demons on Foot well of the electric | | . . | | 6 0 | 40 | |
| | Tucumcari ES | 1999 | Classrooms | Clrm 16 | Dist | Interior Walls | PreVent | BS-SB9 | Repair damage on East wall of the classroom | | sf | | \$0 | \$0 | |
| | Tuoumos: CC | 4000 | Phase 1 | | Diet | Interior Wells | Dro\/ont | DC CDC | Repair cracked walls in boys and girls restrooms, | | of | | ф- | # 0 | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | and in room behind restrooms Correct water damage and movement in walls due | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phone 4 | | Dist | Interior Walls | Pro\/ont | BS-SB9 | to water infiltration in corridor next to gym | | sf | | ¢Ω | \$0 | |
| | Tucumcari ES Tucumcari ES | 2002 | Phase 4 Phase 4 | Gymnasium | | Interior Walls | PreVent PreVent | BS-SB9 | Repair split face cracking in north wall of gym | | st sf | | \$0 \$0 | \$0 \$0 | |
| | i ucumcall E3 | 2002 | Phase 4 | Gymnasium | ופוח | intenu vvalis | rievent | DO-9D9 | nepaii spiii iace ciacking in north wall of gym | | 21 | | \$0 | Φ0 | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Interior Walls | PreVent | BS-SB9 | Repair wall cracks in classrooms | | sf | | \$0 | \$0 | |
| | i acamean LO | 2002 | Ciassioullis | 1 | اداط | II ROHOL YYAHO | I ICACIII | מחס סח | rropaii waii oraono iii olaooroonio | | ٥ı | | φυ | φυ | |

| | 1 | | • | T | • | | • | 1 | | | | | • | • | |
|----------|-----------------|-------|-----------------------|--------------|------------|---------------------------------|------------|---------|--|-----|------|-------------|------------|---------------|-------------|
| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | | | PreK-2nd Grade | | | | | | Investigate and address standing water in corridor | | | | | | |
| | Tucumcari ES | 1998 | Bldg | | Dist | Plumbing | PreVent | BS-SB9 | by administration | C | sf | \$0.00 | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Gym | | Dist | Roof | PreVent | BS-SB9 | Correct roof leaks | | sf | | \$0 | \$0 | |
| | =. | | Phase 1 | | | | | | | | | | | • | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Roof | PreVent | BS-SB9 | Repair water filtration in skylites | | sf | | \$0 | \$0 | |
| | | 4000 | Phase 1 | | D | | D 14 4 | DO 000 | | | | | | | |
| | Tucumcari ES | 1998 | Classrooms | Lounge | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | | | | | |
| | T | 4000 | Phase 2 | | D:-1 | D f | Duraktoria | DO 000 | Denote as West Lands | | _ (| | # 0 | r.o. | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Roof | PreVent | BS-SB9 | Repair ceiling leaks | | Sī | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Dhasa 2 | | Diet | Doof | Due)/eset | DC CDO | Correct demand due to water filtration in alculitae | | -4 | | ¢o. | \$0 | |
| | rucumcan ES | 2000 | Phase 3 | | Dist | Roof | PreVent | BS-SB9 | Correct damage due to water filtration in skylites | | Sī | | \$0 | \$0 | |
| | Tucumcari ES | 1999 | Phase 2 Classrooms | Clrm 17 | Dist | Wall Finishes | PreVent | BS-SB9 | Repair window sill in classroom | | of | | \$0 | \$0 | |
| | Tucumcan ES | 1999 | Phase 1 | Cillii 17 | DIST | Wall Fillisties | rieveiii | D3-3D9 | Repair window siii in classiooni | | 51 | | Φυ | Φυ | |
| | Tucumcari ES | 1998 | Classrooms | | Dist | Wall Finishes | PreVent | BS-SB9 | Correct loose tile on planter in commons area | | of | | \$0 | \$0 | |
| | rucumcan E3 | 1990 | Classiconis | Special | Dist | waii i iiisiies | Fieveni | DO-3D9 | Correct loose tile on planter in commons area | | 51 | | φυ | φυ | |
| 1 | | | | Programs | | | | | | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Wall Finishes | PreVent | BS-SB9 | Repair crack at window and cracked walls | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2002 | Phase 4 | Library | Dist | Wall Finishes | PreVent | BS-SB9 | Repair wall damage in library | | sf | | \$0 | \$0 \$0 | |
| | r addition LO | 2002 | Phase 2 | Library | טוטנ | TYAN I IIIIOIIOO | i iovoiit | 20 009 | Tropan wan damage in library | | JI . | | φυ | φυ | |
| | Tucumcari ES | 1999 | Cafeteria | | Dist | Wall Finishes | PreVent | BS-SB9 | Repair base of wall in custodian room | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Wall Finishes | | BS-SB9 | Repair wall damage due to water in restrooms | | sf | | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 and 4 | | Dist | Z-Walkways | PreVent | BS-SB9 | Recaulk perimeter of building | | If | \$2.00 | \$0 | \$0 | |
| | Tucumcari HS | 1946 | Rattler Gym | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair hard ceiling in women's locker restroom | | " | \$1.00 | \$0 | \$0 | |
| | Tucumcari HS | 10.10 | GreenHouse | | Dist | Other Equipment | PreVent | BS-SB9 | Install netting and screens on cooling side | (| ea | \$0.00 | \$0 | \$0 | |
| | Tucumcari MS | 1980 | Trojan Gym | | Dist | Plumbing | FacRen | BS-SB9 | Repair showers in men's lockers | | ea | \$12,500.00 | \$0 | \$0 | |
| | T dodinodit Wie | 1000 | rrojan Cym | | 2.00 | T Tarribing | racracii | 20 020 | Tropan onewore in mone tookere | | ou | ψ12,000.00 | ΨΟ | ΨΟ | |
| | Tucumcari MS | 1970 | Original Building | Classroom 9 | Dist | Plumbing | FacRen | BS-SB9 | Replace sink and casework in classroom 9 | | ea | | \$0 | \$0 | |
| | | 1010 | | | 1 | - remaining | | | | | | - | 7. | ** | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace stained ceiling tiles in classroom 5 | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Replace stained ceiling tiles throughout building | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair hole in ceiling in boys restroom | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | Dist | Ceiling Finishes | PreVent | BS-SB9 | Repair cracked ceiling at girls restroom | | sf | | \$0 | \$0 | |
| | | | | | | • | | | Repair frame of exterior door in wood shop; frame | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Exterior Doors | PreVent | BS-SB9 | is rusted | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | Room 1 | Dist | Floor Finishes | PreVent | BS-SB9 | Repair interior water damage (6x6 AVT) | | sf | | \$0 | \$0 | |
| | | | | | | | | | Replace / repair cracked VCT in classrooms and | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Floor Finishes | PreVent | BS-SB9 | corridors | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair / replace cracked VCT in corridor outside | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | boys restrooms | | sf | | \$0 | \$0 | |
| | | | | | | | | | Repair / replace cracked VCT in the lounge's | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | PreVent | BS-SB9 | restroom | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| 1 | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | PreVent | BS-SB9 | Replace plastic laminate in girls restroom | | ea | | \$0 | \$0 | |
| | | | - | | | | | | Repair cracked walls in classroom 9 and outside | | | | 7.0 | ** | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Interior Walls | PreVent | BS-SB9 | room 1 | | sf | | \$0 | \$0 | |
| | | | Ĭ | | | | | | Repair cracked walls in classrooms, wood shop | | | | · | · I | |
| | Tucumcari MS | 1996 | Addition | | Dist | Interior Walls | PreVent | BS-SB9 | and lounge | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | | Wall Finishes | PreVent | BS-SB9 | Repair wall due to water damage in classroom 9 | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | Classroom 16 | Dist | Wall Finishes | PreVent | BS-SB9 | Repair window sill in classroom 16 | | sf | | \$0 | \$0 | \$1,093,565 |
| | | | | | | | | | Install ramp in steep hill to access west playground | | | | | | |
| | Tucumcari ES | 1998 | Site | | Dist | Z-Walkways | LHSS | L-GOB | and basketball courts | | sf | | \$0 | \$0 | \$0 |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| 1A | District Wide | | | | Dist | Code | LHSS | L-SB9 | Address life-health-safety-security issues | 5 | yr | \$120,700 | \$603,500 | \$603,500 | |
| | | | | | | Life-Health-Safety-Security-ADA | | | | | | | | | |
| | District Wide | | | | Dist | Code | LHSS | L-SB9 | Install vehicle barracades at front of each school | | | | | | |

| ISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|---------|--------------------------|-------|-------------------|------|------------|----------------------------------|----------|---------|---|-----|------|-------------|-------------|---------------|----------|
| RIORITY | FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTAL |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | | LHSS | L-SB9 | Replace door lock in janitor's room | | ea | | \$0 | \$0 | |
| | | | | | | Life-Health-Safety-Security-ADA- | | | | | | | | | |
| | Tucumcari ES | | | | Dist | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | | | | | | Life-Health-Safety-Security-ADA- | | | | | | | | | |
| ľ | Tucumcari ES | | | | Dist | Code | LHSS | L-SB9 | Install security cameras: inside and outside | | | | | | |
| | | | | | | | | | Correct ponding in courtyard between gym and the | | | | | | |
| | Tucumcari ES | 2002 | Phase 4 | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | PreK-2nd grade building | | ea | | \$0 | \$0 | |
| | | | | | | Life-Health-Safety-Security-ADA- | | | | | | | | | |
| | Tucumcari HS | | | | Dist | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Other Equipment | LHSS | L-SB9 | Replace stage curtain | | ea | \$1.00 | \$0 | \$0 | |
| | | | | | | | | | Install fence between Rattler Gym and Football | | | | | | |
| | Tucumcari HS | 1946 | Site | | Dist | Z-Fencing | LHSS | L-SB9 | Field | | sf | \$1.00 | \$0 | \$0 | |
| | Tucumcari HS | 1946 | Site | | Dist | | LHSS | L-SB9 | Install ADA ramp to practice field | C |) sf | \$1.00 | \$0 | \$0 | |
| | Tucumcari MS | 1996 | Addition | | | | LHSS | L-SB9 | Replace ADA signage | | ea | | \$0 | \$0 | |
| , | Tucumcari MS | 1996 | Addition | | Dist | Institutional Equipment | LHSS | L-SB9 | Repair locker frame | | sf | | \$0 | \$0 | |
| | | | | | | | | | | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Interior Doors | LHSS | L-SB9 | Upgrade door in admin section; not ADA hardware | | ea | | \$0 | \$0 | |
| | | | | | | Interior Doors, Partitions, | | | Repair ladder to roof in boiler room. Ladder is | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | | LHSS | L-SB9 | detached from wall | | ea | | \$0 | \$0 | |
| | | | | | | Life-Health-Safety-Security-ADA- | | | | | | | | | |
| | Tucumcari MS | | | | Dist | Code | LHSS | L-SB9 | Create secure entry | | | | | | |
| | | | | | | | | | Correct drainage in area between Cafeteria and | | | | | | |
| ľ | Tucumcari MS | 1970 | Site | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | Rattler Gym | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | Correct ponding next to north courtyard | | ea | | \$0 | \$0 | |
| | | | | | | | | | Correct drainage at main entry; water drains off | | | | | | |
| | Tucumcari MS | 1996 | Addition | | Dist | Z-Landscaping / Drainage | LHSS | L-SB9 | roof onto entry slab | | ea | | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Walkways | LHSS | L-SB9 | Repair sidewalk by Cafeteria and Gym | | sf | | \$0 | \$0 | |
| | Tucumcari MS | 1970 | Site | | Dist | Z-Walkways | LHSS | L-SB9 | Correct tripping hazard at entry sidewalk | | sf | | \$0 | \$0 | \$60 |
| | | | | | | | | | Upgrade IT equipment, software, training district | | | | | | |
| 1C | District Wide | | | | Dist | Technology | Tech | Tech | wide | 5 | yr | \$30,250.00 | \$151,250 | \$151,250 | |
| | | | Phase 1 | | | | | | | | | | | | |
| ŀ | Tucumcari ES | 1998 | Classrooms | | Dist | Air/Ventilation Equipment | Tech | Tech | Install split system for cooling in server room | C | ea | \$7,500.00 | \$0 | \$0 | |
| | Tucumcari ES | 2000 | Phase 3 | | Dist | Air/Ventilation Equipment | Tech | Tech | Install split system for cooling in IT room | C | ea 💮 | \$7,500.00 | \$0 | \$0 | |
| i | | | Ag/Welding | | | | | | | | | | · | | |
| ŀ | Tucumcari HS | 1990 | Shop | | FAD | Technology | Tech | Tech | | | ea | \$1,187.00 | \$0 | \$0 | |
| i e | Tucumcari HS | 1946 | Rattler Gym | | FAD | Technology | Tech | Tech | | | ea | \$4,772.00 | \$0 | \$0 | |
| ŀ | Tucumcari HS | 1985 | Auditorium | | FAD | Technology | Tech | Tech | | | ea | \$3,702.00 | \$0 | \$0 | \$15 |
| | ife-Health-Safety-Securi | | | | | | | • | - | | | | \$1,848,315 | \$1.848.315 | \$1,848 |

| ty 2 Building / Site Syste | m Upgrades | s: | | | | | | | | | |
|----------------------------|------------|----------------|------|--------------------|--------|--------|---|-----------|--------------|-------------|-------------|
| Mountain View ES | | | Dist | Roof | FacRen | BS-GOB | Replace Roof | 7,000 sf | \$20.00 | \$140,000 | \$182,000 |
| Mountain View ES | | | Dist | Z-Parking Lots | FacRen | BS-GOB | Resurface parking lot | 30,000 sf | \$4.00 | \$120,000 | \$156,000 |
| | | PreK-2nd Grade | | | | | | | | | |
| Tucumcari ES | 1998 | Bldg | FAD | HVAC | AdqStd | BS-GOB | | 1 FAD | \$82,559.00 | \$82,559 | \$107,327 |
| Tucumcari ES | 2006 | Kind Addition | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 2,367 ea | \$20.00 | \$47,340 | \$61,542 |
| | | PreK-2nd Grade | | | | | | | | | |
| Tucumcari ES | 1998 | Bldg | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 22,339 ea | \$20.00 | \$446,780 | \$580,814 |
| | | Phase 2 | | | | | | | | | |
| Tucumcari ES | 1999 | Classrooms | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning in all classroom | 77,301 ea | \$20.00 | \$1,546,020 | \$2,009,826 |
| | | Rhodes Field | | | | | | | | | |
| Tucumcari HS | 1970 | House | Dist | HVAC | AdqStd | BS-GOB | Install Air Conditioning | 12,713 sf | \$20.00 | \$254,260 | \$330,538 |
| Tucumcari HS | 1985 | Auditorium | Dist | Roof | FacRen | BS-GOB | Replace auditorium flat roofs | 6,000 sf | \$20.00 | \$120,000 | \$156,000 |
| Tucumcari HS | 1962 | Main Bldg | FAD | Water Distribution | FacRen | BS-GOB | Bldg replaced in 2006 | 0 FAD | \$209,879.00 | \$0 | \$0 |
| Tucumcari HS | 1946 | Rattler Gym | FAD | Water distribution | FacRen | BS-GOB | | 1 FAD | \$91,331.00 | \$91,331 | \$118,730 |
| | | Rhodes Field | | | | | | | | | |
| Tucumcari HS | 1970 | House | FAD | Water Distribution | FacRen | BS-GOB | | 1 FAD | \$24,397.00 | \$24,397 | \$31,716 |
| Tucumcari HS | 1985 | Auditorium | FAD | Water Distribution | FacRen | BS-GOB | | 1 FAD | \$70,848.00 | \$70,848 | \$92,102 |

| DISTRICT | | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|----------|---------------------------|--------------|-----------------------------|-----------|-------------|----------------------------|------------------|------------------|--|--------|-----------|----------------|-----------------|----------------------|-------------|
| PRIORITY | FACILITY NAME | Year | AREA | ROOM | Bv | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| | Tucumcari HS | 1946 | Site | ROOM | , | Z-Parking Lots | FacRen | BS-GOB | Beyond Expected Life Portion | _ | FAD | \$103,618.00 | \$103,618 | \$134,703 | COBTOTALO |
| | Tucumcan no | 1940 | Site | | IAD | 2-1 arking Lots | raciteri | D3-00B | Beyond Expected Life: District installed all new | | ו אט | ψ103,010.00 | Ψ103,010 | Ψ134,703 | |
| | | | | | | | | | heating units in 2002. District needs air | | | | | | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | HVAC | AdgStd | BS-GOB | conditioning. Installed 2018 | 0 | FAD | \$1,063,074.00 | \$0 | \$0 | |
| | | | onginai ziag | | | | 7.0000 | 20 002 | Units were in good condition \$197,007. Install air | | 1.7.5 | ψ.,σσσ,σσσ | ΨÜ | Ψ | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | HVAC | AdqStd | BS-GOB | conditioning in gym | 15,800 | sf | \$20.00 | \$316,000 | \$410,800 | |
| | Tucumcari MS | 1972 | Cafeteria | | | HVAC | AdqStd | BS-GOB | Install air conditioning in cafeteria | 15,800 | | \$20.00 | \$316,000 | \$410,800 | |
| | Tucumcari MS | 1996 | Clrm Addition | | Dist | HVAC | AdqStd | BS-GOB | Install air conditioning. Completed 2018 | | sf | , | \$0 | \$0 | |
| | | | | | | | i . | | | | | | · | · | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | HVAC Controls | AdqStd | BS-GOB | System was in use. Vent covers are old and worn | 0 | FAD | \$148,470.00 | \$0 | \$0 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | HVAC Controls | AdqStd | BS-GOB | System was in good condition. | 1 | FAD | \$27,514.00 | \$27,514 | \$35,768 | |
| | Tucumcari MS | 1970 | Original Bldg | | FAD | Roof | FacRen | BS-GOB | Beyond Expected Life: Replaced 2018 | | FAD | \$242,907.00 | \$0 | \$0 | |
| | Tucumcari MS | 1972 | Cafeteria | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | 1 | FAD | \$34,944.00 | \$34,944 | \$45,427 | |
| | Tucumcari MS | 1970 | Original Bldg | | | Water Distribution | FacRen | BS-GOB | In good condition | | FAD | \$97,288.00 | \$97,288 | \$126,474 | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Water Distribution | FacRen | BS-GOB | In good condition | 1 | FAD | \$2,941.00 | \$2,941 | \$3,823 | |
| | | | | | | | | | Beyond Expected Life \$197,512: Repave west | | | | | | |
| | Tucumcari MS | 1970 | Site | | | Z-Parking Lots | FacRen | BS-GOB | parking lot | 30,000 | | \$6.00 | \$180,000 | \$234,000 | \$5,228,392 |
| | Tucumcari ES | 2006 | Kind Addition | 23 and 24 | FAD | Ceiling Finishes | FacRen | BS-SB9 | In rooms 23 and 24 | 1 | FAD | \$5,006.00 | \$5,006 | \$6,508 | |
| | | | 3rd and 4th | | | | | | Doors opened and closed properly in this asset | | | | | | |
| | Tucumcari ES | 2000 | Grade Bldg | | | Exterior Doors | FacRen | BS-SB9 | \$41,937: Replace all exterior doors and frames | | FAD | \$41,937.00 | \$41,937 | \$54,518 | |
| | Tucumcari ES | 1999 | Campus wide | | Dist | Exterior Doors | FacRen | BS-SB9 | Replace all exterior doors and frames | 50 | ea | \$5,000.00 | \$250,000 | \$325,000 | |
| | | | | Library & | | | | | | | | | | | |
| | | | | Special | | | | | Upgrade carpet in library and Special Programs | | | 4 | | | |
| | Tucumcari ES | 2002 | Phase 4 | Programs | Dist | Floor Finishes | FacRen | BS-SB9 | Offices | 5,427 | sf | \$6.00 | \$32,562 | \$42,331 | |
| | | | Phase 4 | | | | | | | | | | . | . = | |
| | Tucumcari ES | 2002 | Classrooms | | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in classrooms and computer lab | 2,500 | st | \$6.00 | \$15,000 | \$19,500 | |
| | | | 5 | | | | | | | | | | | | |
| | | | Phase 1 | | | E. E | | | Upgrade carpet in classrooms, computer lab and | | | | . | * 4 4 0 = 0 | |
| | Tucumcari ES | 1998 | Classrooms | | | Floor Finishes | FacRen | BS-SB9 | offices. Carpet is in good condition in classroom 8 | 5,750 | | \$6.00 | \$34,500 | \$44,850 | |
| | Tucumcari ES | 2006 | Kind Addition | | FAD | Floor Finishes | FacRen | BS-SB9 | Tiles and carpet were in good condition | 1 | FAD | \$12,201.00 | \$12,201 | \$15,861 | |
| | T | 1998 | PreK-2nd Grade | | | Deef | ГааВаа | BS-SB9 | TPO and metal pitched roof. Roof was in good condition | _ | FAD | \$400,007,00 | ¢ο | ¢o. | |
| | Tucumcari ES Tucumcari ES | 2002 | Bldg Phase 4 | | FAD Dist | Roof | FacRen | BS-SB9 | | | | \$162,087.00 | \$0 \$75,000 | \$97,500 | |
| | | | | | | Z-Landscaping / Drainage | FacRen | | Replace sprinkler system: valves and pipes | | ea FAD | \$75,000.00 | | \$97,500 | |
| | Tucumcari HS | 1962 1946 | Main Bldg | | | Drain, Waste and Vent | FacRen FacRen | BS-SB9 BS-SB9 | Bldg replaced in 2006 | | FAD | \$209,879.00 | \$0 \$91,331 | 7.5 | |
| | Tucumcari HS | 1946 | Rattler Gym Rhodes Field | | FAD | Drain, Waste and Vent | racken | DO-2D9 | | l | FAD | \$91,331.00 | Ф 91,331 | \$118,730 | |
| | Tucumcari HS | 1970 | House | | FAD | Drain, Waste and Vent | FacRen | BS-SB9 | | 1 | FAD | \$24,397.00 | \$24,397 | \$31,716 | |
| | Tucumcari HS | 1985 | Auditorium | | | Drain, Waste and Vent | FacRen | BS-SB9 | | | FAD | \$70,848.00 | \$70,848 | \$92,102 | |
| | Tucumcari HS | 1985 | Auditorium | | | Exhaust Ventilation System | FacRen | BS-SB9 | | | FAD | \$40,731.00 | \$40,731 | \$52,950 | |
| — | Tucumcari HS | 1985 | Auditorium | | | Exterior Doors | FacRen | BS-SB9 | | | FAD | \$40,731.00 | \$40,731 | \$53,296 | |
| | Tucumcari HS | 1985 | Auditorium | | | Exterior Windows | FacRen | BS-SB9 | | | FAD | \$40,997.00 | \$40,997 | \$53,296 | |
| | Tucumcari HS | 1985 | Auditorium | | | Institutional Equipment | FacRen | BS-SB9 | Install presentation system | | ea | \$50,000.00 | \$50,000 | \$65,000 | |
| | Tucumcari HS | 1985 | Auditorium | | | Institutional Equipment | FacRen | BS-SB9 | Update sound system: Completed | | ea | \$1.00 | \$0,000 | \$0 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Lighting / Branch Circuits | FacRen | BS-SB9 | Update stage lighting | 1,000 | | \$8.00 | \$8,000 | \$10,400 | |
| | Tucumcan no | 1903 | Additorium | | Dist | Lighting / Branch Olicula | raciteri | DO-0D9 | Update electrical on stage to provide more power | 1,000 | 31 | ψο.οο | ψ0,000 | ψ10,400 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Main Power/Emergency | FacRen | BS-SB9 | outlets | 1,000 | ef | \$8.00 | \$8,000 | \$10,400 | |
| | Tucumcan no | 1903 | Additorium | | Dist | Main i Ower/Emergency | raciteri | DO-0D9 | Replace missing sink in backstage women's | 1,000 | 31 | ψο.οο | ψ0,000 | ψ10, 4 00 | |
| | Tucumcari HS | 1985 | Auditorium | | Dist | Plumbing | FacRen | BS-SB9 | restroom | 1 | ea | \$5,000.00 | \$5,000 | \$6,500 | |
| | Tucumcari HS | 1990 | GreenHouse | | | Roof | FacRen | BS-SB9 | Replace green house roof | 800 | | \$20.00 | \$16,000 | \$20,800 | |
| | | 1000 | 0.00.1110000 | | 2.00 | | 1 401.011 | 10000 | Tropiado groom nodo roor | 000 | 1 | Ψ20.00 | ψ10,000 | Ψ20,000 | |
| | | | | | | | | 1 | Replace ceiling tiles throughout building in | | | | | | |
| | Tucumcari MS | 1970 | Original Building | | Dist | Ceiling Finishes | FacRen | BS-SB9 | classrooms. Ceiling Tiles replaced in corridor 2002. | 14,759 | sf | \$6.00 | \$88,554 | \$115,120 | |
| | . addition into | 1370 | original ballaring | | 5.00 | | I dorton | 50 000 | Tiles in locker rooms, offices and store rooms were | 17,700 | 31 | Ψ0.00 | ψ00,004 | ψ110,120 | |
| | | | | | | | | | in good condition. Ceiling over the gym was in | | | | | | |
| | Tucumcari MS | 1980 | Trojan Gym | | FAD | Ceiling Finishes | FacRen | BS-SB9 | good condition. | 1 | FAD | \$53,594.00 | \$53,594 | \$69,672 | |
| | uiiiouii ivio | .500 | i i ojani Oyini | | | | 1 401 (011 | 20 000 | 500 00 10 10 11 11 11 11 11 11 11 11 11 1 | | | Ψ00,004.00 | Ψ00,00Τ | Ψ00,012 | |

| Tocumcart MS | DISTRICT | FACILITY NAME | AREA- Year | AREA | ROOM | Identified Bv | SYSTEM | CATEGORY | Funding Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | TOTAL PROJECT COST | SUBTOTALS |
|--|----------|---------------|---------------|-------------------|------|------------------|----------------------------|----------|-------------------|--|--------|------|--------------------|-----------------------|-----------------------|-------------|
| Trustment MS | | | | | itoo | , | | | | | | | | | | 0021017120 |
| Four-most HS 1987 Topin Grap AD Oran Works and Yest Section Bit Section Four-most Act Four-m | | | | | | | , | | | | | | | ' ' | | |
| Tearners 148 1970 Organ Religio FAID East of Dates FAIR 85.550 April According to the Author 1 FAID 558.6650 535.567 | | | | | | | , | | | | | | | | | |
| Fusion Facility | | | 1000 | | | | | | 1 | Exterior doors are original: New exterior door at | | | + 10,000100 | - + 10,000 | 400,000 | |
| Trummort MS | | | | | | | | | | | | | | | | |
| Tourners IVS | | | | | | | | | | | | | | | | |
| Textment MS | | Tucumcari MS | 1970 | Original Bldg | | FAD | Exterior Doors | FacRen | BS-SB9 | | 1 | FAD | \$56,605.00 | \$56,605 | \$73,587 | |
| Tournant MS 1990 Triser Orn FAD Exercit Doors FarRan 85-898 March 1970 251,780 451,7 | | | | | | | | | | | | | , , | · · | . , | |
| Tournest MS | | Tucumcari MS | 1980 | Trojan Gym | | FAD | Exterior Doors | FacRen | BS-SB9 | | 1 | FAD | \$25,176.00 | \$25,176 | \$32,729 | |
| Fourment MS | | | | | | | | | | Front doors are original; all doors in kitchen new, | | | | | | |
| Tourvail MS | | Tucumcari MS | 1972 | Cafeteria | | FAD | Exterior Doors | FacRen | BS-SB9 | except for 2 exit doors | 0 | FAD | \$20,220.00 | \$0 | \$0 | |
| Tourners MS | | Tucumcari MS | 1972 | Cafeteria | | FAD | Exterior Windows | FacRen | BS-SB9 | Replace all windows | 1 | FAD | \$20,220.00 | \$20,220 | \$26,286 | |
| Tournear MS | | | | | | | | | | The old portion would be locker rooms floors. | | | | | | |
| Tucument MS | | | | | | | | | | Floors were in good condition. Wood floor replaced | | | | | | |
| Trummari MS | | Tucumcari MS | 1980 | Trojan Gym | | FAD | Floor Finishes | FacRen | BS-SB9 | 2011. \$62,700 | 2,500 | sf | \$6.00 | \$15,000 | \$19,500 | |
| Trummari MS | | | | | | | | | | | | | | | | |
| Trumman MS | | | | | | | | | | Beyond Expected Life: upgrade carpet in middle | | | | | | |
| Tournean MS | | Tucumcari MS | 1970 | Original Building | | Dist | Floor Finishes | FacRen | BS-SB9 | corridors, reception area and classroom 14 | 2,750 | sf | \$6.00 | \$16,500 | \$21,450 | |
| Tournean MS | | | | | | | | | | | | | | | | |
| Tucumcan HS | | Tucumcari MS | 1970 | Original Building | | Dist | Floor Finishes | FacRen | BS-SB9 | Replace asbestos floor tile in 4 north classrooms | 3,771 | sf | \$20.00 | \$75,420 | \$98,046 | |
| Tucumcan HS | | | | | | | | | | | | | | • | | |
| Tucumcari MS 1990 Trojan Gym FAD Institutional Equipment FAD Institutional Face FAD | | Tucumcari MS | 1996 | Addition | | Dist | Floor Finishes | FacRen | BS-SB9 | Upgrade carpet in classrooms and computer lab | 15,000 | sf | \$6.00 | \$90,000 | \$117,000 | |
| Tucumcant MS | | Tucumcari MS | 1970 | Original Bldg | | FAD | Institutional Equipment | FacRen | BS-SB9 | | 1 | FAD | \$67,230.00 | \$67,230 | \$87,399 | |
| Tucumcart MS | | Tucumcari MS | 1980 | Trojan Gym | | | | FacRen | | | 1 | FAD | | | \$38,871 | |
| Tucumcan MS | | Tucumcari MS | 1972 | | | FAD | Lighting / Branch Circuits | | | | 1 | FAD | | | \$90,496 | |
| Tucumcari ES 1999 | | Tucumcari MS | 1970 | Original Bldg | | FAD | | FacRen | | Beyond Expected Life: Updated to LED in 2016 | 0 | FAD | | | \$0 | |
| Tucumcari ES 1999 | | Tucumcari MS | 1980 | Trojan Gym | | | | | | | 15,800 | sf | | \$47,400 | \$61,620 | \$2,202,191 |
| Tucumcari ES 2002 Gym FAD Communications / Security LHSS LGOB System was in good condition 0 FAD \$4,221,00 \$50 \$50 | | | | | | | | | | | , | | · · | | | , , , , |
| Tucumcari ES 2002 Sym FAD Communications / Security LHSS L-GOB System was in good condition 0 FAD \$4,221,00 \$0 \$0 \$0 \$0 \$0 \$0 \$0 | | Tucumcari ES | 1999 | Library/SPED | | FAD | Communications / Security | LHSS | L-GOB | System was in good working condition | 0 | FAD | \$29,762.00 | \$0 | \$0 | |
| Tucumcari ES 1998 Classrooms Dist Fire Sprinklers LHSS LGOB Building is not sprinklered 22,319 ft \$10,00 \$223,190 \$290,147 \$10,000 \$224,190 \$290,147 \$10,000 \$200,000 \$10,0035 \$130,046 \$10,000 \$10,0035 \$130,046 \$10,000 \$10,0005 \$10,000 | | Tucumcari ES | 2002 | Gym | | FAD | Communications / Security | | L-GOB | System was in good condition | 0 | FAD | \$4,221.00 | \$0 | \$0 | |
| Tourwari ES 1999 | | | | Phase 1 | | | • | | | | | | | · | | |
| Tocumear ES 1998 Prek. 2nd Grade FAD Floor Finishes LHSS L-GOB Confidence of the asset LFAD \$100,035.00 \$1 | | Tucumcari ES | 1998 | Classrooms | | Dist | Fire Sprinklers | LHSS | L-GOB | Building is not sprinklered | 22,319 | sf | \$10.00 | \$223,190 | \$290,147 | |
| Tucumean ES 1999 | | | | | | | · | | | To the b side doors leading to the floors. District is | | | | | | |
| Trucumcari ES 1998 Site Prek Zero Grade Protection Protect | | | | Cafeteria/ | | | | | | monitoring. The remaining areas are in good | | | | | | |
| Tucumcari ES | | Tucumcari ES | 1999 | Library/SPED | | FAD | Floor Finishes | LHSS | L-GOB | condition | 1 | FAD | \$100,035.00 | \$100,035 | \$130,046 | |
| Tucumcari ES 1998 Site Dist Z-Fencing LHSS L-GOB Complete perimeter fencing 2,000 ft \$100.00 \$200,000 \$260,000 Tucumcari ES 1998 Site Dist Z-Fencing LHSS L-GOB Replace west playground 1 ea \$50,000.00 \$50,00 | | | | PreK-2nd Grade | | | | | | Correction of tiles in the hallways and in the | | | | | | |
| Tucumcari ES | | Tucumcari ES | 1998 | Bldg | | FAD | Floor Finishes | LHSS | L-GOB | classrooms due to the settlement of the asset | 1 | FAD | \$156,782.00 | \$156,782 | \$203,817 | |
| Tucumcari ES 1998 Site Dist Z-Fencing LHSS L-GOB Complete perimeter fencing 2,000 if \$100.00 \$200.000 \$260.000 \$260.000 Tucumcari ES 1998 Site Dist Z-Playground Equipment LHSS L-GOB Replace west playground 1 ea \$50,000.00 \$50,000 \$65,000 \$65,000 Tucumcari ES 1998 Site Dist Z-Playground Equipment LHSS L-GOB Install swings at the old playground 1 ea \$20,000.00 \$20,000 \$26,000 | | | | PreK-2nd Grade | | | | | | Filling cracks and monitoring the areas of the | | | | | | |
| Tucumcari ES | | Tucumcari ES | 1998 | Bldg | | FAD | Interior Walls | LHSS | L-GOB | cracks in this asset | 1 | FAD | \$138,705.00 | \$138,705 | \$180,317 | |
| Tucumcari ES | | Tucumcari ES | 1998 | Site | | Dist | Z-Fencing | LHSS | L-GOB | Complete perimeter fencing | 2,000 | lf | \$100.00 | \$200,000 | \$260,000 | |
| Tucumcari HS 1962 Main Bldg FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$0.00 \$0 \$0 \$0 \$0 \$0 \$0 | | Tucumcari ES | 1998 | | | Dist | Z-Playground Equipment | LHSS | | Replace west playground | | | \$50,000.00 | \$50,000 | \$65,000 | |
| Tucumcari HS 1962 Main Bldg FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life: Bldg was replaced in 2006 0 FAD \$0.00 \$0 \$0 \$0 \$0 \$0 \$0 | | Tucumcari ES | 1998 | Site | | | | | | Install swings at the old playground | 1 | ea | \$20,000.00 | \$20,000 | \$26,000 | |
| Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 | | | | | | | | | | | | | | | | |
| Tucumcari HS 1946 Rattler Gym FAD Fire Sprinklers LHSS L-GOB Beyond Expected Life 1 FAD \$86,046.00 \$86,046 \$111,860 | | Tucumcari HS | 1962 | Main Bldg | | | Fire Sprinklers | | L-GOB | Beyond Expected Life: Bldg was replaced in 2006 | | | | \$0 | \$0 | |
| Tucumcari MS 1996 Addition FAD Communications / Security LHSS L-GOB Upgrade intercom \$32,182 27,520 sf \$2.50 \$68,800 \$89,440 | | Tucumcari HS | 1946 | Rattler Gym | | FAD | Fire Sprinklers | | L-GOB | Beyond Expected Life | 1 | FAD | \$86,046.00 | \$86,046 | \$111,860 | |
| Tucumcari MS 1996 Addition FAD Communications / Security LHSS L-GOB Upgrade intercom \$32,182 27,520 sf \$2.50 \$68,800 \$89,440 | | | 1962 | Main Bldg | | | Main Power/Emergency | | L-GOB | Bldg replaced in 2006 | | | | 7 - | 7 - | |
| Tucumcari MS 1972 Cafeteria Dist Communications / Security LHSS L-GOB Upgrade intercom \$32,182 15,800 sf \$2.50 \$39,500 \$51,350 | | Tucumcari MS | 1996 | Addition | | | | | L-GOB | Upgrade intercom \$32,182 | | | | \$68,800 | \$89,440 | |
| Tucumcari MS 1972 Cafeteria Dist Communications / Security LHSS L-GOB Upgrade intercom \$32,182 15,800 sf \$2.50 \$39,500 \$51,350 | | Tucumcari MS | 1970 | Main Bldg | | | | | | | | | | \$75,375 | \$97,988 | |
| Tucumcari MS 1980 Trojan Gym Dist Fire Detection / Alarm LHSS L-GOB No fire alarm in this building 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1996 Addition FAD Fire Detection/Alarm LHSS L-GOB \$32,182 27,520 sf \$3.50 \$96,320 \$125,216 Tucumcari MS 1970 Original Bldg Dist Fire Detection/Alarm LHSS L-GOB 30,150 sf \$3.50 \$105,525 \$137,183 Tucumcari MS 1972 Cafeteria Dist Fire Detection/Alarm LHSS L-GOB The building is not sprinklered 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$301,500 \$391,950 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 sf \$10.00 \$301,500 \$391,950 < | | Tucumcari MS | 1972 | | | Dist | Communications / Security | | | Upgrade intercom \$32,182 | | | | | | |
| Tucumcari MS 1980 Trojan Gym Dist Fire Detection / Alarm LHSS L-GOB No fire alarm in this building 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1996 Addition FAD Fire Detection/Alarm LHSS L-GOB \$32,182 27,520 sf \$3.50 \$96,320 \$125,216 Tucumcari MS 1970 Original Bldg Dist Fire Detection/Alarm LHSS L-GOB 30,150 sf \$3.50 \$105,525 \$137,183 Tucumcari MS 1972 Cafeteria Dist Fire Detection/Alarm LHSS L-GOB The building is not sprinklered 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$301,500 \$391,950 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 sf \$10.00 \$301,500 \$391,950 < | | Tucumcari MS | 1980 | Trojan Gym | | | | | L-GOB | There is no intercom in this building | | | | | \$51,350 | |
| Tucumcari MS 1970 Original Bldg Dist Fire Detection/Alarm LHSS L-GOB 30,150 sf \$3.50 \$105,525 \$137,183 Tucumcari MS 1972 Cafeteria Dist Fire Detection/Alarm LHSS L-GOB 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$158,000 \$205,400 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 sf \$10.00 \$301,500 \$391,950 Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 sf \$10.00 \$275,200 \$357,760 | | Tucumcari MS | 1980 | | | Dist | Fire Detection / Alarm | LHSS | L-GOB | No fire alarm in this building | | | \$3.50 | \$55,300 | \$71,890 | |
| Tucumcari MS 1972 Cafeteria Dist Fire Detection/Alarm LHSS L-GOB 15,800 sf \$3.50 \$55,300 \$71,890 Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$158,000 \$205,400 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 sf \$10.00 \$301,500 \$391,950 Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 sf \$10.00 \$275,200 \$357,760 | | | 1996 | | | | | | L-GOB | \$32,182 | | | | ' ' | | |
| Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$158,000 \$205,400 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 \$10.00 \$301,500 \$391,950 Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 \$10.00 \$275,200 \$357,760 | | | 1970 | Original Bldg | | Dist | Fire Detection/Alarm | | | | | | | \$105,525 | \$137,183 | |
| Tucumcari MS 1980 Trojan Gym Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 15,800 sf \$10.00 \$158,000 \$205,400 Tucumcari MS 1970 Original Building Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 30,150 \$10.00 \$301,500 \$391,950 Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 \$10.00 \$275,200 \$357,760 | | Tucumcari MS | 1972 | Cafeteria | | Dist | Fire Detection/Alarm | LHSS | | | | | | | | |
| Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 sf \$10.00 \$275,200 \$357,760 | | Tucumcari MS | 1980 | Trojan Gym | | Dist | Fire Sprinkler | LHSS | L-GOB | The building is not sprinklered | 15,800 | sf | \$10.00 | \$158,000 | \$205,400 | |
| Tucumcari MS 1996 Addition Dist Fire Sprinkler LHSS L-GOB The building is not sprinklered 27,520 sf \$10.00 \$275,200 \$357,760 | | | | | | | | | | | | | | | | |
| | | | 1970 | Original Building | | | | | L-GOB | The building is not sprinklered | | | \$10.00 | \$301, <u>5</u> 00 | \$391,950 | |
| Tucumcari MS 1970 Original Bldg FAD Fire Sprinkler LHSS L-GOB Required by UBC. Grandfathered in \$70,780 30,150 ea \$10.00 \$301,500 \$391,950 | | Tucumcari MS | 1996 | | | Dist | Fire Sprinkler | | L-GOB | | | | \$10.00 | \$275,200 | | |
| | | Tucumcari MS | 1970 | Original Bldg | | FAD | Fire Sprinkler | LHSS | L-GOB | Required by UBC. Grandfathered in \$70,780 | 30,150 | ea | \$10.00 | \$301,500 | \$391,950 | |

| DISTRICT | AREA- | | | Identified | | | Funding | | | | | | TOTAL PROJECT | |
|--------------------------------------|-------------|-------------------|------|------------|------------------------|----------|---------|---|-------|------|--------------|-----------------|---------------|--------------|
| PRIORITY FACILITY NAME | Year | AREA | ROOM | Ву | SYSTEM | CATEGORY | Source | FACILITY NEEDS | QTY | UNIT | COST/UNIT | MACC | COST | SUBTOTALS |
| Tucumcari MS | 1972 | Cafeteria | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 | FAD | \$8,363.00 | \$0 | \$0 | |
| Tucumcari MS | 1970 | Original Bldg | | | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 | FAD | \$23,411.00 | \$0 | \$0 | |
| Tucumcari MS | 1980 | Trojan Gym | | FAD | Main Power / Emergency | LHSS | L-GOB | In good condition | 0 | FAD | \$10,413.00 | \$0 | \$0 | |
| Tucumcari MS | 1970 | Original Building | | Dist | Plumbing | LHSS | L-GOB | Upgrade staff and students restrooms to ADA compliant | 400 | sf | \$300.00 | \$120,000 | \$156,000 | |
| Turumani MC | 4070 | Cofetaria | | Diet | Diversities | 11100 | | Beyond Expected Life: Upgrade restrooms in cafeteria to ADA compliant; restrooms alcoves not | 200 | -4 | ¢200.00 | \$20,000 | ¢447.000 | |
| Tucumcari MS | 1972 | Cafeteria | | | Plumbing | | L-GOB | ADA | 300 | | \$300.00 | \$90,000 | \$117,000 | |
| Tucumcari MS | 1970 | Site | | | Z-Fencing | | | Complete perimeter fencing | 2,500 | | \$100.00 | \$250,000 | \$325,000 | |
| Tucumcari MS | 1970 | Site | | FAD | Z-Playground Equipment | LHSS | L-GOB | No playground equipment | 0 | FAD | \$66,835.00 | \$0 | \$0 | |
| Tucumcari MS | 1970 | Site | | Dist | Z-Site Specialties | LHSS | L-GOB | Install solar traffic signs | 2 | ea | \$2,500.00 | \$5,000 | \$6,500 | \$3,915,051 |
| Tucumcari ES | 1998 | Site | | FAD | Z-Walkways | LHSS | | Could split as there is large fine sections. Being monitored for further damage by the district | 1 | FAD | \$315,170.00 | \$315,170 | \$409,721 | |
| Tucumcari MS | 1970 | Site | | FAD | Z-Walkways | LHSS | | The facility has lots of spalding and cracking | 1 | FAD | \$223,448.00 | \$223,448 | \$290,482 | \$700,203 |
| Priority 2 Building / Site System Up | grades Tota | al Needs: | | | | | | | | | | \$9,266,029 | \$12,045,838 | \$12,045,838 |

| ority 3 | Capital Projects Total No | eeds: | | | | | | \$4,959,250 | \$6,447,025 | \$6,447, | | |
|---------|---------------------------|-------|-------------------|------------------|--------|--------|---|-------------|-----------------|-------------|-------------|---------|
| 6 | Tucumcari MS | 1970 | Original Builidng | Renovation | EdPro | MP-GOB | Renovate Home Economics Lab | 1,450 | sf \$200. | \$290,000 | \$377,000 | \$6,447 |
| 2 | Tucumcari MS | | Site | Demolition | AdqStd | MP-GOB | Demolish old maintenance bldg. across from MS and create new parking lot with site lighting | 22,720 | sf \$12. | \$284,000 | \$369,200 | |
| 9 | Tucumcari HS | | Vo.Ag. Bldg. | New Construction | LocPol | MP-GOB | Create a storefront (small building) for customers to buy student vegetables | 120 | sf \$125. | \$15,000 | \$19,500 | |
| 1 | Tucumcari HS | | Site | New Construction | LocPol | MP-GOB | Create district baseball and softball field complex: lighted fields, concessions, restrooms, irrigated grass, bleachers, pressbox | 1 | ea \$3,750,000. | \$3,750,000 | \$4,875,000 | |
| 7 | Tucumcari HS | | Site | New Construction | LocPol | MP-GOB | Install canopies at Track & Field | 4 | ea \$25,000. | \$100,000 | \$130,000 | |
| 3 | Tucumcari HS | | 1948 | Renovation | FacRen | MP-GOB | Renovate Rattler Field Concessions | 250 | sf \$75. | 00 \$18,750 | \$24,375 | |
| 5 | Tucumcari ES | | Site | New Construction | EdPro | MP-GOB | Install Turf at South ES playground | 12,500 | sf \$8. | \$100,000 | \$130,000 | |
| 3 | Mountain View ES | | | Demolition | AdqStd | MP-GOB | Demolish part of bldg. / keep part of bldg. for Head Start Program | 16,060 | sf \$25. | \$401,500 | \$521,950 | |

Tucumcari Public Schools • 5-Year Facilities Master Plan GS Architecture • 2019